

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : **(65) 6476 3333**
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel : **(65) 6272 3892**
Fax : (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

05/11/2018

EQ INSURANCE CO LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110

Attention :- **XA039**

Page # :- 1

Veh # :- SKW1246A

Veh Model :- VW TOURAN 1.6

Estimate# :- CK418232

Claim # :-

ACC. Date :- 02/11/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BOOT	1 PC	2,455.15	2,455.15
2.	REAR BOOT LOGO	1 PC	184.20	184.20
3.	REAR BOOT EMBLEM "TOURAN"	1 PC	146.15	146.15
4.	REAR BOOT EMBLEM "TDI"	1 PC	98.35	98.35
5.	REAR BOOT EMBLEM "BLUEMOTION"	1 PC	101.15	101.15
6.	REAR BOOT LOCK	1 PC	283.35	283.35
7.	REAR BOOT LOCK INNER TRIM	1 PC	183.60	183.60
8.	REAR BOOT WINDSCREEN MOULDING	1 PC	289.60	289.60
9.	REAR BUMPER	1 PC	1,423.25	1,423.25
10.	REAR BUMPER LOWER	1 PC	668.75	668.75
11.	REAR BUMPER REFLECTOR LH	1 PC	86.10	86.10
12.	REAR BUMPER SPONGE	1 PC	84.35	84.35
13.	REAR BUMPER REINFORCEMENT	1 PC	668.65	668.65
14.	REAR BUMPER SIDE BRACKET L & R	2 PCS	41.05	82.10
15.	REAR BUMPER RIVET	10 PCS	4.00	40.00
LIST TOTAL S\$				6,794.75
10% DISCOUNT S\$				-679.48
				6,115.27
SPECIAL NET ITEMS :				
1.	REAR BOOT WINDSCREEN SEALANT	1 PC	80.00	80.00
2.	REVERSE SENSOR	1 PC	250.00	250.00
3.	REAR NUMBER PLATE	1 PC	80.00	80.00
SPECIAL NET TOTAL S\$				410.00
LABOUR :				
TO CUT WELD REAR PANEL, REAR FLOOR PANEL. TO REPAIR REAR FLOOR PANEL, REAR FENDER LH, REAR CHASSIS MEMBER. TO REMOVE AND REFIX DAMAGED PARTS, STRAIGHTEN AND RE-ALIGN AFFECTED AREAS				600 840.00
TO SPRAY AFFECTED AREAS				600 780.00
TO REMOVE AND REFIX REAR WINDSCREEN GLASS				120 180.00
TO REMOVE AND REFIX REAR BOOT MECHANISM, CHECK & TEST REAR WIPER MOTOR, AND CENTRE LOCKING SYSTEM				50 80.00
TO REMOVE AND REFIX THIRD ROLL CUSHION, SIDE COVER, SIDE GARNISH AND OTHER ATTACHMENT PARTS				50 180.00
TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE				30 60.00
TO RUST PROOF AFFECTED AREAS				30 50.00

Estimate

05/11/2018

EQ INSURANCE CO LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110

Attention :- **XA039**

Page # :- 1 133143

Veh # :- SKW1246A

Veh Model :- VW TOURAN 1.6

Estimate# :- CK418232

Claim # :-

ACC. Date :- 02/11/18

Terms :- C.O.D Days

Remarks :-

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: **(65) 6476 3333**
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: **(65) 6272 3892**
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
	LABOUR TOTAL S\$			2,170.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 8,695.27

GST @ 7 % 608.67

AMOUNT DUE S\$ 9,303.94

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Tanpin 97895749
 WP 9/11/18 @ 3pm
 Resum after repair
 05 days
 suv@movaltd.com