

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. :

SMA 7244 H

Make & Model :

HONDA SHUTTLE

Chassis No. :

GP71208824

Submit By :

CARMEN LIM

Year Manufacture :

2018

Engine No. :

Cost / List**Supplementary**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear Windscreen 1011-00 Shattered	1	\$1,011.00		✓
2	Wiper Arm Cover Cot	1	\$15.00	✓	✓
3	Tail Door Inner Pocket Del	1	\$19.50	✓	✓
4	Cargo Box CM	1	\$295.00	✓	✓
5	Rear Bumper Tow Cover Rd S	1	\$16.50	✓	X
6	Antenna PZ CM	1	\$58.10	✓	X
7	Condenser B1	1	\$985.00 ✓		✓
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

2400.10