SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aroresaid.		
	ACCIDENT STATEMENT	
Date Of Report	30/10/2018 11:36	
Date Of Accident	29/10/2018 12:55	
Exact Location Of Accident	TURNING TO FARRER ROAD	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	EL6750G	
Insured/Policyholder		
Name Of Registered Owner	YU SHI MING@JU SHI MING	

NRIC No S1204549B

 Email Address
 RSTYUSM@NUS.EDU.SG

 Mobile Phone No
 (LOCAL) +65-97366131

 Alternative Phone No
 OFFICE-64672092

Vehicle Particulars

Manufacturer

Model Q5 2.0 TFSI QU

Exact Purpose for which vehicle was being used at PRIVATE USE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

AUDI

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 2100406859-03

Cover Note Number

Driver

Name of Driver YU SHI MING@JU SHI MING

 NRIC No
 \$1204549B

 Date Of Birth
 08/05/1956

 Occupation
 INDOOR

 Date Of Driving Pass
 18/05/1979

Driving Experience 39 YEARS AND 5 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97366131

Fax Number

Contact Number OFFICE-64672092

EMail Address RSTYUSM@NUS.EDU.SG

Address

24 KING'S DRIVE

Postcode

266391

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

2

Number of Passengers (Including Driver)

Passenger 1

NAME:

: KHOO CHYE CHUANG

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

WE WERE WAITING TO TURN TO FARRER RD ON 29/10. THERE WAS THIS CAR, NO. SKT 136 G IN FRONT OF US. WHEN THE ROAD WAS CLEAR FOR TURNING, WE MAKE OUR TURN, HOWEVER THE CAR IN FRONT DIDN'T MOVE ON AS EXPECTED. THERE BY CAUSING US TO DONE INTO THE REAR

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKT136G

Vehicle Make/Model/Colour

HONDA/CIVIC

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

MRS WONG

NRIC/Passport Number

S0068412J

Contact Number

97877129

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the <u>Authorised Driver</u>.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (G.A) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing traud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

MINET SAVE PROPERTY

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name: WON'T WHOM'T SENT, FICEOUX NRIC/FIN NO : 62987143

SKETCH PLAN	•	
	Forrer Rd	
	6-F16750	
DECEMBE C	S - ST 136 G RCUMSTANCES OF THE ACCIDENT	
We w	vere writing to turn to flavor Road on 29/10. There w	clear
Abs Con	ring, we imake our turn, however the our in that	didnit

We were water is cor No. Sk	T 136 G TO	au to true	when the	rood was	clear
of turning, we.	as experted.	m, however there by	the cor- cusing us	in that	into

I/We declare the foregoing particulars are true in every respect.


policyholder's Signature Date & Time:

Official Sept 11 - Toronto.

Driver's Signature (if driver is not the policyholder) Date & Time: Meporting Centre Personnel's Signature Name: Welfin klassin JEAA HOYK NRIC/FIN No.: 62987/47X


















CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

YUSHIMNG @JUSHIMNG

Period of Insurance

231 Mar 2018 To 30 Mar 2019

Engine No

: CNC051604: : WAUZZZ8R5EA112392

Chassis No.

EL 6750G Vetricle No. 5. Policy No. 7.11

Endorsement No.

Issued Date

ABOUT THE COVER

Make/Model

: AUDI Q5 2.0 TFSI QU (FACELIFT)(DYNAMIC STEERING)

Engine Capacity/Tonnage : 1,984.00 CC

Sum Insured : Market Value

First Year of Registration : 2015

: NA

Off Peak Car : No

Insuring with COE/PARF : Yes

Driver Restriction

Person or Classes of Persons Entitled to Drive*:

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition

: All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving furtion, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1000 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

YU SHI MING @JU SHI MING - \$1000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS

1.Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hottine at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from ITunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: OCBC Bank Ltd

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act. (Cap. 189). Part I/V of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125208

PREMIUM LEASING - SLOH

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$1295578B





KHOO CHYE CHUANG

彩庄

CHINESE Date of Birth

15-10-1958 SINGAPORE



REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$1204549B




YU SHI MING @JU SHI MING

余 熙 明

CHINESE Date of Birth 08-05-1956 Country of Birth INDONESIA







05-09-1993

24 KING'S DRIVE SINGAPORE 266391

\$1295578B Date: 03-06-1999 No: 2856322

1250225



NRC No. S1204549B

Date of saus Blood Group

05-09-1993

24 KING'S DRIVE SNCAPORE 200301 NRIC No: \$1204549B Date: 03-06-1999 No: 2856321


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES!

PASS DATE

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

18 May 1979

NP 428A





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: YU SHI MING @JU SHI MING

Period of Insurance

: 31 Mar 2018 To 30 Mar 2019

Engine No.

: CNC051604

Chassis No.

: WAUZZZ8R5EA112392

Vehicle No.

: EL6750G

Policy No.

2100406859-03

Endorsement No.

Issued Date

: 02 Mar 2018

ABOUT THE COVER

Make/Model

: AUDI Q5 2.0 TFSI QU (FACELIFT)(DYNAMIC STEERING)

Engine Capacity/Tonnage: 1,984.00 CC

Sum Insured : Market Value

First Year of Registration : 2015

Driver Restriction

· NA

Off Peak Car : No

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*:

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition

: All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving fulfion, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

EXCESS

Fire - \$0 Own Damage - \$1000 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

YU SHI MING @JU SHI MING - \$1000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency notline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: OCBC Bank Ltd

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125208

Copyright & 2018

PREMIUM LEASING - SLOH

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Reference : PA/OD/1264/2018/JT

Date : 8-Nov-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr.Yu Shi Ming
Address : 24 Kings Drive

Singapore 266391

 Telephone
 : (HP) 81611158

 Type of Claim
 : Own Damage Claim

 Policy No.
 : 2100406859-03

 Vehicle No
 : EL 6750 G

 Model Code
 : Audi QS 2.0 TFSI qu

Model / Year : Mar-15
Engine No : CNC 051604

Chassis No : WAUZZZ8R5EA112392

Mileage Date In

Liability : Excess Cost :

Estimated By : Johnny Boo / Allan Wu

Accident Date : 29-Oct-18
Place of Accident : Farrer Road

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. EL 6750 G.

			Estimated
S/N	Nature of Jobs		Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washers and front parking aid.	S/N	\$ 480.00
2	To dismantle and renew front bumper assy and LHS headlight. Re-organize front crash management components. Reinstall all parts		\$ 1,409.00 500.
3	To respray front bumper and front bumper lower spoiler		\$ 1,400.00 550
4	To carry out diagnostic checks.	S/N	\$ 192.00
	TOTAL LABOUR CHARGES	:	\$ 3,472.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EL 6750 G.

					rts & Prices
S/N	Parts Description			S/NETT	REMARKS
	22.7 (8)			2,237.00	×
1	FRONT BUMPER Report		\$		
2	FRONT BUMPER FIXING PARTS 2	ne wer	\$	236.00	-
3	FRONT BUMPER SPOILER		\$	540.00	
4	FRONT BUMPER LOWER CLOSING	ELEMENT AND	\$	180.00	
5	FOAM FILLER PIECE		\$	97.00	
6	PULL STRAP		4 \$	175.00	×
7	SECURING STRIP		\$	64.00	*
8	TOP COVER NEC		s	109.00	*
9	AIR GRILLE - LHS		\$	307.00	×
10	CAUTION & A/C STICKER		\$	19.00	
11	RADIATOR GRILLE (acled.		\$	1,556.00	~ 1244.80
12	"quattro" EMBLEM west New	/	\$	83.00	X
13	RADIATOR GRILLE STRIKER PLATE	24 m	\$	107.00	?
14	FRONT REINFORCEMENT BEAM	724 	\$	571.00	*
15	REINFORCEMENT TOP COVER		\$	56.00	*
16	FRONT BUMPER GUIDE - LHS		5	32.00	14
	FRONT BUMPER SUPPORT - LHS	NZ		50.00	1 ×
17		NCC		421.00) *
18	FRONT PARKING AID	V'		\$ 2,414.00	
19	HEADLIGHT - LHS			\$ 227.00	
20	FOG LIGHT - LHS	1	200	\$ 9,481.00	 0
	SUB TOTAL PARTS CHARGES		•	\$ 9,461.00	<u></u>
	t to all the second of Co	40 F/S			

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EL 6750 G.

				Damage Part	ts & Prices
				S/NETT	REMARKS
S/N	Parts Description				
	WEAD I CHT WASHER ASSY-LHS HIR MIR		\$	174.00k	X
21	-990 White	S/N	\$	25.00	200
22	FRONT NO PLATE		s	300.00 ?	X
23	JOHORIES		-		
	TOTAL PARTS CHARGES	1	3	974	
		1	\$	S/NETT 174.00 <i>t</i>	
	FRONT NO PLATE SINDRIES TOTAL PARTS CHARGES TOTAL LABOUR CHARGES GRAND TOTAL All charges are not inclusive of GST. Legend: Remarks (OK) = Approved, Remarks (X) = Not approved	13,452.00			
		185			
	All charges are not inclusive of GST.				
	Demarks (Y)	= Not approved			
	Spare parts are Special Nett.				

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date **Authorised Date**

Excess Cost

Liability

Remarks

LEF Aur Linsuitants hence notify

- To resigner, name what spike cainting
- To primary a marged partis) during resurvey.
- Pars : se inhaudient to continuation.
- . Truro curty survey is on a "Without Prejudice" basis
- No iffegal modification(s) is allowed.
- Supplementary (tem(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

: Authorised Repairs, 03 Days.

Adrian Ling. 08/11/18.

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate

Accident Repairs

Workshop

Ubi Road 1

Contact No

6366 2323

Fax No

6841 1183

Reference

: PA/OD/1264/2018/JT

Date

8-Nov-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

Mr.Yu Shi Ming

Address

24 Kings Drive

Singapore 266391

Telephone

(HP) 81611158

Type of Claim

Own Damage Claim

Policy No.

2100406859-03

Vehicle No

EL 6750 G

Model Code

Audi Q5 2.0 TFSI qu

Model / Year

Mar-15

CNC 051604

Engine No

WAUZZZ8R5EA112392

Chassis No

.

Mileage Date In

.

Liability

. .

Excess Cost

ž (7)

Estimated By

Johnny Boo / Allan Wu

Accident Date

29-Oct-18

Place of Accident

Farrer Road

Hi Adrian 3 days - ok - jb - 17 Dec 18

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. EL 6750 G.

S/N	Nature of Jobs		 stimated Charges	_	
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washers and front parking aid.	S/N	\$ 480.00	\$	480.00
2	To dismantle and renew front bumper assy and LHS headlight. Re-organize front crash management components. Reinstall all parts removed.		\$ 1,400.00	s	500.00
3	To respray front bumper and front bumper lower spoiler		\$ 1,400.00	\$	550.00
4	- diagnostic chacks	S/N	\$ 192.00	\$	192.00
	TOTAL LABOUR CHARGES	:	\$ 3,472.00	\$	1,722.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EL 6750 G.

				Damage Part	s &	Prices
	- L Borietion			S/NETT		REMARKS
S/N	Parts Description					
	FRONT BUMPER		\$	2,237.00		
1	FRONT BUMPER FIXING PARTS		\$	236.00		
2	FRONT BUMPER SPOILER		\$	540.00		
3	FRONT BUMPER LOWER CLOSING ELEMENT		\$	180.00		
4			5	97.00		
5	FOAM FILLER PIECE	4		175.00		
6	PULL STRAP	- 0	\$	64.00		
7	SECURING STRIP		\$	109.00		
8	TOP COVER		50.74-0.15	307.00		
9	AIR GRILLE - LHS		\$	27770707000		
10	CAUTION & A/C STICKER		\$	19.00		1,244.80
11	RADIATOR GRILLE		\$		\$	1,244.00
12	"quattro" EMBLEM		\$	83.00		
13	RADIATOR GRILLE STRIKER PLATE		\$	107.00		
14	FRONT REINFORCEMENT BEAM		\$	571.00		
15	REINFORCEMENT TOP COVER		\$	56.00		
11507719	FRONT BUMPER GUIDE - LHS		\$	32.00		
16	FRONT BUMPER SUPPORT - LHS		s	50.00		
17			\$	421.00		
18			\$	2,414.00		
19			\$	227.00		
20		100	_	halis Salas	\$	1,244.80
	SUB TOTAL PARTS CHARGES	17	\$	9,461.00	φ	1,241.00

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EL 6750 G.

				Damage Pa	rts i	& Prices
	THE SHALL CONTRACT OF CONTRACTOR			S/NETT		REMARKS
S/N	Parts Description	c/f			\$	1,244.80
0.4	HEADLIGHT WASHER ASSY - LHS		\$	174.00		
21		S/N	\$	25.00	\$	25.00
22	FRONT NO PLATE		\$	300.00		
23	SUNDRIES		Φ	70.000.000.000	•	1,269.80
	TOTAL PARTS CHARGES	1	\$	9,980.00	\$	
		1	\$	3,472.00	\$	1,722.00
	TOTAL LABOUR CHARGES	:	•	13,452.00	\$	2,991.80
	GRAND TOTAL		-	15,452.00	-	

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept Yr Ref: EL 6750 G Norah Khai 6768 9911 6841 1183 Nora.khai@premiumauto.com.sg

19 Jan 2019

Body & Paint Dept

PA/OD/1264/2018/MAS

from

Telephone +65-Telefax +65-

EMail

Our department

Our Ref Your Ref

Date

Dear Sir,

RE: INSURANCE CLAIM FOR EL 6750 G, Audi Q5 2.0 TFSI Qu

With reference to the above-mentioned vehicle, no. EL 6750 G claimant, Mr. Yu Shi Ming @Ju Shi Ming, please find the related document per attached.

- A copy of the Original invoice no. 85013355 S\$2,131.23
- A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encl AIG – EL 6750 G Bramium Automobi

total pages

Premium Automobiles Pte Ltc Showroom 9 Leng Kee Road Singapore 159090 Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

Coco	Notified	Est Submitted	Adj Assigned	Adj Rp	t 1	dj Submitted	Ins Auth'ed	100000000000000000000000000000000000000		
Case	30 Oct 2018	LSI Submittee	08 Nov 2018 17:54 Edit Adj Rpt	S\$2,991 Edit Estim	2000 H	S\$2,991.80 View Rpt		Pending Report Cancel	Case	
	Main	R	eference	CI	aim Detai	is)	Docume	nts	Show All	
CLAIM S Insured:	UBFOLDER DE		II MING@JU SHI I	MING, ID:	S1204549I	3, Tel: +6597	366131, Email	ated by insu :: RSTYUSM@I 0/2018 12:00	NUS.EDU.SG - :59	
Vehicle R	eg. No.:	EL67	ELU/30G		Date of Loss:			Date (Man Yr)	577	
Claim Typ	pe:	OD /						2100406859 (Comprehensive) Coverage: 31/03/2018 - 30/03/2019		
			Exce				1 1 1	S\$1,000.00		
Repairer:		Prem	ium Automobiles	Pte Ltd (UB	1) 55 Ubi	Road 1, 408699	Ubi - Tel: 6768	9828/9827/9	911	
Handling		Tongs	sia Pacific Insura hing.Loo@aig.com							
Adjuster:		due	Auto Consultants 19/11/2018]			56-3561 [Hai :: S1204549B,			[Final Kpt	
Driver/Co	ustodian:	YU SI	II MING@JU SHI MI	ING (02 / Ma	ie), incic	312043470,	101111003100			
ASSOCI	ATED MAIL RE	CEIVED					View Al	Comp	ose Case Mail	
AIG_S	G (13/11/2018)	: EL6750G / OD	/ 29/10/2018 /	Coverage &	Excess u	pdate				
Е	202-000-00-00					7/2			4	
	SOCIATED TAS	SKS			View	All Search	Tasks Cri	eate New Task	Complete	
Due D		Type Task	Group Subject	ct Handle	er Ass	igned By	Completed Or	Create	d On Done	

Claim Documents

*EL6750G (6374475010SG) OD
Oct 29 2018 12:00PM
[YU SHI MING@JU SHI MING]
Premium Automobiles Pte Ltd

1	Upload Documents	Upload Photos Compose New Letter Upload Video Upload Audio		Use Viewer	THE .
Pho	tos/Images		3 per	March Co.	7
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	-	Thumbnail	-
1	20/12/18 17:00	General View	0	Load JPG	V
2	20/12/18 17:00	General View	0	Load JPG	V
3	20/12/18 17:00	General View	0	Load JPG	7
4	20/12/18 17:00	General View	0	Load JPG	V
5	20/12/18 17:00	General View	0	Load JPG	V
33	20/12/18 17:00	General View	Ð	Load JPG	V
6	Marie Control Control Control		0	Load JPG	V
7	20/12/18 17:00	General View	0	Load JPG	7
8	20/12/18 17:00	General View	0	Load JPG	V
9	20/12/18 17:00	General View			1
10	20/12/18 17:00	General View	0	Load JPG	V
11	20/12/18 17:00	General View	0	Load JPG	V
12	20/12/18 17:00	General View	0	Load JPG	V
13	20/12/18 17:00	General View	Ð	Load JPG	V
14	20/12/18 17:00	General View	0	Load JPG	V
500		General View	0	Load JPG	V
15		43 (000 h) 200 (000) 400 (0	Load JPG	V
16	20/12/18 17:00	General View	0	Load JPG	V
17	20/12/18 17:00	General View	-	1 2000	1 100
	cumentation		1 per	page 🔻	V
		LKK Auto Consultants Pte Ltd (HQ)		Thumbnai	I Print
No 1	Relabel/Reorder 09/11/18 16:22	ESTIMATE	0		
2	09/11/18 16:22	DRIVING LICENSE AND NRIC	0		
3	09/11/18 16:23	Certificate of Insurance	0		-
4	25/01/19 08:31	WORKSHOP INVOICE	0	Charles and the second	-
5	25/01/19 08:31	DISCHARGE VOUCHER	0	Load PDF	

Linked Accident Report Documents

		2.7		
sment Reports		1 per p	page 🕶	V
inalized On	Premium Autocare Centre (Alexandra)	V. I	Thumbnail	Print
		0	Load HTM	
	Addendum Sheet	0	Load JPG	1
2/11/18 11:19	Accident Statement Addm. #1	0	MTH bool	
-/Imagas		3 per i	page •	V
	Premium Autocare Centre (Alexandra)		Thumbnail	Print
		0	Load JPG	V
		0	Load JPG	V
	N. A.	0	Load JPG	V
24 2-W-200-1-20-20	Accident Photo	0	Load JPG	V
		0	Load JPG	V
		0	Load JPG	V
	Abdulate (Market Market)	0	Load JPG	V
		0	Load JPG	V
		0	Load JPG	V
000000000000000000000000000000000000000	/10/18 15:27 2/11/18 11:19			

10	02/11/18 11:18	Accident Photo	Load JPG	V
	02/11/18 11:18	Accident Photo	Load JPG	V
10.00	02/11/18 11:18	Accident Photo	1 Load JPG	V
Doc	umentation		1 per page ▼	U
	1	Premium Autocare Centre (Alexandra)	Thumbnai	Print
	Finalized On	Sketch Plan	€ Load JPG	V
2	02/11/18 11:00	Sketch Plan #2	■ Load JPG	V

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	•
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way #08-16 Our File No:

CC3/AIG18020259/ATBN2

Singapore 079120

Date:

25/01/2019

REFERENCE

Insured/Claimant:

YU SHI MING@JU SHI MING

Policy No:

2100406859

Claim No: 6374475010SG

Date of Loss:

29/10/2018

Nature of Claim:

OD

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Colour:

Price:

EL6750G

Make & Model:

AUDI Q5, 2.0 TFSI Quattro (A) 31/03/2015 (Man. Year: 2014)

Engine No: Chassis No: Odometer:

CNC051604 WAUZZZ8R5EA112392

36796 km

Reg. Date:

Black

Engine Capacity: Market Value/New Car 1984 cc

S\$120,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

235/55R19

Rear Tyre Size:

235/55R19

Front Left Side:

Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side:

Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 9,980.00 0.00	Adjuster's 1,269.80 0.00	8,710.20 0.00	Diff % 87.28
Labour Paintwork Labour	3,472.00 0.00	1,722.00 0.00	1,750.00 0.00	50.40
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$) - Excess (S\$)	13,452.00 1,000.00	2,991.80 1,000.00	10,460.20 0.00	77.76 0.00
(S\$)	12,452.00	1,991.80	10,460.20	84.00
+ GST 7.00/7.00% (S\$)	871.64	139.43	732.21	84.00
Nett Amount (S\$)	13,323.64	2,131.23	11,192.41	84.00

INSPECTION

Date of Assignment:

08/11/2018

Date Inspected:

08/11/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair:

3.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

No.	Qty	mended Parts Part No. Particulars	Condition	Repairer's	Amount
_	41	*FRONT BUMPER	Repair	2,237.00 FS	*- FS
1	1	*FRONT BUMPER FIXING PARTS	Not Necessary	236.00 FS	*-FS
2	-19	*FRONT BUMPER SPOILER	Not Necessary	540.00 FS	*-FS
3	1	*FRONT BUMPER LOWER CLOSING ELEMENT	Not Necessary	180.00 FS	*-FS
4	-34	*FOAM FILLER PIECE	Not Necessary	97.00 FS	*-FS
5	1	*PULL STRAP	Not Necessary	175.00 FS	*-FS
6	4	*SECURING STRIP	Not Necessary	64.00 FS	*-FS
7	1	*TOP COVER	Not Necessary	109.00 FS	*-FS
8	-1	*AIR GRILLE-LHS	Not Necessary	307.00 FS	*-FS
9	1	*CAUTION & A/C STICKER	Not Necessary	19.00 FS	*-FS
10	1	*RADIATOR GRILLE	Cracked	1,556.00 FS	*1,244.80 FS
11	1	*QUATTRO EMBLEM	Not Necessary	83.00 FS	*-FS
12	- 1	*RADIATOR GRILLE STRIKER PLATE	Not Necessary	107.00 FS	*-FS
13	1	*FRONT REINFORCEMENT BEAM	Not Necessary	571.00 FS	*-FS
14	1	*REINFORCEMENT TOP COVER	Not Necessary	56.00 FS	
15	1	*FRONT BUMPER GUIDE-LHS	Not Necessary	32.00 FS	*-FS
16	1	*FRONT BUMPER SUPPORT-LHS	Not Necessary	50.00 FS	
17 18	1	*FRONT PARKING AID	Not Necessary	421.00 FS	
400000	-	*HEADLIGHT-LHS	Not Necessary	2,414.00 FS	*- FS
19	1	*FOG LIGHT-LHS	Not Necessary	227.00 FS	*- FS
20		*HEADLIGHT WASHER ASSY-LHS	Not Necessary	174.00 FS	*- F8
21	1	*FRONT NO PLATE	Necessary	25.00 FS	*25.00 FS
22	1	*SUNDRIES	Not Necessary	300.00 FS	*- F8
100,000	ranchis	e part. S=SpcNett.		-	1 11 2/2 200
10.75	DE TOTTIO	म् । संस्थाः स्थान्य । स्थान्य स्थान्य । । । । । । । । । । । । । । । । । । ।	Total Parts (S\$	9,980.00	1,269.80

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Re	commended Labour			727 70.002
No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items		550000	
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHERS AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ASSY AND LHS HEADLIGHT.RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,400.00	500.00
3	TO RESPRAY FRONT BUMPER AND FRONT BUMPER LOWER SPOILER	New	1,400.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
	Gross Labo	ur Cost (S\$)	3,472.00	1,722.00
	Report was unsubmitted dur	ing this print-out.		

< END OF ESTIMATES >