

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SH6271C

DATE: 7. Nov. 2018

MAKE : HYUNDAI

MODEL : Sonata

DOA: 6. Nov. 2018

**EQ**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Fender – RH <i>X repair</i>			\$593.00
1	Front Door - RH <i>X repair</i>			\$1,345.00
<b>SUB TOTAL</b>				<b>\$1,938.00</b>
<b>LESS 20%</b>				<b>\$387.60</b>
<b>DISCOUNTED TOTAL</b>				<b>\$1,550.40</b>
<b>1 Front Door Comfort Sticker</b>				<b>\$75.00</b> <b>Nett</b>
<b>Labour Charge</b>				
1	Panel Beating			<del>\$500.00</del> <sup>200</sup>
1	Spray Painting Charge			<del>\$500.00</del> <sup>400</sup>
1	Tuff Kote			<del>\$50.00</del> <sup>X</sup>
1	Wiring Charge			<del>\$50.00</del> <sup>X</sup>
<b>TOTAL LABOUR</b>				<b>\$1,100.00</b>
<b>ESTIMATE TOTAL</b>				<b>\$2,725.40</b>
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

*Kalin 11/11/18*  
*8/11/18 11:55h*  
*2 Days*  
*4/3*  
*After Repair photo*

Larry Ng