

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: NGO SAU WEI SHAWN

Date: 12 Nov 2018

Preliminary Advice

Vehicle No	: SLD5734U	Accident Date	: 27/10/2018
Make	: AUDI A3	Policy No.	: D18MTPV01009763
Assignment Date	: 08/11/2018	Excess	: S\$0.00
Date of Inspection	: 09/11/2018	Est. Duration of Repair	: 4 days
Inspection At	: ComfortDelGro Engineering Pte Ltd (Ubi) 320 UBI ROAD 3 Singapore 408649		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,559.30
Revised Amount	:S\$	4,583.80
Check Items (Estimated)	:S\$	44.00
Total	:S\$	4,627.80
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	53,705.00
Salvage Value	:S\$	
Margin for Repair	:S\$	31,295.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :