



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 04/12/2018

Survey Details:

Date of loss	7-Nov-18
Date of appointment	9-Nov-18
Date of survey	9-Nov-18
Location of survey	CONNECT 3

Vehicle Details:

Claim Type:	Third party
Vehicle number	PA 9396D
Make and Model	TOYOTA HIACE COMMUTER GL 3.0A 2982cc
Date of registration	14-Oct-14
Excess	
Market Value (est)	\$22,000.00
Parf Rebate (est)	\$2,107.00
Nett Loss (est)	\$19,893.00

Repair details:

Initial Estimate	\$ 12,176.63
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 2,910.91
Check items (estimate)	
Labour	\$ 2,220.00
Total	\$ 5,130.91
Lump Sum(if applicable)	\$ 4,100.00

Number of days for repair	<u>6 DAYS</u>
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

We have not authorized repairs. Based on TP video footage, Insured vehicle was from minor road. A letter was sent out to the Insured and no feedback received till date. TP LOD IN. For mandate approval.

Mandate:

Liability(TP)		100%
Proposed Repair Cost	\$	4,387.00 w/gst
Loss of Use	\$	600.00 \$100 x 6 day
Loss of Rental	\$	- no. of days
Loss of Income	\$	- no. of days
LTA/GIA search fees	\$	-
Others	\$	-
Proposed Total	\$	4,987.00