

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBE1820T181018

Estimate

Customer

Name: AXA Insurance Singapore Pte Ltd

Date: 04-10-18

Address: Motor Claims Department

Vehicle No: GBE1820T

8 Shenton Way #27-01

Model/Make: Toyota Hiace

AXA Tower

Singapore 068811

Van Turbo 5

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>3.085.00</i>	\$ 1,850.00	
2	Tailgate Lock <i>twi/gm</i>	\$ 359.00	
3	Tailgate Weatherstrip <i>twi</i>	\$ 391.20	
4	Number Plate "Metal" <i>2ul</i>	\$ 28.00	<i>15SN</i>
5	Number Plate Lamp Outer Garnish <i>11</i>	\$ 346.50	<i>X</i>
6	Tailgate Inner Trim Board <i>for</i>	\$ 480.00	<i>X</i>
7	Tailgate Inner Trim Board Clips 1 set <i>11</i>	\$ 65.00	<i>SN X</i>
8	Tailgate "70 KM/H" Sticker <i>rec</i>	\$ 14.00	<i>SN 10SN</i>
9	Tailgate "Toyota Logo" Motif <i>rec 58.10</i>	\$ 167.00	<i>+</i>
10	Tailgate "Corporate" Advertisement Sticker <i>rec</i>	\$ 380.00	<i>SN 280SN</i>
11	Tail Lamp 02 pcs (@ S\$365.10) <i>one</i>	\$ 730.20	
12	Exhaust Silencer <i>2</i>	\$ 917.60	<i>X</i>
13	Bumper <i>D.S</i>	\$ 465.00	
14	Bumper Clips 1 set <i>rec</i>	\$ 48.00	
15	Bumper Bracket 02 pcs (@ S\$39.10) <i>1 set</i>	\$ 78.20	<i>+</i>
16	Bumper Reverse Sensor <i>shut</i>	\$ 220.00	<i>SN 200SN</i>
17	Spare Tyre Carrier <i>1</i>	\$ 299.10	<i>X</i>
18	End Panel Inner	\$ 936.20	<i>7</i>
19	End Panel Outer <i>Body</i>	\$ 566.10	
20	Floor Panel Beam <i>Body</i>	\$ 260.00	
21	Tailgate Windscreen Glass Moulding <i>NS</i>	\$ 219.00	<i>X</i>
22	Tailgate Windscreen Glass Sealant <i>rec</i>	\$ 50.00	<i>SN 40SN</i>
	Remove and refix rear tailgate components & mechanism	\$ 80.00	<i>60</i>
	To check all wiring & electrical component for proper function	\$ 80.00	<i>20</i>
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,200.00	<i>800</i>
	To putty & spray painting & including touch up paint on accident aff	\$ 1,000.00	<i>700</i>
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 80.00	<i>11</i>
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 120.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 11,430.10

Total amount in Lump Sum Basis for repaired vehicle

\$ -

SDLS:

to Consultants hence notify
repairer of the following:
To survey before/after spray painting
To display damaged part(s) during resurvey
The prices are subject to confirmation
The survey is on a "Without Prejudice" basis
Legal modification(s) is allowed
Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer



M/s Liu's Brother Auto Engrg Wks

Not Authorized
*Law**1/3 &*
to be paid after 14-
13/11/18
6/11