

ASS. REC. BY:

REF:

CA/SMO18020421/Agb n2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Agnes Chan

of SMO

Date/Time: 12/11/2018

Meimian

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GZ5367P

Insured: GQJFU

at Workshop m/s Ho Beng

Tel: 81862100

of BK-3020A Ubi Rd 1 #01-33

Policy No: D18MTPCVE003557

Claim No: CMTD1804913

Sum Insured:

Excess:

Make of Veh:

D.O.A. 9/1/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>GZ5367P-X</u>
	<u>GQJFU - NA/NSA17010191/h4 DOA: 24/5/2017</u>
<u>13/11/18 @ 11:40am</u>	<u>Informed Agnes Chan, we are pending estimate from repairer.</u>
<u>30/11/18 @ 5:44pm</u>	<u>revised to Agnes Chan via Meimian.</u>

ASSIGNMENT

Adrian

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S		O/S	

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: G25367P Yr Regn: 2006 June

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace c.c. 2494

Colour: Black A/C: Insured / Std / NI / NA

Sp.Reading: 345357 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFH502P800047629

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: 195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A.	D.O.I. <u>12/11/18</u>

Survey held at Ho Bery

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP: <u>Sompo</u>
	COE Expiry: <u>07/06/21</u>
	* Lump Sum <u>\$5200</u> / days of repair <u>8</u> (Red. <u>\$9735.25, 65%</u>)
	MV: <u>22K</u> MV: <u>\$77K (est)</u>
	PV: <u>11.5K</u> UPA: <u>11489</u>
	Nett: <u>10.5K</u> NV: <u>10511</u>
	RECEIVED 31 JAN 2019
	8136W

Date/Time, File Pass to?	Date/Time, File Return to?
1) <u>2/1/19</u>	2)
3)	4)
5)	6)
Prel. Report:	
Final Report:	

Part Prices Check:	
IN	OUT

Survey Fee:	Date:
Basic & Add.	<u>350</u>
S + RS, SI	<u>10</u>
Photos	
Others	
TOTAL	<u>360</u>

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: IRENE JAMES HENRY

Date: 30 Jan 2019

Preliminary Advice

Insured Vehicle No	: GW27U	Accident Date	: 09/11/2018
TP Vehicle No	: GZ5367P	Assignment Date	: 12/11/2018
Make	: TOYOTA HIACE	Est. Duration of Repair	: 8.00
Date of Inspection	: 12/11/2018		
Inspection At	: HO BENG TRADING (HQ) BLK 3020A #01-33, UBI ROAD 1 SINGAPORE 408714		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,791.25
Revised Amount	:S\$	6,487.88
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,487.88
Lump Sum Repair	:S\$	5,200.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Nov 2018		12 Nov 2018 12:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

[Created by insurer]

CLAIM SUBFOLDER DETAILS

Insured:	TAYLOR STANLEY MARKETING PTE LTD , Co. Reg. No.: A200507051E		
Main Claimant:	ORCHID THAI CATERING , Co. Reg. No.: 52998136W		
Vehicle Reg. No.:	GZ5367P	Date of Loss:	09/11/2018 12:00 - :59
Claim Type:	TP / CMTD1804913	Policy/Cover Note No.:	D18MTPCVE003557 (Third Party Only)
Vehicle Reg. No. (Insured):	GW27U	Policy No. (Claimant):	
		Excess:	
Repairer:	Ho Beng Trading (HQ) Blk 3020A #01-33, Ubi Road 1, 408714 Ubi - Tel: 81862100		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/11/2018]		
Driver/Custodian (Insured):	TAN SIEW CHOO NANCY (), NRIC: S0071569G, Tel: +6597399218		

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

(IN)

PFB

12/11 @ 2:02pm

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Tuesday, 13 November 2018 11:40 AM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE GZ 5367P (YOUR REF: CMTD1804913)

This mail is associated with :
***GZ5367P (CMTD1804913)**
[GW27U]
TP
ORCHID THAI CATERING
Nov 9 2018 12:00PM
[TAYLOR STANLEY MARKETING PTE LTD]
Ho Beng Trading

Dear Agnes,

Please be informed that we have inspected the vehicle GZ 5367P on 12/11/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle No. is Exported:

Intended Registration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

POP Paid:

COE Rebate Amount:

Total Rebate Amount:

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 11 Nov 2018

Business

8138W

GZ5357P

Yes

11 Nov 2018

TOYOTA

HIACE MANUAL

Silver

2006

2JD1467111

JTFHSC2P800047629

\$22,810.00

08 Jun 2006

08 Jun 2006

1

\$1,191.00

No

\$0.00

07 Jun 2021

C - Goods Vehicle & Bus

5

\$22,926.00

\$11,489.00

\$11,489.00

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	8136W
Vehicle Details	
Vehicle No.:	GZ5367P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	2JD1467111
Chassis No.:	JTFHS02P800047629
Maximum Power Output:	-
Open Market Value:	\$23,810.00
Original Registration Date:	08 Jun 2006
First Registration Date:	08 Jun 2006
Transfer Count:	1
Actual ARF Paid:	\$1,191.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Jun 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,326.00
COE Rebate Amount:	\$11,477.00
Total Rebate Amount:	\$11,477.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 12 Nov 2018

OK

CHEAPEST CAR INSURANCE RENEWAL

Choice of \$0 excess | Option of any workshop

GET A CHEAPER QUOTE NOW!

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad |
 Advertiser Login |
 Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5a

2.88%p.a Lowest Interest@GV
 Cars Financing \$2000
 Downpayment Monthly From \$488
 GV Credit Pte Ltd StarAd

AutoInn
An Inspiration For Car Buyers

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category Save Search Print « Back (1 2) Next »

31 vehicles | **Search** Hiace Advanced Search Search View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection	Hiace	Any	Any	> 10 year(s) old	Any	Any	Any	Available
	<input type="checkbox"/> Toyota Hiace (COE till 09/2020) Fuel Type: Diesel	\$11,438	\$6,070 /yr	06-Oct-2000	2,986 cc	-	Van	Available
<p> Posted: 22-Sep-2018 Tags: 2000 Toyota Hiace, 2000 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota</p>								
	<input type="checkbox"/> Toyota Hiace (COE till 09/2022) Fuel Type: Diesel \$0 Drive Away. Best Buy. Current Paper \$23383. Best Buy. Trade In Welcome.	\$29,000	\$7,460 /yr	21-Oct-2002	2,986 cc	-	Van	Available
<p> Posted: 15-Oct-2018 Tags: 2002 Toyota Hiace, 2002 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota</p>								
	<input type="checkbox"/> Toyota Hiace (COE till 07/2023) Fuel Type: Diesel	\$25,900	\$5,490 /yr	15-Aug-2003	2,986 cc	-	Van	Available
<p> Posted: 06-Oct-2018 Tags: 2003 Toyota Hiace, 2003 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota</p>								
	<input type="checkbox"/> Toyota Hiace (COE till 08/2019) Fuel Type: Diesel Cheapest In The Market! Well Maintained By Previous Owner! No Repairs Needed! Wear And Tear Replaced! Eligible For New ETS Scheme Up To 35% Discount! Low Maintenance! Hassle Free Machine! A Definite W... Net Link Partners Pte Ltd	\$21,800	\$28,620 /yr	18-Aug-2004	2,986 cc	-	Van	Available
<p> Posted: 19-Oct-2018 Tags: 2004 Toyota Hiace, 2004 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota</p>								
<p>GET YOUR COE RENEWAL LOAN</p> <p>Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.</p>								
	<input type="checkbox"/> Toyota Hiace (COE till 02/2022) Fuel Type: Diesel COE. Left 4 Years.	\$25,000	\$7,580 /yr	14-Oct-2004	2,986 cc	-	Van	Available
<p> Posted: 28-Oct-2018 Tags: 2004 Toyota Hiace, 2004 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota</p>								
	<input type="checkbox"/> Toyota Hiace (COE till 04/2021) Fuel Type: Diesel Most Reliable And Popular Commercial Van In The Market. Selling, Done Servicing, New Paintwork, No Repair Needed, Excellent Condition, We Provide High Loan/High Trade In. 100% Loan Available, Call Our...	\$21,800	\$8,910 /yr	24-Apr-2006	2,494 cc	-	Van	Available
<p> Posted: 06-Nov-2018 Tags: 2006 Toyota Hiace, 2006 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota</p>								
	<input type="checkbox"/> Toyota Hiace (COE till 07/2021)	\$23,000	\$8,460 /yr	04-Sep-2006	2,494 cc	-	Bus	Available
<p> Compare</p>								



Fuel Type: Diesel

DIRECT OWNER

Can Convert To School Bus (CB Plate) If Available As Where It Is Condition. Do Not Miss This Opportunity Again. Make An Exclusive Appointment To View Now.

☆ Posted: 11-Sep-2018 Tags: 2006 Toyota Hiace, 2006 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace (COE till 03/2022) \$27,800 \$8,220 /yr 10-Apr-2007 2,982 cc 195,000 km Van Available

Fuel Type: Diesel

\$3k Drive Away! No Intro Needed For This Japanese Workhorse! Good For New Start-Up Business! Very Well Maintained By Previous Owner! No Repairs Needed! Can Drive To Your Trusted Workshop For Checking!...

PREMIUM AD

Car (S) Pte Ltd

☆ Posted: 12-Nov-2018 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace (COE till 05/2022) \$28,300 \$8,110 /yr 09-May-2007 2,982 cc - Van Available

Fuel Type: Diesel

One And Only Auto Transmission Toyota Hiace At This Price And Condition! Full Carpet Upholstery Cargo Space! Full Glass Window Panels Done! Genuine Low Mileage! Agent Maintained! Borneo Unit! Call Now...

PREMIUM AD

Net Link Partners Pte Ltd

☆ Posted: 10-Nov-2018 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace (COE till 06/2022) \$31,800 \$8,920 /yr 06-Jun-2007 2,982 cc - Van Available

Fuel Type: Diesel

Very Well Maintained By Previous Owner. Most Importantly, Accident Free! Buy With No Worries As Toyota Usually Doesn't Give Much Headaches. Don't Want To Invest Too Much On A Brand New Vehicle? No Pro...

☆ Posted: 29-Oct-2018 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Up to 20.88% petrol discount at Esso

Save up to 20.88% at Esso with the best petrol discount credit cards. Updated with the latest offers and promotions.

Find out more!



Toyota Hiace (COE till 07/2027) \$48,000 \$5,550 /yr 03-Jul-2007 2,982 cc 200,232 km Van Available

Fuel Type: Diesel

Auto Transmission. Only 5.5k Depreciation Per Year, Easy Loan, Cheapest In The Market! Well Maintained By Previous Owner. No Repairs Needed! Wear And Tear Replaced And Very Low Maintenance! Definitely ...

☆ Posted: 28-Oct-2018 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace (COE till 07/2022) \$29,800 \$8,020 /yr 13-Aug-2007 2,982 cc 200,000 km Van Available

Fuel Type: Diesel

PREMIUM AD

☆ Posted: 26-Oct-2018 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace Commuter \$48,800 N.A 28-Sep-2007 2,982 cc 132,000 km Bus Available

Fuel Type: Diesel

New 10 Years COE. Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only!

Boeki Auto & Marine

☆ Posted: 07-Nov-2018 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace Commuter (COE till 10/2022) \$29,800 \$7,540 /yr 26-Oct-2007 2,494 cc - Bus Available

Fuel Type: Diesel

Excellent Condition 12 Seater Hiace Bus! Call To View Now Before It Is Too Late! In House Loan Available.

Hui Hua Credit Pte Ltd

☆ Posted: 20-Oct-2018 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace Commuter (COE till 11/2022) \$38,888 \$9,670 /yr 20-Nov-2007 2,982 cc 76,000 km Bus Available

Fuel Type: Diesel

One Owner Only With Low Mileage Unit! Road Tax Till May 2018! Brand New Paintwork. Definitely Good To Go For Another 5/10 Years. Most Popular Japan Make And Model Van. Most Of The Wear And Tear Has Be...

DIRECT OWNER

☆ Posted: 08-Sep-2018 Tags: 2007 Toyota Hiace, 2007 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace (COE till 03/2023) \$30,800 \$7,030 /yr 01-Apr-2008 2,982 cc - Van Available

Fuel Type: Diesel

PREMIUM AD

Additional Insurance Discount Will Be Given When You Purchase A Vehicle From Us! One Of The Most Durable And Reliable Workhorse For Sales! Just Renew 5 Years COE, No Repairs Needed, Easy To Maintenan...

KSL Automotive Pte Ltd

SHORTLISTED HISTORY Compare

HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714
 Tel: (65) 69664526 HP: 92712214 Fax: (65) 69664526
 Email: chris_cuanbebe@hotmail.com

JTFH502 P8000A7629

12^{NO} Nov 2018

BLOCK 3020A UBI ROAD 1
 # 01-33
 Singapore 408714

TP Sampo.
 Xiao Chen

Accident date: 09th NOV 2018
 Estimated repair cost for vehicle no: GZ5367P TOYOTA HIACE '06

S/n	Qty	Items	U/price	Amount
1	1	rear panel -LH <i>Repr</i>		\$2,815.20 <i>X</i>
2	1	Rear panel inner trim board-LH <i>new</i>		\$561.80 <i>X</i>
3	10	Rear panel inner trim board clips <i>new</i>	\$12.90	\$129.00 <i>X</i>
4	1	Rear panel inner panel-LH <i>Repr</i>		\$1,210.70 <i>✓</i>
5	1	Rear panel center moulding-LH <i>new</i>		\$361.55 <i>X</i>
6	1	rear panel logo <i>new</i>		\$800.00 <i>500(SW)</i>
7	1	Rear L/H tire <i>new</i>		\$350.00 <i>X</i>
8	1	Rear L/H tire rim <i>new</i>		\$300.00 <i>X</i>
9	1	Rear boot lid <i>cracked</i>		\$1,850.00 <i>1755</i>
10	1	Rear boot lid 70 km/h logo <i>new</i>		\$25.00 <i>10(SW)</i>
11	1	Rear boot lid inner rubber <i>wt</i>		\$287.70 <i>✓</i>
12	1	Rear tail lamp-LH <i>cracked</i>		\$329.10 <i>✓</i>
13	1	Rear bumper <i>damaged</i>		\$482.20 <i>✓</i>
14	3	Rear bumper clips <i>new</i>	\$12.90	\$103.20 <i>30</i>
15	2	Rear bumper side bracket <i>LH damaged</i>	\$121.10	\$242.20 <i>121.10</i>
16	1	Rear bumper reverse sensor <i>damaged</i>		\$350.00 <i>200(SW)</i>
17	1	Rear end panel outer <i>Distorted</i>		\$561.40 <i>X</i>
18	1	Rear end panel top moulding <i>HP new</i>		\$182.20 <i>X</i>

Air Vent *cracked*
 Tailgate Advertisement *8 stickers new* *44 ✓* *300 250* Subtotal :- \$10,941.25
 3610.50 SW: 960
 2707.87

Labour charges

To remove & re-fix rear windscreen	\$150.00	120
Gum KCC	\$50.00	/
To remove & re-fix cushion	\$150.00	60
To remove & re-fix undercarriage	\$0.00	X
To wheel alignment computer	\$120.00	X
Tuff kote	\$120.00	60
To Check Wiring System	\$60.00	30
Towing fee	\$0.00	X
Panel beating	\$1,500	1300
Spray painting	\$1,500	1200

2820

Subtotal :- \$2,850.00

Total:- \$13,791.25

total: 6487.87
 4/s: 92k
 08 days

14935.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18020421/AQBN2

Date: 31/01/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE003557
Claimant Vehicle No :	GZ5367P	Insured Vehicle No :	GW27U
Date of Loss:	09/11/2018	Nature of Claim:	TP
		Claim No:	CMTD1804913

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GZ5367P	Engine No:	2JD1467111
Make & Model:	TOYOTA HIACE, 2.0 (M)	Chassis No:	JTFHS02P800047629
Reg. Date:	08/06/2006 (Man. Year: 2006)	Odometer:	345357 km
Colour:	Black		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,335.25	3,717.87	7,617.38	67.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	2,770.00	830.00	23.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,935.25	6,487.87	8,447.38	56.56
Approved Total (Overridden) (\$\$)		5,200.00		
Nett Amount (\$\$)	14,935.25	5,200.00	9,735.25	65.18

INSPECTION

Date of Assignment:	12/11/2018	Inspected At:	Ho Beng Trading (HQ)
Date Inspected:	12/11/2018		Blk 3020A #01-33, Ubi Road 1
			Singapore 408714
Estimated Period of Repair:	8.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$22,000.00 (EST) -LTA REIMBURSEMENT VALUE: \$11,489.00=NETT VALUE: \$10,511.00

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 31 Jan 2019)
Parts:	N/A TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ5367P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR PANEL-LH	Repair	2,815.20 F	*- FL
2	1		*REAR PANEL INNER TRIM BOARD-LH	Not Necessary	561.80 F	*- FL
3	10		*REAR PANEL INNER TRIM BOARD CLIPS	Not Necessary	129.00 F	*- FL
4	1		*REAR PANEL INNER PANEL-LH	Repair	1,210.70 F	*- FL
5	1		*REAR PANEL CENTER MOULDING-LH	Not Necessary	361.55 F	*- FL
6	1		*REAR L/H TIRE	Not Necessary	350.00 F	*- FL
7	1		*REAR L/H TIRE RIM	Not Necessary	300.00 F	*- FL
8	1		*REAR BOOT LID	Buckled	1,850.00 F	*1,755.00 FL
9	1		*REAR BOOT LID INNER RUBBER	Cut	287.70 F	*287.70 FL
10	1		*REAR TAIL LAMP-LH	Cracked	329.10 F	*329.10 FL
11	1		*REAR BUMPER	Deformed	482.20 F	*482.20 FL
12	8		*REAR BUMPER CLIPS	Necessary	103.20 F	*30.00 FL
13	1		*REAR BUMPER SIDE BRACKET	N/s Damaged	242.20 F	*121.10 FL
14	1		*REAR END PANEL OUTER	Distorted	561.40 F	*561.40 FL
15	1		*REAR END PANEL TOP MOULDING	Not Necessary	182.20 F	*- FL
16	1		*AIR VENT	Cracked	44.00 F	*44.00 FL
17	1		*REAR PANEL LOGO	Necessary	800.00 FS	*500.00 FS
18	1		*REAR BOOT LID 70KM/H LOGO	Necessary	25.00 FS	*10.00 FS
19	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
20	1		*TAILGATE ADVERTISEMENT STICKER	Necessary	300.00 FS	*250.00 FS
21	1		*GUM	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,335.25	4,620.50
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	902.63
Total Parts (\$\$)	11,335.25	3,717.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & RE-FIX REAR WINDSCREEN	New	150.00	120.00
2	TO REMOVE & RE-FIX CUSHION	New	150.00	60.00
3	TO REMOVE & RE-FIX UNDERCARRIAGE (NPA)	New	0.00	0.00
4	TO WHEEL ALIGNMENT COMPUTER	New	120.00	0.00
5	TUFF KOTE	New	120.00	60.00
6	TO CHECK WIRING SYSTEM	New	60.00	30.00
7	TOWING FEE (NPA)	New	0.00	0.00
8	PANEL BEATING	New	1,500.00	1,300.00
9	SPRAY PAINTING	New	1,500.00	1,200.00
Gross Labour Cost (S\$)			3,600.00	2,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >