

ASS. REC. BY:

REF:

CS/11CS18020448/KH62

Special Instruction:

Survivor

menmen

ASSIGNMENT (Office)

From (Person): Janice Goh of ECICS Date/Time: 12/11/2018

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJS1217S Insured:

at Workshop m/s Cheng Hoe Tel: 67556142

of BLK1019 Yishun #01-374

Policy No: MPC18A00279800 Claim No: DMPC1800417H/JG

Sum Insured: Excess: \$000

Make of Veh: D.O.A 6/11/2018
(Client's Record)CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12/11 Person Contacted: June Vehicle IN OUT

Date/Time	Action/Instruction () Estimate
	SJS1217S-X
13/11@15hrs	Revert via menmen repayer asking for \$6000/-
14/11 15:53pm	authorize by crystabelle Tan
14/11@5:10pm	inform June on the margin repair, As i spoken to crystabelle she say owner top up. but June will email crystabelle clarify on AIA Guide line.

ASS. REC. BY:

REF: 1051

Kennaeth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Soon:

Consistent? : Yes or No

Est. Repairs:

10

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STS12175

Yr Regn:

07, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Honda Odyssey cc

2354

Colour:

M. Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

138122

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

J14MRB38509C201479

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

215/55R17

BS / RUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

2

mm

L/Bal.

2

mm

D.O.A.

6/11/18

Rear

R/Bal.

3

mm

L/Bal.

3

mm

D.O.I.

12/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/11

File pass to Catherine

21/11

Inform June on the GIA Guild to line

Lump Sum \$5500

(Red: 246540: 30%)

- Top up amount \$637.50 (already done in menmen don't delete)

Total: \$4912.50 before GST.

RECEIVED 8 APR 2019

Date/Time, File Pass to?

11/14 Typst

Date/Time, File Return to?

21

☐ : Prel. Report☒ : Final Report

Days Of Repair: 10

Resurvey No. of Trip: 1

Survey Fee:

250

Transportation:

Fees:

Others

10

TOTAL

260

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format:

OD

Lump Sum / I.B.I. (\$

5500-

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Nov 2018 14:30 Sendback Est	12 Nov 2018 14:40 S\$8,015.40	12 Nov 2018 15:52 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	WANG CHIN HAN CHRISTOPHER, ID: S8027118B, Email: chrisdubbdw@gmail.com		
Vehicle Reg. No.:	SJS1217S	Date of Loss:	06/11/2018 12:00 - :59 [111 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DMPC1800417H/JG	Policy/Cover Note No.:	MPC18A00279500 (Comprehensive) Coverage: 08/08/2018 - 07/08/2019
		Excess:	S\$0.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Bldg 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Janice Goh - 6303 0182]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/11/2018]		
Driver/Custodian:	WANG CHIN HAN CHRISTOPHER (38 / Male), NRIC: S8027118B		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 21 November 2018 11:05 AM
To: 'chmotor@singnet.com.sg'
Subject: SJS 1217S

Dear June,

As spoken, please refer to be Guide line of GIA formula from ECICS Janice. Insured policy excess is \$0.00



Wed 21/11/2018 10:58 AM

Janice Goh Siew Geok (ECICS, Claims) <Janice_Goh@ecics.com.sg>

RE: SJS1217S / OD / DMPC1800417H/JG

To Denise Tay (LKKAuto)

 Click here to download pictures. To help protect your privacy, Outlook prevented automatic download of some pictures in this message.

Action Items

Hi Denise

Please proceed to authorise repair at \$5,137.50 (\$4,275.00 + \$862.50).

Repairer Requested	\$6,000.00
Margin for Repair	\$4,275.00
Exceed amount	\$1,725.00
Insurer - 50%	\$ 862.50
Policyholder - 50%	\$ 862.50

Based on guide by GIA - 50% share of the exceed amount btw insurer and policyholder.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 9 April 2019 9:47 AM
To: Efeeda (Cheng Hoe -Yishun)
Subject: RE: SJS 1217S

Dear Efeeda,

Please see breakdown:

Repairer Requested	\$5,550.00
Margin for Repair	\$4,275.00
Exceed amount	\$1,275.00
Insurer - 50%	\$637.50
Policyholder - 50%	\$637.50

$\$4,275.00 + \$637.50 = \$4,912.50$

Based on guide by GIA - 50% share of the exceed amount btw insurer and policyholder

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 3 April 2019 9:07 AM
To: 'Efeeda (Cheng Hoe -Yishun)' <chmotor@singnet.com.sg>
Subject: RE: SJS 1217S

Dear Efeeda,

Item no 25. 1PC a;ternator belt Kenneth say no photo. Cannot give.

Therefore finalized at lump sum \$5550/-

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Efeeda (Cheng Hoe -Yishun) <chmotor@singnet.com.sg>
Sent: Tuesday, 2 April 2019 12:06 PM

Cheng Hoe Motor Pte Ltd (Yishun-June)

From: "Denise Tay (LKKAuto)" <denisetay@lkkauto.com>
 Date: Wednesday, November 21, 2018 11:04 AM
 To: <chmotor@singnet.com.sg>
 Subject: SJS 1217S

Dear June,

As spoken, please refer to be Guide line of GIA formula from ECICS Janice. Insured policy excess is \$0.00



Wed 21/11/2018 10:58 AM

Janice Goh Siew Geok (ECICS, Claims) <Janice_Goh@ecics.com.sg>

RE: SJS1217S / OD / DMPC1800417H/JG

To: Denise Tay (LKKAuto)

Click here to download pictures. To help protect your privacy, Outlook prevented automatic download of some pictures in this message.

Action Items

Hi Denise

Please proceed to authorise repair at \$5,137.50 (\$4,275.00 + \$862.50).

Repairer Requested	\$6,000.00	5550/-
Margin for Repair	\$4,275.00	4275/-
Exceed amount	\$1,725.00	1275
Insurer - 50%	\$ 862.50	637.5
Policyholder - 50%	\$ 862.50	637.50

Based on guide by GIA - 50% share of the exceed amount btw insurer and policyholder.

Thank you.

Regards,
 Janice Goh
 Claims Division
 DID: +65 6303 0182
 FAX: +65 6338 9267

ECICS Limited
 10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

21/11/2018

View Received Message

This mail is associated with :

SJS1217S (DMPC1800417H/JG)

OD

Nov 6 2018 12:00PM

[WANG CHIN HAN CHRISTOPHER]

Cheng Hoe Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From ECICS Limited (HQ) (ECICS), sent on 14/11/2018 15:53 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$4275.00) - SJS1217S - Claim Handler: Janice Goh

Approved:4275.00:Please upload log card

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Janice Goh

Date: 13 Nov 2018

Preliminary Advice

Vehicle No	: SJS1217S	Accident Date	: 06/11/2018
Make	: HONDA ODYSSEY	Policy No.	: MPC18A00279500
Assignment Date	: 12/11/2018	Excess	: S\$0.00
Date of Inspection	: 12/11/2018	Est. Duration of Repair	: 10.00
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,015.40
Revised Amount	:S\$	6,190.61
Check Item	:S\$	1,394.80
Total	:S\$	7,585.41
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	23,000.00
COE / PARF Rebate	:S\$	18,725.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,275.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Repairer is asking repair cost at all in \$6000/-

Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 7118B

Vehicle Details

Vehicle No.: SJS1217S
Vehicle to be Exported: No
Intended Deregistration Date: 09 Nov 2018
Vehicle Make: HONDA
Vehicle Model: ODYSSEY 2.4L AT SR
Primary Colour: Purple
Manufacturing Year: 2009
Engine No.: K24Z21301486
Chassis No.: JHMRB38509C201479
Maximum Power Output: 132.0 kW (177 bhp)
Open Market Value: \$34,796.00
Original Registration Date: 29 Jul 2009
First Registration Date: 29 Jul 2009
Transfer Count: 2
Actual ARF Paid: \$34,796.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Jul 2019
PARF Rebate Amount: \$17,398.00

Intended COE Rebate Details

COE Expiry Date: 28 Jul 2019
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$18,501.00
COE Rebate Amount: \$1,327.00
Total Rebate Amount: \$18,725.00

The information contained herein is correct as at 09 Nov 2018

OK

MV - \$23,300 -
less rebate (18,700)
4600
in A guide 2500
(5% of \$5000) \$7100
ERV ✓

Inchcape
Pre-Owned
6303 6303

FREE SERVICE & TYRE CREDITS
WHEN YOU PURCHASE A CAR FROM INCHCAPE-PREOWNED

PIT & GO
FREE SERVICE & TYRE CREDITS
VALUE \$1,500
FOR RICHARDS ABOVE \$15K

PIT & GO
FREE SERVICE & TYRE CREDITS
VALUE \$3,000
FOR RICHARDS ABOVE \$30K



LEARN MORE
»

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Toyota Estima,



Very Good Condition!
Direct Owner Stock



Browse by Category

< Back (1 2) Next >

Sort by Date Posted

20 results/page

21 vehicles

Honda Odyssey

Advanced Search

	Name	Model	Price	Depreciation	Reg. Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Odyssey		Any	Any	2009	Any	Any	Any	Available
	Honda Odyssey 2.4A Absolute (New 10-yr COE)		\$59,500	\$5,950 /yr	25-Feb-2009	2,354 cc	126,000 km	MPV	Available
	Car Has Been Perfectly Maintain And Driven By Previous Mature Owner! Paintwork In Perfect Showroom Condition! Interior Of The Car In Neat And Clean Look! Comes With Alpine Headunit, All Rounded Sensor...								
	Wheeler Dealers 2018 Pte Ltd								
	Posted: 09-Nov-2018 Tags: 2009 Honda Odyssey, 2009 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda								
	Honda Odyssey 2.4A Absolute (New 10-yr COE)		\$60,800	\$6,080 /yr	25-Mar-2009	2,354 cc	151,000 km	MPV	Available
	Full Loan With Monthly \$1012. 1 Owner, Low Mileage, 6 Months Warranty For Engine And Gearbox. Clean And Well Maintained Leather Seats. Superb Condition With All Wear And Tear Replaced. White On Beige ...								
	Posted: 09-Nov-2018 Tags: 2009 Honda Odyssey, 2009 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda								
	Honda Odyssey 2.4A		\$28,800	\$9,060 /yr	30-Dec-2009	2,354 cc	88,800 km	MPV	Available
	Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.								
	Boeki Auto & Marine								
	Posted: 09-Nov-2018 Tags: 2009 Honda Odyssey, 2009 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda								
	Honda Odyssey 2.4A Sunroof		\$23,800	\$9,370 /yr	15-Aug-2009	2,354 cc	154,500 km	MPV	Available
	Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.								
	Boeki Auto & Marine								
	Posted: 09-Nov-2018 Tags: 2009 Honda Odyssey, 2009 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda								
	Honda Odyssey 2.4A Sunroof		\$23,300	\$10,120 /yr	30-May-2009	2,354 cc	-	MPV	Available
	\$4k Down Payment! 5 Yr COE \$42,800, 10 Yr COE \$58,800, One Of The Most Reputable MPV For It's Reliability, Interior & Exterior Condition Well Taken Care Of, Regular Servicing & Maintenance Done, STA E...								
	Starline Automobile								
	Posted: 08-Nov-2018 Tags: 2009 Honda Odyssey, 2009 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda								
	Honda Odyssey 2.4A (New 10-yr COE)		\$59,900	\$5,990 /yr	19-Feb-2009	2,354 cc	170,000 km	MPV	Available
	Must View! Must Test! Must Buy! Odyssey Buyers Must Not Miss! You Will Know Why Once You Come For A Test Drive! Super Silent & Smooth Drive! Interior Is Like New! New Tyres/Batt/Engine & Gear Oil! Br...								
	Posted: 07-Nov-2018 Tags: 2009 Honda Odyssey, 2009 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda								
	Honda Odyssey 2.4A Sunroof		\$25,900	\$10,340 /yr	22-Sep-2009	2,354 cc	130,000 km	MPV	Available
	For Coe Renewal, Low Depre! Affordable Down Payment Plus! Professional Evaluation And Grooming Package Available. A Car Not To Be Missed. apt In Tip Top Condition By Previous Owner. Buy It ...								

Complete

odyssey, Used Honda

**Honda Odyssey 2.4A EXV Premium****\$24,500****N/A****18-Mar-2009****2,354 cc****118,000 km****MPV****Available**

Highest OMV Of \$37136. Road Tax Renewed Till October 2018. Well Maintained! No Repairs Needed! Great Short Term Drive! Beautiful Facelifted Model! Accident Free! Great Drive And Spacious Yet Luxurious...

DIRECT OWNER

Posted: 12-Sep-2018

Tags: 2009 Honda Odyssey, 2009 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda

**Honda Odyssey 2.4A Sunroof (New 5-yr COE)****\$39,800****\$7,960 /yr****16-Feb-2009****2,354 cc****127,000 km****MPV****Available**

1 Year Warranty! \$3K Drive Away! Accident Free Quality Pre-Owned With Low Mileage Done For Peace Of Mind, 100% Loan Approval With Our Flexible In House Financing Options. View Today!

Motor Universe Credit Pte Ltd

Posted: 06-Sep-2018

Tags: 2009 Honda Odyssey, 2009 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda

**Honda Odyssey 2.4A EXV Premium****\$32,000****\$17,110 /yr****05-Oct-2009****2,354 cc****210,000 km****MPV****Available**

One Owner And Agent Maintained.

DIRECT OWNER

Posted: 06-Sep-2018

Tags: 2009 Honda Odyssey, 2009 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

Home

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view [Expired ads](#)

◀ Back (1 2) Next ▶

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Honda Odyssey, Honda Odyssey Singapore, used Honda Odyssey Singapore, used Honda Odyssey, used vehicles Singapore or even buy used Honda Odyssey Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

500+ dealers
competed to
buy my car!



Sell ur Car for More Cash
Highest Price or Get \$100 Free
Get Paid Now, Handover Later

SELL YOUR CAR

HONDA ODYSSEY

Price Range

Depreciation

2009

Vehicle Type

Submit

Home > Used Cars > Starise Automobile > Honda Odyssey 2.4A Sunroof

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Honda Odyssey 2.4A Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map



STARISE AUTOMOBILE

Member of



Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$23,300	
Depreciation	\$10,070 /yr View models with similar depreciation	1
Reg Date	30-May-2009 (6mths 17days COE left)	
Manufactured	2008	2
Mileage	-	
Transmission	Auto	
Engine Cap	2,354 cc	
Road Tax	\$1,628 /yr	3
Power	132.0 kW (177 bhp) View specs of the Honda Odyssey (2008-2014)	
Curb Weight	1,680 kg	4
Features	Powerful And Responsive 2.4L DOHC 16 Valve I-VTEC Engine With 177Bhp, 5 Speed Auto Transmission, ABS, Cruise Control, SRS Airbags.	
Accessories	Sports Rim, Touch Screen DVD System, Reverse Sensor, Reverse Camera, Leather Seats, Retractable Side Mirrors, Rear Aircon, Sunroof.	
Description	\$4k Down Payment! 5 Yr COE \$42,800, 10 Yr COE \$58,800, One Of The Most Reputable MPV For It's Reliability, Interior & Exterior Condition Well Taken Care Of, Regular Servicing & Maintenance Done, STA Evaluation Can Be Arrange For Peace Of Mind Purchase, Option To Renew For 5 Or 10 Years COE, High Loan & High Trade In Available, Call Our Professional Sales Consultants For More Info Before It's Gone.	
COE	-	5
OMV	\$35,675	6
ARF	\$35,675	7
Dereg Value	\$17,838 as of today (change)	8
No. of Owners	3	9



Seller Information

Company	Starise Automobile  • dealer's prelist • 57 vehs sold 28 veh
Address	210 Turf Club Road Lot Search cars nearby this
Location	Car Mall @ The Grand
Office No	64697277
Contact Person(s)	Eric David Eddie Sam

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/11/2018 13:11
Date Of Accident	06/11/2018 12:50
Exact Location Of Accident	YISHUN CENTRAL
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJS1217S
Insured/Policyholder	
Name Of Registered Owner	WANG CHIN HAN, CHRISTOPHER (YUAN JUNHAN, CHRISTOPH
NRIC No	S8027118B
Email Address	CHRISDUBBDUW@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94758245
Alternative Phone No	OTHERS-94758245
Vehicle Particulars	
Manufacturer	HONDA
Model	ODYSSEY 2.4L AT SR
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC18A00279500
Cover Note Number	08/08/18 - 07/08/19
Driver	
Name of Driver	WANG CHIN HAN, CHRISTOPHER (YUAN JUNHAN, CHRISTOPH
NRIC No	S8027118B
Date Of Birth	11/09/1980
Occupation	OUTDOOR
Date Of Driving Pass	28/08/2000
Driving Experience	18 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94758245
Fax Number	
Contact Number	OTHERS-94758245
Email Address	CHRISDUBBDUW@GMAIL.COM

Address	BLK 328 YISHUN RING ROAD #03-1368
Postcode	760328
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SON GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Location is along Yishun Central at the junction with Yishun Ave 9. Both car A and car B moved off from an earlier junction before entering to the accident location. Car B began to accelerate and created a big gap with the adjacent lane. Just as car B was approaching the accident junction, the light turned amber and car B put in a hard brake and came to a full stop suddenly. Car A was following safely behind and tried to react by switching to the empty lane on the left. However, as there was a motorcycle that may also stop, to avoid committing to the lane change, car A stopped changing lane and prepared for impact.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ5639H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	97560340
Address	
Postcode	
Insurance Company Name	



DMA: 6/11/18 12:50pm

Both Car A and Car B moved off from an earlier junction before entering to the accident location.

Car B began to accelerate and created a big gap with the adjacent lane. Just as Car B was approaching the accident Junction, the light turned amber and Car B put in a hard brake and came to a full stop suddenly.

Car A was following safely behind and tried to react by switching to the empty lane on the left. However, as there was a motorcycle that may also stop, to avoid committing to the lane change, Car A stopped changing lane and prepared for impact.

Note : Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

I/We declare the foregoing particulars are true in every respect.


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

(✓) Reporting Only

() Claim OD/TP at other workshop ()

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: **ECICS Limited (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD ECICS
Policy No:	MPC18A00279500	Date of Loss:	06/11/2018
Vehicle Reg. No.:	SJS1217S	Driveable?	
Driver Age/Info:	38 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WANG CHIN HAN CHRISTOPHER		
Driver:	WANG CHIN HAN CHRISTOPHER		
Make/Model:	HONDA ODYSSEY, 2.4 (A)	Vehicle Reg. Date:	29/07/2009
Vehicle Colour:	PURPLE		
Engine No:	K24Z21301486	Chassis No:	JHMRB38509C201479
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

Not Authorised
6/11/18
Remedy After Paving

COST OF CLAIMS	Amount
Parts	5,075.40
Miscellaneous Items	200.00
Labour	2,740.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	8,015.40
+ GST 7.00% (S\$)	561.08
Nett Amount (S\$)	8,576.48

This claim is handled by: **JUNE PHUA LIAN HUA**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Nov 2018)

Parts: M1-MPV HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SJS1217S/12/11/2018 14:40

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 PC FRT BUMPER	0.00	0.00	*460.00 F	✓
2	1		*1 PC FRT BUMPER FOG LAMP RH	0.00	0.00	*210.00 F	✓
3	1		*1 PC FRT BUMPER SIDE RETAINER RH	0.00	0.00	*11.00 F	✓
4	1		*1 PC FRT BUMPER REINFORCEMENT	0.00	0.00	*185.00 F	✓
5	1		*6 PCS FRT BUMPER CLIP @2/PCE	0.00	0.00	*12.00 F	✓
6	1		*1 PC FRT BUMPER TOP CHROME MOULDING	0.00	0.00	*280.00 F	✓
7	1		*1 PC FRT GRILLE	0.00	0.00	*155.00 F	✓
8	1		*1 PC FRT GRILLE MOULDING	0.00	0.00	*160.00 F	✓
9	1		*1 PC FRT GRILLE LOGO	0.00	0.00	*17.00 F	✓
10	1		*4 PCS FRT GRILLE CLIP @1.50/PCE	0.00	0.00	*6.00 F	✓
11	1		*1 PC FRT RH HEADLAMP	0.00	0.00	*450.00 F	✓
12	1		*1 PC FRT RH HEADLAMP ECU	0.00	0.00	*245.00 F	✓
13	1		*1 PC FRT RH HEADLAMP BULB	0.00	0.00	*198.00 F	✓
14	1		*1 PC FRT RH HEADLAMP SOCKET	0.00	0.00	*15.00 F	✓
15	1		*1 PC FRT RH HEADLAMP WIRE HARNESS	0.00	0.00	*230.00 F	✓
16	1		*1 PC FRT SUPPORT PANEL	0.00	0.00	*320.00 F	✓
17	1		*1 PC BONNET	0.00	0.00	*455.00 F	✓
18	1		*1 PC BONNET INNER RUBBER (FRT)	0.00	0.00	*38.00 F	✓
19	1		*1 PC FRT RH FENDER	0.00	0.00	*370.00 F	✓
20	1		*1 PC FRT RH FENDER INNER SHIELD	0.00	0.00	*75.00 F	✓
21	1		*6 PCS FRT RH FENDER INNER SHIELD CLIP @1.50/PCE	0.00	0.00	*9.00 F	✓
22	1		*1 PC FRT RH FENDER INNER PANEL	0.00	0.00	*390.00 F	✓
23	1		*1 PC RADIATOR SPARE TANK	0.00	0.00	*45.00 F	✓
24	1		*1 PC FRT SIPER TANK	0.00	0.00	*60.00 F	✓
25	1		*1 PC A;TERNATOR BELT	0.00	0.00	*70.00 F	✓
26	1		*1 PC ABS WIRE SENSOR	0.00	0.00	*148.00 F	✓

F=Franchise part.

Sub Total (\$\$) 4,614.00

+ Margin on L,N Items 10.00% (\$\$) 461.40

Total Parts (\$\$) 5,075.40

Cheng Hoe Motor Pte Ltd/SJS1217S/12/11/2018 14:40. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 SET FRT PARKING SENSOR	200.00 ✓
Sub Total (\$\$)			200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	1) TO PERFORM PANEL BEATING	New	1,200.00 ¹⁰⁰⁰
2	2) TO REMOVE AND REFIX AIRCON, CHECK, VACUUM AND REFILL GAS	New	100.00 ✓
3	3) TO REMOVE AND REFIX FRT RH UNDERCARRIAGE, ENGINE, CHECK MOUNTING, REPLACE ABS PUMP AND SENSOR AND RESET SYSTEM	New	300.00 ²⁵⁰
4	4) TO REMOVE AND REFIX WIRE HARNESS AND CHECK WIRING	New	80.00 ⁶⁰
5	5) TO PUTTY AND RESPRAY ON FRT RH ACCIDENT AFFECTED AREAS	New	1,000.00 ⁹⁰⁰
6	6) TO CHECK FRT RH UNDERCARRIAGE AND CONDUCT COMPUTERISED WHEEL ALIGNMENT	New	60.00 ?
Gross Labour Cost (S\$)			2,740.00

Cheng Hoe Motor Pte Ltd/SJS1217S/12/11/2018 14:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Nov 2018)
 Parts: M1-MPV HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/SJS1217S/12/11/2018 14:40
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

SJS1217S Odyssey
 02/82/LS

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT BUMPER	0.00	0.00	*460.00 F
2	1		*1 PC FRT BUMPER FOG LAMP RH	0.00	0.00	*210.00 F
3	1		*1 PC FRT BUMPER SIDE RETAINER RH	0.00	0.00	*11.00 F
4	1		*1 PC FRT BUMPER REINFORCEMENT	0.00	0.00	*185.00 F
5	1		*6 PCS FRT BUMPER CLIP @2/PCE	0.00	0.00	*12.00 F
6	1		*1 PC FRT BUMPER TOP CHROME MOULDING	0.00	0.00	*280.00 F
7	1		*1 PC FRT GRILLE	0.00	0.00	*155.00 F
8	1		*1 PC FRT GRILLE MOULDING	0.00	0.00	*160.00 F
9	1		*1 PC FRT GRILLE LOGO	0.00	0.00	*17.00 F
10	1		*4 PCS FRT GRILLE CLIP @1.50/PCE	0.00	0.00	*6.00 F
11	1		*1 PC FRT RH HEADLAMP	0.00	0.00	*450.00 F
12	1		*1 PC FRT RH HEADLAMP ECU	0.00	0.00	*245.00 F
13	1		*1 PC FRT RH HEADLAMP BULB	0.00	0.00	*198.00 F
14	1		*1 PC FRT RH HEADLAMP SOCKET	0.00	0.00	*15.00 F
15	1		*1 PC FRT RH HEADLAMP WIRE HARNESS	0.00	0.00	*230.00 F
16	1		*1 PC FRT SUPPORT PANEL	0.00	0.00	*320.00 F
17	1		*1 PC BONNET	0.00	0.00	*455.00 F
18	1		*1 PC BONNET INNER RUBBER (FRT)	0.00	0.00	*38.00 F
19	1		*1 PC FRT RH FENDER	0.00	0.00	*370.00 F
20	1		*1 PC FRT RH FENDER INNER SHIELD	0.00	0.00	*75.00 F
21	1		*6 PCS FRT RH FENDER INNER SHIELD CLIP @1.50/PCE	0.00	0.00	*9.00 F
22	1		*1 PC FRT RH FENDER INNER PANEL	0.00	0.00	*390.00 F
23	1		*1 PC RADIATOR SPARE TANK	0.00	0.00	*45.00 F
24	1		*1 PC FRT SIPER TANK	0.00	0.00	*60.00 F
25	1		*1 PC A;TERNATOR BELT	0.00	0.00	*70.00 F
26	1		*1 PC ABS WIRE SENSOR	0.00	0.00	*148.00 F

F=Franchise part.

Sub Total (\$\$) 4,614.00
 + Margin on L,N Items 10.00% (\$\$) 461.40
 Total Parts (\$\$) 5,075.40

Cheng Hoe Motor Pte Ltd/SJS1217S/12/11/2018 14:40. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 SET FRT PARKING SENSOR	200.00
Sub Total (\$\$)			200.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			100.
1	1) TO PERFORM PANEL BEATING	New	1,200.00
2	2) TO REMOVE AND REFIX AIRCON, CHECK, VACUUM AND REFILL GAS	New	150.00
3	3) TO REMOVE AND REFIX FRT RH UNDERCARRIAGE, ENGINE, CHECK MOUNTING, REPLACE ABS PUMP AND SENSOR AND RESET SYSTEM	New	300.00
4	4) TO REMOVE AND REFIX WIRE HARNESS AND CHECK WIRING	New	80.00
5	5) TO PUTTY AND RESPRAY ON FRT RH ACCIDENT AFFECTED AREAS	New	1,000.00
6	6) TO CHECK FRT RH UNDERCARRIAGE AND CONDUCT COMPUTERISED WHEEL ALIGNMENT	New	60.00
Gross Labour Cost (\$\$)			2,740.00

Cheng Hoe Motor Pte Ltd/SJS12175/12/11/2018 14:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

parts — #4051
add 10% #40510
#4456.10
200.00
SN
lab 2370.00
#7026.10
4/5 = \$5600

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Nov 2018 14:30 Sendback Est	12 Nov 2018 14:40 S\$8,015.40	12 Nov 2018 15:52 Edit Adj Rpt	S\$5,550.00 Edit Estimates	S\$5,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured: **WANG CHIN HAN CHRISTOPHER**, ID: S80271188, Email: chrisdubbdw@gmail.com

Vehicle Reg. No.: **SJS1217S** Date of Loss: 06/11/2018 12:00 - :59
[111 Months and 8 Days From LTA Reg Date (Man Yr)]

Claim Type: **OD / DMPC1800417H/JG** Policy/Cover Note No.: MPC18A00279500 (Comprehensive)
Coverage: 08/08/2018 - 07/08/2019

Excess: S\$0.00

Repairer: **Cheng Hoe Motor Pte Ltd (Yishun)** Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142

Handling Insurer: **ECICS Limited (HQ)** - Tel: 63374779 / 6303 0178 ... [Handled by **Janice Goh** - 6303 0182]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **KENNETH KONG**] ... [Final Rpt due 21/11/2018]

Driver/Custodian: **WANG CHIN HAN CHRISTOPHER (38 / Male)**, NRIC: S80271188 Email: chrisdubbdw@gmail.com

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- ECICS (09/04/2019): Alert - Adj Mandate Approved (S\$5550.00) - SJS1217S - Claim Handler: Janice Goh
- ECICS (14/11/2018): Alert - Adj Mandate Approved (S\$4275.00) - SJS1217S - Claim Handler: Janice Goh

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJS1217S (DMPC1800417H/JG)
OD
Nov 6 2018 12:00PM
[WANG CHIN HAN CHRISTOPHER]
Cheng Hoe Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On			Thumbnail	Print
1	12/11/18 14:40	Cheng Hoe Motor Pte Ltd (Yishun)	Repairer Estimates	Load HTM	
No	Finalized On			Thumbnail	Print
1	13/11/18 15:00	LKK Auto Consultants Pte Ltd (HQ)	Adjuster Immediate Advice	Load HTM	
2	09/04/19 10:03		Adjuster Immediate Advice	Load HTM	

Photos/Images				3 per page	☒
No	Relabel/Reorder			Thumbnail	Print
1	13/11/18 15:01	LKK Auto Consultants Pte Ltd (HQ)	General View	Load JPG	☒
2	13/11/18 15:01		General View	Load JPG	☒
3	13/11/18 15:01		General View	Load JPG	☒
4	13/11/18 15:01		General View	Load JPG	☒
5	13/11/18 15:01		General View	Load JPG	☒
6	13/11/18 15:01		General View	Load JPG	☒
7	13/11/18 15:01		General View	Load JPG	☒
8	13/11/18 15:01		General View	Load JPG	☒
9	13/11/18 15:01		General View	Load JPG	☒
10	13/11/18 15:01		General View	Load JPG	☒
11	13/11/18 15:01		General View	Load JPG	☒
12	13/11/18 15:01		General View	Load JPG	☒
13	13/11/18 15:01		General View	Load JPG	☒
14	13/11/18 15:01		General View	Load JPG	☒
15	13/11/18 15:01		General View	Load JPG	☒
16	09/04/19 10:29		Reinspection Photo	Load JPG	☒
17	09/04/19 10:29		Reinspection Photo	Load JPG	☒
18	09/04/19 10:29		Reinspection Photo	Load JPG	☒
19	09/04/19 10:29		Reinspection Photo	Load JPG	☒
20	09/04/19 10:29		Reinspection Photo	Load JPG	☒
21	09/04/19 10:29		Reinspection Photo	Load JPG	☒
22	09/04/19 10:30		Reinspection Photo	Load JPG	☒

Documentation				1 per page	☒
No	Finalized On			Thumbnail	Print
1	12/11/18 14:39	Cheng Hoe Motor Pte Ltd (Yishun)	E-filed GIA report	Load PDF	
2	12/11/18 14:40		Driver's Driving License	Load JPG	☒
No	Relabel/Reorder			Thumbnail	Print
1	13/11/18 15:04	LKK Auto Consultants Pte Ltd (HQ)	ESTIMATE	Load PDF	
2	14/11/18 17:07		LOG CARD	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Repairer ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunoss Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS18020448/KTBE2

Date: 09/04/2019

REFERENCE

Insured/Claimant: WANG CHIN HAN CHRISTOPHER Policy No: MPC18A00279500
Date of Loss: 06/11/2018 Nature of Claim: OD Claim No: DMPC1800417H/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS1217S**
Make & Model: HONDA ODYSSEY, 2.4 (A) Engine No: K24Z21301486
Reg. Date: 29/07/2009 (Man. Year: 2009) Chassis No: JHMRB38509C201479
Colour: Metallic Maroon Odometer: 139122 km
Engine Capacity: 2354 cc
Market Value/New Car Price: S\$23,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Dunlop 2 mm Rear Left Side: Dunlop 3 mm
Front Right Side: Dunlop 2 mm Rear Right Side: Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,075.40	4,379.10	696.30	13.72
Miscellaneous Items	200.00	200.00	0.00	0.00
Labour	2,740.00	2,370.00	370.00	13.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,015.40	6,949.10	1,066.30	13.30
Approved Total (Overridden) (S\$)		5,550.00		
- Top-Up Amount (S\$)	0.00	637.50	-637.50	
(S\$)	8,015.40	4,912.50	3,102.90	38.71
+ GST 7.00/7.00% (S\$)	561.08	343.88	217.20	38.71
Nett Amount (S\$)	8,576.48	5,256.38	3,320.10	38.71

INSPECTION

Date of Assignment: 12/11/2018 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected: 12/11/2018 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761
Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Apr 2019)	
Parts: M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SJS1217S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT BUMPER (WCP)	Bent	460.00 F	*460.00 F
2	1		*1 PC FRT BUMPER FOG LAMP RH (WCP)	Mtg Cracked	210.00 F	*210.00 F
3	1		*1 PC FRT BUMPER SIDE RETAINER RH (WCP)	Cracked	11.00 F	*11.00 F
4	1		*1 PC FRT BUMPER REINFORCEMENT (WCP)	Repair	185.00 F	*- F
5	1		*6 PCS FRT BUMPER CLIP @2/PCE (WCP)	Necessary	12.00 F	*12.00 F
6	1		*1 PC FRT BUMPER TOP CHROME MOULDING (WCP)	Cracked	280.00 F	*280.00 F
7	1		*1 PC FRT GRILLE (WCP)	Dented	155.00 F	*155.00 F
8	1		*1 PC FRT GRILLE MOULDING (WCP)	Dented	160.00 F	*160.00 F
9	1		*1 PC FRT GRILLE LOGO (WCP)	Necessary	17.00 F	*17.00 F
10	1		*4 PCS FRT GRILLE CLIP @1.50/PCE (WCP)	Necessary	6.00 F	*6.00 F
11	1		*1 PC FRT RH HEADLAMP (WCP)	Broken	450.00 F	*450.00 F
12	1		*1 PC FRT RH HEADLAMP ECU (WCP)	Cracked	245.00 F	*245.00 F
13	1		*1 PC FRT RH HEADLAMP BULB (WCP)	Broken	198.00 F	*198.00 F
14	1		*1 PC FRT RH HEADLAMP SOCKET (WCP)	Cracked	15.00 F	*15.00 F
15	1		*1 PC FRT RH HEADLAMP WIRE HARNESS (WCP)	Serviceable	230.00 F	*- F
16	1		*1 PC FRT SUPPORT PANEL (WCP)	Bent	320.00 F	*320.00 F
17	1		*1 PC BONNET (WCP)	Bent	455.00 F	*455.00 F
18	1		*1 PC BONNET INNER RUBBER (FRT) (WCP)	Torn	38.00 F	*38.00 F
19	1		*1 PC FRT RH FENDER (WCP)	Bent	370.00 F	*370.00 F
20	1		*1 PC FRT RH FENDER INNER SHIELD (WCP)	Cracked	75.00 F	*75.00 F
21	1		*6 PCS FRT RH FENDER INNER SHIELD CLIP @1.50/PCE (WCP)	Necessary	9.00 F	*9.00 F
22	1		*1 PC FRT RH FENDER INNER PANEL (WCP)	Bent	390.00 F	*390.00 F
23	1		*1 PC RADIATOR SPARE TANK (WCP)	Dented	45.00 F	*45.00 F
24	1			Dented	60.00 F	*60.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*1 PC FRT SIPER TANK (WCP)			
25	1		*1 PC A;TERNATOR BELT (WCP)	Serviceable	70.00 F	*- F
26	1		*1 PC ABS WIRE SENSOR (WCP)	Serviceable	148.00 F	*- F
F=Franchise part.						
Sub Total (S\$)					4,614.00	3,981.00
+ Margin on L,N Items 10.00/10.00% (S\$)					461.40	398.10
Total Parts (S\$)					5,075.40	4,379.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	1 SET FRT PARKING SENSOR (TORN)	200.00	200.00
Sub Total (S\$)			200.00	200.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	1) TO PERFORM PANEL BEATING	New	1,200.00	1,000.00
2	2) TO REMVOE AND REFIX AIRCON, CHECK, VACUUM AND REFILL GAS	New	100.00	100.00
3	3) TO REMOVE AND REFIX FRT RH UNDERCARRIAGE, ENGINE, CHECK MOUNTING, REPLACE ABS PUMP AND SENSOR AND RESET SYSTEM	New	300.00	250.00
4	4) TO REMOVE AND REFIX WIRE HARNESS AND CHECK WIRING	New	80.00	60.00
5	5) TO PUTTY AND RESPRAY ON FRT RH ACCIDENT AFFECTED AREAS	New	1,000.00	900.00
6	6) TO CHECK FRT RH UNDERCARRIAGE AND CONDUCT COMPUTERISED WHEEL ALIGNMENT	New	60.00	60.00
Gross Labour Cost (S\$)			2,740.00	2,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >