

INS. CASE OWNER:

6 / MG 180 20462, H j03

1YK:
LWAC

Surveyor:

ump

DOI:

ASSIGNMENT

12/11/2018

Date / Time:

12/11/18

Registered in Merimen:

12/11/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKT7924C

Name of Insured:

Lim Yat Yi

Insured Tel No.:

HP:

Excess Sec II : S3

D.O.A.:

10-11-18

Is driver the owner?

(YES) NO

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES/NO)

OI GIA REPORT: YES/NO ; TP GIA REPORT: YES/NO

Insured Liability: % Final? Yes/No

S6E 872 T



INSRS:

WSP:

Tel:

Liability:

RMKS:

Modern.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

20/11
2018

S6E 872 T. X:

SKT 7924 C. X

HEAD TO HEAD

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

201 14-2-19

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

X

After call ltr to OI:

X

Authorisation To Act:

X

Release Voucher:

X

Final Repair Bill:

X

Car Rental Invoice:

X

Towing Invoice:

X

LTA / GIA:

X

Medical Bill:

X

FIR:

X

Mandate/Reject Instruction:

X

LOD:

X

Payment Breakdown Form:

X

Post-Repair Photos:

X

Others:

X

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email:

Call:

FINAL SETTLEMENT

Date/Time:

Confirm with:

GRACE

Email:

Call:

Final Liability:

%

100

(Assessed / Assessed) BOLA S/N No.:

27

Repair Cost:

S\$

4,868.50

Loss of Rental (LOR):

S\$

500.00 x 5

days)

100

Loss of Use (LOU):

S\$

— (\$ x days)

Loss of Income (LOI):

S\$

— (\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

7.45

Medical:

S\$

—

Disbursement:

S\$

—

(e.g. Tow/ Independent)

Legal Cost:

S\$

—

Total:

S\$

5,375.95

Global Sum S\$:

5,375

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

S\$

5,375.24

Name 1:

MODERN AUTOMOTIVE PTE LTD

Payee 2: (Strike if N.A.)

S\$

—

Name 2:

X

Payee 3: (Strike if N.A.)

S\$

—

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

ASSIGNMENT

Adrian

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGE8212T Yr Regn: 2006 MarchType: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Altis cc 1598Colour: Grey A/C: Insured / Std / Nil / NASp. Reading: 24/5267 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: MROS3ZEC10711330Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 185/70R14R: 185/70R14BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 12/11/18Survey held at ModernDes. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ALGCOE Expiry: 26/03/21mv 17Kpv 117KNet 5.3KL/S \$4,550R(\$3,423.45/43%)

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report

Final Report

Part Prices Check

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS. \$

Photos

Others

TOTAL

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
78 Shenton Way #07-16
Singapore 079120
Tel : 6419 - 3000
Fax : 8835 - 7416

Quotation

DATE : 22.11.2018
VEH NO : SGE8212T
MODEL : Toyota Corolla
D O A : 10.11.2018
YR REF : SK 7924C

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SGE8212T (TOYOTA COROLLA)

Item	Description	Qty	Amnt
NO	LIST ITEMS		
1	Rear Bumper <i>Defunct</i>	1	411.80 ✓
2	Rear Bumper Clips <i>As</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>As</i>	2	50.80 ✓
4	Rear Bumper Impact Bracket - LH & RH <i>As</i>	2	86.40 ✓
5	Rear End Panel <i>Defunct</i>	1	700.50 ✓
6	Rear End Panel Top Garnish <i>Defunct</i>	1	75.20 ✓
7	Tail Lamp - LH & RH <i>LH out, RH cracked</i>	2	579.40 ✓
8	Tail Lamp Panel - LH & RH <i>Defunct</i>	2	749.00 ✓
9	Tail Lamp Lower Apron - LH & RH <i>Defunct</i>	2	179.20 ✓
10	Boot Lid <i>Backlid</i>	1	788.10 ✓
11	Boot Lid Lock <i>Damaged</i>	1	63.20 ✓
12	Boot Lid Weatherstripe <i>at</i>	1	157.00 ✓
13	Boot Lid Hinge - LH & RH <i>not new</i>	2	161.60 ✗
14	Boot Lid Reflector - LH & RH <i>As</i>	2	316.20 ✗
15	Corolla Emblem	1	42.90 ✓
16	Altis Emblem	1	38.00 ✓
17	1.5 Emblem	1	35.60 ✓
18	E Emblem	1	35.90 ✓
19	VVTi Emblem	1	37.80 ✓
20	Spare Tyre Panel Top Cover <i>Torn</i>	1	185.40 ✓
21	Rear Exhaust Pipe <i>3 new</i>	1	458.50 ✗
22	Rear Exhaust Mounting	1	32.10 ✗

Less 25%

5,204.60
(1,301.15)
\$ 3,903.45

S/NETT ITEMS

1 Reverse Sensor *Damaged* 1 280.00 *200*

RE : ESTIMATE FOR ACCIDENT REPAIR SGE8212T (TOYOTA GORDILLA)

2	Rear End Panel Sealant <i>new</i>	1	60.00 ✓
3	Rear Camera <i>new</i>	1	480.00 X
			<hr/>
			\$ 820.00
	Total Parts		\$ 4,723.45

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,200.00 1000
2	To putty & spray up paint works	\$	1,200.00 1000
3	To check wiring	\$	50.00 30
4	To underseal	\$	150.00 60
5	To remove upholstery	\$	150.00 60
6	To remove reverse sensor	\$	100.00 50
7	To remove rear camera	\$	100.00 50
8	To transfer bootlid fittings	\$	150.00 60
9	To remove exhaust pipe	\$	150.00 X
	Total Labour	\$	3,250.00
	Grand Total	\$	7,973.45

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 5689.85

2/5: 4550.

070/25

the following:

in the: rear spray painting

aged part(s) during repair

are subject to confirmation

survey is on a "Without Prejudice" basis

allocation(s) is allowed

entry item(s) must be resurveyed and

to final approval from Insurance Company

Approved by Registrar

Signature:

Date:

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01 - 61

SINGAPORE 408717

GST REG. NO : 200501102H

TEL : 6748-4422 / 6745-4422 FAX : 6-747- 6720

Email: chin@modernautomotive.com.sg

Your Ref : SKT7924C

Our Ref : SGE8212T

Date : 11.12.2018

The Claims Manager

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78, Shenton Way #07-16

Singapore 079120

Tel : 6-419-300 Fax : 6-415-3727

Attn : The Motor Claim Dept

RE : ACCIDENT INVOLVING SGE8212T & SKT7924C ON 10.11.2018

ALONG PASIR RIS DRIVE 3 TOWARDS PASIR RIS CENTRAL

We refer to the above matter.

We have been authorized by our client Mr Lim How Seng to make claim against your insured vehicle No.SKT7924C in respect of the above accident for the following :

Repair Cost	\$ 4,868.50 (Incl GST)
Loss of rental (\$120 x 5 days)	\$ 600.00
Search fee	\$ 7.45
Total :	\$ 5,475.95

Enclosed herewith a copy each of the supporting documents for your perusal.
Kindly process the above and remit the payment to us asap

Yours faithfully



Modern Automotive Pte Ltd

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Tuesday, 19 February 2019 10:07 AM
To: 'loislin@hotmail.com'
Cc: Admin A
Subject: ACCIDENT INVOLVING SKT 7924C AND SGE 8212T ON 10/11/2018

Our ref: CC6/AIG18020462/Aja3

LIN YAT YI

Policy Holder

Dear Sir/Madam,

ACCIDENT INVOLVING SKT 7924C AND SGE 8212T ON 10/11/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us.

We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

LETTER OF AUTHORIZATION

Date: 12/11/18

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

SGE8212T & SK77924C

ON 10/11/18 ALONG Pasir Ris Drive 3 twds


Pasir Ris Central

This letter is to authorize **MODERN AUTOMOTIVE PTE LTD** at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, **MODERN AUTOMOTIVE PTE LTD** has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of **MODERN AUTOMOTIVE PTE LTD**.

MODERN AUTOMOTIVE PTE LTD is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully

X 
Signature of Owner

Lim How Seug S00129251
Name / NRIC

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, MODERN AUTOMOTIVE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$5,375.00 (Global Sum) for vehicle no. SGE 8212T that was damaged pursuant to the accident which occurred on 10/11/2018 (date) along PASIR RIS DRIVE 3 (location) involving vehicle no/s SKT 7924C. This is pursuant to the inspection conducted on 12/11/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LIM HOW SENG ("the third party claimant") of vehicle no. SGE 8212T make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGE 8212T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 20 (day) of Feb (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01- 58 / 61 SINGAPORE 408717
TEL : 67474422, 67454422 FAX : 67476720
GST REG. NO : 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
SINGAPORE 079120

Attention : Motor Claim Department
Contact : 6415-3727 6419-3000

Tax Invoice : TP001290

Date : 11/12/2018
Vehicle Num. : SGE 8212T
Make/Model : TOYOTA COROLLA-2006
Chassis/Eng# :
Accident Date : 10/11/2018
Claim No. :
Reference :
Policy No. : 5058398758-05

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		ACCIDENT REPAIR (LUMPSUM)		4,550.00
		Labour Total S\$:		4,550.00

Total S\$: 4,550.00
GST @ 7% S\$: 318.50
Amount Due S\$: 4,868.50
=====



MODERN AUTOMOTIVE PTE LTD

MODERN SALES & LEASING

MODERN LEASING

BLK 3023A UBI ROAD
#01-81, SINGAPORE 408717
TEL: 6747 4422 FAX: 6747 6720

#01-61 SINGAPORE 408717 TEL: 6747 4422

REG NO. 53324316E

FAX: 6747 6720

No. 0143

VEHICLE RENTAL AGREEMENT

DATE: 12/11/18

PARTICULARS OF HIRER

Name: Lim How Seng

Address: Blk 761 Pasir Ris St 71

#12-208 S 510 761

Tel (O): (Fax):

(HP): 9758 3707 Email:

Contact Person:

PARTICULARS OF DRIVER / AUTHORISED DRIVER

Name (as in IC): - As Above -

I/C or Passport No.:

Address:

Nationality:

D/Exp: (Yrs) D/L No:

D/L Type: Local / International (please circle)

D/L Pass Date: (dd/mm/yy)

Date of Birth: (dd/mm/yy)

Tel (O): (Fax):

(HP): Email:

Additional Remarks:**VEHICLE DETAILS**

Vehicle No: SGR 9611A

Vehicle Type:

Vehicle Make: Mit Lancer

Vehicle Model:

Vehicle Colour:

Vehicle Mileage:

RENTAL DETAILS

Start Date and Time: 12/11/18 10.20am

End Date and Time: 17/11/18 4:10pm

RENTAL CHARGES (#120 x 5 days)

Daily Charge: \$120 Deposit:

Weekly Charge: Adv. Payment:

Monthly Charge: Total Charges: \$600.00

***Note:** INTEREST OF LATE PAYMENT IS AT 2% PER MTH.
THE ABOVE RENTAL CHARGES INCLUDE SERVICING,
PREVENTIVE MAINTENANCE & REPAIR OF THE SAID
VEHICLE UNLESS THE DAMAGES WERE CAUSED
BY OPERATOR'S NEGLIGENCE OR ACCIDENTS.

IMPORTANT NOTICE

- Hirer is **LIABLE** for the first (\$) 2000 excess in any accident plus cost of repair to the rented vehicle.
- For usage to Malaysia subject to higher excess all claims of \$5000/- and different rental rate.
- Driver or authorized driver should be at least 22 years old with minimum 2 years of driving experience.
- Hirer is fully liable for all damages, losses, fines, summons and claims to and against the vehicle.
- The vehicle is not to be used in any activities which may violate traffic rule or law, or in any other manner by which the vehicle might become liable to seizure or confiscation.
- No refund will be given for vehicle returns early.
- No refund will be given for petrol left in vehicle.
- Replacement car will be given, if vehicle is under repair in workshop during rental period for more than 1 working day.
- By signing this agreement, the hirer confirms having read all the terms and conditions and acknowledges that all information given above is true to his/her knowledge.

Stamp and/or Signature of Hirer

Signature of Driver / Authorised Driver

MODERN LEASING

MODERN SALES & LEASING

BLK 3023A UBI ROAD 1 # 01-61 SINGAPORE 408717

TEL : 67474422 FAX : 67476720

REG NO. 53324316E

OFFICIAL RECEIPT

No. C/00008

Date: 17.11.2018

Received from Lim How Seng the sum of Dollars Six Hundred Only

being payment of SGR9611A from 12.11.2018 to 17.11.2018

For Modern Sales & Leasing



> Back to OneMotoring

Land Transport Authority
 10 Sin Ming Drive
 Singapore 575701
 GST Registration No. : M4-0006529-2

Print Date/Time : 12 Nov 2018 / 11:42:14

Receipt Date/Time : 12 Nov 2018 / 11:42:14

Tax Invoice/Receipt

Receipt No. : ITNET-00000-181112-000847

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SKT7924C				
As at 10 Nov 2018/19:10:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SKT7924C			
	Enquiry Fee	7.00	0.49	7.49
	20181112114115777533			
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
Paid By				
	xxxxxxxxxxxx2896	Credit Card:		7.45
		Visa/MasterCard		
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Nov 2018 Edit Reg		12 Nov 2018 00:00 Edit Adj Rpt	S\$4,550.00 Edit Estimates	S\$4,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LIN YAT YI, ID: S7670815J								
Main Claimant:	LIM HOW SENG, ID: S0012925I								
Vehicle Reg. No.:	SGE8212T	Date of Loss:	10/11/2018 19:00 - :59 [151 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0743100432SG	Policy/Cover Note No.:	2100418765 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKT7924C	Policy No. (Claimant):	5058398758-05						
		Excess:							
Repairer:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/11/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGE8212T (0743100432SG)
[SKT7924C]
TP
LIM HOW SENG
Nov 10 2018 7:00PM
[LIN YAT YI]
Modern Automotive Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser ▼	
Letters/Correspondences						1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown				Edit	
Documentation						1 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	12/11/18 19:21	TP GIA REPORT				Load PDF	
2	21/02/19 12:11	WORKSHOP INVOICE				Load PDF	
3	21/02/19 12:11	AUTHORISATION TO ACT FORM				Load PDF	
4	21/02/19 12:11	Release Voucher				Load PDF	
5	21/02/19 12:11	RENTAL RECEIPT				Load PDF	
6	21/02/19 12:11	LTA SEARCH				Load PDF	
7	21/02/19 12:11	LETTER TO OI				Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)				Thumbnail	Print
1	13/11/18 09:15	OI GIA REPORT				Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>		

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKT7924C (Insd veh)	Model:	TOYOTA COROLLA 1.6 (M)
	SGE8212T (TP veh)		
Date of Accident:	10/11/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	8,531.59
Final Repair Cost	:	\$	5,375.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	5 days
LTA / GIA Search Fee	:	\$	_____
Others:	:	\$	_____
	:	\$	_____
Final Settlement Sum (Global Sum)	:	\$	5,375.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____100____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Modern Automotive Pte Ltd	:	\$ 5,375.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

21 Feb
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18020462/AJA3Q2

Date: 21/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100418765
Claimant Vehicle No : SGE8212T **Insured Vehicle No :** SKT7924C
 Date of Loss: 10/11/2018 Nature of Claim: TP Claim No: 0743100432SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGE8212T**
 Make & Model: TOYOTA COROLLA, 1.6 (M) Engine No: 3ZZ4546202
 Reg. Date: 27/03/2006 (Man. Year: 2006) Chassis No: MR053ZEC107113301
 Colour: Grey Odometer: 245267 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,723.45	3,379.85	1,343.60	28.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	2,310.00	940.00	28.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,973.45	5,689.85	2,283.60	28.64
Approved Total (Overridden) (S\$)		4,550.00		
(S\$)	7,973.45	4,550.00	3,423.45	42.94
+ GST 7.00/7.00% (S\$)	558.14	318.50	239.64	42.94
Nett Amount (S\$)	8,531.59	4,868.50	3,663.09	42.94
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,375.95		
Global Sum Settlement (S\$)		5,375.00		

INSPECTION

Date of Assignment: 12/11/2018
 Date Inspected: 12/11/2018 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	411.80 FL	*411.80 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	2		*REAR BUMPER SIDE HOLDER-LH & RH	Necessary	50.80 FL	*50.80 FL
4	2		*REAR BUMPER IMPACR BRACKET -LH & RH	Not Necessary	86.40 FL	*- FL
5	1		*REAR END PANEL	Dented	700.50 FL	*700.50 FL
6	1		*REAR END PANEL TOP GARNISH	Deformed	75.20 FL	*75.20 FL
7	2		*TAIL LAMP -LH & RH	N/S Cut / O/S Cracked	579.40 FL	*579.40 FL
8	2		*TAIL LAMP PANEL -LH & RH	Dented	749.00 FL	*749.00 FL
9	2		*TAIL LAMP LOWER APRON -LH & RH	Dented	179.20 FL	*179.20 FL
10	1		*BOOT LID	Buckled	788.10 FL	*788.10 FL
11	1		*BOOT LID LOCK	Damaged	63.20 FL	*63.20 FL
12	1		*BOOT LID WEATHERSTRIPE	Cut	157.00 FL	*157.00 FL
13	2		*BOOT LID HINGE -LH& RH	Not Necessary	151.60 FL	*- FL
14	2		*BOOT LID REFLECTOR -LH & RH	Not Necessary	316.20 FL	*- FL
15	1		*COROLLA EMBLEM	Necessary	42.90 FL	*42.90 FL
16	1		*ALTIS EMBLEM	Necessary	38.00 FL	*38.00 FL
17	1		*1.5 EMBLEM	Necessary	35.60 FL	*35.60 FL
18	1		*E EMBLEM	Necessary	35.90 FL	*35.90 FL
19	1		*VVTI EMBLEM	Necessary	37.80 FL	*37.80 FL
20	1		*SPARE TYRE PANEL TOP COVER	Torn	185.40 FL	*185.40 FL
21	1		*REAR EXHAUST PIPE	Not Necessary	458.50 FL	*- FL
22	1		*REAR EXHAUST MOUNTING	Not Necessary	32.10 FL	*- FL
23	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
24	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
25	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,024.60	4,419.80
- List Item Discount on L Items 25.00/25.00% (S\$)	1,301.15	1,039.95

Total Parts (S\$)	4,723.45	3,379.85
-------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,200.00	1,000.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,200.00	1,000.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	60.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO REMOVE REVERSE SENSOR	New	100.00	50.00
7	TO REMOVE REAR CAMERA	New	100.00	50.00
8	TO TRANSFER BOOTLID FITTINGS	New	150.00	60.00
9	TO REMOVE EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (S\$)			3,250.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >