

T & B MOTOR REPAIRS SERVICES PTE LTD

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

KOH KIM LENG

BLK 613 HOUGANG AVENUE 8 #05-430

SINGAPORE 530613

Attention : Motor Claim Department

Supplementary Estimate : ES003332

Date : 12/11/2018

Vehicle Num. : SLB3010Z

Make/Model : HONDA VEZEL

Chassis/Eng# :

Accident Date : 10/11/2018

Claim No. :

Reference :

Policy No. : D18MTPV01004219

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	4	REAR BOOT COVER WINDSCREEN GLASS MOULDING	35.00	140.00 ✓
2.	1	REAR BOOT WEATHERSTRIP		148.50 ✓
3.	1	REAR FLOOR UNDER BASE COVER		195.00 ✓
4.	4	REAR FLOOR UNDER BASE COVER CLIPS	10.00	40.00 ✓
List Total S\$:				523.50
25.00% Discount S\$:				130.88
30				392.62
LABOUR :				
REMOVE & STRIAGHTEN THE TAIL PIPE EXHAUST SLIENCER BOX				280.00 80/
Labour Total S\$:				280.00

SingDollars : Six Hundred Seventy-Two & Cents Sixty-Two Only

E. & O.E.

Total S\$: 672.62

for T & B MOTOR REPAIRS SERVICES PTE LTD