Attn:

Motor Claims Department

Re: Accident Involving Motor Vehicle Nos. SUL 7927A & STV 8979?

At/Along Tampines F-x7rasway Tooks Chayion 09/11/18 @ 08:50

I am the owner of vehicle no. $\frac{5LL7927A}{7979}$ that was involved in an accident with your insured vehicle no. $\frac{57V89797}{7999}$ of the above accident.

As the accident was caused by your insured negligent/inconsiderate driving, thus I am claiming from you for the following: -

I hereby give you fourteen (14) days to comply with the above, failing which, I shall instruct my solicitor to commence legal action against you. If you have any queries, please contact the representative of CYCLE & CARRIAGE INDUSTRIES PTE LTD at Telephone No: 67714377 (Mr Alan Quek) / 67714304 (Ms Amanda Ang).

I hereby give full authority to CYCLE & CARRIAGE INDUSTRIES PTE LTD and their representative to negotiate/comprise settlement of the above claim on my behalf.

Your co-operation and immediate attention to the above is greatly appreciated. I hereby look forward to hearing from you soon.

Yours faithfully

Name & Signature

Address: C/o. 188 Pandan Loop Singapore 128378

Cc: Mr Alan Quek/ Ms Amanda Ang

E-mail: alan.quek@cyclecarriage.com.sg / amanda.ang@cyclecarriage.com.sg

Fax No. 67795383



Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

TAX INVOICE

M BPNSUN POLICY NO/ACC DATE :2100503108 // 09-11-2018 DRIVE IN/:9-11-18 // TP CAR NO.SJV8979P (AXA INSURANCE) DATE IN/DATE SURVEY:21-11-2018 // LKK RASUL BY/AUTHRIZED ON :LKK VIC ALPEH // 19-11-2018 A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. A BPIRES RESPRAY LH/FRONT BUMPER, LH/F FENDER, LH/F DOOR AND LH/R DOOR S BPNSUB LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR.NETT A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT X LH/H EADLAMP UNIT X LH/R DOOR X LH/R DOOR 1.00 1642.61 16 X LH/R DOOR WEATHERSTRIP 1.00 280.72		In	voice Name & Address			Owne	r Name & Vehicl	e Info	
Reg No/Reg Date SLL/92/A 7 10/03/2017 C/O AXA INSURANCE PTE LTD Date In/Mileage 21/11/2018 33426 MOTOR CLAIM DEPARTMENT SHENTON WAY #24-01 SINGAPORE 068811 Engine No 27091031104292 Contact No 63387288 Make/Model MB/MB CLA 200 COUPE (C117) "FACELIFT" Contact No 63387288 Colour/Trim 025 589 Jupiter Re/ 041 151-Leather Tw: Account No Terms Date/Time Printed CSE Operator WIP No Invoice/Credit Note CS100001 Cash 28/11/2018/ 23:08 AQ 305 / Alan Quek Ai Lun 28243 28148346 Description of Goods / Services Qty Unit Price SS Among Policy No/Acc Date : 2100503108 // 09-11-2018 DATE IN/0ACC DATE : 2100503108 // 09-11-2018 DATE IN/:9-11-18 // TP CAR No. S3V8979P (AXA INSURANCE) DATE IN/DATE SURVEY: 21-11-2018 // LKK RASUL BPY/AUTHRIZED ON : LKK VIC ALPEH // 19-11-2018 A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. A BPIRES RESPRAY LH/FRONT BUMPER, LH/F FENDER, LH/F DOOR AND LH/R DOOR S BPNSUB LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD O.19 ABPILAB					Cust No/Name	WCV29181/	Ms Tan Tse W	oon Alicia	
MOTOR CLAIM DEPARTMENT S SHENTON WAY #24-01 Engine No 27091031104292 SINGAPORE 068811 Engine No 27091031104292 Contact No 63387288 Colour/Trim 025 589 Jupiter Re/ 041 151-Leather Twide Review Rev		Ms Tan Tse	e Woon Alicia		Reg No/Reg Date	SLL7927A	/ 10/03/2	2017	
8 SHENTON WAY #24-01 \$INGAPORE 068811 Contact No 63387288 Colour/Trim 025 589 Jupiter Re/ 041 151-Leather Tw: Account No Terms Date/Time Printed CSE Operator Wilp No Invoice/Credit Note I CSI00001 Cash 28/11/2018/ 23:08 AQ 305 / Alan Quek Ai Lun 28243 28148346 Description of Goods / Services Qty Unit Price S\$ Amm M BPNSUN POLICY NO/ACC DATE :2100503108 // 09-11-2018 DRIVE IN/:9-11-18 // TP CAR No.SJV8979P (AXA INSURANCE) DATE IN/DATE SURVEY:21-11-2018 // LKK RASUL BY/AUTHRIZED ON :LKK VIC ALPEH // 19-11-2018 A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. A BPIRES RESPRAY LH/FRONT BUMPER, LH/F FENDER, LH/F DOOR AND LH/R DOOR S BPNSUB LABOUR TO REMOVE AND INSTALL TYPE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL TYPE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL TYPE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL ALIGNMENT. NETT A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT. NETT X LH/R DOOR X LH/R DOOR X LH/R DOOR X LH/R DOOR WEATHERSTRIP 1.00 2813.62 28 X LH/R DOOR WEATHERSTRIP 2.00 280.72 22	MOTOR CLAIM DEPARTMENT			Date In/Mileage	21/11/201	8/ 33426			
SINGAPORE 068811 Engine No				Chassis No	WDD117343	32N430241			
Make/Model					Engine No	270910311	.04292		
Colour/Trim 025 589 Jupiter Re/ 041 151-Leather Twi Account No Terms Date/Time Printed CSE Operator WIP No Invoice/Credit Note CSI00001 Cash 28/11/2018/23:08 AQ 305 / Alan Quek Al Lun 28243 28148346 Description of Goods / Services Qty Unit Price S\$ Amm M BPNSUN POLICY NO/ACC DATE :2100503108 // 09-11-2018 DATE IN/DATE SURVEY:21-11-2018 // LKK RASSUL BY/AUTHRIZED ON :LKK VIC ALPEH // 19-11-2018 A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. A BPILAB LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL TYRE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT X LH/ HEADLAMP UNIT X LH/ HEADLAMP UNIT X LH/R DOOR WEATHERSTRIP Colour/Trim 025 589 Jupiter Re/ 041 151-Leather Twi					Make/Model	MB/MB CLA	200 COUPE (C117) "FACEL	IFT"
Account No Terms Date/Time Printed CSE Operator WIP No Invoice/Credit Note CS100001 Cash 28/11/2018/ 23:08 AQ 305 / Alan Quek Ai Lun 28243 28148346 Description of Goods / Services Qty Unit Price S\$ Amo M BPNSUN POLICY NO/ACC DATE :2100503108 // 09-11-2018 DRIVE IN/:9-11-18 // TP CAR NO.SJV8979P (AXA INSURANCE) DATE IN/DATE SURVEY:21-11-2018 // LKK RASUL BY/AUTHRIZED ON :LKK VIC ALPEH // 19-11-2018 A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. A BPIRES RESPRAY LH/FRONT BUMPER, LH/F FENDER, LH/F DOOR AND LH/R DOOR S BPNSUB LABOUR TO REMOVE AND INSTALL TYRE FROM RIM. (RUN FLAT) WHEEL BALANCE AND INSTALL TYRE FROM RIM. (RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR.NETT A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT X LH/ HEADLAMP UNIT 1.00 2813.62 28 X LH/R DOOR WEATHERSTRIP 1.00 280.72 22		Contact No			Colour/Trim	880			
CSIO0001 Cash 28/11/2018 / 23:08 AQ 305									
Description of Goods / Services Qty Unit Price S\$ Amm M BPNSUN POLICY NO/ACC DATE :2100503108 // 09-11-2018 DRIVE IN/:9-11-18 // TP CAR NO.SJV8979P (AXA INSURANCE) DATE IN/DATE SURVEY:21-11-2018 // LKK RASUL BY/AUTHRIZED ON :LKK VIC ALPEH // 19-11-2018 A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. A BPIRES RESPRAY LH/FRONT BUMPER, LH/F FENDER, LH/F DÖOR AND LH/R DOOR S BPNSUB LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR.NETT A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT X LH/ HEADLAMP UNIT 1.00 2813.62 28 X LH/R DOOR X LH/R DOOR WEATHERSTRIP 1.00 280.72	Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	Invoice/Cred	lit Note No
M BPNSUN POLICY NO/ACC DATE :2100503108 // 09-11-2018 DRIVE IN/:9-11-18 // TP CAR No.SJV8979P (AXA INSURANCE) DATE IN/DATE SURVEY:21-11-2018 // LKK RASUL BY/AUTHRIZED ON :LKK VIC ALPEH // 19-11-2018 A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. A BPIRES RESPRAY LH/FRONT BUMPER, LH/F FENDER, LH/F DOOR AND LH/R DOOR S BPNSUB LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR.NETT A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT X LH/ HEADLAMP UNIT 1.00 2813.62 X LH/R DOOR X LH/R DOOR WEATHERSTRIP 1.00 280.72	CSI00001	Cash	28/11/2018/ 23:08	AQ	305 / Alan Quek	Ai Lun	28243	28148346	
POLICY NO/ACC DATE :2100503108 // 09-11-2018 DRIVE IN/:9-11-18 // TP CAR No.SJV8979P (AXA INSURANCE) DATE IN/DATE SURVEY:21-11-2018 // LKK RASUL BY/AUTHRIZED ON :LKK VIC ALPEH // 19-11-2018 A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. A BPIRES RESPRAY LH/FRONT BUMPER, LH/F FENDER, LH/F DOOR AND LH/R DOOR S BPNSUB LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR.NETT A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT X LH/ HEADLAMP UNIT 1.00 2813.62 X LH/R DOOR X LH/R DOOR WEATHERSTRIP 1.00 280.72 2			Description of Good	ds / Services		Qty	Unit Price S	\$	Amount S\$
LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR.NETT A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT X LH/ HEADLAMP UNIT X LH/R DOOR X LH/R DOOR WEATHERSTRIP 1.00 2813.62 28 28 28 28 28 28 30.72	A BPILAB DISASS A BPIRES RESPRA	EMBLE AND R	EPLACE ATTACHED DAMAG	ED PARTS &					1440.00 2400.00 60.00
A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR.NETT A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT X LH/ HEADLAMP UNIT X LH/R DOOR 1.00 2813.62 28 X LH/R DOOR 1.00 1642.61 16 X LH/R DOOR WEATHERSTRIP 1.00 280.72		TO REMOVE	AND INSTALL TYRE FROM	RIM, (RUN F	FLAT)			1-000	00.00
REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR.NETT A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT X LH/ HEADLAMP UNIT X LH/R DOOR 1.00 2813.62 28 X LH/R DOOR 1.00 1642.61 16 X LH/R DOOR WEATHERSTRIP 1.00 280.72 28		BALANCE AND	INSTALL NEW VALVE HE	AD				0 10	400.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT X LH/ HEADLAMP UNIT X LH/R DOOR X LH/R DOOR WEATHERSTRIP 1.00 2813.62 28 1.00 1642.61 16 280.72 2		& TRANSFER	DOOR MECHANICAL & EL	ETRICAL INS	STALL TO NEW DOOR.NET	T		0.15	100100
X LH/ HEADLAMP UNIT 1.00 2813.62 28 X LH/R DOOR 1.00 1642.61 16 X LH/R DOOR WEATHERSTRIP 1.00 280.72 2	A BPILAB								540.00
	X LH/ HE X LH/R D X LH/R D X ABSORB	ADLAMP UNIT OOR OOR WEATHER ING DOOR	STRIP			1.00 1.00 1.00	1642.61 280.72 62.05		2813.62 1642.61 280.72 62.05 25.19

Parts	4,824.19	Nett	9,664.19
Labour	4,780.00	7% GST on 9664.19	676.49
Standard Menu	0.00		
Specialist Job	60.00	Total Payable	10,340.68
Diagnostics Job	0.00	Paid	0.00
Sundry/Others	0.00	Total Due	10,340.68
Total(w/o GST)	9,664.19		

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No:

GR-18-174551

Date of Request:

12/11/2018

Your Ref No:

Online Purchase

Cycle & Carriage Industries Pte Ltd 188 Pandan Loop

188 Pandan Loop Singapore 128378

Dear Sir/Madam,

Enquiry Date

12/11/2018

Enquiry By

LYNN WONG LAI YIN

TP Vehicle No.

SJV8979P

Accident Date

09/11/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJV8979P	AXA Insurance Pte Ltd	17/02/2018-16/02/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No:

GR-18-174551

Date of Request:

12/11/2018

Your Ref No:

Online Purchase

Cycle & Carriage Industries Pte Ltd 188 Pandan Loop

188 Pandan Loop Singapore 128378

Dear Sir/Madam,

Enquiry Date

12/11/2018

Enquiry By

LYNN WONG LAI YIN

TP Vehicle No.

SJV8979P

Accident Date

09/11/2018

DESCRIPTION	AMOUNT (S\$)	
TP Insurer Enquiry	1.87	
GST Amount	0.13	
Total Amount Due (GST Inclusive)	2.00	

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque



CERTIFICATE OF INSURANCE

MERCEDES-BENZ MOTOR INSURANCE PRIVATE VEHICLE

Name of Policyholder

: Tan Tse Woon, Alicia

Period of Insurance

: 10 Mar 2018 To 09 Mar 2019

Engine No. Chassis No.

: 27091031104292

: WDD1173432N430241

Vehicle No.

: SLL7927A

Policy No.

Issued Date

: 2100503108-01

Endorsement No.

: 22 Feb 2018

ABOUT THE COVER

Make/Model

: MERCEDES Benz CLA200 Coupe

Engine Capacity/Tonnage: 1,595.00 CC

Sum Insured : Market Value

First Year of Registration : 2017

Driver Restriction

: NA

Off Peak Car : No

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*:

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition

: All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 2000cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

Tan Tse Woon, Alicia - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Eunos Service Center (For accident reporting only) Add: 330 Ubi Road 3 Singapore 408650 67412338

2.Pandan Loop Service Center - Body Care & Repair (For accident repair & accident reporting) Add: 188 Pandan Loop Singapore 128378 67778388

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

Hire Purchase Company/Employer's Loan: Daimler Financial Services Africa & Asia Pacific Ltd

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504380204

AlG Asia P

CYCLE & CARRIAGE - ANDYTH 239 ALEXANDRA ROAD SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Marile

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S 7 9 0 7 9 4 8 J**

Name:

TAN TSE WOON, ALICIA

Birth Date: **14 Mar 1979** Issue Date: **08 Aug 2003** FOR C&C USE ONLY



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

13 Aug 1999

FOR C&C USE ONLY

NP 428A

