

MBM WHEELPOWER PTE LTD

Your Ref: SKT9107G

Our Ref: SJZ3141B


To: FWD SINGAPORE

CC

Fax

Not Notified
Assuming B4 repair
4 days

Date: 13/11/2018
From: Stephanie
Fax: 64525333
Contact: 86865188
Make / Model: MERCEDES E220 AUTO
Chassis No.: WDD2130042A083898
Engine No.: 65492080039304
Year of Make: 2016
Accident Date: 9 November 2018



ESTIMATE FOR VEHICLE NO. : SJZ3141B

DESCRIPTION

REAR BUMPER
REAR BUMPER CLIPS @ \$9 EACH
RIVET @ \$9 EACH
REAR BUMPER RH TOW COVER
REAR BUMPER LOWER TRIM
REAR BUMPER LOWER CENTER MOULDING
REAR BUMPER SWITHC BRACKET
REAR BUMPER SIDE MOUNTING LH
REAR BUMPER SIDE MOUNTING RH
REAR BUMPER SIDE TOP MOUNTING LH
REAR BUMPER SIDE TOP MOUNTING RH
REAR BUMPER LOWER RH EXHUAUST COVER
REAR BUMPER LOWER LH EXHUAUST COVER
REAR BUMPER LH EXHUAUST MOULDING
REAR BUMPER RH EXHUAUST MOUDLING
REAR BUMPER INNER TOP CENTER BRACKET
REAR REINFORCEMENT
END PANEL
END PANEL TOP GARNISH
END PANEL TOP GARNISH CLIPS @ \$9 EACH
REVERSE SENSOR @ \$250 EACH

QTY

1 \$ 2,408.00 ✓
10 \$ 90.00 ✓
10 \$ 90.00 ✓
1 \$ 80.00 X
1 \$ 335.00 ✓
1 \$ 388.00 ✓
1 \$ 102.00 ✓
1 \$ 85.00 X
1 \$ 85.00 X
1 \$ 46.00 ✓
1 \$ 46.00 ✓
1 \$ 125.00 ✓
1 \$ 125.00 X
1 \$ 201.00 X
1 \$ 201.00 ✓
1 \$ 153.00 ✓
1 \$ 990.00 ✓
1 \$ 1,603.00 X
1 \$ 465.00 X
10 \$ 90.00 X
4 \$ 1,000.00 ✓

Total: \$ 8,708.00

LESS 10% \$ (870.80)

Parts Total: \$ 7,837.20

SPECIAL NETT

BODY SEALANT

1

\$

1, 80.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.

\$

1,000.00

TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT

\$

nn 80.00 /

TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS

\$

nn 100.00 /

TO CHECK & RECONNECT ALL NECESSARY WIRING

\$

201 80.00

TO APPLY ANTI RUST COATING

\$

nn 100.00 /

TO REMOVE & REPLACE BUMPER SENSORS

\$

40.00 L

TO RE-ADJUST REAR EXHAUST

\$

200.00 ?

TO SPRAY PAINT ON THE AFFECTED AREAS

\$

500/ 800.00

Total: \$ 10,317.20

7% GST: \$ 722.20

Grand Total: \$ 11,039.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mbm wheelpowerpte ltd

160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY

t62628888 f64525333

Company Registration Number : 200204110W