

# 威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,  
SINGAPORE 575644.  
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com  
Business Regn No: 269436/00J

*Not Notched*  
*11 Lyr @ 150ch*  
*Re-may After Paint*

13, Nov 2018

EQ Insurance Company Ltd  
5, Maxewll Road #17-00  
Tower Block MND Complex S 069110

Attn: Motor claim dept-3<sup>rd</sup> party claim  
Claiming against your insured vehicle no: YN6478X  
Accident involving vehicle no: SLX3153D/YN6478X  
DOA: 13/11/2018 AT 10 Eunoss Road

Dear officer incharge  
Re: Estimate of repair for vehicle no: SLX3153D  
To supply—

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Description	Qty	Amount
Front bumper	1 <i>Br</i>	576.00 ✓
Front bumper enforcement	1 <i>R</i>	210.00 X
Front bumper retainer	1 <i>Dis</i>	42.00 ✓
Front fender	1 <i>Br</i>	537.00 ✓
Headlamp	1 <i>Gr</i>	242.00 ✓
Headlamp lower bracket	1 <i>R</i>	48.00 X
Bumper foglamp	1 <i>R</i>	276.00 X
Total		1,931.00
Parts less 20%		386.20
		1,544.80

To remove damaged parts and attachments.  
Repair/reshape damaged areas.  
Replace/align all parts into position  
To spray paint.

850.00 *400d*  
550.00 *400d*  
-----  
2,944.80