

100000

INS. CASE OWNER:

CC 3 /AIG1802

LKK

IDAC

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

SKL 5949L

AMINAH BTE HASSAN

HP:

D.O.A:

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: NURPIN BIN ABONL

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

674247549459

2017H5045

TRINIA

WOODLANDS INTERPRINT

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SMF 444AB



INSRS:
WSP:
Tel:
Liability:
RMKS:

Performance



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting Itr (1st):
Non-Reporting Itr (2nd):
Non-Reporting Itr (Final):
Notification Itr (if non-pickup):
Call OI: 22/11/18
After call Itr to OI: 27/11/18

Documentation Check List: Handler Typist

Notification Itr (if non-pickup):
After call Itr to OI:
Authorisation To Act:
Release Voucher:
Final Repair Bill:
Car Rental Invoice:
Towing Invoice:
LTA / GIA:
Medical Bill:
PIR:
Mandate/Reject Instruction:
LOD:
Payment Breakdown Form:
Post-Repair Photos:
Others:

20/11/18
pohkion

22/11/18
OJ Doughter

SMF 444AB - F SKL 5949L - F

Spoke to OJD (daughter), confirmed accident details, OJD was passing in the lane and change lane causing collision. informed liability is not in favour and referred to claim and HCD 344c. They agree to settle and waive HCD 41 be affected. send letter to OJ.

Final Liability Clear
posting to OJ ✓
File pass to type mandate report

before post photo ✓

PRELIMINARY ADVICE

Date/Time:

Sent By:

21/11/18

LSP

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS 13,918.10

19 days Reduction: 12.86 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Confirm by:

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No. : 411

If NO or B 28, Ass. Lia:

Repair Cost:

SS 14,902.01

Loss of Rental (LOR):

SS

1 days

Loss of Use (LOU):

SS

13 days

Loss of Income (LOI):

SS

5 days

LOR only ☐ LOU only ☐

☒

LOR + LOU

☐

LOR + LO

☐

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

Disbursement

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee

Total:

SS

16,205.07

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Confirm by:

Payee 1:

SS

16,205.07

Name 1:

Performance Motors Limited

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

OJD Change lane (1 way queue)
COPY SENT
6/11/18

Tanpin

REF: ALH

+

ASSIGNMENT

From: Date: 19.12.2018

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMF 4949B

at Workshop n/s:

Pertamane
305 Alexandra Rd

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Kevin

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bat. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 1/81 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No

SMF4949B

Yr Regn

218 Jly

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

BMW 520I

C.C

1998

Colour

White

A/C

Insured / Std / NI / NA

Sp. Reading

9630

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No

WBASAP200WE60132

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NL / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

14/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

15,925.00 15,925.00

Date / Time

Action / Instruction

P/P 13,929.10 / Red 2,055.30 / 12.86%

Date/Time. File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) S + RS \$

2) Photos

3) Others

4) TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18020726/fb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 15-11-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKL 5949L	Veh. Inspected	SMF 4949B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	15/11/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	11/11/2018	Inspection Date
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401599W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

180, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

15 NOV 2018

ESTIMATE

Estimate No. : b1 49118
Date Estimated : 15/11/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Low Wee Hong Jimmy
100 Edgedale Plains
#04-42

Singapore 828690

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMF4949B	WE60132	30/07/2018	520i	0

DESCRIPTION

VALUE

To replace rear left door. To repair on front left side panel, front left door, rear left side panel, rear bumper & all attachments cause by accident.

4250 5,100.00

Painting on front left side panel, front left door, rear left door, rear left side panel & rear bumper

4/20 4,578.00

To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function.

902451 531.00

To check electrical wiring systems for proper fnction.

150 177.00

To carry out body cavity preservation.
(Per panel) Rear left door

200 160 118.00

Sundries.

7 150.00

Total Labour 1: 10,654.00

DESCRIPTION

QTY PRIC

VALUE

REAR LH DOOR ALUMINIUM
EMBLEM (M)
REAR LH DOOR WINDOW GUIDE
REAR LH DOOR TOP WINDOW FRAME FINIS
RR LH DOOR COLUMN B COVER (GLANZSCH
LH WINDOW GUIDE WEB COVER (GLANZSCH
REAR LH DOOR OUTER CHANNEL COVER (G
REAR LH DOOR LOWER SEAL
LH TRIM AIR DUCT SIDE PANEL (GLANZS

1	1,863.20
1	81.90
1	109.35
1	239.15
1	49.10
1	100.70
1	114.80
1	42.60
1	64.60

66	1,863.20
1	81.90
1	109.35
1	239.15
1	49.10
1	100.70
1	114.80
1	42.60
1	64.60

Total Parts : 2,665.40

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



315, Alexandra Road
Sime Darby Performance Centre
Singapore 119941
Tel. 63190190 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

285, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 119944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49118
Date Estimated : 15/11/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMF4949B	WE60132	30/07/2018	520i	0

Client's DO / PO / Party / Insurance / License / Direct Settlement

Regn No. _____ Client No. _____

Date & Time: 14/12/18 13:50

Surveyor's Name: *Tan Kah* Sign: *[Signature]*

Surveyor's Tel: 974963749 Authorized Yes / No

Authorized Date: _____ Time: _____

REPAIR PARTS FACTED BY SURVEYOR Yes / No Yes / No

Surveyor's Email: *tan.kah@hampson.com*

No. of Vehicles to be Repaired: 8-9 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Labour 1	:	10,654.00
Parts	:	2,665.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	932.36
Grand Total	:	14,251.76

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



SUPPLEMENTARY

Estimate No. : b1 49118
Date Estimated : 15/11/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Low Wee Hong Jimmy
100 Edgedale Plains
#04-42

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 828690

REGN. NO	CHASSIS NO	REGN. DATE	MODEL	MILEAGE
SMF4949B	WE60132	30/07/2018	520i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT LH DOOR ALUMINIUM * ✓ h	1,863.20	1.00		1,863.20 ✓
# (S/L) DOOR WEATHERSTRIP * ✓ h	173.90	2.00		347.80 ✓

Total Labour :	
Total Parts :	2,211.00
Total Labour & Parts :	2,211.00



FINAL REPORT

Estimate No. : b1 49118
Date Estimated : 15/11/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Low Wee Hong Jimmy
100 Edgedale Plains
#04-42

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 828690

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SMF4949B	WE60132	30/07/2018	520i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front/rear LH doors and attachments include making good the front LH fender, rear LH fender, rear bumper and knocking out dents caused by the accident	4250.00		4,250.00	
To spray paint front LH fender, front LH door, rear LH door, rear LH fender and rear bumper	4120.00		4,120.00	
* To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function (2x)	902.00		902.00	
To check electrical wiring systems and lightings at the LH section for proper function	150.00		150.00	
* To carry out body cavity preservation (2x) (Per panel)	200.00		200.00	
Sundries	150.00		150.00	

9772

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT LH DOOR ALUMINIUM *	1,863.20	1.00		1,863.20
REAR LH DOOR ALUMINIUM	1,863.20	1.00		1,863.20
EMBLEM (M)	81.90	1.00		81.90
# (S/L) DOOR WEATHERSTRIP *	173.90	2.00		347.80

SUPPLEMENTARY ITEMS

Total Labour :	9,772.00
Total Parts :	4,156.10
Total Labour & Parts :	13,928.10
Deduction for Excess :	0.00
Total Repair Costs less Excess:	13,928.10
GST @7%:	974.97
Grand Total :	14,903.07

From: Poh Kin (LKKAuto)
Sent: Thursday, 22 November 2018 2:36 PM
To: PBSP
Cc: Admin A
Subject: RE: REQUEST FOR DIRECT SETTLEMENT - SMF4949B & SKL5949L ON 11/11/2018
***LKK REF:CC3/AIG18020726/fb3

Importance: High

WITHOUT PREJUDICE

Our Ref: CC3/AIG18020726/fb3
Your Ref: SMF 4949B

Dear sir/madam,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKL 5949L AND SMF 4949B ON 11/11/2018

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

In the meantime, kindly arrange TP survey ASAP.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Poh Kin (LKKAUTO)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Friday, 31 May 2019 1:09 PM
To: Poh Kin (LKKAUTO)
Cc: Admin A
Subject: Re: MANDATE - SMF4949B & SKL5949L ON 11/11/2018 ***LKK
REF:CC3/AIG18020726/fb3

Dear Poh Kin

We have instructions to accept your revised offer for LOU.

Please proceed to let us have your payment.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Poh Kin (LKKAUTO) <pohkin@lkkauto.com>
Sent: Tuesday, 28 May 2019 9:34:36 AM
To: PBSP
Cc: 甯珺 ©
Subject: RE: MANDATE - SMF4949B & SKL5949L ON 11/11/2018 ***LKK REF:CC3/AIG18020726/fb3

WITHOUT PREJUDICE SAVE AS TO COSTS

Our Ref: CC3/AIG18020726/T1fb3
Your Ref: SMF 4949B

Dear Caroline,

We refer to above matter.

Apologies for late reply.

Towards an amicable settlement and without admission of liability to our Insured's part, we have instruction to offer settlement as below:

1. Cost of Repair (w/gst)	S\$ 14,903.07
2. Loss of Use (\$100.00 x 13 days)	S\$ 1,300.00
3. GIA search fee	<u>S\$ 2.00</u>
	<u>S\$ 16,205.07</u>

kindly confirm acceptance on this matter.

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Tuesday, 28 May 2019 9:35 AM
To: PBSP
Cc: Admin A
Subject: RE: MANDATE - SMF4949B & SKL5949L ON 11/11/2018 ***LKK
REF:CC3/AIG18020726/fb3

Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC3/AIG18020726/T1fb3
Your Ref: SMF 4949B

Dear Caroline,

We refer to above matter.

Apologies for late reply.

Towards an amicable settlement and without admission of liability to our Insured's part, we have instruction to offer settlement as below:

1. Cost of Repair (w/gst)	S\$ 14,903.07
2. Loss of Use (\$100.00 x 13 days)	S\$ 1,300.00
3. GIA search fee	<u>S\$ 2.00</u>
	<u>S\$ 16,205.07</u>

kindly confirm acceptance on this matter.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."


Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Thursday, 23 May 2019 8:06 PM
To: 'Kesaval, Jaclyn-M'
Subject: SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKL 5949L (OI) AND SMF 4949B (TP) ON 11-11-2018; LKK ref : CC3/AIG18020726/T1fb3; AIG ref: 6352935998SG

Importance: High

Hi, please ignore my previous e-mail

Your Ref: 6352935998SG
Our Ref: CC3/AIG18020726/T1fb3

Dear Jaclyn,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKL 5949L (OI) & SMF 4949B (TP) ALONG WOODLANDS CHECKPOINT ON 11/11/2018

We refer to the above matter.

The accident occurred when our insured was queue in the lane (custom) and decide to change lane and causing collision with TP. Liability is down against our insured.

We did clarify with Insured daughter the nature of the accident and they agree to settle and aware that NCD (if any) would be affected.

We hereby seek your approval to offer to Third Party repairer, "Performance Motors Ltd" is as follows: -

	<u>Amount Claimed</u>	<u>Amount Revised</u>
1. Cost of Repair	\$ 15,983.40	\$ 14,903.07 (\$13,928.10 + 7% GST)
2. Loss of Use	\$ 1,560.00 (13 days x \$120.00)	\$ 1,300.00 (13 days x \$100.00)
3. GIA search	\$ 2.00	\$ 2.00
Total	\$17,545.40	\$ 16,205.07

Total amount of claim (Liability 100%) **\$16,205.07**

***Recommended 9 repair days + 1 day public holiday(Christmas) + 2 days weekend(Saturday/Sunday) = 13 days LOU

All the relevant documents had been uploaded in Merimen for your perusal.

Print Received Message

This mail is associated with :

***SMF4949B (6352935998SG)
[SKL5949L]**

TP
LOW WEE HONG JIMMY
Nov 11 2018 3:00PM
[AMINAH BTE HASSAN]
Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 27/05/2019 19:36 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$16205.07) - SMF4949B - Claim Handler: Loh, Chee-Heng

Approved:16205.07.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SMF 4949B	Model:	BMW
Date of Accident:	11-11-2018		

Global Sum Settlement:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	: \$	14251.76	
Final Repair Cost	: \$	14903.07	
Loss of Use	: \$	1560.00	13 days at \$120 per day
Rental (if any)	: \$		days
LTA / GIA Search Fee	: \$	2.00	
Others	: \$		
	: \$		
Final Settlement Sum	: \$	16465.07	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop: Agreed Liability _____ (%)			
B) For GIA Registered Workshop: BOLA Application: Yes / No			
BOLA Scenario No: _____			
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks			

Payment Instruction: Payee's Breakdown			
1)	Performance Motor Limited	: \$	14903.07
2)	Performance Motors Ltd	: \$	2.00
3)	Low Wee Hong Jimmy	: \$	1560.00

Signed by appointed surveyor

Date

Please attach all the supporting documents to the form.
Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report / Bill (if any)

Our Ref: CC3/AIG18020726/fb3

27th November 2018

AMINAH BTE HASSAN
Block 2B Geylang Serai,
#02-13,
Singapore 404002.

Attn: Mr Nordin Bin Abdul

Dear Sir/Madam,

**ROAD TRAFFIC ACCIDENT INVOLVING NOS. SKL 5949L AND SMF 4949B ALONG
WOODLANDS CHECK POINT ON 11.11.2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,



Poh Kin Chong
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: pohkin@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Low Wae Hong Jimmy ("the third party claimant")
of 100 Edgedale Plains #04-42 (828690) (address),
owner of SME4949B (vehicle no.) hereby authorize
Performance Motors Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SME4949B that was
damaged pursuant to the accident which occurred on 11/11/2018 (date) along
Woodland ICA (location)
involving vehicle no/s SKL5949L ("the accident").


I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 15th day of November (month) 20 19 (year)



Signed by "the third party claimant"



Signed by "the workshop"



RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK into Consultants Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$ 14903.07 (repair costs), S\$ 1,300.00 (loss of use/rental) S\$ 2.00 (search fees) for vehicle no. SMF4949B that was damaged pursuant to the accident which occurred on 11.11.2018 (date) along Woodland ICA (location) involving vehicle no/s SKL5949L.

This is pursuant to the inspection conducted on 19.12.2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Low Wee Hong ("third party claimant") of vehicle no. SMF4949B to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SMF4949B (vehicle no.) as a result of the accident.


We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 3rd day of June (month) 20 19 (year)

 MTH

Signed by AIG appointed surveyor


PERFORMANCE MOTORS LIMITED
303 Alexandra Road
Dartby Performance Centre
Singapore 119941
TEL: 63150100 (Sales)
63190111 (Afternoon)

Chopped & Signed by "the workshop"

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63390888 (AfterSales)
Fax. 63449773113, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190128 (AfterSales)
63190133/310 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)**SERVICE TAX INVOICE**Repair Order No. : **B1 1324614**Date IN : **19/12/2018**Cust. Svc. Advisor: **Kevin Leong Wai Kit**Page No. : **1 of 2**Invoice Number : **2067696 / WSB**Invoice Date : **20/02/2019**Payment Terms : **30 Days From Invoice**Invoice By : **Sharon Heng****- CUSTOMER INFORMATION -****Mr Low Wee Hong Jimmy**
100 Edgedale Plains
#04-42**Singapore 828690****- INVOICE TO - 121****AIG Asia Pacific Insurance Pte. Ltd.**
78 Shenton Way
#08-16 Chartis Building
Singapore 079120REGN. NO.
SMF4949BCHASSIS NO.
WE60132REGN. DATE
30/07/2018MODEL
520IMILEAGE
9630**- - - - LABOUR 1 - - - -****NETT**To replace rear left door and front left door including to
make good the rear bumper, front left fender, rear left
fender and knock out dented**4,250.00**area caused by the accident. To remove and install body parts in
order to carry out painting job.To respray front left fender, rear left fender, front left
door, rear left door and rear bumper etc.**4,120.00**To transfer lock mechanism from old to new both left
doors including conduct checks on new door power window
system for proper functions.**902.00**To check electrical wiring systems and lighting at the
left section for proper frction.**150.00**

To carry out body cavity preservation.

200.00

Sundries.

150.00

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

0.00

DATE OF ACCIDENT : 11.11.2018. 3RD PARTY CAR : SKL5949L.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO
CONSULTANTS PTE LTD ON 19.12.2018 AT 1.30 PM.
AUTHORISED REPAIR BY MR CHONG POH KIN FROM LKK ON
22.11.2018 VIA E-MAIL.PROPOSE LOSS OF USE = \$120X13. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.**0.00**

GIA SEARCH FEE = \$2.00.

0.00**Total Labour 1: 9,772.00****- - - - PARTS - - - -**Retail
Qty Price**NETT**

REAR LH DOOR ALUMINIUM

1 1,863.20

1,863.20

EMBLEM (M)

1 81.90

81.90

FRT LH DOOR ALUMINIUM

1 1,863.20

1,863.20

(S/L) DOOR WEATHERSTRIP

2 173.90

347.80**Total Parts : 4,156.10**



303, Alexandra Road
Sims Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

200, Kampong Arang Road
East Coast Centre
Singapore 478180
Tel: 63190888 (AfterSales)
Fax: 63445773

311, Alexandra Road
Sims Darby Business Centre
Singapore 159944
Tel: 63190838 (AfterSales)
63190833 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1324614	Page No. : 2 of 2
Date IN : 19/12/2018	Invoice Number : 2067696 / WSB
Cust. Svc. Advisor: Kevin Leong Wai Kit	Invoice Date : 20/02/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

Labour Charges : 9,622.00	Total Labour & Parts Charges : S\$ 13,928.10
Parts Charges : 4,156.10	Less Insurance Excess : S\$ 0.00
Lubricant/Misc : 150.00	Invoice Total Amount Exclude GST : S\$ 13,928.10
	GST @ 7% : S\$ 974.97
	Invoice Total Amount Include GST : S\$ 14,903.07

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 14,903.07**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-177027

Date of Request: 15/11/2018

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 15/11/2018
Enquiry By Melanie Setiawati
TP Vehicle No. SKL5949L
Accident Date 11/11/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKL5949L	AIG Asia Pacific Insurance Pte. Ltd.	29/11/2017-28/11/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-177027

Date of Request: 15/11/2018

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 15/11/2018
Enquiry By Melanie Setiawati
TP Vehicle No. SKL5949L
Accident Date 11/11/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ [X] GIRO ☐ [] Cash ☐ [] Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING









Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Nov 2018 Edit Reg		19 Dec 2018 00:00 Edit Adj Rpt	S\$13,928.10 Edit Estimates	S\$13,928.10 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	AMINAH BTE HASSAN , ID: S0642730H								
Main Claimant:	LOW WEE HONG JIMMY , ID: S7920070J								
Vehicle Reg. No.:	SMF4949B	Date of Loss:	11/11/2018 15:00 - :59 [3 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6352935998SG	Policy/Cover Note No.:	2100358065 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKL5949L	Policy No. (Claimant):	GA380690						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 26/11/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (27/05/2019): Alert - Adj Mandate Approved (S\$16205.07) - SMF4949B - Claim Handler: Loh, Chee-... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMF4949B (6352935998SG)**
[SKL5949L]
TP
LOW WEE HONG JIMMY
Nov 11 2018 3:00PM
[AMINAH BTE HASSAN]
Performance Motors Limited

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <div>View in Browser</div>			
Letters/Correspondences											1 per page		<div></div>	<div></div>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown									1	Edit		
Photos/Images											3 per page		<div></div>	<div></div>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	12/02/19 11:19	Odometer Reading									1	Load JPG	<div></div>	
2	12/02/19 11:19	Chassis Number									1	Load JPG	<div></div>	
3	12/02/19 11:19	General View									1	Load JPG	<div></div>	
4	12/02/19 11:19	General View									1	Load JPG	<div></div>	
5	12/02/19 11:19	General View									1	Load JPG	<div></div>	
6	12/02/19 11:19	General View									1	Load JPG	<div></div>	
7	12/02/19 11:19	General View									1	Load JPG	<div></div>	
8	12/02/19 11:19	General View									1	Load JPG	<div></div>	
9	12/02/19 11:19	General View									1	Load JPG	<div></div>	
10	12/02/19 11:19	General View									1	Load JPG	<div></div>	
11	12/02/19 11:19	General View									1	Load JPG	<div></div>	
12	12/02/19 11:19	General View									1	Load JPG	<div></div>	
13	12/02/19 11:19	General View									1	Load JPG	<div></div>	
14	12/02/19 11:19	General View									1	Load JPG	<div></div>	
15	12/02/19 11:19	General View									1	Load JPG	<div></div>	
16	12/02/19 11:19	General View									1	Load JPG	<div></div>	
17	12/02/19 11:19	General View									1	Load JPG	<div></div>	
18	12/02/19 11:19	General View									1	Load JPG	<div></div>	
19	12/02/19 11:19	General View									1	Load JPG	<div></div>	
20	12/02/19 11:19	General View									1	Load JPG	<div></div>	
21	12/02/19 11:19	General View									1	Load JPG	<div></div>	
22	12/02/19 11:19	General View									1	Load JPG	<div></div>	
23	12/02/19 11:19	General View									1	Load JPG	<div></div>	
24	12/02/19 11:19	General View									1	Load JPG	<div></div>	
25	12/02/19 11:19	General View									1	Load JPG	<div></div>	
26	12/02/19 11:19	General View									1	Load JPG	<div></div>	
27	12/02/19 11:19	General View									1	Load JPG	<div></div>	
28	12/02/19 11:19	General View									1	Load JPG	<div></div>	
29	12/02/19 11:19	General View									1	Load JPG	<div></div>	
30	12/02/19 11:19	General View									1	Load JPG	<div></div>	
31	12/02/19 11:19	General View									1	Load JPG	<div></div>	
32	12/02/19 11:19	General View									1	Load JPG	<div></div>	
33	26/02/19 15:27	Reinspection Photo									1	Load JPG	<div></div>	
34	26/02/19 15:27	Reinspection Photo									1	Load JPG	<div></div>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	26/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	26/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	26/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	26/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	26/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	26/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	26/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	26/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	26/02/19 15:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/11/18 16:54	TP EST & GIA REPORT	 Load PDF	
2	21/12/18 17:41	TP ESTIMATE- MARKED	 Load PDF	
3	28/02/19 11:26	GIA SEARCH	 Load PDF	
4	28/02/19 11:26	LETTER TO OI	 Load PDF	
5	23/05/19 20:00	TP Estimate-Marked revise + supplementary	 Load PDF	
6	23/05/19 20:06	seek mandate e-mail	 Load PDF	
7	10/06/19 12:32	WORKSHOP INVOICE	 Load PDF	
8	10/06/19 12:32	AUTHORISATION TO ACT FORM	 Load PDF	
9	10/06/19 12:32	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	16/11/18 10:21	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKL5949L (Insd veh)	Model:	BMW 520i 2.0 LED NAV
	SMF4949B (TP veh)		MSPT (A)
Date of Accident:	11/11/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	17,102.24
Final Repair Cost	:	\$	14,903.07
Loss of Use	:	\$	1,300.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	16,205.07

13.00 days at \$100.00 per day

days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____(%)

B) For **GIA Registered Workshop**: BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: _____

BOLA Liability: _____100_____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 16,205.07
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

10 Jun
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18020726/T1FB3Q2

Date: 10/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100358065
 Claimant Vehicle No: SMF4949B Insured Vehicle No: SKL5949L
 Date of Loss: 11/11/2018 Nature of Claim: TP Claim No: 6352935998SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMF4949B
 Make & Model: BMW 520i, 2.0 LED NAV MSPT (A) Engine No: 21575338B48B20A
 Reg. Date: 30/07/2018 (Man. Year: 2018) Chassis No: WBAJA12000WE60132
 Colour: White Odometer: 9630 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,026.40	4,306.10	720.30	14.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,957.00	9,622.00	1,335.00	12.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,983.40	13,928.10	2,055.30	12.86
+ GST 7.00/7.00% (S\$)	1,118.84	974.97	143.87	12.86
Nett Amount (S\$)	17,102.24	14,903.07	2,199.17	12.86
+ Loss of Use (13.0 x S\$100.00/day) (S\$)		1,300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		16,205.07		

INSPECTION

Date of Assignment: 19/12/2018
 Date Inspected: 19/12/2018 Inspected At: Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941
 Estimated Period of Repair: 9.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Poh Kin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*REAR LH DOOR ALUMINIUM	Bent	1,863.20 FS	*1,863.20 FS
3	1		*EMBLEM (M)	Necessary	81.90 FS	*81.90 FS
4	1		*REAR LH DOOR WINDOW GUIDE	Not Necessary	109.35 FS	*- FS
5	1		*REAR LH DOOR TOP WINDOW FRAME FINIS	Not Necessary	239.15 FS	*- FS
6	1		*RR LH DOOR COLUMN B COVER (GLANZSCH)	Not Necessary	49.10 FS	*- FS
7	1		*LH WINDOW GUIDE WEB COVER (GLANZSCH)	Not Necessary	100.70 FS	*- FS
8	1		*REAR LH DOOR OUTER CHANNEL COVER (G)	Not Necessary	114.80 FS	*- FS
9	1		*REAR LH DOOR LOWER SEAL	Not Necessary	42.60 FS	*- FS
10	1		*LH TRIM AIR DUCT SIDE PANEL (GLANZS)	Not Necessary	64.60 FS	*- FS
11	1		*FRT LH DOOR ALUMINIUM	Bent	1,863.20 FS	*1,863.20 FS
12	2		*(S/L) DOOR WEATHERSTRIP	Necessary	347.80 FS	*347.80 FS
Total Parts (\$\$)					5,026.40	4,306.10

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR LEFT DOOR .TO REPAIR ON FRONT LEFT SIDE PANEL ,FRONT LEFT DOOR ,REAR LEFT SIDE PANEL,REAR BUMPER & ALL ATTACHMENTS CAUSE BY ACCIDENT	New	5,100.00	4,250.00
2	PAINTING ON FRONT LEFT SIDE PANEL ,FRONT LEFT DOOR ,REAR LEFT DOOR ,REAR LEFT SIDE PANEL & REAR BUMPER	New	4,578.00	4,120.00
3	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION	New	902.00	902.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS FOR PROPER FUNCTION	New	177.00	150.00
5	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) REAR LEFT DOOR	New	200.00	200.00
Gross Labour Cost (\$\$)			10,957.00	9,622.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >