

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000390

Date : 15/11/2018
 Vehicle Num. : SLQ 6102T (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 14/11/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR BOOT LID		1,300.00 DEF
2.	1	REAR BOOT HYBRID EMBLEM (VEZEL)		89.00 NEC
3.	1	REAR BOOT VEZEL EMBLEM (VEZEL)		89.00 NEC
4.	1	REAR BOOT LOCK ASSY		300.00 XSVL
5.	1	REAR WINDSCREEN GLASS MOULDING		250.00 NEC
6.	2	REAR BOOT REFLECTOR LAMP	580.00	1,160.00 XSVL
7.	1	REAR BOOT WEATHER STRIP		180.00 ?
8.	1	REAR END PANEL		680.00 ?
9.	1	REAR END PANEL TOP GARNISH		260.00 ?
10.	1	REAR BUMPER		900.00 CRK
11.	2	REAR TAIL LAMP	580.00	1,160.00 XSVL
12.	2	REAR BUMPER REFLECTOR LENS	120.00	240.00 ?
13.	2	REAR BUMPER RETAINER	89.00	178.00 ?
14.	1	SMART BUZZER SENSOR		180.00 ?
15.	1	REAR ANTENNA SENSOR		180.00 ?
16.	1	REAR SIDE BUMPER - LH		250.00 X R
List TotalS\$:				7,396.00
20.00% Discount S\$:				1,479.20
				5,916.80

SPECIAL NETT ITEMS :				
1.	1	REAR WINDSCREEN SEALANT		100.00 NEC
2.	1	REAR END PANEL TOP GARNISH CLIPS		40.00 ?
3.	1	REAR BUMPER CLIP		40.00 NEC
4.	1	REVERSE SENSOR		280.00 SCR
5.	1	REAR TAILLAMP CLIPS		40.00 XNW
Special Nett Total S\$:				500.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000390

Date : 15/11/2018
 Vehicle Num. : SLQ 6102T (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 14/11/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :				
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES			180.00	60
REMOVE & REFIT REAR WINDSCREEN GLASS			180.00	80 120
TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.			180.00	50
TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.			1,400.00	600
TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS			1,400.00	500
TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS			180.00	20 (reverse sensor)
DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME. (HV HYBRID SYSTEM SAFETY PROCEDURES)			450.00	?
PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINTIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)			450.00	150
Labour Total S\$:				4,120.00

E. & O.E.

Total S\$: 10,536.80

=====

for WORLD AUTO PTE LTD

NAZ LKK
 15/11/18
 4 days
 P/P-
 CHECK ITEMS PHOTOS
 BEFORE PAINT PHOTOS.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: