

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Owner : Nur Hidayat Bin Hatwi

Accident Date : 9-Nov-18

Vehicle No : FBG 7845 Y

Vehicle Model : Yamaha FZ16

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ 70.00
2	Fork inner tubes	\$ 440.00
1	Front brake disc	\$ 155.00
1	Front rim shaft	\$ 45.00
1	Front rim bearing	\$ 38.00
1	Meter panel	\$ 150.00
1	Side mirror	\$ 60.00
1	Headlamp	\$ 380.00
1	Lamp stay	\$ 80.00
1	Handle bars	\$ 270.00
2	Handle bar balancers	\$ 56.00
1	Hand grip (1 set)	\$ 80.00
1	Clutch lever	\$ 45.00
1	Brake lever	\$ 45.00
2	Front signals	\$ 100.00
1	Windshield	\$ 220.00
1	Top fairing	\$ 210.00
1	Side fairing	\$ 165.00
1	Front footrest	\$ 38.00
1	Front footrest bracket	\$ 90.00
1	Brake pedal	\$ 45.00
1	Rear footrest	\$ 42.00
1	Rear signal -R/H	\$ 50.00
1	Exhaust assy	\$ 450.00
1	Exhaust end cap	\$ 48.00
1	Exhaust protector	\$ 65.00
		\$ 3,437.00
	Less 10%	\$ 343.70
		\$ 3,093.30

- 820
102
738

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Owner : Nur Hidayat Bin Hatwi

Accident Date : 9-Nov-18

Vehicle No : FBG 7845 Y

Vehicle Model : Yamaha FZ16

Estimated Repair Costs

c/f: \$ 3,093.30

Special Nett Items

1	Number plate (1 set)	\$ 17	28.00	x
2	Fork oils	\$ 17	30.00	x
2	Fork oil seals	\$ 17	56.00	x
1	Steering cone (1 set)	\$ 17	95.00	x
1	Rear box	\$ 500	250.00	x
1	Rear box bracket	\$ 17	100.00	x
		\$	559.00	

S/No. Labour

1	To provide towing service.	\$	50.00	35
2	To remove, refit and align front fork tubes.	\$	180.00	60
3	To check wiring and reset headlamp focusing.	\$ 17	80.00	x
4	To provide labour.	\$	380.00	200
		\$	690.00	

Grand Total

\$ 4,342.30

Dollars: Four Thousand Three Hundred Forty-Two And Thirty Cents Only.

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: