

ASS. REC. BY:

REF: CS/SPF18020856 / Nuber

Special Instruction:

Surveyor:

ASSIGNMENT (Office)From (Person): Lim Wei Yea of SPF Date/Time: 19/12/18 10:54am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: QX 687R Insured: _____at Workshop m/s SMRT Tel: _____of 60 Woodlands Ind Park E4Policy No: _____ Claim No: HOMSPFETQ16000399

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. _____
(Client's Record)**CA / REV / REP. / REV 24 HRS**

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time	Action/Instruction () Estimate
	<u>QX 687R - X</u>
<u>6/12/18</u>	<u>Email revised to Wei Yea</u>
<u>26/12/18</u>	<u>@ 359pm Wei Yea said we can submit our report.</u>
<u>27/12/18</u>	<u>Parts \$ 4210 mgn HR - 28.5</u>

CHARGE: NAZ

REF: SPF

ASSIGNMENT

From Date: 20.11.2018

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: QX 687R

at Workshop m/s: SMRT

of

Insured

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Mr. Kong

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: QX 687R

Yr Regn:

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: FORD EVEREST

C.C.

Colour: BLUE

A/C: ☒ Insured / Std / NI / NA

Sp. Reading: 125,488

T/Radio: ☒ Insured / Std / NI / NA

Eng/No:

CtNo: MNBLS 4090 AW 811488

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: 245/70 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 21/11/18

Survey held at: SMRT (KRANJI)

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 27 DEC 2018

4/5

Date/Time. File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time. File Return to?

2)

21/12 - typist

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

____ \$ + RS ____ \$

____ PHOTOS

____ OTHERS

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

200

200

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 17 December 2018 4:51 PM
To: 'Wei Yea LIM (SPF)'
Cc: 'Kim Pang CHAY (SPF)'; 'Kwee Huat TAN (SPF)'; 'Perry HE (SPF)'; 'Bernard SEAH (SPF)'; 'Peng Seng NG (SPF)'; 'Rashid ABU HASAN (SPF)'
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX687R)
Attachments: QX 687R.xls

Dear Wei Yea,

Please refer attached.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Monday, 17 December 2018 4:28 PM
To: 'Wei Yea LIM (SPF)' <LIM_Wei_Yea@spf.gov.sg>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX687R)

Dear Wei Yea,

Please refer attached.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Monday, 17 December 2018 3:57 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX687R)

Hi Veron,

Just want to check if Labour item #2.6 in the RE-ADJUST version includes "Putty & spray paint for bonnet cover"?

This description was present in the previous version of your estimates but was not in the RE-ADJUST version.

Please clarify if this removal was intentional or a typo mistake.

Thanks to advise.

RE-ADJUST Version

2.6	Bonnet Cover					3
	Remove & replace "POLICE" wording sticker on bonnet cover (To be provided by AEMD)					
	Panel beating for bonnet cover					
2.7	Front LH Fender					2
	Re-align front LH fender					
COSTING		TOTAL PARTS COST			\$4,210.00	
		TOTAL MAN-HOUR				28.5

Previous Estimate

2.6	Bonnet Cover					3
	Remove & replace "POLICE" wording sticker on bonnet cover (To be provided by AEMD)					
	Panel beating for bonnet cover					
	Putty & spray paint for bonnet cover					
2.7	Front LH Fender					2
	Re-align front LH fender					
COSTING		TOTAL PARTS COST			\$4,210.00	
		TOTAL MAN-HOUR				16.5

Thank you and best regards,

WeiYea LIM

Contract Management

AEMD, Police Logistics Department

Singapore Police Force

DID: (65) 6478 4844



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>

Sent: Tuesday, 11 December 2018 10:32

To: Wei Yea LIM (SPF) <LIM Wei Yea@spf.gov.sg>; SUR <sur@lkkauto.com>

Cc: Kim Pang CHAY (SPF) <CHAY Kim Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN Kwee Huat@spf.gov.sg>; Perry HE (SPF) <Perry HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG Peng Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid Abu Hasan@spf.gov.sg>

Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX687R)

Dear Wei Yea,

Enclosed herewith re-adjusted report.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) <LIM Wei Yea@spf.gov.sg>

Sent: Friday, 7 December 2018 6:10 PM

To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Kim Pang CHAY (SPF) <CHAY Kim Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN Kwee Huat@spf.gov.sg>; Perry HE (SPF) <Perry HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG Peng Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid Abu Hasan@spf.gov.sg>

Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX687R)

Importance: High

Hi Veron,

May I check if you are able to update by next week?

There is an on-going internal investigation on the incident involving this vehicle and the cost of repair is being looked at.

Thank you and best regards,

WeiYea LIM

Contract Management

AEMD, Police Logistics Department

Singapore Police Force

DID: (65) 6478 4844



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Thursday, 6 December 2018 15:40
To: Wei Yea LIM (SPF) <LIM Wei Yea@spf.gov.sg>; SUR <sur@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY Kim Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN Kwee Huat@spf.gov.sg>; Perry HE (SPF) <Perry HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG Peng Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid Abu Hasan@spf.gov.sg>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX687R)

Dear Wei Yea,

We will check and revert.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) <LIM Wei Yea@spf.gov.sg>
Sent: Thursday, 6 December 2018 2:58 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY Kim Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN Kwee Huat@spf.gov.sg>; Perry HE (SPF) <Perry HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG Peng Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid Abu Hasan@spf.gov.sg>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX687R)

Hi Veron,

Some queries regarding unconfirmed items:

- 1) MATERIALS
 - a. Need your help to understand the "UNCONFIRM" items.
 - b. Please advise what is meant by "UNCONFIRMED" and why they were not able to be confirmed?
- 2) LABOUR
 - a. If these items were to be replaced, what would be the nominal Man-Hours?
 - b. Please provide the estimates.

S/N	ITEM DESCRIPTION	PARTS			
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TO (C) AF
1	MATERIALS				
1.1	FRONT BUMPER	1	CRACKED	\$725.00	
1.2	FRONT RH BUMPER RETAINER	1	SERVICEABLE	\$50.00	
1.3	FRONT LH BUMPER RETAINER	1	MISSING	\$50.00	

1.4	FRONT BUMPER REINFORCEMENT	1	UNCONFIRM	\$475.00	\$
1.5	FRONT SUPPORT PANEL	1	BENT	\$525.00	\$
1.6	LHS HEAD LAMP	1	CRACKED	\$440.00	\$
1.7	LHS HEAD LAMP LOWER BRACKET	1	UNCONFIRM	\$45.00	
1.8	RADIATOR	1	UNCONFIRM	\$565.00	\$
1.9	RADIATOR FAN ASSY	1	UNCONFIRM	\$500.00	\$
1.10	RADIATOR COWLING	1	UNCONFIRM	\$70.00	
1.11	AIR CON CONDENSER	1	UNCONFIRM	\$815.00	\$
2	SCOPE OF REPAIRS				
2.4	Radiator				
	Remove & replace radiator		Unconfirm		
	Remove & replace radiator fan blade				
	Remove & replace radiator cowling				
	Top up coolant				
2.5	Air Con Condenser				
	Remove & replace air con condenser		Unconfirm		
	Top up air con gas				

Thank you in advance for your advice.

Best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Thursday, 6 December 2018 11:20
To: Wei Yea LIM (SPF) <LIM Wei Yea@spf.gov.sg>; SUR <sur@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY Kim Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN Kwee Huat@spf.gov.sg>; Perry HE (SPF) <Perry HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG Peng Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid Abu Hasan@spf.gov.sg>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX687R)

Dear Wei Yea,

Please refer attach.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 3 December 2018 5:55 PM

To: 'Wei Yea LIM (SPF)' <LIM Wei Yea@spf.gov.sg>; SUR <sur@lkkauto.com>

Cc: 'Kim Pang CHAY (SPF)' <CHAY Kim Pang@spf.gov.sg>; 'Kwee Huat TAN (SPF)' <TAN Kwee Huat@spf.gov.sg>; 'Perry HE (SPF)' <Perry HE@spf.gov.sg>; 'Bernard SEAH (SPF)' <Bernard SEAH@spf.gov.sg>; 'Peng Seng NG (SPF)' <NG Peng Seng@spf.gov.sg>; 'Rashid ABU HASAN (SPF)' <Rashid Abu Hasan@spf.gov.sg>; assignments <assignments@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX687R)

Dear Wei Yea,

Thank you for your email.

Dear Veron,

FYNA. Our Ref: CS/SPF18020856/Nvb

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) [mailto:LIM Wei Yea@spf.gov.sg]

Sent: Monday, 3 December, 2018 5:51 PM

To: assignments <assignments@lkkauto.com>

Cc: Kim Pang CHAY (SPF) <CHAY Kim Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN Kwee Huat@spf.gov.sg>; Perry HE (SPF) <Perry HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG Peng Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid Abu Hasan@spf.gov.sg>; 'Ai Phing (LKKAuto)' <aiphing@lkkauto.com>; 'Shiau Chan (LKKAuto)' <siewsc@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX687R)

Hi Catherine,

May I check if there is an update on this assessment please?

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Wei Yea LIM (SPF)
Sent: Monday, 19 November 2018 10:54
To: 'assignments' <assignments@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; 'Ai Phing (LKKAuto)' <aiphing@lkkauto.com>; 'Shiau Chan (LKKAuto)' <siewsc@lkkauto.com>
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX687R)

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- QX687R

In attached, please find the recommended Parts and Labour required for the repair of these vehicles.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Registration No. QX 687R

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	FRONT BUMPER	1	CRACKED	\$725.00	\$725.00	
1.2	FRONT RH BUMPER RETAINER	1	SERVICEABLE	\$50.00		
1.3	FRONT LH BUMPER RETAINER	1	MISSING	\$50.00	\$50.00	
1.4	FRONT BUMPER REINFORCEMENT	1	BENT	\$475.00	\$475.00	
1.5	FRONT SUPPORT PANEL	1	BENT	\$525.00	\$525.00	
1.6	LHS HEAD LAMP	1	CRACKED	\$440.00	\$440.00	
1.7	LHS HEAD LAMP LOWER BRACKET	1	BENT	\$45.00	\$45.00	
1.8	RADIATOR	1	BENT	\$565.00	\$565.00	
1.9	RADIATOR FAN ASSY	1	CRACKED	\$500.00	\$500.00	
1.10	RADIATOR COWLING	1	BROKEN	\$70.00	\$70.00	
1.11	AIR CON CONDENSER	1	BENT	\$815.00	\$815.00	
2	SCOPE OF REPAIRS					
2.1	Front Bumper					
	Remove & replace front RH bumper retainer					5
	Remove & replace front LH bumper retainer					
	Remove & replace front bumper					
	Putty & spray paint for front complete bumper					
2.2	Front Bumper Reinforcement & Front Support Panel					
	Remove & replace front bumper reinforcement					6

[illegible]

Veron Chen (LKKAUTO)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Thursday, 6 December 2018 2:58 PM
To: Veron Chen (LKKAUTO); SUR
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF)
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX687R)

Hi Veron,

Some queries regarding unconfirmed items:

- 1) MATERIALS
 - a. Need your help to understand the "UNCONFIRM" items.
 - b. Please advise what is meant by "UNCONFIRMED" and why they were not able to be confirmed?
- 2) LABOUR
 - a. If these items were to be replaced, what would be the nominal Man-Hours?
 - b. Please provide the estimates.

S/N	ITEM DESCRIPTION	PARTS				MAN- HOUR QTY	REMARKS
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP		
1	MATERIALS						
1.1	FRONT BUMPER	1	CRACKED	\$725.00	\$725.00		
1.2	FRONT RH BUMPER RETAINER	1	SERVICEABLE	\$50.00			
1.3	FRONT LH BUMPER RETAINER	1	MISSING	\$50.00	\$50.00		
1.4	FRONT BUMPER REINFORCEMENT	1	UNCONFIRM	\$475.00	\$475.00		
1.5	FRONT SUPPORT PANEL	1	BENT	\$525.00	\$525.00		

1.6	LHS HEAD LAMP	1	CRACKED	\$440.00	\$440.00	
1.7	LHS HEAD LAMP LOWER BRACKET	1	UNCONFIRM	\$45.00	\$45.00	
1.8	RADIATOR	1	UNCONFIRM	\$565.00	\$565.00	
1.9	RADIATOR FAN ASSY	1	UNCONFIRM	\$500.00	\$500.00	
1.10	RADIATOR COWLING	1	UNCONFIRM	\$70.00	\$70.00	
1.11	AIR CON CONDENSER	1	UNCONFIRM	\$815.00	\$815.00	
2	SCOPE OF REPAIRS					
2.4	Radiator					
	Remove & replace radiator		Unconfirm			
	Remove & replace radiator fan blade					
	Remove & replace radiator cowlng					
	Top up coolant					
2.5	Air Con Condenser					
	Remove & replace air con condenser		Unconfirm			
	Top up air con gas					

Thank you in advance for your advice.

Best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Sent: Thursday, 6 December 2018 11:20

To: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; SUR <sur@lkkauto.com>

Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>

Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX687R)

Dear Wei Yea,

Please refer attach.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 3 December 2018 5:55 PM

To: 'Wei Yea LIM (SPF)' <LIM_Wei_Yea@spf.gov.sg>; SUR <sur@lkkauto.com>

Cc: 'Kim Pang CHAY (SPF)' <CHAY_Kim_Pang@spf.gov.sg>; 'Kwee Huat TAN (SPF)' <TAN_Kwee_Huat@spf.gov.sg>; 'Perry HE (SPF)' <Perry_HE@spf.gov.sg>; 'Bernard SEAH (SPF)' <Bernard_SEAH@spf.gov.sg>; 'Peng Seng NG (SPF)' <NG_Peng_Seng@spf.gov.sg>; 'Rashid ABU HASAN (SPF)' <Rashid_Abu_Hasan@spf.gov.sg>; assignments <assignments@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX687R)

Dear Wei Yea,

Thank you for your email.

Dear Veron,

FYNA. Our Ref: CS/SPF18020856/Nvb

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) [mailto:LIM_Wei_Yea@spf.gov.sg]

Sent: Monday, 3 December, 2018 5:51 PM

To: assignments <assignments@lkkauto.com>

Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; 'Ai Phing (LKKAuto)' <aiphing@lkkauto.com>; 'Shiau Chan (LKKAuto)' <sjewsc@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX687R)

Hi Catherine,

May I check if there is an update on this assessment please?

Thank you and best regards,

WeiYea LIM

Contract Management

AEMD, Police Logistics Department

Singapore Police Force

DID: (65) 6478 4844



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Wei Yea LIM (SPF)
Sent: Monday, 19 November 2018 10:54
To: 'assignments' <assignments@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; 'Ai Phing (LKKAuto)' <aiphing@lkkauto.com>; 'Shiau Chan (LKKAuto)' <siewsc@lkkauto.com>
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX687R)

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- QX687R

In attached, please find the recommended Parts and Labour required for the repair of these vehicles.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Catherine Chong (LKK Auto)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Monday, 19 November, 2018 10:54 AM
To: assignments
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF); 'Ai Phing (LKKAuto)'; 'Shiau Chan (LKKAuto)'
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ16000399 (QX687R)
Attachments: QX687R.xlsx

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- QX687R

In attached, please find the recommended Parts and Labour required for the repair of these vehicles.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	SMRT	VEH TYPE :	SUV	UNIT :	PCG GUL BASE
VEH NO :	QX687R	REPAIR TYPE :	ACCIDENT		
VEH MAKE/MODEL :	FORD EVEREST	ODOMETER :	-		

Reference No.	0687/SPF/4W/18/11/11
iLMS No.	1100014145

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	Front Bumper	\$725.00	1		725.00	725.00
1.2	Front RH Bumper Retainer	\$50.00	1		50.00	50.00
1.3	Front LH Bumper Retainer	\$50.00	1		50.00	50.00
1.4	Front Bumper Reinforcement	\$475.00	1		475.00	475.00
1.5	Front Support Panel	\$525.00	1		525.00	525.00
1.6	LHS Head Lamp	\$440.00	1		440.00	440.00
1.7	LHS Head Lamp Lower Bracket	\$45.00	1		45.00	45.00
1.8	Radiator	\$565.00	1		565.00	565.00
1.9	Radiator Fan Assy	\$500.00	1		500.00	500.00
1.10	Radiator Cowling	\$70.00	1		70.00	70.00
1.11	Air Con Condenser	\$815.00	1		815.00	815.00
2	Additional Services					
2.1	NA	\$0.00	0	0%	0.00	0.00
Remarks:		Item 1.11 requires Overseas Indentment ETA:- 12 to 16 weeks			Parts Total:	\$ 4,260.00

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	Front Bumper:		5	0.00
	Remove & Replace Front RH Bumper Retainer			
	Remove & Replace Front LH Bumper Retainer			
	Remove & Replace Front Bumper			
	Putty & Spray Paint for front Complete Bumper			
1.2	Front Bumper Reinforcement & Front Support Panel:		6.5	0.00
	Remove & Replace Front Bumper Reinforcement			
	Remove & Replace Front Support Panel			
1.3	LHS Head Lamp:		0.5	0.00
	Remove & Replace LHS Head Lamp Lower Bracket			
	Remove & Replace LHS Head Lamp			
	Wiring for LHS Head Lamp			
1.4	Radiator:		6	0.00
	Remove & Replace Radiator			
	Remove & Replace Radiator Fan Blade			
	Remove & Replace Radiator Cowling			
	Top Up Coolant			
1.5	Air Con Condenser:		8	0.00
	Remove & Replace Air Con Condenser			
	Top Up Air Con Gas			
1.6	Bonnet Cover:		3	0.00
	Remove & Replace 'POLICE' Wording Sticker on Bonnet Cover (To be provided by AEMD)			
	Panel Beating for Bonnet Cover			
	Putty & Spray Paint for Bonnet Cover			
1.7	Front LH Fender:		2	0.00
	Re-Align Front LH Fender			
SUB-TOTAL			31	0.00
2	Additional Services			
2.1	Towing Service From Station to Workshop (SOR 10)	176.80	1	176.80
2.2	Return Service From Workshop to Station (SOR 9)	61.20	1	61.20
SUB-TOTAL			2	238.00
			Labour Total:	\$ 238.00
			GRAND TOTAL :	\$ 4,498.00
			Total sum billed under SOR only :	\$ 238.00
			Total sum billed under CVR only :	\$ 4,260.00
Contractor shall complete the entire repair within <u>90</u> working days upon approval date . (Include parts awaiting time)				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18020856/Nvbe2

CONTRACT MANAGEMENT SECTION
(SINGAPORE POLICE FORCE) 1 MOUNT
PLEASANT ROAD BLK 8 OLD POLICE
ACADEMYSINGAPORE 298333

Date : 07-01-2019



ATTN : LIM WEI YEA

Code : SPF3

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	QX 687R
Policy No.		Coverage (\$)	0.00
Claim No.	HOMSPFETQ16000399	Excess (\$)	0.00
Assign From	LIM WEI YEA	Assign Date	19/11/2018

2. Vehicle Particulars & Condition

Make & Model	FORD EVEREST	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	MNBLS4090AW311468	Colour	BLUE
Odometer	125488	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/70 R16	FALKEN	6 mm
L/H Front Tyre	245/70 R16	FALKEN	6 mm
R/H Rear Tyre	245/70 R16	FALKEN	6 mm
L/H Rear Tyre	245/70 R16	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date		Inspection Date	21/11/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

--



Registration No. QX 687R

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	FRONT BUMPER	1	CRACKED	\$725.00	\$725.00	
1.2	FRONT RH BUMPER RETAINER	1	SERVICEABLE	\$50.00		
1.3	FRONT LH BUMPER RETAINER	1	MISSING	\$50.00	\$50.00	
1.4	FRONT BUMPER REINFORCEMENT	1	BENT	\$475.00	\$475.00	
1.5	FRONT SUPPORT PANEL	1	BENT	\$525.00	\$525.00	
1.6	LHS HEAD LAMP	1	CRACKED	\$440.00	\$440.00	
1.7	LHS HEAD LAMP LOWER BRACKET	1	BENT	\$45.00	\$45.00	
1.8	RADIATOR	1	BENT	\$565.00	\$565.00	
1.9	RADIATOR FAN ASSY	1	CRACKED	\$500.00	\$500.00	
1.10	RADIATOR COWLING	1	BROKEN	\$70.00	\$70.00	
1.11	AIR CON CONDENSER	1	BENT	\$815.00	\$815.00	
2	SCOPE OF REPAIRS					
2.1	Front Bumper					
	Remove & replace front RH bumper retainer					5
	Remove & replace front LH bumper retainer					
	Remove & replace front bumper					
	Putty & spray paint for front complete bumper					
2.2	Front Bumper Reinforcement & Front Support Panel					
	Remove & replace front bumper reinforcement					6
	Remove & replace front support panel					
2.3	LHS Head Lamp					
	Remove & replace LHS head lamp lower bracket					0.5
	Remove & replace LHS head lamp					

	Wiring for LHS head lamp					
2.4	Radiator					
	Remove & replace radiator					4
	Remove & replace radiator fan blade					
	Remove & replace radiator cowling					
	Top up coolant					
2.5	Air Con Condenser					
	Remove & replace air con condenser					8
	Top up air con gas					
2.6	Bonnet Cover					
	Remove & replace "POLICE" wording sticker on bonnet cover (To be provided by AEMD)					3
	Panel beating for bonnet cover					
	Putty & spray paint for bonnet cover					
2.7	Front LH Fender					
	Re-align front LH fender					2
COSTING		TOTAL PARTS COST			\$4,210.00	
		TOTAL MAN-HOUR				28.5

Registration No. QX 687R
Vehicle Inspected By

MUHD NAZRIL (NAZ)
Technical Investigator
LL.B. (Hons) London

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.