

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1317/2018/GW
Date : 19-Nov-18

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tan Han Tiong
Address : Blk 231 Jurong East St 21
#09-671
Singapore 300231
Telephone : HP +65 9728 7068
Type of Claim : Own Damage Claim
Policy No. : 2100420834-03
Vehicle No : **SKT 9658 H**
Model Code : Audi A4 1.8 TFSI M u
Model / Year : Jun-15
Engine No : CJE 102258
Chassis No : WAUZZZ8K0FA125541
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Nov-18
Place of Accident : Ayeh Rajah Expressway

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKT 9658 H

S/N	Nature of Jobs	Estimated Charges
1	To remove and reinstall front wire harness for headligths. Horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 X-
2	To remove and transfer rhs front door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00 ✓
3	To dismantle front bumper and rhs front door. To repair rhs front fender and rhs sill panel. To renew rhs front door and rhs wing mirror assy. Re-organise crash management components. Reinstall all parts removed.	\$ 2,400.00 750
4	To respray rhs front fender, rhs sill panel, rhs front door, and rhs wing mirror cover.	\$ 2,400.00 1400
5	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>5,632.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 9658 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT DOOR -RH <i>sewted</i>	\$ 2,509.00	✓
2	FRONT OUTER DOOR SEAL-RH <i>neu</i>	\$ 184.00	✓
3	BONDING AGENT <i>?</i>	\$ 43.00	?
4	CLEANING SOLUTION <i>?</i>	\$ 64.00	?
5	FRONT DOOR CATCH-RH <i>3 neu</i>	\$ 105.00	+
6	FRONT DOOR CATCH COVER-RH	\$ 14.00	+
7	FRONT EXTERIOR MIRROR MOUNTING-RH <i>could</i>	\$ 959.00	✓
8	FRONT MIRROR CAP-RH <i>neu</i>	\$ 501.00	+
9	FRONT TURN SIGNAL INDICATOR-RH <i>neu</i>	\$ 88.00	+
10	FRONT MIRROR GLASS-RH <i>neu</i>	\$ 190.00	+
11	FRONT SEAL-RH <i>neu</i>	\$ 11.00	+
12	FRONT WINDOW SLOT SEAL WITH TRIM STRIP-RH <i>neu</i>	\$ 265.00	+
13	MOLDING ROOF-RH <i>neu</i>	\$ 543.00	+
14	FRONT WINDOW GUIDE-RH <i>neu</i>	\$ 392.00	+
15	DATA PRESSURE FOR TYRE <i>neu</i>	\$ 17.00	✓
16	SUNDRIES <i>?</i>	\$ 500.00	?
TOTAL SPARE PARTS		\$ 6,385.00	
TOTAL LABOUR CHARGES		\$ 5,632.00	
GRAND TOTAL		\$ 12,017.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lj

Surveyed Date

: 19/11/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 05 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant