

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA13172018 7-Dec-18 JAMES SKT 9658 H Audi A4 1.8 TFSI M u
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT DOOR WINDOW CHROME SEAL (RH) <i>not reported</i>	\$ 265.00	X
2	FRONT DOOR 'B' PILLAR TRIM (RH) <i>new</i>	\$ 187.00	X 1.68
3	CLIPS <i>new</i>	\$ 3.00	X
4	FRONT DOOR WINDOW (RH) <i>new</i>	\$ 232.00	X
5	REAR DOOR WINDOW (RH) <i>new</i>	\$ 232.00	X 185.60
6	FRONT DOOR WINDOW CORNER TRIM (RH) <i>new</i>	\$ 82.00	X
7	REAR DOOR HANDLE (RH) <i>3 Repairs</i>	\$ 131.00	X
8	REAR DOOR HANDLE CAP (RH)	\$ 26.00	X
9	REAR DOOR WINDOW GUIDE (RH) <i>new</i>	\$ 392.00	X
10	REAR DOOR WINDOW CHROME SEAL (RH) <i>new</i>	\$ 256.00	X
11	REAR DOOR 'B' PILLAR TRIM <i>new</i>	\$ 197.00	X
		\$ 2,003.00	
<u>LABORS</u>			
1	To repair and respray RHS Rear Door	\$ 1,000.00	550 ✓
2	To respray Door Handle	\$ 100.00	✓
TOTAL		\$ 3,103.00	

For Premium Automobiles Pte Ltd

Adrian Ling
10/12/18

Authorised Signature