		of SMO	Date/Time: 20/11/18@ 10:37
Estimate OD (-T)		Bill to:	
To Inspe	WS+TP RES / OD RES / EVA		6.46
		Hends Automotive Sence	sured: GY 2972 S
of	17 Kaki Bu	Lil bold thouse	10 0849 9954
Policy N	OLD MADOUE ON 256	Claim No: (1440 194 194
Sum Ins	ued:		MID1 604 861
Make of	Veh:	Excess:	
(Client's			D.O.A. 03/11/18
CA / F	EV / REP. / REV 24 HRS		HODE I
_ Date/Ti	15. 11.080m@ 20/11/18 Pers	son Contacted Idram	H.O.D. Endorsement
Date/Tir			vende ny. ou
Date/11	Tasadusadon (-
	SGK 8080A-CS	INC12002503/Rlgh	DOA: 3/2/12
	94 29728 -X		
10/10	Kensed preli	aduse via onenime	1
12/12	0		
17/12	lump Sum \$7,6	00 (Red: 1600! 50%)	
17/12	lump Sum \$7,6	00 CRed: 1600; 50%,	

i					
					-
			9		
					-100
Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check	Survey Fee:	Date:	

Date/Time, File Pass to?	Date/Time, File Return to?
1) 12/12 Typist	2)
3)	(4)
5)	6)
Preli. Report:	
Final Report	4

Basic & Add. 250 _S+RS, _SI Photos Others

TOTAL

260

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

4046.30

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

From:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

GNOH PAU LOONG

Date:

12 Dec 2018

Preliminary Advice

Insured Vehicle No : GY2972S

TP Vehicle No

: SGK8080A

Accident Date

: 03/11/2018

Make

: SUBARU FORESTER

Assignment Date

: 20/11/2018

Date of Inspection

: 20/11/2018

Est. Duration of Repair

: 4.00

Inspection At

: WOODLANDS AUTOMOTIVE SERVICE PTE LTD (HQ)

17 KAKI BUKIT ROAD 4, #01-58 BARTLEY BIZ CENTRE

SINGAPORE 417809

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,200.00
Revised Amount	:S\$	1,600.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,600.00

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and process and process are also confirmed excess at all the process are also confirmed excess and also	oolicy	coverage.	Kindly
200	let us have your authorisation.			

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(x) Other comments : Survey on WP

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sut	mitted	Ins Auth'ed	Status	
Main	07 Nov 2018		20 Nov 2018 10:37 Assign					New Assign Cancel Case	
Þ	tain	Re	ference		Claim Details	T	Docume	nts	Show All
CLAIM SUI	BFOLDER DE	TAILS				[Creat	ed by insurer]		
Insured:	FANCO FA	N MARKETING	TE LTD, Co. R	Reg. No.: 20	1313448W				
Main Claimant:	LIM TECK	POH (LIN DING	BAO), ID: S	7401615D					
Vehicle Reg. No.:	SGK808	0A			Date of Loss	03/11/2 [38 Mo	2018 11:00 - :59 nths and 6 Days F	rom LTA Reg Da	te (Man Yr)]
Claim Type:	TP / CM	MTD1804861			Policy/Cover Note No.:	D18MT	PCVE002563 (Thir	d Party Only)	
Vehicle Reg No. (Insured):	GY2972S				Policy No. (Claimant):				
(21,001,00)					Excess:				
Repairer:	Woodland	is Automotive S	ervice Pte Ltd	(HQ) 17 KA	KI BUKIT ROAD	4, #01-58	BARTLEY BIZ CE	NTRE, 417809 K	aki Bukit - Tel
Handling Insurer:	The Control of the Co						GNOH PAU LOON	G - 63295217]	
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel	: 6256-3561	[Final Rp	t due 29	/11/2018]		
Driver/Cust dian (Insured):	YOU HAIF	ENG (), NRIC: G	2987777M, Te	el: +658437	3053				
Adj Asg. Remarks:	PLEASE A	RRANGE TO SURV	EY THE VEHICLE	between 14	400-1700hrs TO	N UOY YAC	MAY CONTACT IDR	AM AT 6844 945	7/ 87489825
ASSOCIAT	ED MAIL RE	CEIVED						View All Co	mpose Case M
There are n	o mail for this	case.							
ALL ASSO	CIATED TAS	sks ⁼				View	All Search Tasks	Create New	Task Comple
Due Dat			Group Sub	piect Ha	ndler Assic	ned By	Completed (On Create	d On Don

Nivitha (LKK Auto)

From:

Teo, Grace <grace.teo@sompo.com.sg>

Sent:

Tuesday, 20 November 2018 10:44 AM

To:

assignments@lkkauto.com; assignments@lkkauto.com

Cc:

Henry, Irene James; Gnoh, Pau Loong; Muham'mad Idram Bin Abdul Rahman

Subject:

CMTD1804861/GPL - SUV(LKK)/ GY2972S & SGK8080A D.O.A: 03/11/2018

HI LKK AUTO,

Please refer to the email below and make arrangement to conduct the survey for SGK8080A on a without Prejudice and any admission of liability basis.

Please submit with your report via merimen upon completion of survey.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @





¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Muham'mad Idram Bin Abdul Rahman [mailto:muhammad.idram@pitstop.com.sg]

Sent: Tuesday, November 20, 2018 10:31 AM

To: Gnoh, Pau Loong

Cc: Henry, Irene James; Teo, Grace

Subject: RE: Direct Settle; RE: CMTD1804861/GPL - SUV(20/11)/ GY2972S & SGK8080A D.O.A: 03/11/2018

Dear Sir.

Please be inform that the vehicle is already in the workshop.

The surveyor may come anytime from the propose timing given.

Thank you.

Best Regards

Muhammad Idram

Service Advisor, Pitstop@Bartley




Woodlands Automotive Service Pte Ltd

17 Kaki Bukit Road 4 Bartley Biz Centre #01-58, Singapore417809 Fax

Main Line : +65 6844 9449 Direct Line: +65 6844 9457

www.woodlandstransport.com.sg

Group of Companies:







From: Gnoh, Pau Loong [mailto:PauLoong.Gnoh@sompo.com.sg]

Sent: Tuesday, 20 November, 2018 8:13 AM

To: Muham'mad Idram Bin Abdul Rahman <muhammad.idram@pitstop.com.sg>

Cc: Henry, Irene James <irene.henry@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>

: +65 6844 9463

Subject: Direct Settle; RE: CMTD1804861/GPL - SUV(20/11)/ GY29725 & SGK8080A D.O.A: 03/11/2018

Dear Sir,

As captioned above, we would like to direct settle and please survey / finalise with our surveyor, thank you.

Best Regards Gnoh Pau Loong

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG







¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential

and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy.

From: Teo, Grace

Sent: Monday, 19 November, 2018 8:59 AM

To: Muham'mad Idram Bin Abdul Rahman < muhammad.idram@pitstop.com.sg>

Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: CMTD1804861/GPL - SUV(20/11)/ GY2972S & SGK8080A D.O.A: 03/11/2018

Hi Idram,

Noted.

Best Regards Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147





Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG







¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Muham'mad Idram Bin Abdul Rahman [mailto:muhammad.idram@pitstop.com.sg]

Sent: Saturday, November 17, 2018 11:25 AM

To: Teo, Grace

Cc: Gnoh, Pau Loong; Ye, Yong Kang Melvin; Henry, Irene James

Subject: RE: CMTD1804861/GPL - LIA(SUV)/ GY2972S & SGK8080A D.O.A: 03/11/2018

Dear Grace/Gnoh, Pau Loong,

Can you scheduled the surveyor come on 20/11/18 between 1400-1700hrs?

Thank you.

Best Regards

Muhammad Idram

Service Advisor, Pitstop@Bartley



Woodlands Automotive Service Pte Ltd

17 Kaki Bukit Road 4 Bartley Biz Centre #01-58, Singapore417809 Fax

Main Line : +65 6844 9449

Direct Line: +65 6844 9457

www.woodlandstransport.com.sg 69





: +65 6844 9463



From: Teo, Grace [mailto:grace.teo@sompo.com.sg]

Sent: Monday, 12 November, 2018 2:04 PM

To: Muham'mad Idram Bin Abdul Rahman < muhammad.idram@pitstop.com.sg >

Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry,

Irene James <irene.henry@sompo.com.sg>

Subject: CMTD1804861/GPL - LIA(SUV)/ GY2972S & SGK8080A D.O.A: 03/11/2018

Our Claim Reference: CMTD1804861/GPL

Your Reference: SGK8080A

Hi Idram,

We acknowledged receipt of your claim documents.

Please be informed that Mr. Gnoh Pau Loong is the handler of this case.

Please advise when your client will be leaving the vehicle at your premises for repair + survey.

We proposed the vehicle to be left at your premises for the day or at least half a day for survey between (1100-1400hrs) or (1400-1700hrs) for survey.

Aside to Pau Loong,

Please refer to the liability request from Woodlands Automotive Service Pte Ltd.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @





³ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Muham'mad Idram Bin Abdul Rahman [mailto:muhammad.idram@pitstop.com.sg]

Sent: Monday, November 12, 2018 11:16 AM

To: Claims - Motor Survey

Subject: LIABILITY CHECK: SGK8080A claim against GY2972A - D.O.A: 03/11/2018

Dear Officer-In-Charge,

LIABILITY CHECK: SGK8080A claim against GY2972A - D.O.A: 03/11/2018

Our Client Vehicle: SGK8080A Your insured Vehicle: GY2972A

Kindly advise and confirm the liability at soonest as our insured SGK8080A is claiming against your insured GY2972S.

Location::PITSTOP@Bartley 17 Kaki Bukit Road 4 Bartley Biz Centre #01-58 Singapore 417809

P.I.C: Idram - 87489825

Thank you and look forward to your favourable reply.

Best Regards

Muhammad Idram

Service Advisor, Pitstop@Bartley



Woodlands Automotive Service Pte Ltd

17 Kaki Bukit Road 4 Bartley Biz Centre #01-58, Singapore417809

Main Line : +65 6844 9449 Fax

: +65 6844 9463

Direct Line: +65 6844 9457
www.woodlandstransport.com.sg

Group of Companies: Www. Transport WYStravel CASHBOX



REPAIR ESTIMATE

Client:

SOMPO INSURANCE

05-01/06 LAND TOWER, RAFFLES PLACE, SINGAPORE LAND TOWER, Singapore 048623

Date:

12/11/2018 SGK8080A

Address:

Attention: Motor Claim Department

Veh No:

Veh Model: SUBARU FORESTER 2.0I-L AWD CVT

Contact No: 6461 6555

JFISJSKCSFGOS4353

Mileage:

Fax No: Email:

Service Advisor		Payment Terms	Quotation Validity
Name:	Muhammad Idram @ Aldi		
Contact N	10:87489825 (8449463		
Email:	muhammad .idram@pitstop.com.sg	Due Upon Receipt	
Fax No:			

S/No		Description	Price	Act	ions	Remarks
1	REAR BUMPER FACE	h	\$750.00	Accept	Reject	
2	LHS REAR BUMPER BRACKET	Ket Na	\$35.00	Accept	Reject	
3	RHS REAR BUMPER BRACKET	Her	\$35.00	Accept	Reject	
4	LHS CORNER REAR BUMPER	BRACKET NHT ME	\$40.00	Accept	Reject	
5	RHS CORNER REAR BUMPER	BRACKET THE M	\$40.00	Accept	Reject	
6	RHS REAR TAIL LAMP	Lit 487	\$650.00	Accept	Reject	
7	REAR BUMPER INNER BEAM	Best . 320	\$400.00	Accept	Reject	
8	BUMPER TOW HOOK COVER	xun	\$50.00	Accept	Reject	
9	OUTPUT CHROME PIPE COV	R Bert	\$150.00	Accept	Reject	
10	LABOUR:TO DISMANTLE AND	REFIX THE ABOVE MENTIONED PARTS	\$600:00	Accept	Reject	150
11	BODYWORKS:TO SPRAY THE	REAR BUMPER 250	\$450.00	Accept	Reject	670
Remark	*We will advise if further su	oplementary items are necessary*				
stimated	Working	Sub-Total	\$3,200.00		/ de	
Days of	4 Day	Gst				
Repair:	75	Total	\$3,392.50			

The above is based on initial assessment. We will advise further if there is supplementary repair.

Customer Signature / Date

(To accept this quotation, please sign & return)

List 1742 Undo/, 139360 Labour: 650 tolal: 2043.60

2/5: 1.61c 04 Duys.

Company Stamp

96893735.

- is alvey to fore after stony painting
- s saulay damaged perios) during resurvey
- Plants priving are subject to confir hation.
- Third printy survey is on a "Within the "gudice" basis
- No illegal modification(s) is allo.
- Suppliementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer Signature:

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

D18MTPCVE002563

Engine No:

Odometer:

Chassis No:

CS/SMO18020933/ATD3N2

FB201746424

38690 km

JF1SJ5KC5FG054353

Date:

13/12/2018

REFERENCE

Handling

Sompo Insurance Singapore Pte.

Insurer:

Claimant Vehicle No:

Date of Loss:

SGK8080A

03/11/2018

No:

Policy No:

Insured Vehicle

TP Nature of Claim:

GY2972S

Claim No:

CMTD1804861

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Colour:

SGK8080A

Make & Model: Reg. Date:

SUBARU FORESTER, 2.0 I-L CVT AWD SR (A) 28/08/2015 (Man. Year: 2015)

Bronze

Engine Capacity:

Market Value/New Car Price:

1995 cc

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size: Front Left Side: Front Right Side: 225/60R17

Yokohama 6 mm Yokohama 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 225/60R17 Yokohama 6 mm Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,150.00	1,393.60	756.40	35.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	650.00	400.00	38.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,200.00	2,043.60	1,156.40	36.14
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	3,200.00	1,600.00	1,600.00	50.00
+ GST 7.00/7.00% (S\$)	224.00	112.00	112.00	50.00
Nett Amount (S\$)	3,424.00	1,712.00	1,712.00	50.00

INSPECTION

Date of Assignment:

20/11/2018

Date Inspected:

20/11/2018 Inspected At:

Woodlands Automotive Service Pte Ltd

17 KAKI BUKIT ROAD 4, #01-58

BARTLEY BIZ CENTRE Singapore 417809

Estimated Period of Repair:

4.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Dec 2018)

Parts: M1-SUV SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGK8080A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FACE	Deformed	750.00 F	*750.00 FL
2	1		*LHS REAR BUMPER BRACKET	Not Necessary	35.00 F	*- FL
3	1		*RHS REAR BUMPER BRACKET	Necessary	35.00 F	*35.00 FL
4	1		*LHS CORNER REAR BUMPER BRACKET	Not Necessary	40.00 F	*- FL
5	1		*RHS CORNER REAR BUMPER BRACKET	Not Necessary	40.00 F	*- FL
6	1		*RHS REAR TAIL LAMP	Cut	650.00 F	*487.00 FL
7	1		*REAR BUMPER INNER BEAM	Bent	400.00 F	*320.00 FL
8	1		*BUMPER TOW HOOK COVER	Not Necessary	50.00 F	*- FL
9	1		*OUTPUT CHROME PIPE COVER	Bent	150.00 F	*150.00 FL
F=Fra	nchise	part. L=ListIte	emDisc.	-		
				Sub Total (S\$)	2,150.00	1,742.00
			- List Item Discount on L Ite	ms 0.00/20.00% (S\$)	0.00	348.40
				Total Parts (S\$)	2,150.00	1,393.60
			Report was unsubmitted during t	his print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO DISMANTLE AND REFIX THE ABOVE MENTIONED PARTS	New	600.00	400.00
2	TO SPRAY THE REAR BUMPER	New	450.00	250.00
	Gross Labo	ur Cost (S\$)	1,050.00	650.00
	Report was unsubmitted dur	ing this print-out.		

< END OF ESTIMATES >