

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 15 NOVEMBER 2018

Third Party Insurer: INDIA

Vehicle No: SLX7915X

Third Party Veh No: SJE6927S

Model: TOYOTA SIENTA

Date of Accident: 19/11/18

Chassis: NHP170-7109935

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT LH FENDER			<i>As</i> \$568.50 ✓
2	FRONT LH FENDER HYBRID EMBLEM			<i>na</i> \$75.10 ✓
3	FRONT LH DOOR			<i>As</i> \$1,136.90 ✓
4	FRONT LH 15" STEEL RIM			\$321.60 ?
5	FONT LH 15" STEEL RIM HUB CAP			<i>na</i> \$182.90 ✓
6	FRONT LH SUSPENSION KNUCKLE ARM			<i>na</i> \$498.00 X
7	FRONT LH SUSPENSION KNUCKLE ARM BEARING			<i>na</i> \$165.70 X
SUB TOTAL				\$2,948.70
LESS 25%				-\$737.18
PARTS TOTAL				\$2,211.52

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

5501
\$800.00

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

\$700.00 *6001*

TO TUFF KOTE / ANTI-RUST

\$60.00 ✓

TO DISMANTLE & REPLACED REAR RH DOOR INNER COMPONENT MECHANISM TO FACILITATE REPAIR WITH CHECK FOR FUNCTION

\$180.00 *601*

TO SEND VEHICLE FOR 3D COMPUTERISED CHECK & ADJUSTED ALL WHEEL ALIGNMENT

\$60.00 ✓

TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD

\$150.00 ?

LABOUR TOTAL \$1,950.00

TOTAL \$4,161.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Authorised
Resurvey by paint
5 days