



Immediate Advice

To : AXA Insurance Pte Ltd

Date: 11/1/2019

Survey Details:

Date of loss	18.11.18
Date of appointment	20.11.18
Date of survey	20.11.18
Location of survey	ABWIN

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKS 2392A
Make and Model	HONDA ODY 2356CC
Date of registration	31.03.2015
Excess	
Market Value	\$ 90,000.00
Parf Rebate	\$ 68,000.00
Nett Loss	\$ 22,000.00

Repair details:

Initial Estimate	\$ 14,106.33
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 3,434.88
Check items (estimate)	
Labour	\$ 1,530.00
Total	
Lump Sum(if applicable)	4,964.88

Number of days for repair	<u>6</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

REPAIR NOT AUTHORIZED. HEAD TO REAR ; OI BEHIND

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	5,312.42
Loss of Rental	\$	1,200.00
Loss of Use		
LTA search fees	\$	2.00
Proposed Total	\$	6,514.42