

LAKSHI

INS. CASE OWNER

Smitheng

CC 4 ASM AXA1802

0968, T. 6679

LKK

IDAC

Surveyor:

ATH

DOI:

ASSIGNMENT

12/1/18

Date / Time:

10/1/18

Registered in Meriten:

Pre-assign / CCU / FTE



Insured Vehicle No.

SFZ 36495

Name of Insured

LEGEND MOTORS & LEASING

Insured Tel No.

HP:

Claim No.

S8mo 1218 82102/10507

Policy No.

0199604

Make / Model:

Toyota

Place of Accident:

130A Wimping Rd 4P

Excess Sec II :SS

11500

D.O.A:

18/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

RAY LAM TOL

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

Final ? Yes / No

SFT 1852



INSRS:

WSP:

Tel:

Liability:

RMKS:

performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time:

SFT 1852-X

SFZ 36495-X

STAGE

DATE/ PIC

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call OI:

After call hr to OI:

Documentation Check List: Handler Typist

Notification hr (if non-pickup):

After call hr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time: 26-2-19

Confirm with: CAROLINE

Confirm by: MTH

Repair Cost:

PIR

S\$ 3,314.60

(3 days) Reduction:

19 %

FINAL SETTLEMENT

Date/Time: 08-04-19

Confirm with: CAROLINE

Email: [] Call: []

Final Liability:

900

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

Repair Cost:

Mileage

S\$ 3,546.63

OO-411 PHOTOS TP

Loss of Rental (LOR):

S\$ 383.20

(3 days) x = 120

Loss of Use (LOU):

S\$ -

(5 x days)

Loss of Income (LOI):

S\$ -

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search:

S\$ 00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost:

S\$ -

Total:

S\$ 3,933.83

Global Sum SS:

FINAL PAYMENT

Date/Time: 08-04-19

Confirm with: CAROLINE

Email: [] Call: []

Payee 1:

S\$ 3,933.83

Name 1:

PERFORMANCE MOTORS LIMITED

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT 10/6/19

BUREAU

Taufin

REF:

AYN.

e

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res:

Yes or No

Lum Sum:

-

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Han.

Veh No: SFT 185Z Yr Regn: 2012 / Jly.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 320I

C.C.

1997

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

158854

T/Radio:

Insured / Std / NI / NA

Eng/No:

Ch/No:

WBA3B16090N P42899.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: looser / Jammed / Leaked / Burnt or

Brake: looser / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225 / 50 R17.

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fallen

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

17/12/18

Survey held at

pmc.

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Check back

Net cost: \$ 55,660 :

P/P: → 3,314.60 (RSD: → T10-40 A1/2)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. 50

) Photo

) Other

) -

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18020968/eb3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 20-11-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKZ 3649S	Veh. Inspected	SFT 185Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/11/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/11/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Mon 17/12 @ 10am

SFT185Z

S&R

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401539M GST Reg. NO M2-0020081-X



383, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

290, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

20 NOV 2018

ESTIMATE

Estimate No. : b1 49160
Date Estimated : 19/11/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Teo Puay Yong
Blk 171 Gangsa Road
#06-28

Singapore 670171

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFT185Z	NP42899	30/07/2012	320iA/4	0

DESCRIPTION

To replace front bumper & attachments including to knock out dented area caused by the accident

850 ✓ 1,275.00
705

To respray front bumper

734 ✓ 1,038.00
840.60

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 ✓ 177.00
135

To supply front emboss number plate.

66 ✓ 83.00
83

Sundries. *Net*

? ✓ 80.00
80

Total Labour 1: 2,653.00

DESCRIPTION

RIVET
FRONT SHOCK ABSORBER
PARTIALLY OPEN GRID RH
INSERT AIR INTAKE CENTER
FRT BUMPER TRIM PRIMED (SRA)
FLAP TOWING EYE PRIMED
FRT RH GRILLE (BASIS)
LICENCE PLATE BASE (ECE)

QTY	PRIC	VALUE
10	0.50	5.00 ✓
1	42.20	42.20 ✓
1	68.30	68.30 ✓
1	97.90	97.90 ✓
1	1,007.30	1,007.30 ✓
1	43.25	43.25 ✓
1	98.80	98.80 ✓
1	69.25	69.25 ✓

Total Parts : 1,432.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401539W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64743770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

319, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190828 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49160
Date Estimated : 19/11/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFT185Z	NP42899	30/07/2012	320iA/4	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 17/12/2012 Excess S\$ _____Surveyor's Name Tan Jie Sign [Signature]Surveyor's Tel 97495868 Authorised Yes / No _____Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail Tan Jie@lkk.comNo. of Working Days Recommend 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Labour 1	:	2,653.00
Parts	:	1,432.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	285.95
Grand Total	:	<u>4,370.95</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 49160
Date Estimated : 19/11/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Teo Puay Yong
Blk 171 Gangsa Road
#06-28

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 670171

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SFT185Z	NP42899	30/07/2012	320iA/4	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# PARTIALLY OPEN GRID RH *	68.30	1.00	3.00	66.25
# RH SUPPORT FOGLAMP *	41.85	1.00	3.00	40.59
# PLAQUE 82MM *	71.25	1.00	3.00	69.11

Total Labour :	
Total Parts :	175.95
Total Labour & Parts :	175.95

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-4



FINAL REPORT

Estimate No. : b1 49160
Date Estimated : 19/11/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Teo Puay Yong
Blk 171 Gangsa Road
#06-28

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 670171

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SFT185Z	NP42899	30/07/2012	3201A/4	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, RH foglamp support include knocking out dented areas caused by the accident	850.00	10.00	765.00	
To respray front bumper	934.00	10.00	840.60	
To check electrical wiring systems at the front section for proper function	150.00	10.00	135.00	
To supply front emboss number plate	83.00	0.00	83.00	
Sundries	80.00	0.00	80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# PARTIALLY OPEN GRID RH *	68.30	1.00	3.00	66.25
INSERT AIR INTAKE CENTER	97.90	1.00	3.00	94.96
# RH SUPPORT FOGLAMP *	41.85	1.00	3.00	40.59
FRT BUMPER TRIM PRIMED (SRA)	1,007.30	1.00	3.00	977.08
FRT RH GRILLE (BASIS)	98.80	1.00	3.00	95.84
LICENCE PLATE BASE (ECE)	69.25	1.00	3.00	67.17
# PLAQUE 82MM *	71.25	1.00	3.00	69.11

SUPPLEMENTARY ITEMS

Total Labour :	1,903.60
Total Parts :	1,411.00
Total Labour & Parts :	3,314.60
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,314.60
GST @7%:	232.02
Grand Total :	3,546.62



MANDATE IA (S8M013I8)

Type

🔗 Question

Message

Liability: Insured hit third party parked vehicle. Settlement: Repair Cost : \$3,546.62 (w/GST) Loss of Rental: \$385.20 (3days x \$120)(w/GST) LTA: \$2.00 Total: \$3,933.82 Immediate Advice with Mandate and relevant document uploaded for your easy reference. Please kindly let us have your approval / instruction if any.
Thank you - Asher Sng (22/03/2019)

Reply

◀ DS

Type

🔗 Question

Message

PLS PROCEED AS RECOMMENDED

Reply

THE SCHEDULE

Private Car Insurance Policy

This Policy sets out the terms of a contract between NTUC Income Insurance Co-operative Limited (INCOME) and you (the Policyholder named in the schedule to this Policy).

The statements, information and declaration provided by you at the time of proposal shall form the basis of this contract. We (INCOME) will provide the insurance set out in this Policy in respect of events occurring during the Period of Insurance shown in the Schedule and any further period for which we may accept a renewal premium.

The provision of this insurance is subject to:

1. any Endorsement specified as operative in the Schedule
2. the Conditions and General Exclusions of this Policy, and
3. the payment of the premium specified in the Schedule.

This Policy, the Schedule and the Certificate of Insurance are to be read together as one document.

GST Reg No. M4-0003030-8

Policy Number	: 5055004384-06	
The Policyholder	: TEO PUAY YONG	
	: BLK 171 #06-28	
	: GANGSA RD	
	: SINGAPORE 670171	
Period of Insurance	: 30 Jul 2018 To 29 Jul 2019	
Sum Insured	: Market Value of Insured Vehicle at Time of Loss	
Premium (inclusive GST)	: S\$1,087.52	
Interest Insured		
Cover Type	: drive PREMIUM	
Primary Driver	: TEO PUAY YONG	
Named Driver (1)	: N/A	
Named Driver (2)	: N/A	
Make/Model	: BMW/320i	Capacity : 2000cc
Registration Number	: SFT185Z	Registration Year : 2012
Chassis Number	: WBA3B16090NP42899	Off-peak Car : No
Repair at Owner's Preferred Workshop	: Yes	Insure with COE : Yes
Excess (Section 1)	: N/A	NCD Entitlement : 50%
Excess (Section 2)	: N/A	NCD Protection : Yes(Free)
Windscreen Excess	: S\$100	Loyalty Discount : 5%
Additional Excess	: N/A	
Unnamed Driver Excess	: Please refer to Terms and Conditions	
Hire Purchase Company	: UNITED OVERSEAS BANK LIMITED	
Optional Cover		
Transport Allowance	: Yes	
Excess Waiver	: Yes	

Memo A : Premium is net after \$100 Orange Eye discount.

Endorsement Operative : M4, M7, M8, M9

Agency : INCOME-BRANCH SERVICES (00000034490)
Date of Issue : 30 Jul 2018 10:22 hrs

DUTY OF DISCLOSURE

We would remind you that you must disclose to us, fully and faithfully, the facts you know or ought to know, otherwise you may not receive any benefit from your Policy.

Signed in Singapore by order of the Board of Directors



Chief Executive

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7146661B



Name

TEO PUAY YONG

張 佈 場

Race

CHINESE

Date of birth

27-12-1971

Sex

M

S7146661B

Country of birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number S7146661B

Doc. No.

TEO PUAY YONG

Birth Date: 27 Dec 1971

Issue Date: 20 Mar 2003



000322113A



4444444



NRIC No. S7146661B

Date of issue

18-03-2010

Address

APT BLK 171 GANGSA ROAD
#06-28
SINGAPORE 670171

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

PASS DATE

Class 2B: Motorcycles <= 120 CC
Class 2A: Motorcycles between 120 CC and 400 CC
Class 2: Motor cars <= 3500 kg (incl) <= 7 passengers, exclusive of the driver, and motor motorcycles <= 2500 kg

18 Mar 1999

31 Mar 2017

31 Mar 1991

S7146661B

S / No. 9000269995

License No. S7146661B



NP 428A



(A)

AXA Insurance Pte Ltd
8 Shenton Way
#27-01
Singapore 068811
Attention: Motor Claims

"Without Prejudice"

Your Ref:

Our Ref:

Date:

Subject:

22 February 2019

ACCIDENT INVOLVING VEHICLES SFT185Z & SKZ3649S ON 18.11.2018

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	:	S\$	3546.62
Car Rental	:	S\$	385.20
GIA search fee	:	S\$	2.00
Total	:	S\$	3933.82

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & GIA search slip
3. Copy of Car Rental bill & Car Rental Agreement & Certificate of Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation & Discharge Voucher

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

Teng Wai Khan
Customer Service Manager, Body & Paint

Performance Motors
Limited
1800-Call-BMW
(1800-2255-2699)

www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel After-sales
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel After-sales
6319 0527
Fax 6479 6624

280
Kampung Arang Rd
East Coast Centre
Singapore 438180
Tel After-sales
6319 0888
Fax 6344 1332

Registered office
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No:
197401559W

Performance Motors Limited

A member of the Sime Darby Group



LETTER OF AUTHORISATION

ACCIDENT INVOLVING SFT185Z & SKZ36495 ON 18/11/18.


I, MR JEE PUAY YONG owner of Vehicle Registration No. SFT185Z
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and
settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all
documents whatsoever in relation to this matter and to accept and receive any payment
due to me in respect of my claim above.


I hereby declare that all acts and documents done by virtue of this Letter of Authorisation
on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if
the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement
amount in respect of such claim shall constitute the full discharge of my claim in respect of
such loss and damage.

Signed by:


Name: JEE PUAY YONG (Date) 19/11/18
NRIC No.: 57146661B

In the presence of:


Name: _____ (Date) 19/11/18
NRIC No.: _____

HAN KWAN YONG
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941



DISCHARGE VOUCHER

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SKZ3649S.

Dated this 08 day of APRIL 2019

Signature

: S7146661B

1	HAN KWAN YONG	
---	---------------	--

3434821214 Road
Eyre Derby Regional Council

AXA Insurance Pte Ltd (Company Reg. No. 1999050125)
8 Shenton Way, #24-01 AXA Tower, Singapore 068811
Customer Centre #B1-01
Tel: +65 6590 4888 Fax: +65 6330 2622 Website: www.axa.com.sg

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401337W GST Reg. No. M2-0020081-a



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64787770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63448773

119, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64786601 (AfterSales)
64786624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1323443

Date IN : 17/12/2018

Cust. Svc. Advisor: Han Kwan Yong

Page No. : 1 of 2

Invoice Number : 2068131 / WSB

Invoice Date : 21/02/2019

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mr Teo Puay Yong
Blk 171 Gangsa Road
#06-28

Singapore 670171

- INVOICE TO - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFT185Z	NP42899	30/07/2012	320IA/4	158854

- - - - LABOUR 1 - - - -

To replace front bumper and attachments including to
remove and install body parts in order to carry out painting
job.

To respray front bumper

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 18.11.2018. 3RD PARTY CAR : SKZ3649S.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO
CONSULTANTS PTE LTD ON 17.12.2018 AT 12.05 PM.
AUTHORISED REPAIR BY MS ASHER SNG FROM LKK ON
5.12.2018 VIA E-MAIL.

PROPOSE CAR RENTAL = \$385.20. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

GIA SEARCH FEE = \$2.00.

Retail

Price

DISC%

NETT

850.00

10.00

765.00

934.00

10.00

840.60

150.00

10.00

135.00

80.00

0.00

80.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

Total Labour 1 : 1,820.60

- - - - PARTS - - - -

FRT BUMPER TRIM PRIMED (SRA)

PARTIALLY OPEN GRID RH

INSERT AIR INTAKE CENTER

LICENCE PLATE BASE (ECE)

FRT RH GRILLE (BASIS)

RH SUPPORT FOGLAMP

PLAQUE 82MM

Retail

Qty

Price

DISC%

NETT

1

1,007.30

3.00

977.08

1

68.30

3.00

66.25

1

97.90

3.00

94.96

1

69.25

3.00

67.17

1

98.80

3.00

95.84

1

41.85

3.00

40.59

1

71.25

3.00

69.11

Total Parts : 1,411.00

- - - - LABOUR 2 - - - -

To supply front silver emboss lettering black base number
plate

Retail

Price

DISC%

NETT

83.00

0.00

83.00

0.00

0.00

0.00

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64767770

280, Kampung Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

119, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICERepair Order No. : **B1 1323443**Date IN : **17/12/2018**Cust. Svc. Advisor: **Han Kwan Yong**Page No. : **2 of 2**Invoice Number : **2068131 / WSB**Invoice Date : **21/02/2019**Payment Terms : **30 Days From Invoice**Invoice By : **Sharon Heng**Total Labour 2: **83.00**

Labour Charges : **1,823.60**
Parts Charges : **1,411.00**
Lubricant/Misc : **80.00**

Total Labour & Parts Charges : **S\$ 3,314.60**
Less Insurance Excess : **S\$ 0.00**
Invoice Total Amount Exclude GST : **S\$ 3,314.60**
GST @ 7% : **S\$ 232.02**
Invoice Total Amount Include GST : **S\$ 3,546.62**

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 3,546.62**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





TAX INVOICE

Invoice No. 55 - 512827

Page 1 of 1

MR TEO PUAY YONG

BLK 171 GANGSA ROAD #06-28
670171 SINGAPORE

SIME DARBY SERVICES PTE LTD

Thrifty International Licensee

305 Alexandra Road, #03-01

Vantage Automotive Centre, Singapore 159942

p (65) 6447 3388 f (65) 6345 7247

Co. Reg. No. 197501065W GST Reg. No. M2-0021986-4

INVOICE DATE : 20-DEC-2018

R.A. No. 55005267 / Benjamin Loo ZhiWei

TITLE	: MR	KILOMETER OUT/IN	: 44610 / 44819
AUTHORIZED DRIVER	: TEO PUAY YONG	KILOMETER DRIVEN	: 209
NRIC/PASSPORT NO.	: S7146661B	PETROL LEVEL OUT/IN	: FULL / FULL
MAKE & MODEL	: BMW 520i (A)	DATE & TIME OUT	: 17-DEC 2018 10:15
CAR REGISTRATION NO.	: SKP8805C / UNIT #: 0002557	DATE & TIME IN	: 20-DEC 2018 10:30
CAR GROUP GIVEN	: J	CHECK IN LOCATION	: SHORT TERM-HQ (SIN55)-THRIFTY
CAR GROUP CHARGED	: H	NO. OF DAY(S) CHARGED	: 3 DAY(S)

DESCRIPTION	UNIT PRICE (SGD)	UNIT	AMOUNT BEFORE GST (SGD)	GST @ 7%	AMOUNT (SGD)
INSURANCE CLAIMS RATES 2017					
3 DAY(S) @ \$120.00 / DAY			360.00	25.20	385.20
SUB-TOTAL			360.00	25.20	385.20
REMARKS: BMW OWNER. SFT185Z \$150.00 / DAY 2.0CC PML CSA: HAN					
		TOTAL (SGD) :	360.00	25.20	385.20
* ITEMS NOT SUBJECT TO GST					
		VISA XXXXXXXXXXXX1830			-385.20
		BALANCE DUE			0.00

NOTE:

I / WE HEREBY AGREE TO THE TERMS AND CONDITIONS AND BE HELD LIABLE FOR ALL AMOUNT DUE UNDER THIS AGREEMENT. ALL TRAFFIC FINES INCLUDING ADMIN FEES INCURRED DURING PERIOD OF HIRE; ANY COSTS INCURRED BY SIME DARBY SERVICES PTE LTD FOR MY FAILURE TO REPORT ANY ACCIDENT WITHIN 24 HOURS. FINAL CHARGES IS SUBJECT TO FULL INSPECTION OF THE VEHICLE BY A COMPANY REPRESENTATIVE.

HIRER'S AND/OR ADDITIONAL DRIVER'S SIGNATURE

DATE/TIME: 20-DEC-18 10:27:46
 MID: 0008861000630006
 TID: 39263134 INV: 011959
 BATCH: 003784 TRACE: 019782
 CARD: 011559-001724019782
 APP/AUTH CODE: 419853
MOTO SALES
 VISA
 BASE : S\$ 385.20
 TOTAL : S\$ 385.20

Printed on 20-Dec-2018 10:27

Entered by Muhammad Lukman bin Mohamed

**SIME DARBY SERVICES PTE LTD**

Thrifty International Licensee

305 Alexandra Road, #03-01

Vantage Automotive Centre, Singapore 159942

p (65) 6447.3388 f (65) 6345.7247

Co. Reg. No. 197501065W GST Reg. No. M2-0021986-4

TO BE PAID BY

PAYMENT: VISA - XXXXXXXXXXXX1830

HIRER'S DETAILS

TITLE MR
 NAME TEO PUAY YONG
 ADDRESS BLK 171 GANGSA ROAD
 #06-28
 870171
 SINGAPORE

NRIC/PASSPORT NO S7146661B ISSUE 18/03/2010

ISSUED BY SINGAPORE
 LICENSE S7146661B EXPIRY 31/12/2099

ISSUED BY SINGAPORE
 NATIONALITY SINGAPOREAN D.O.B. 17/12/1971

FREQUENT FLYER NO

LOCAL CONTACT 9008 2205

HOTEL

COMPANY'S DETAILS

NAME

ADDRESS

RENTAL AGREEMENT NUMBER : 55005267

RENTAL LOCATION : SHORT TERM-HQ (SIN55)-THRIFTY

CHECKOUT

UNIT # / REGN NO 00002557 / SKP8805C
 MAKE & MODEL BMW 520i (A)
 CAR GROUP GIVEN J CHARGE: H
 KILOMETER OUT 44,610
 PETROL LEVEL OUT FULL
 DATE & TIME OUT 17/12/2018 10:15
 DUE DATE & TIME IN 20/12/2018 10:15
 CHECKIN LOCATION SHORT TERM-HQ (SIN55)-THRIFTY

RENTAL RATES

AS: INSURANCE CLAIMS RATES 2017

DAILY @ S\$ 120.00

EXTRA DAY @ S\$ 120.00

EXTRA HOUR @ S\$ 24.00

TOTAL: S\$ 385.20**FOR RATES TO APPLY**

MINIMUM 24 HOURS
 CAR MUST BE RETURNED TO RENTING LOCATION
 ON THE DUE DATE

INSURANCE

BY INITIALS, THE HIRER

INCLUSIVE LDW

NON-WAIVERABLE DAMAGE EXCESS: S\$ 3,000.00 (SIN USE)

DECLINES PAI @ S\$ 5.00 PER DAY

DECLINES WSC @ S\$ 5.00 PER DAY

THIS CAR IS FOR SINGAPORE USE ONLY THERE IS NO INSURANCE
 COVERAGE FOR USE OUTSIDE SINGAPORE

OTHER CHARGES

FUEL SERVICES @ S\$2.70 / LITRE

CASH & CHEQUE DEPOSIT**REMARKS**

BMW OWNER: SFT185Z

\$150.00 / DAY 2.0CC

PML CSA: HAN

HI RESERVATION

RES. ID#
 Benjamin Loo ZhiWei

TACO#
 REF SRC IN5CLAIMS

Printed on 17-Dec-2018 10:06
 Entered by Benjamin Loo ZhiWei

IMPORTANT NOTICE

- Hirer is liable for all traffic fines including admin fees that are issued by Singapore or Malaysia authorities for a grace period of 12 months from the date of car return.
- A security deposit depending on the respective car group rented will be withheld on the Hirer's credit card.
- Any accident has to be reported within the next working day to Sime Darby Services Pte Ltd. In the event of failure to report, hirer shall be liable for any costs incurred by Sime Darby Services Pte Ltd or claims made by the other party.
- Smoking, durians and pets are not allowed in the vehicle. An additional 3 day's rental would be imposed if smoking and durian smell/pet's fur is detected upon car return.
- Hirer must inform Sime Darby Services Pte Ltd in advance for vehicle drop-off in Thrifty Malaysia renting location. A one-way rental fee and Malaysia surcharge are applicable as stated in our One Way Rental policy.
- Hirer is responsible for any missing items/car accessories or loss of keys will be charged accordingly.
- The excess do not cover i) Car accessories ii) Loss of key iii) Vandalism iv) Alcohol/Intoxicants/drugs.
- Vehicles are prohibited to be driven into Thailand.
- Strictly no key-drop services allowed, security deposit will be forfeited.

The vehicle is rented subject to all terms and conditions on this page and on the reverse side whether printed or handwritten. Hirer represents that they have read, understand and agree with the conditions of the rental agreement. The hirer authorises all amounts due under the rental agreement to be charged to the hirer's credit card shown on this form.

x 
 Hirer

x
 Additional Driver

ADDITIONAL DRIVERS:



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-178481
Date of Request: 19/11/2018

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date: 19/11/2018
Enquiry By: Han Kwan Yong
TP Vehicle No.: SKZ3649S
Accident Date: 18/11/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKZ3649S	AXA Insurance Pte Ltd	24/10/2018-23/10/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the report or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-178481
Date of Request: 19/11/2018

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date: 19/11/2018
Enquiry By: Han Kwan Yong
TP Vehicle No: SKZ3649S ✓
Accident Date: 18/11/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	
GST Amount	
Total Amount Due (GST Inclusive)	

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKZ 3649Z (Insd veh)	Model:	B.M.W. 320I
	SFT 185Z (TP veh)		
Date of Accident:	18/11/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	4,559.22
Final Repair Cost	:	\$	3,546.62
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	385.20 3 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00

	:	\$	
Final Settlement Sum	:	\$	3,933.82
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop: Agreed Liability _____ (%)			
B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____			
BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	PERFORMANCE MOTORS LIMITED	:	\$ 3,933.82

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

16/04/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18020968/T1eb3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG		Date : 16-04-2019		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 3649S	Veh. Inspected	SFT 185Z	
Policy No.	P1917604	Coverage (\$)	0.00	
Claim No.	S8M013IB	Excess (\$)	0.00	
Assign From		Assign Date	20/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 320I	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WBA3B16090NP42899	Colour	RED	
Odometer	158854	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	FALKEN	6 mm	
L/H Front Tyre	225/50 R17	FALKEN	6 mm	
R/H Rear Tyre	225/50 R17	FALKEN	6 mm	
L/H Rear Tyre	225/50 R17	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/11/2018	Inspection Date	17/12/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFT 185Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT EMBOSS NUMBER PLATE (SN) (CONSISTENT)	BENT	83.00	83.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	80.00	80.00
10	RIVET (SN) (CONSISTENT)	NOT NECESSARY	5.00	-
1	FRONT SHOCK ABSORBER (SN) (CONSISTENT)	NOT NECESSARY	42.20	-
1	PARTIALLY OPEN GRID RH (SN) (CONSISTENT)	NOT NECESSARY	68.30	-
1	INSERT AIR INTAKE CENTER (SN) (CONSISTENT)	DEFORMED	97.90	94.96
1	FRT BUMPER TRIM PRIMED (SRA) (SN) (CONSISTENT)	DEFORMED	1,007.30	977.08
1	FLAP TOWING EYE PRIMED (SN) (CONSISTENT)	NOT NECESSARY	43.25	-
1	FRT RH GRILLE (BASIS) (SN) (CONSISTENT)	CUT	98.80	95.84
1	LICENCE PLATE BASE (ECE) (SN) (CONSISTENT)	DEFORMED	69.25	67.17
1	PARTIALLY OPEN GRID RH (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	66.25	66.25
1	RH SUPPORT FOGLAMP (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	40.59	40.59
1	PLAQUE 82MM (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	69.11	69.11
			1,770.95	1,574.00
LABOUR				
TO REPLACE FRONT BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT.			1,275.00	765.00
TO RESPRAY FRONT BUMPER.			1,038.00	840.60
TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.			177.00	135.00
			2,490.00	1,740.60
GRAND TOTAL			4,260.95	3,314.60
RECOMMENDED COST OF REPAIRS				3,314.60

Report Ref No/CC4/ASM18020968/T1eb3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Chain

S00401388

Reference

CC4/ASH19020968/71eb3a2

Loss Date

18 November 2018

Report Date

20 Nov 2018 1:06:00 PM

Request Date

22 March 2019

Due Date

Actions

Next Step

Wait for Approve Invoice

Add Progress

Vehicle Information

Incident Vehicle Registration #

SFT18SZ

Make

TPVO BMW

Model

320i-2.0 (A)

Service Address

Primary Contact/Insured

LEGEND MOTORS & LEASING PTE LTD
20 TUAS AVENUE 2, #394-51, Singapore 633800B3

Claim Handler

KHOR Saw Theng
6568804754
sawtheng.khor@lxa.com.sg

Additional Instructions

Document Type

Document SubType

Upload Document

Messages

Invoices

History















Documents

Assessment

Metrics

Notes

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Metriops	
LockInvoice1 (10).pdf	Invoice	Surveyor/ Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)	18 April 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 April 2019
 payment breakdown.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 April 2019
 LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 April 2019
 LKK Inspection (4).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 April 2019
 LKK Adjustment 1a (4).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 April 2019
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 April 2019
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	18 April 2019
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	18 April 2019
 WORKSHOP INVOICE.pdf	Invoice	Receipts	LKK AUTO CONSULTANTS PTE LTD (TP)	18 April 2019
 Immediate Advice with Mandate.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	22 March 2019
 FINAL REPORT.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	22 March 2019
 LKK Resurvey Photo.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	22 March 2019
 TP ESTIMATE MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	22 March 2019
 LKK Survey Photo.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	22 March 2019

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
 UCZ364YS INSD GUA PDF	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	20 November 2018