



ACCIDENT TIME REPORTED	0800HRS
ACCIDENT DATE	16-Nov-18
BUS CAPTAIN NAME	ONG LUAY KIONG
EMPLOYEE NUMBER	

BUS REGISTRATION NUMBER	SBS6324C
BUS TYPE (SD/DD)	SD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

	Part No.	Part or Item Description	Quantity	Total Cost
	77200691	Flap Engine - Rear Engine Door <i>HA</i>	1	\$3,295.63
	77016355	DAMPENING CENTER (ENGINE DOOR/PANEL REAR) <i>new</i>	1	\$253.50
	77200885	License plate lamp rear (LED) <i>CR</i>	1	\$49.14
	77200617	BUMPER REAR <i>Repair</i>	1	\$996.94
	77040875	VINYL CUT OUT STICKERS FOR "SG <3 BUS" <i>new</i>	1	\$45.50
	77040871	TOWER TRANSIT CUT OUT LOGO STICKERS <i>new</i>	1	\$19.50
			7% GST	\$326.21
			FINAL TOTAL COST	\$4,986.43

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)		TOTAL COST
TO REPLACE/REPAIR THE DAMAGED PARTS (INCLDING SPRAY PAINTING)	2820	\$3,800.00
	7% GST	\$245.00
	FINAL TOTAL COST	\$4,066.00

6,483.27
4 days

ESTIMATED ACCIDENT REPAIR COST



SECTION 5: REPAIRS TO BUS ADVERTISEMENT VINYL/PANELS (ADVERTISEMENT COST)

TOTAL ADVERTISEMENT REPAIR COST	-
---------------------------------	---

SECTION 6: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 7: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

<table><tr><td>BUS TYPE (SD / DD)</td><td>SD</td></tr></table>		BUS TYPE (SD / DD)	SD	Date In For Repairs	20/11/2018
		BUS TYPE (SD / DD)	SD		
		Date Out From Repairs	24/11/2018		
Number of Days Under Repair	4				
LOSS OF USE COST		\$1,200.00			

SUMMARY	
SECTION NO.	COST
1	\$4,986.43
2	\$2,996.00
3	-
4	-
5	\$1,200.00
ESTIMATED ACCIDENT REPAIR COST (1+2+3+4+5)	\$9,182.43

Rasul
Hy 90010068
4 days
P/P
19/11/18 @ 1555
Recovery 50 print