

INS. CASE OWNER:

CC 4, ALG 180 2024, Lea3

LKK:
IDAC

Survivor:

DOI:

ASSIGNMENT

20/11/18

Date / Time:

19-11-18

Registered in Merimen:

20-11-18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLB 177X

Claim No.:

Name of Insured:

Bon Tze Yin Charlene

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

14-11-18

Place of Accident:

Lornie Highway

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SJT 2348K



INSRS:

WSP:

Tel:

Liability:

RMKS:

BU Auto.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

22/11
PCHSJT 2348K. X; SLB 177X. X
31.11.18 15:30 (PAID ON CONFIRMED ACCIDENT. A REPAIR ORDER TP, REPORT TP
CLAIM ADDED TO SETTLE AND AVOID FROM THE ISSUE.

Email WSP LORNIER CLAME.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

Email 23.1.19

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: KCC

Repair Cost:

SS 1/150-00

(4 days) Reduction:

60 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 26-2-19

Confirm with: PCH

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

21

If NO or B 28, Ass. Lin:

Repair Cost:

SS 2/150-50

on REPAIR ORDER TP

Loss of Rental (LOR):

SS 400-00

(4 days) x 400

Loss of Use (LOU):

SS -

(5 x days)

Loss of Income (LOI):

SS -

(5 x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search:

SS 2-00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

9300 + 420

Total:

SS 3488.50

Global Sum SS:

FINAL PAYMENT

Date/Time: 26-2-19

Confirm with: PCH

Email ☒ Call ☐

Payee 1:

SS 3488.50

Name 1: BU AUTO SERVICES PTE LTD

Payee 2 (Strike if N.A.)

SS

Name 2:

Payee 3 (Strike if N.A.)

SS

Name 3:

REF: **ATW****ASSIGNMENT**From: _____ Date: **20-11-2018**

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SJT 2348X**at Workshop n/s: **BH Auto**of **BH 1 Sm Ming Ind Est #01-115**

Insured _____

Policy No. _____


Claims No. _____

Sum Insured _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

10:30am

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **817k**

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **04** days Res: Yes or NoLum Sum: **20** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SJT 2348X** Yr Regn: **09 09**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Honda Airwave** C.C. **1496**Colour: **M. Gray** A/C: Insured / Std / NI / NASp. Reading: **158460** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **GJI 1307135**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: **Green Max 205/50R16**R: **Yoko**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: **9** mmL/Bal: **9** mmD.O.A: **14/11/18**

Rear

R/Bal: **4** mmL/Bal: **4** mmD.O.A: **20/11/18**

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: **21/11** Action / Instruction: **File pass to Corbett****45:41,450 (RED: +3,138.60 62%)**

Date/Time, File Pass to?

☐ : Preli. Report

(1)

☐ : Final Report

Date/Time, File Return to?

21

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS + GI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

ATTN : MOTOR CLAIMS DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
AIG BUILDING
78 SHENTON WAY
#07-16 SINGAPORE 079120
TEL : 6419 3000

DATE : 17/11/2018

PAGE : 1 OF 2

Not Notified

L1 Pump &

Resurvey After Paint

ACCIDENT REPAIR ON : SJT2348K
MODEL : HONDA AIRWAVE 1.5M
POLICY NO : GA059425/1
CHASSIS NO : GJ11307135
YEAR OF MANUFACTURE : 2008
DATE / TIME OF ACCIDENT : 14/11/2018@09:50HRS
LOCATION : ALONG LORNE EXPRESSWAY TOWARDS FARRER ROAD
THIRD PARTY VEHICLE NO : SLB177X

REPLACEMENT OF PARTS		QUANTITY	UNIT PRICE	AMOUNT
1	REAR TAILGATE	1	<i>By</i>	\$ 936.00 ✓
2	REAR TAILGATE WINDSCREEN MOULDING	1	<i>Ste</i>	\$ 55.00 ✓
3	REAR TAILGATE "AIRWAVE" EMBLEM	1	<i>Ste</i>	\$ 45.00 ✓
4	REAR TAILGATE "LOGO" EMBLEM	1	<i>Ste</i>	\$ 28.00 X
5	REAR TAILGATE OUTER CHROME MOULDING	1	<i>Ste</i>	\$ 245.00 X
6	REAR TAILGATE OUTER GARNISH	1	<i>Ste</i>	\$ 398.00 X
7	REAR TAILGATE OUTER LOCK HANDLE	1	<i>Ste</i>	\$ 65.00 X
8	REAR TAILGATE REVERSE CAMERA	1	<i>Ste</i>	\$ 480.00 ✓
9	REAR TAILGATE NUMBER PLATE WITH HOLDER	1	<i>Not</i>	\$ 55.00 ✓
10	REAR TAILGATE NUMBER PLATE LAMP LH	1	<i>Ste</i>	\$ 65.00 X
11	REAR TAILGATE NUMBER PLATE LAMP RH	1	<i>Ste</i>	\$ 65.00 X
12	REAR TAILGATE MECHANISM LOCK	1	<i>Ste</i>	\$ 115.00 X
13	REAR TAILGATE INNER TRIM BOARD	1	<i>Ste</i>	\$ 585.00 X
14	REAR TAILGATE HINGE LH	1	<i>Ste</i>	\$ 62.00 X
15	REAR TAILGATE HINGE RH	1	<i>Ste</i>	\$ 62.00 X
16	REAR TAILGATE WEATHERSTRIP	1	<i>Ste</i>	\$ 151.00 X
17	REAR BUMPER	1	<i>By</i>	\$ 739.00 ✓
18	REAR BUMPER SIDE RETAINER LH	1	<i>Ste</i>	\$ 28.00 X
19	REAR BUMPER SIDE RETAINER RH	1	<i>Ste</i>	\$ 28.00 X
20	REAR END PANEL LOCK STRIKER	1	<i>Ste</i>	\$ 35.00 ✓
21	REAR END PANEL INNER TOP GARNISH	1	<i>Ste</i>	\$ 145.00 ✓
		SUB TOTAL		\$ 4,387.00
		LESS 20%		\$ (877.40)
		PARTS TOTAL		\$ 3,509.60

SPECIAL NETT ITEMS		QUANTITY	UNIT PRICE	AMOUNT
1	REAR TAILGATE WINDSCREEN SEALANT	1	<i>Ste</i>	\$ 100.00 <i>Not</i>
2	REAR TAILGATE OUTER CHROME MOULDING CLIPS	4	\$ 5.90	\$ 23.60 X
3	REAR TAILGATE OUTER GARNISH CLIPS	6	\$ 5.90	\$ 35.40 X
4	REAR TAILGATE INNER TRIM BOARD CLIPS	10	\$ 5.90	\$ 59.00 X
5	REAR BUMPER CLIPS	10	\$ 5.50	\$ 55.00 ✓
6	REAR END PANEL INNER TOP GARNISH CLIPS	4	\$ 6.50	\$ 26.00 X
		PARTS TOTAL		\$ 299.00

ACCIDENT REPAIR ON : SJT2348K

MODEL : HONDA AIRWAVE 1.5M

POLICY NO : GA059425/1

CHASSIS NO : GJ11307135

YEAR OF MANUFACTURE : 2008

DATE / TIME OF ACCIDENT : 14/11/2018@09:50HRS

LOCATION : ALONG LORNIE EXPRESSWAY TOWARDS FARRER ROAD

THIRD PARTY VEHICLE NO : SLB177X

DATE : 17/11/2018

PAGE : 2 OF 2

LABOUR CHARGES FOR REAR PORTION		AMOUNT
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	\$ 500.00
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.	\$ 500.00
3	REMOVE AND REFIX REAR TAILGATE WINDSCREEN GLASS TO FACILITATE REPAIRS	\$ 120.00
4	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS.	\$ 80.00
5	DISCONNECT, CHECK, RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING, HARNESS, WIRE SOCKETS AND ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 80.00
LABOUR TOTAL		\$ 1,280.00

TOTAL PARTS & LABOUR	\$ 5,088.60
GST 7%	\$ 356.20
GRAND TOTAL	\$ 5,444.80
ESTIMATE REPAIR DURATION	5 DAYS

YOURS SINCERELY,

ESTIMATOR : KIT

TEL : 8405 4058

FAX : 6269 2404

EMAIL : karkit.ngai@bhauto.com.sg

Parts : \$1830 - 20% = \$1464.00
 8/NETT : \$95.00

LABOUR : \$890.00

TOTAL : \$2449.00 - 20% L/S
 = \$1959.20

SURVEY ATTENDED BY :

R. 2 \$1950.00 ✓/k

NAME	Kenneth
COMPANY	LLKIC
DATE	20/11/18
TIME	10.55am
TEL	969,0663
EMAIL	

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 8572B

Vehicle Details

Vehicle No.: SJT2348K
Vehicle to be Exported: No
Intended Deregistration Date: 16 Nov 2018
Vehicle Make: HONDA
Vehicle Model: AIRWAVE 1.5M A
Primary Colour: Silver
Manufacturing Year: 2008
Engine No.: L15A5208685
Chassis No.: GJ11307135
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$18,105.00
Original Registration Date: 29 Sep 2009
First Registration Date: 29 Sep 2009
Transfer Count: 0
Actual ARF Paid: \$18,105.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Sep 2019
PARF Rebate Amount: \$9,052.00

Intended COE Rebate Details

COE Expiry Date: 28 Sep 2019
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$15,589.00
COE Rebate Amount: \$1,351.00
Total Rebate Amount: \$10,403.00

The information contained herein is correct as at 16 Nov 2018

OK

CHEAPEST CAR INSURANCE RENEWAL



Choice of
\$0 excess



Option of any
workshop

GET A CHEAPER QUOTE NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Aila 1.6A



2.88% p.a. Lowest Interest, SGV
Car Financing \$2000
Downpayment Monthly From
\$568
GV Credit Pte Ltd [StarAd](#)

**Lake View
Credit Pte Ltd**

[view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

7 vehicles

Honda Airwave

Sort by Date Posted

20 results/page

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Airwave	Any	Any	2009	Any	Any	Any	Available
	Honda Airwave 1.5A M (New 5-yr COE)	\$28,800	\$5,760 /yr	06-Mar-2009	1,496 cc	117,731 km	Stationwagon	Available
Spacious Stationwagon! Huge Boot Space! Fuel Efficient And Reliable! Selling Cheap! Monthly Installment From \$428! Call For A Viewing Appointment Today! Mayfair Motoring Posted: 15-Nov-2018 Tags: 2009 Honda Airwave, 2009 honda airwave, Honda Airwave, honda airwave, Honda, Airwave, airwave, Used Honda								
	Honda Airwave 1.5A (New 5-yr COE)	\$27,800	\$5,560 /yr	10-Feb-2009	1,496 cc	106,339 km	Stationwagon	Available
1 Year Comprehensive Warranty Inclusive! \$3K Down Payment! Accident-Free Quality Pre-Owned With Low Mileage Done For Peace Of Mind. 100% Loan Approval With Our Flexible In House Financing Options, Vie... Cosmo Automobiles Posted: 14-Nov-2018 Tags: 2009 Honda Airwave, 2009 honda airwave, Honda Airwave, honda airwave, Honda, Airwave, airwave, Used Honda								
	Honda Airwave 1.5A M (New 5-yr COE)	\$29,800	\$5,960 /yr	19-Feb-2009	1,496 cc	128,000 km	Stationwagon	Available
Only 1 Owner, \$2888 Drive Away, No Gimmick, Facelifted Model With Climate Digital Aircon, Choice Of Colors, Neat And Clean Interior, Well Maintain. Bank Or In-House Loan Available. Test Drive Welcome. Posted: 13-Nov-2018 Tags: 2009 Honda Airwave, 2009 honda airwave, Honda Airwave, honda airwave, Honda, Airwave, airwave, Used Honda								
	Honda Airwave 1.5A M	\$19,000	\$9,590 /yr	03-Dec-2009	1,496 cc	113,213 km	Stationwagon	Available
1 Owner With New Paint Work, Excellent Condition, 1 Year 4 Months To Go! Lowest Priced, Hurry Up! Get It Now. Posted: 04-Nov-2018 Tags: 2009 Honda Airwave, 2009 honda airwave, Honda Airwave, honda airwave, Honda, Airwave, airwave, Used Honda								
GET YOUR COE RENEWAL LOAN Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	Honda Airwave 1.5A M (New 5-yr COE)	\$28,800	\$5,760 /yr	02-Feb-2009	1,496 cc	148,000 km	Stationwagon	Available
In House Finance And Low Down Payment From \$3,800 Monthly Installment From \$569 Only! COE Loan Available! Beautiful White Airwave! Most Popular Honda Hatchback For Your Family! View To Believe. Even C... Speedo Motoring Posted: 29-Oct-2018 Tags: 2009 Honda Airwave, 2009 honda airwave, Honda Airwave, honda airwave, Honda, Airwave, airwave, Used Honda								
	Honda Airwave 1.5A M Skyroof (New 10-yr COE)	\$47,800	\$4,780 /yr	29-Apr-2009	1,496 cc	105,240 km	Stationwagon	Available
\$5K Driveaway, Optional 5 Yrs COE Available, AA Trust Certified Quality 1 Owner Vehicle! Rare Panoramic Skyroof Model. Extremely Well Maintained By 1 Owner. 100% Accident Free. Spacious And Comfortable... AA Trust Automotive Posted: 16-Oct-2018 Tags: 2009 Honda Airwave, 2009 honda airwave, Honda Airwave, honda airwave, Honda, Airwave, airwave, Used Honda								

Compare

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

ATTN : MOTOR CLAIMS DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
AIG BUILDING
78 SHENTON WAY
#07-16 SINGAPORE 079120
TEL : 6419 3000

DATE : 17/11/2018

PAGE : 1 OF 2

Not Notified

1/1/18

Resurvey After Paint

ACCIDENT REPAIR ON : SJT2348K
MODEL : HONDA AIRWAVE 1.5M
POLICY NO : GA059425/1
CHASSIS NO : GJ11307135
YEAR OF MANUFACTURE : 2008
DATE / TIME OF ACCIDENT : 14/11/2018@09:50HRS
LOCATION : ALONG LORNIE EXPRESSWAY TOWARDS FARRER ROAD
THIRD PARTY VEHICLE NO : SLB177X

REPLACEMENT OF PARTS	QUANTITY	UNIT PRICE	AMOUNT
1 REAR TAILGATE	1	<i>Bu</i>	\$ 936.00 ✓
2 REAR TAILGATE WINDSCREEN MOULDING	1		<i>Stc</i> 55.00 ✓
3 REAR TAILGATE "AIRWAVE" EMBLEM	1		<i>Stc</i> 45.00 ✓
4 REAR TAILGATE "LOGO" EMBLEM	1		\$ <i>an</i> 28.00 X
5 REAR TAILGATE OUTER CHROME MOULDING	1	<i>Stc</i>	\$ 245.00 X
6 REAR TAILGATE OUTER GARNISH	1	<i>Stc</i>	\$ 398.00 X
7 REAR TAILGATE OUTER LOCK HANDLE	1		\$ <i>Stc</i> 65.00 X
8 REAR TAILGATE REVERSE CAMERA	1	<i>Stc</i>	\$ 480.00 ✓
9 REAR TAILGATE NUMBER PLATE WITH HOLDER	1	<i>Ref</i>	\$ 55.00 ✓
10 REAR TAILGATE NUMBER PLATE LAMP LH	1	<i>Stc</i>	\$ 65.00 X
11 REAR TAILGATE NUMBER PLATE LAMP RH	1	<i>Stc</i>	\$ 65.00 X
12 REAR TAILGATE MECHANISM LOCK	1	<i>Stc</i>	\$ 115.00 X
13 REAR TAILGATE INNER TRIM BOARD	1		\$ <i>Stc</i> 585.00 X
14 REAR TAILGATE HINGE LH	1		\$ <i>Stc</i> 62.00 X
15 REAR TAILGATE HINGE RH	1		\$ <i>Stc</i> 62.00 X
16 REAR TAILGATE WEATHERSTRIP	1	<i>Stc</i>	\$ 151.00 X
17 REAR BUMPER	1	<i>Bu</i>	\$ 739.00 ✓
18 REAR BUMPER SIDE RETAINER LH	1		\$ <i>Stc</i> 28.00 X
19 REAR BUMPER SIDE RETAINER RH	1		\$ <i>Stc</i> 28.00 X
20 REAR END PANEL LOCK STRIKER	1		\$ <i>Stc</i> 35.00 ✓
21 REAR END PANEL INNER TOP GARNISH	1		\$ <i>Stc</i> 145.00 ✓
SUB TOTAL			\$ 4,387.00
LESS 20%			\$ (877.40)
PARTS TOTAL			\$ 3,509.60

SPECIAL NETT ITEMS	QUANTITY	UNIT PRICE	AMOUNT
1 REAR TAILGATE WINDSCREEN SEALANT	1	<i>Stc</i>	\$ 100.00 <i>for Stc</i>
2 REAR TAILGATE OUTER CHROME MOULDING CLIPS	4	\$ 5.90	\$ <i>an</i> 23.60 X
3 REAR TAILGATE OUTER GARNISH CLIPS	6	\$ 5.90	\$ <i>an</i> 35.40 X
4 REAR TAILGATE INNER TRIM BOARD CLIPS	10	\$ 5.90	\$ <i>an</i> 59.00 X
5 REAR BUMPER CLIPS	10	\$ 5.50	\$ <i>Stc</i> 55.00 ✓
6 REAR END PANEL INNER TOP GARNISH CLIPS	4	\$ 6.50	\$ <i>an</i> 26.00 X
PARTS TOTAL			\$ 299.00

THIRD PARTY VEHICLE NO : SLB177X

PAGE : 2 OF 2

LABOUR TOTAL	\$ 1.280.00
--------------	-------------

4 day

SINCERELY,

EMAIL : karkit.ngai@bhauto.com.sg

SURVEY ATTENDED BY :

NAME	Kenneth
COMPANY	LICL
DATE	20/11/18
TIME	10.55am
TEL	969,0883
EMAIL	

BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636

Tel: 6559 8944 Fax: 6269 2404

CO. REG. NO. 200917512K

GST REG NO. 200917512K

PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING

Your Reference: SLB177X

Our Reference: SJT2348K

Date: 14/01/2019

M/s AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16
Singapore 079120

BY EMAIL ONLY

Attention: Claims Department

CLAIMANT: JERRY TSO HAN

PROPERTY DAMAGED CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 14/11/2018 ALONG LORNIE EXPRESSWAY TOWARDS FARRER ROAD. INVOLVING VEHICLE NO SJT2348K & SLB177X

We act for JERRY TSO HAN, who was the owner of motor vehicle no. SJT2348K

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on 14/11/2018 involving our client's vehicle registration number SJT2348K and vehicle registration number SLB177X, driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/you insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1	Cost of Repair (Included 7% GST)	\$ 2086.50
2	Loss of Rental (\$ 130.00 x 4days)	\$ 520.00
3	LTA Search Fee	\$ 2.00
	Total :	\$ 2608.50

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA/ Police report lodged by driver of;
- (b) Final Repair Bill
- (c) Rental Invoice / Loss Of Use
- (d) LTA Search Fee Invoice
- (e) Letter Of Authorization

Kindly revert to our client's claim within the next 7 days.

Yours faithfully,

Yun Shi

(O): 6559 8944 (F): 6269 2404

Email: yunshi.chan@bhauto.com.sg



Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Wednesday, 23 January 2019 4:32 PM
To: 'CHARLENE.BOH@GMAIL.COM'
Subject: ACCIDENT INVOLVING SLB 177X AND SJT 2348K ON 14/11/2018

Our Ref: CC4/AIG18021024/Kea3

23 JAN 2019

BOH TZE YIN CHARLENE

Dear Sir/Madam,

ACCIDENT INVOLVING SLB 177X AND SJT 2348K ON 14/11/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION

Name of owner of m/vehicle

JERRY TSO HAN

Address

1 FARRER ROAD #05-06 SINGAPORE 268817.

NRIC No

S7788572B

RE ACCIDENT ON

14/11/2015 ALONG LORNE EXPRESSWAY TOWARDS FARRER ROAD

INVOLVING

SJT2348K VS SLB 177X

In consideration of **BH AUTO SERVICES PTE LTD** ('the Workshop') repairing my/our vehicle no SJT 2348K at my/our request. I/We the abovenamed owner of motor vehicle no SJT 2348K hereby authorise the Workshop to demand claim, negotiate, settle my/our claim for cost of repairs loss of use and all other expenses and damages arising out of the above accident.

I/We further authorise the Workshop to appoint solicitors to demand, claim, negotiate, settle and/or commence legal proceedings in my/our name for the above purpose and at the sole discretion of the Workshop. All sums recovered therefrom shall belong to the Workshop absolutely and I/We further authorise the Workshop to give absolute discharge on my/our behalf and to sign all discharge vouchers and other documents in relation to the same on my/our behalf. I/We further agree to fully co-operate with the solicitors appointed by the Workshop on my/our behalf and attend all Court hearings that are necessary to prosecute the claims maintained by the Workshop.

I/We agree that in the event that the claim is rejected for whatsoever reason or the Workshop decides not to proceed with legal proceedings or for whatsoever reason the Workshop is unable to recover all of the repair costs or are only able to recover a portion of the same I/we hereby undertake to pay them the full repair costs and or any portion thereof that cannot be recovered and all expenses including legal costs that they may have incurred in pursuing the claim within 7 days from the date of the written notice for payment by them to my/our last known address.

I/We hereby declare that I/we will always remain and be liable to the Workshop for the cost of repair to my/our motor vehicle and expenses incurred on my/our behalf. In the event that Workshop has to issue any notice or commence legal proceedings against me/us to enforce this undertaking against me/us, I/we shall be liable for the Workshop's expenses and legal cost (including solicitor and client cost) on an indemnity basis.

I/We further authorise the Workshop to give to the other party/parties absolute discharge in respect of any liability and any sum, whether agreed or not made the Workshop or to the law firm appointed by the Workshop towards full settlement of my/our claim it shall be regarded as full and final discharge of the claim.

I/We further authorise the Workshop to settle the above mentioned claim in a manner that they deem fit and the Workshop is further authorised to receive payment further to settlement of my claim with payment cheque/s being made in favour of the Workshop.

Date this 15 (day) of 11 (month) 18 (year)

Signed



Owner of m/vehicle JERRY TSO HAN

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **BH AUTO SERVICES PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$2,086.50** (Repair Cost), **S\$400.00** (Loss of Use/Rental), **S\$2.00** (Disbursement) for vehicle no. **SJT 2348K** that was damaged pursuant to the accident which occurred on **14/11/2018** (date) along **LORNIE EXPRESWAY TOWARDS FARRER ROAD** (location) involving vehicle no/s **SLB 177X**.

This is pursuant to the inspection conducted on **20/11/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **JERRY TSO HAN** ("the third party claimant") of vehicle no. **SJT 2348K** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SJT 2348K** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 14 (day) of 06 (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE

SECTOR C #01-115 SINGAPORE 575636

Tel: 6743 3494

Fax: 6269 2404

CO. REG. NO. 201006106C

GST REG NO. 201006106C

TAX INVOICE

Final Repair Bill

Our Ref: SJT2348K

Date: 14/01/2019

M/s AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way

#07-16

Singapore 079120

BY EMAIL ONLY

Vehicle No : **SJT2348K**
Make/ Model : **HONDA AIRWAVE**
Year of Manufacture : **2008**
Chassis No. : **GJ11307135**
Colour : **SILVER**
D.O.A : **14/11/2018**

QTY	ITEM/PARTICULARS	AMOUNT (S\$)
-----	------------------	--------------

1. Repair Cost for Motor Vehicle No. **SJT2348K**
Type of repair: LUMP SUM :S\$ 1950.00

GST @ 7% : S\$ 136.50

GRAND TOTAL:S\$ 2086.50

Total : Singapore Dollars Two Thousand Eighty-Six Dollars and Fifty Cents Only.



Company's Stamp & Signature

B 萬豐利汽車服務

BAN HONG LEE MOTOR SERVICES

Blk 5033, Ang Mo Kio Industrial Park 2, #01-279 (off. Ang Mo Kio Ave. 3)
Singapore 569536 Tel: 6482 5577 (3 Lines) Fax: 6482 5000
Reg. No: 263102/00M
TOWING SERVICE: 6858 4067 (After 10.30pm)

Truck Rental
Motor Repair
Motor Insurance Claims
Insurance Agent
Dealer in Used Car
Authorised Carpool Service Centre

公司及車房出租
汽車修理
保險賠償
代理保險
買賣汽車
維修服務中心



車輛出租合同

VEHICLE RENTAL AGREEMENT

Date: 11/12/18
Owner: BAN HONG LEE MOTOR SERVICES ("the owner")
Hirer: JERRY TSO HAN
Address: 1 FARRER ROAD #05-06 SINGAPORE 268817.
NRIC / Co. Reg. No: _____
Tel: _____ Fax: _____ H/P: 92252287

Owner and Hirer have agreed to enter into this Vehicle Rental Agreement for the motor vehicle described below and upon the terms and conditions contained on both sides of this document. Hirer acknowledges having read and understood all the terms and conditions and signifies acceptance upon signing.

Vehicle Reg. No: SKW 4785L		Agreement No.: 139566	
Driver's Particulars		Odometer: _____	
Name: VALERIE WAN		Date & Time Out: 11/12/18	
Address: 1 FARRER ROAD #05-06 SINGAPORE 268817.		Date & Time In: 14/12/2018	
I/C No: S8188491I	Dr/Licence No: S8188491I	Hour @\$	
Date of Issue: -	Occupation: INDOOR	04 Days @\$ 130	\$520
Date of Birth: 08/03/1981	Tools: No Spare Tyre: No	Wks @\$	
		Mths @\$	

Third Party Claim

In respect of each third party insurance claim arising from the date of hire to date of return of the vehicle (both dates inclusive), Hirer unconditionally agrees to pay Owner S\$ 200/- comprising excess payable and compensation to Owner for impact of claim on future motor insurance premiums.

Own Vehicle Damage

Hirer is responsible for the first \$ 3500/- excess for collision/damage to first party, (i.e.) BAN HONG LEE MOTOR SERVICES (including windscreen) plus loss of earning while damaged vehicle is under repair.

Authorised Driver

Hirer shall pay additional excess of \$31000 if the Authorised Driver is below the age of 25 or is above 65 years old or has less than 2 years driving experience.

Driver Not Cover By Insurance

General Exception: Insurance policy does not cover against any driver aged below 22 and/or above 70 years old and/or with driving experience of 1 year and below.

Deposit (Refundable):

Sub-Total:


Balance To Pay:

PETROL/DIESEL AT YOUR OWN EXPENSE
FOR LOCAL USE ONLY

BAN HONG LEE MOTOR SERVICES

Authorised Signature

Hirer's Signature



萬豐利汽車服務
星洲宏茂橋第二工業區大牌五〇三三門牌二七九
BAN HONG LEE MOTOR SERVICES

星洲宏茂橋第二工業區大牌五〇三三門牌二七九
BAN HONG LEE MOTOR SERVICES
Block 5033, Ang Mo Kio Industrial Park 2 #01-279
(off Ang Mo Kio Avenue 3) Singapore 569536.
Tel: 6482 5677 (2 Lines)
Fax: 6482 5000
Reg. No. 263102/00M



INVOICE No. 18297

Agreement No. 138566

Date 30/12/18

Payment Terms

[illegible]

E. & O. E.

TOTAL:

550

All cheque payment should made payable to
BAN HONG LEE MOTOR SERVICES

for BAN HONG LEE MOTOR SERVICES





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-177842

Date of Request: 16/11/2018

Your Ref No:

Online Purchase

BH Auto Services Pte Ltd
Blk 1 Sin Ming Industrial Estate Sector C
#01/111/113/115/117
Singapore 575636

Dear Sir/Madam,

Enquiry Date 16/11/2018
Enquiry By Jacelyn Loh Cai Ling
P Vehicle No. SLB177X
Accident Date 14/11/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You,

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-177842
Date of Request: 16/11/2018

Your Ref No: Online Purchase

BH Auto Services Pte Ltd
Blk 1 Sin Ming Industrial Estate Sector C
#01/111/113/115/117
Singapore 575636

Dear Sir/Madam,

Enquiry Date 16/11/2018
Enquiry By Jacelyn Loh Cai Ling
TP Vehicle No. SLB177X
Accident Date 14/11/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLB177X	AIG Asia Pacific Insurance Pte. Ltd.	01/03/2018-28/02/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Nov 2018 Edit Reg		19 Nov 2018 00:00 Edit Adj Rpt	S\$1,950.00 Edit Estimates	S\$1,950.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	BOH TZE YIN CHARLENE, ID: 57700521H								
Main Claimant:	JERRY TSO HAN, ID: 57788572B								
Vehicle Reg. No.:	SJT2348K	Date of Loss:	14/11/2018 09:00 - :59 [109 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0581828021SG	Policy/Cover Note No.:	2100452995 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLB177X	Policy No. (Claimant):	GA059425/1						
		Excess:							
Repairer:	BH Auto Services Pte Ltd (Sin Ming) Bldg 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, 575636 Sin Ming - Tel: 6559 8944								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 29/11/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJT2348K (0581828021SG)
[SLB177X]
TP
JERRY TSO HAN
Nov 14 2018 9:00AM
[BOH TZE YIN CHARLENE]
BH Auto Services Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser
------------------	---------------	--------------------	--------------	--------------	--

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	

Photos/Images				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	23/01/19 16:33	General View		Load JPG	<input checked="" type="checkbox"/>
2	23/01/19 16:33	General View		Load JPG	<input checked="" type="checkbox"/>
3	23/01/19 16:33	General View		Load JPG	<input checked="" type="checkbox"/>
4	23/01/19 16:33	General View		Load JPG	<input checked="" type="checkbox"/>
5	23/01/19 16:33	General View		Load JPG	<input checked="" type="checkbox"/>
6	23/01/19 16:33	General View		Load JPG	<input checked="" type="checkbox"/>
7	23/01/19 16:33	General View		Load JPG	<input checked="" type="checkbox"/>
8	23/01/19 16:33	General View		Load JPG	<input checked="" type="checkbox"/>
9	23/01/19 16:33	General View		Load JPG	<input checked="" type="checkbox"/>
10	23/01/19 16:33	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
11	23/01/19 16:33	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
12	23/01/19 16:33	General View		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	20/11/18 19:45	EMAIL FROM AIG DD 19.11.2018		Load PDF	
2	20/11/18 19:45	TP GIA REPORT		Load PDF	
3	20/11/18 19:45	NOTIFICATION FROM WORKSHOP		Load JPG	<input checked="" type="checkbox"/>
4	20/11/18 19:45	ACKNOWLEDGEMENT EMAIL TO AIG DD 19.11.2018		Load PDF	
5	22/11/18 09:50	TP ESTIMATE - MARKED		Load PDF	
6	23/01/19 16:32	LETTER TO OI		Load PDF	
7	01/07/19 14:27	WORKSHOP INVOICE		Load PDF	
8	01/07/19 14:27	AUTHORISATION TO ACT FORM		Load PDF	
9	01/07/19 14:27	Release Voucher		Load PDF	
10	01/07/19 14:27	RENTAL RECEIPT		Load PDF	
11	01/07/19 14:27	GIA SEARCH		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print	
1	21/11/18 09:25	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

--

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLB177X (Insd veh)	Model:	HONDA AIRWAVE 1.5 M (A)
	SJT2348K (TP veh)		
Date of Accident:	14/11/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	5,444.80
Final Repair Cost	:	\$	2,086.50
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	400.00 4 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	2,488.50

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____100____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	BH Auto Services Pte Ltd	:	\$ 2,488.50
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

01 Jul

2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18021024/KEA3Q2

Date: 01/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100452995

Claimant Vehicle No : SJT2348K

Insured Vehicle No : SLB177X

Date of Loss: 14/11/2018

Nature of Claim: TP

Claim No: 0581828021SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJT2348K

Make & Model: HONDA AIRWAVE, 1.5 M (A)

Engine No: L15A5208685

Reg. Date: 29/09/2009 (Man. Year: 2008)

Chassis No: GJ11307135

Colour: Metallic Grey

Odometer: 158460 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16

Rear Tyre Size: 205/50 R16

Front Left Side: GREEN-MAX 9 mm

Rear Left Side: Yokohama 4 mm

Front Right Side: GREEN-MAX 9 mm

Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,808.60	1,559.00	2,249.60	59.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	890.00	390.00	30.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,088.60	2,449.00	2,639.60	51.87
Approved Total (Overridden) (S\$)		1,950.00		
(S\$)	5,088.60	1,950.00	3,138.60	61.68
+ GST 7.00/7.00% (S\$)	356.20	136.50	219.70	61.68
Nett Amount (S\$)	5,444.80	2,086.50	3,358.30	61.68
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,488.50		

INSPECTION

Date of Assignment: 19/11/2018

Date Inspected: 20/11/2018 Inspected At:

BH Auto Services Pte Ltd (Sin Ming)
Blk 1 Sin Ming Industrial Estate Sector C,

#01/111/113/115/117
Singapore 575636

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	936.00 FL	*936.00 FL
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	55.00 FL	*55.00 FL
3	1		*REAR TAILGATE AIRWAVE EMBLEM	Necessary	45.00 FL	*45.00 FL
4	1		*REAR TAILGATE LOGO EMBLEM	Not Necessary	28.00 FL	*- FL
5	1		*REAR TAILGATE OUTER CHROME MOULDING	Serviceable	245.00 FL	*- FL
6	1		*REAR TAILGATE OUTER GARNISH	Serviceable	398.00 FL	*- FL
7	1		*REAR TAILGATE OUTER LOCK HANDLE	Serviceable	65.00 FL	*- FL
8	1		*REAR TAILGATE REVERSE CAMERA	Serviceable	480.00 FL	*- FL
9	1		*REAR TAILGATE NUMBER PLATE WITH HOLDER	Dented	55.00 FL	*55.00 FL
10	1		*REAR TAILGATE NUMBER PLATE LAMP LH	Serviceable	65.00 FL	*- FL
11	1		*REAR TAILGATE NUMBER PLATE LAMP RH	Serviceable	65.00 FL	*- FL
12	1		*REAR TAILGATE MECHANISM LOCK	Repair	115.00 FL	*- FL
13	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	585.00 FL	*- FL
14	1		*REAR TAILGATE HINGE LH	Repair	62.00 FL	*- FL
15	1		*REAR TAILGATE HINGE RH	Repair	62.00 FL	*- FL
16	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	151.00 FL	*- FL
17	1		*REAR BUMPER	Buckled	739.00 FL	*739.00 FL
18	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	28.00 FL	*- FL
19	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	28.00 FL	*- FL
20	1		*REAR END PANEL LOCK STRIKER	Repair	35.00 FL	*- FL
21	1		*REAR END PANEL INNER TOP GARNISH	Serviceable	145.00 FL	*- FL
22	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
23	4		*REAR TAILGATE OUTER CHROME MOULDING CLIPS	Not Necessary	23.60 FS	*- FS
24	6		*REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	35.40 FS	*- FS
25	10		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	59.00 FS	*- FS
26	10		*REAR BUMPER CLIPS	Necessary	55.00 FS	*55.00 FS
27	4		*REAR END PANEL INNER TOP GARNISH CLIPS	Not Necessary	26.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$) **4,686.00** **1,925.00**
 - List Item Discount on L Items 20.00/20.00% (\$\$) **877.40** **366.00**

Total Parts (\$\$) **3,808.60** **1,559.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS,PANEL BEAT ,CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	500.00	400.00
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES	New	500.00	440.00
3	REMOVE AND REFIX REAR TAILGATE WINDSCREEN GLASS TO FACILITATE REPAIRS	New	120.00	0.00
4	TUFF KOTE AND RUST COATING ALL REPLACE AND REPAIR PARTS	New	80.00	30.00
5	DISCONNECT ,CHECK ,RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING ,HARNESS ,WIRE SOCKETS AND ETC.REMOVE AND REINSTALL DAMAGED PARTS,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	80.00	20.00
Gross Labour Cost (\$\$)			1,280.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >