

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not withharw

ESTIMATE

India International Insurance Pte Ltd

64 Cecil Street

#05 IOB Building

Singapore 049711

Attn: Motor Claims Department

1. B.16/Lup 8?

8-10 days

Date :

19/11/2018

Vehicle No :

SLK2684M

Veh Make/Model :

Honda Vezel 1.5X Hybrid A

YOM :

2016

Chassis No :

RU31213270

Date of Accident :

16/11/2018

No	Qty	Description	Amount \$
		List Items:-	
1	1	Bonnet	\$ <i>R</i> 892.30
2	1	LH headlamp	\$ 1,784.50
3	1	RH headlamp	\$ <i>mgm</i> 1,784.50
4	1	Front grille logo	\$ <i>mc</i> 25.00
5	1	Front grille base	\$ <i>cm</i> 351.80
6	1	Front grille outer garnish	\$ <i>cm</i> 421.00
7	1	Front grille lower chrome	\$ <i>mc</i> 95.00
8	1	Front grille up beam (LH)	\$ 19.60
9	1	Front grille up beam (RH)	\$ 19.60
10	1	Front bumper	\$ <i>B</i> 801.70
11	1	Front bumper tow cover	\$ <i>nd</i> 17.10
12	1	Front bumper fog lamp cover (LH)	\$ <i>sn</i> 327.70
13	1	Front bumper fog lamp cover (RH)	\$ <i>sn</i> 327.70
14	1	Front bumper spoiler	\$ 381.00
15	1	Front bumper reinforcement	\$ <i>B</i> 321.00
16	2	Front bumper side retainer	\$ <i>Di</i> 41.20
17	10	Front bumper clip	\$ <i>mc</i> 38.00
18	1	Front guide (LH)	\$ 36.60
19	1	Front guide (RH)	\$ 36.60
20	1	Support panel	\$ <i>R</i> 576.20
21	1	Support panel top garnish	\$ <i>cm</i> 85.00
22	6	Support panel top garnish clip	\$ <i>mc</i> 22.80
23	1	Aircon condenser	\$ <i>r</i> 586.10
24	1	Front LH fender	\$ <i>R</i> 558.70
25	1	Front RH fender	\$ <i>R</i> 558.70
26	1	Tail gate	\$ <i>B</i> 1,100.90
27	4	Tail gate windscreen moulding	\$ <i>mc</i> 140.00
28	1	Tail gate center garnish	\$ <i>sn</i> 220.00
29	1	Tail gate reflector (LH)	\$ <i>sn</i> 240.00
30	1	Tail gate reflector (RH)	\$ <i>sn</i> 240.00
Balance b/f			\$ 12,050.30

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

India International Insurance Pte Ltd

64 Cecil Street

#05 IOB Building

Singapore 049711

Attn: Motor Claims Department

Date : 19/11/2018

Vehicle No : SLK2684M

Veh Make/Model : Honda Vezel 1.5X Hybrid A

YOM : 2016

Chassis No : RU31213270

Date of Accident : 16/11/2018

No	Qty	Description	Amount \$
		Balance c/f	\$ 12,050.30
31	1	Tail gate logo	\$ 22.70
32	1	Tail gate 'VEZEL' emblem	\$ 42.00
33	1	Tail gate 'HYBRID' emblem	\$ 75.50
34	1	Tail gate lock	\$ 96.60
35	1	Tail gate weatherstrip	\$ 96.80
36	1	Rear LH corner bumper	\$ 155.00
37	1	Rear RH corner bumper	\$ 195.00
38	1	Rear bumper	\$ 762.70
39	1	Rear bumper reflector (LH)	\$ 143.30
40	1	Rear bumper reflector (RH)	\$ 143.30
41	2	Rear bumper side retainer	\$ 35.00
42	10	Rear bumper clip	\$ 38.00
43	1	End panel	\$ 523.60
44	1	End panel top garnish	\$ 81.30
45	6	End panel top garnish clip	\$ 18.00
		Total - List Item	\$ 14,479.10
		Less 20%	\$ 2,895.82
		Total	\$ 11,583.28
		Special Nett Items:-	
1	1	Front number plate with holder	\$ 55.00
2	1	Rear number plate with holder	\$ 55.00
3	1 set	Rear bumper reverse sensor	\$ 270.00
4	1	Tailgate windscreen gum/sealant	\$ 80.00
		Total - SN Item	\$ 460.00
		Balance b/f	\$ 12,043.28

I KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

India International Insurance Pte Ltd
64 Cecil Street
#05 IOB Building
Singapore 049711
Attn: Motor Claims Department

Date : 19/11/2018
Vehicle No : SLK2684M
Veh Make/Model : Honda Vezel 1.5X Hybrid A
YOM : 2016
Chassis No : RU31213270
Date of Accident : 16/11/2018

[illegible]