

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref

: S8M013L7

Date: 09th May 2019

Our Ref

: CC4/ASM18021065/R1ea3s2

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01 AXA Tower Singapore 068811 (The Motor Claims Department)

Attn; Richard Ang

Dear Sir/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO SCY 6888Z ACCIDENT ON 16/11/2018 INSURED SJJ 9674A

Instruction was received to inspect the vehicle Reg. No. SCY 6888Z. The inspection was conducted on 21/11/2018 at the premises of M/s Accord Auto Services Pte Ltd, 10 Ang Mo Kio Industrial Park 2A AMK Auto Point #03-11 Singapore 568047.

The following information were recorded: -

Registration Number

: SCY 6888Z

Make & Model

: Volkswagen Golf 1.4 A

Year of Registration

: 2012

Engine Capacity

: 1390 cc

Body Colour

: Grey

Chassis Number

: WVWZZZ1KZCW156056

Speedometer Reading

: 74017 km

The vehicle sustained damages at the front and rear portion. The Estimated repair cost of such vehicle is S\$7,000.00 (Sin Dollars: Seven Thousand only.) (Details see photographs enclosed).



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as "**uneconomical Total Loss**".

Market Value S\$ 40,000.00

Less: LTA Reimbursement Value (RV) (S\$ 32,234.00)

Nett Liability S\$ 7,766.00

Vehicle Inspected By:

MRB

MOHD. RASUL BIN MOHD YUNUS

AMSOE, AMIRTE, AMSAE-A, M. MATAI

Automotive Assessor

K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK),

MASME(USA), B Bus(Aust), MBA(UK),

IEng(UK), MIIE(mech), MinstAEA, MFIEA,

MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR (USA),

AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),

Licensed Appraiser

<u>OISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.</u> No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.