

Premium Automobiles Pte Ltd



Audi Centre Singapore

281 Alexandra Road

Singapore 159938

Main Telephone 6836 2223

Main Telefax 6471 3733

Alexandra Service Centre

281 Alexandra Road

Singapore 159938

Telephone 6388 2223

Telefax 6475 1023

Ubi Service Centre

55 Ubi Road 1

Singapore 408699

Telephone 6388 2223

Customer Service

Service Appointment

24-hour Breakdown Service

Email

customer.care@premiumauto.com.sg

6366 2323

9828 1233

Page 1 11:08

INSURANCE INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013469

Date : 18/02/2019

Order : SLV7555L

Term : 30

Account: A0006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLV7555L (V 35362)

Regn Date: 05/12/2017

Mileage: 17128

WIP No.: 32147

Model: A4 SEDAN 1.4 TFSI S tronic

Chassis: WAUZZZF45JA041955

Engine: CVN 049910

Dept: U

USB No.:

You have been assisted by :- UB-Jiayee

(33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888	-300.00	1.00	-300.00
S	BODYWORK	Insurance Excess/Liability			
		M:	360.00	1.00	360.00
		TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID			
S	BODYWORK	M:	500.00	1.00	500.00
		TO DISMANTLE AND RENEW FRONT BUMPER. TO REPAIR RHS FRONT FENDER. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED			
S	BODYWORK	M:	1100.00	1.00	1,100.00
S	BODYWORK	M:	192.00	1.00	192.00
		TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.			
		TO CARRY OUT DIAGNOSTIC CHECK			
X	A8W0853888E	SPOILER	1.00	62.70	50.16
X	A8W0807065C GRU	COVER	1.00	1849.00	1,479.20
X	A8W0121764	AIR DUCT	1.00	72.30	57.84

Parts 1,587.20
Labour 0.00
Sublet 2,152.00
Menus 0.00
Lubricant 0.00

Sub-Total

3,439.20

7% GST

240.74

Grand Total

3,679.94



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer