

REPAIR ESTIMATE

21/11/2018 15:42

VEHICLE NO : SH 9970Z

MAKE :

MODEL : TOYOTA PRIUS

Cheney

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
LAMP ASSY, FOG, RH <i>brat</i>			\$ 920.00
FRONT BUMPER COVER <i>109</i>			\$ 499.90
FRONT BUMPER SPONGE <i>Xu</i>			\$ 78.80
FRONT BUMPER CLIPS <i>rec</i>			\$ 22.00
FRONT BUMPER SIDE RETAINER, RH <i>Xu</i>			\$ 77.00
UNIT ASSY, HEADLAMP, RH (LED) <i>brat</i>			\$ 3,455.00
SUB TOTAL			\$ 5,052.70
LESS 25%			\$ 1,263.18
DISCOUNTED TOTAL			\$ 3,789.53
LABOUR CHARGE			
Panel Beating			\$ 200 350.00
Spray Painting Charge			\$ 200 250.00
Wiring Charge			\$ 20 30.00
TOTAL LABOUR			\$ 630.00
ESTIMATE TOTAL			\$ 4,419.53

Kah 1 UKK

N

21/11/18 16:00

2 Dgs.

PIP

Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.