



**GOLDBELL**  
ENGINEERING

**Industrial Vehicles.**  
**20,000 Served. And Counting.**

**GOLDBELL ENGINEERING PTE LTD**

10 Tuas Avenue, #18-01 Singapore 639691

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: [www.goldbell.com.sg](http://www.goldbell.com.sg)

Co. Reg. No.: 198003963C

Date: 21/11/2018

AXA Insurance Singapore Pte Ltd

8 Shenton Way, #24-01 AXA Tower,  
Singapore 063811


Dear Sir,

We are instructed by Metalcut Pte Ltd to notify you of a road traffic accident on 09/11/2018 at about 1620hrs at CTE Towards SLE involving our client's/customer's vehicle registration number GR8980R and vehicle registration number SLM3984M driven by your insured at the material time. A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client/customers' vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days from Date: 21/11/2018 on your receipt of this notice whether you SLM3984M would like to conduct a pre-repair survey of the vehicle by providing to GOLDBELL Engineering Pte Ltd a list of at least 10 motor surveyors. We will reply you our decision to agree or object your named surveyor as a Single Joint Expert following Apr 2016 NMA Protocol process flow. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

Mr. William Go  
GOLDBELL Motor Claim Officer



*bi-SAFE*   