

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721

Tel: 6452 1493

Fax: 6452 9153

GST Reg: 19-9900741 / Z

Claim Ref:

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY, #27-01/02

Date : 21/11/2018

Vehicle No : SJ28668R
Chassis No : WBAUN72070VM22419
Make/Model : BMW 1351MA
Year :

S/N	Qty	Description	cost Price	Amount
1	1pc	FRONT BUMPER <i>mtg cra</i>	\$ 1,116.00	\$ 1,116.00
2	1pc	FRONT HEADLAMP LH ?	\$ 2,013.00	\$ 2,013.00
3	1pc	FRONT HEADLAMP BRACKET LH ?	\$ 63.00	\$ 63.00
4	1pc	FRONT SENSOR REVERSE ?	\$ 160.00	\$ 160.00
5	1pc	FRONT FENDER LH <i>bt</i>	\$ 529.00	\$ 529.00
6	1pc	FRONT FENDER INNER SHIELD <i>cra</i>	\$ 150.00	\$ 150.00
7	1pc	FRONT FENDER WHEEL HOUSE LH ?	\$ 110.00	\$ 110.00
8	1pc	FRONT BUMPER REINTEGRATION LH <i>dis</i>	\$ 28.00	\$ 28.00
9	1pc	FRONT RIM LH <i>DD</i>	\$ 480.00	\$ 480.00
10	1pc	FRONT RIM LOGO COVER LH <i>DD</i>	\$ 15.00	\$ 15.00
11	1pc	FRONT TYRE LH	\$ 195.00	\$ 195.00
12	1pc	FRONT KNUCKER ARM LH	\$ 81.00	\$ 81.00
13	1pc	FRONT WHEEL HUP LH	\$ 127.00	\$ 127.00
14	1pc	FRONT LOWER AMP LH	\$ 81.00	\$ 81.00
15	1pc	FRONT ABSORBER LH	\$ 299.00	\$ 299.00
16	1pc	FRONT TIE ROD LH	\$ 150.00	\$ 150.00
17	1pc	FRONT TORSION BAR LINK LH	\$ 37.00	\$ 38.00

Labour Charges

- 1 To check wiring and system function
- 2 To wheel alignment
- 3 To cutting welding, knucking and remove and refix undercarriage
- 4 To respray accident portion

\$ 120.00 *20*
\$ 80.00 *?*
\$ 800.00 *500*
\$ 800.00 *500*

Grand Total

\$ 8,299.50

Wega Engineering Pte Ltd

Authorised Signature
Leong Chee Kwong
Mobile No: 84917768

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: