

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721

Tel: 6452 1493

Fax: 6452 9153

GST Reg: 19-9900741 / Z

Claim Ref:

**AXA INSURANCE SINGAPORE PTE LTD**  
8 SHENTON WAY, #27-01/02

Date : 21/11/2018

Vehicle No : SJZ8668R  
Chassis No : WBAUN72070VM22419  
Make/Model : BMW 1351MA  
Year :

*Not for Bulk*



*Not for Bulk*  
*1-B1*  
*Recovery B4perm*  
*Ex 8400*

*Fax: 62564315*

| S/N | Qty | Description                 | Unit Price  | Amount      |
|-----|-----|-----------------------------|-------------|-------------|
| 1   | 1pc | FRONT BUMPER                | \$ 1,649.00 | \$ 1,649.00 |
| 2   | 1pc | FRONT HEADLAMP LH           | \$ 2,900.00 | \$ 2,900.00 |
| 3   | 1pc | FRONT HEADLAMP BRACKET LH   | \$ 78.00    | \$ 78.00    |
| 4   | 1pc | FRONT SENSOR REVERSE        | \$ 288.00   | \$ 288.00   |
| 5   | 1pc | FRONT FENDER LH             | \$ 782.00   | \$ 782.00   |
| 6   | 1pc | FRONT FENDER INNER SHIELD   | \$ 220.00   | \$ 220.00   |
| 7   | 1pc | FRONT FENDER WHEEL HOUSE LH | \$ 162.00   | \$ 162.00   |
| 8   | 1pc | FRONT BUMPER RENTANNER LH   | \$ 55.00    | \$ 55.00    |
| 9   | 1pc | FRONT RIM LH                | \$ 880.00   | \$ 880.00   |
| 10  | 1pc | FRONT RIM LOGO COVER LH     | \$ 55.00    | \$ 55.00    |
| 11  | 1pc | FRONT TYRE LH               | \$ 230.00   | \$ 230.00   |
| 12  | 1pc | FRONT KNUCKER ARM LH        | \$ 276.00   | \$ 276.00   |
| 13  | 1pc | FRONT WHEEL HUP LH          | \$ 564.00   | \$ 564.00   |
| 14  | 1pc | FRONT LOWER AMP LH          | \$ 276.00   | \$ 276.00   |
| 15  | 1pc | FRONT ABSORBER LH           | \$ 442.00   | \$ 442.00   |
| 16  | 1pc | FRONT TIE ROD LH            | \$ 336.00   | \$ 336.00   |
| 17  | 1pc | FRONT TORSION BAR LINK LH   | \$ 114.00   | \$ 114.00   |

**Labour Charges**

- 1 To check wiring and system function
- 2 To wheel alignment
- 3 To cutting welding, knucking and remove and refix undercarriage
- 4 To respray accident portion

\$ 120.00  
\$ 80.00  
\$ 800.00  
\$ 800.00

Grand Total

\$ 11,107.00

Wega Engineering Pte Ltd

Authorised Signature  
Leong Chee Kwong  
Mobile No: 84917768

*Workshop not open on Sat plus 10%*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: