

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:29

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Customer

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013934 Date : 18/06/2019 Order : SKX5508M Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SKX5508M (V 28456) Regn Date: 17/12/2015 Mileage: 19463 WIP No.: 33015

Model: A3 SPORTSBACK 1.4 TFSI (AMBIEN Chassis: WAUZZZ8V7GA067472 Engine: CZC 501632 Dept: u

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
Q	OTHERS	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND REPAIR FRONT BUMPER. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER	550.00	1.00	550.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V3853651 1QF	GRILLE Less 020%	1.00	572.50	458.00
X	A8K0010520A	PLATE Less 020%	1.00	12.20	9.76
X	A8V0010515A	STICKER Less 020%	1.00	6.40	5.12

Parts 472.88
Labour 25.00
Sublet 1,602.00
Menus 0.00
Lubricant 0.00



Sub-Total 1,499.88

7% GST 104.99

Grand Total 1,604.87

Received by

For & on behalf of
Premium Automobiles Pte Ltd