

ASS. REC. BY:

REF:

CS/CTI1802/205/USD3

Special Instruction:

Surveyor:
minimen

Marcus

ASSIGNMENT (Office)

From (Person):

Elaine cheong

of

CTI

Date/Time: 23/11/18 @ 1:53pm

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 49455

Insured:

at Workshop m/s

Vfix Auto

Tel:

6455 2957

of

60 Kaki Bukit Ave 6

Policy No:

DMCVSN3094151700

Claim No:

SNM18D0545701

Sum Insured:

Excess:

\$550.00

Make of Veh:

D.O.A.

19/11/2018

(Client's Record)

CA / ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:02pm @ 23/11/18

Person Contacted:

Irene

Vehicle:

☒ IN ☐ OUT

Date/Time	Action/Instruction
	(✓) Estimate check consistency of damage & economical repair limit
	YP 49455-CS/CTI1802/1104/Ntd3 - DOA: 19/11/18
23/11/18	@ 16:01 p.m. revised IA to Elaine cheong via email.
23/11/18	@ 16:09 p.m. mandate requested authorize repair to Elaine cheong via email.
26/11/18	@ 15:38 p.m. revert authorized repair to Irene (repaired) via email.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Nov 2018		23 Nov 2018 11:53 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	M/S MENTAL LINK HARDWARE PTE LTD, Co. Reg. No.: -		
Vehicle Reg. No.:	YP4945S	Date of Loss:	19/11/2018 11:00 - :59
Claim Type:	OD / SNM18D05457C01	Policy/Cover Note No.:	DMCVSN3094151700 (Comprehensive)
		Excess:	S\$550.00
Repairer:	Vfix Auto Service Pte Ltd (HQ) 60 Kaki Bukit Ave 6, ARK@KB, 417892 Kaki Bukit - Tel: 64552957		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/12/2018]		
Driver/Custodian:	TAN CHUNG ENG (49 / Male), NRIC: S6905691A, Tel: +6596328989		
Adj Asg. Remarks:	Please check consistency of the damage & economical repair limit. Kindly revert. Thanks.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 23 Nov 2018

Preliminary Advice

Vehicle No	: YP4945S	Accident Date	: 19/11/2018
Make	: MITSUBISHI CANTER	Policy No.	: DMCVSN3094151700
Assignment Date	: 23/11/2018	Excess	: S\$550.00
Date of Inspection	: 23/11/2018	Est. Duration of Repair	: 5 days
Inspection At	: Vfix Auto Service Pte Ltd (HQ) 60 Kaki Bukit Ave 6, ARK@KB Singapore 417892		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,142.94
Revised Amount	:S\$	12,723.07
Check Items (Estimated)	:S\$	6,012.90
Total	:S\$	18,735.97

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	16,213.00
Salvage Value	:S\$	
Margin for Repair	:S\$	49,787.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 26 November 2018 3:38 PM
To: irenelsk@vfixauto.com.sg
Cc: kentsh@vfixauto.com.sg; SUR
Subject: YP 4945S OD (CTI)

Dear Irene,

As instructed by our client, please proceed to repair the insured vehicle **YP 4945S (Excess \$ 550/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***YP4945S (SNM18D05457C01)**

OD

Nov 19 2018 11:00AM

[M/S MENTAL LINK HARDWARE PTE LTD]

Vfix Auto Service Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 26/11/2018 14:54 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$18735.97) - YP4945S - Claim Handler: Elaine Cheong

Approved:18735.97:Please proceed to authorize repairs UP TO \$18,735.97 before Excess of \$550.00. Re-inspection of vehicle required.

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/11/2018 14:19
Date Of Accident	19/11/2018 11:20
Exact Location Of Accident	KJE TWDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP4945S
Insured/Policyholder	
Name Of Registered Owner	M/S MENTAL LINK HARDWARE PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62692238

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3094151700
Cover Note Number	-

Driver

Name of Driver	TAN CHUNG ENG
NRIC No	S6905691A
Date Of Birth	27/02/1969
Occupation	OUTDOOR
Date Of Driving Pass	20/11/1986
Driving Experience	31 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96328989
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	66 CHESTNUT AVE #23-12
Postcode	679520
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB1180Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Ministry of Transport of Singapore and any relevant government agency/authority (such as the police), for the purpose(s):
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders;



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

KIE TOWARDS Tuas

A) YP A9458

B) GBB 1180Y

A.D.R.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19/10/18 at about 11:30am I was driving along
KIE towards Tuas. Vehicle A in front of me
suddenly stop. I immediately brake but still
hit it rear.

No injury involved

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

WSP/NT/2018/01/01/01/01/01

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4513E
Vehicle Details	
Vehicle No.:	YP4945S
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Nov 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER3SDEB (CBU)
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4P10C36980
Chassis No.:	FEB21EA21028
Maximum Power Output:	-
Open Market Value:	\$34,034.00
Original Registration Date:	28 Dec 2016
First Registration Date:	28 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$1,702.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$20,031.00
COE Rebate Amount:	\$16,213.00
Total Rebate Amount:	\$16,213.00

The information contained herein is correct as at 23 Nov 2018

OK

- A New Chapter - Skoda Singapore
- Today my credit card was hacked
- Japan: Tokyo - Tips and Recommendations?

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 10 Years Coe Renewal Toyota Estima 2.4A



2.88%p.a. Lowest Interest@Gv
Cars Financing \$5800
Downpayment Monthly From
\$890
GV Credit Pte Ltd StarAd



Browse by Category ▾

Sort by Date Posted ▾ 20 results/page ▾

9 vehicles

mitsubishi canter feb21

Advanced Search 🔍

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	mitsubishi canter feb21		Any	Any	2016	Any	Any	Any	Available
	Mitsubishi	Fuso Canter FEB21	\$74,800	\$9,260 /yr	21-Dec-2016	2,998 cc	9,400 km	Truck	Available
Fuel Type: Diesel Power Tailgate With 7ft High Box And 2 Sliding Doors Worth \$12,000. Like Brand New Condition, Super Low Mileage. 1 Owner Only. 1 Ton Dhollandia Power Tailgate Installed By Wong Fong. 100% Accident-Fre... Posted: 20-Nov-2018 Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter FEB21	\$66,800	\$8,510 /yr	28-Sep-2016	2,998 cc	-	Truck	Available
Fuel Type: Diesel As Good As New, With New Canopy, High Trade-In, Low Interest, Door Step View, Call Now For Appointment! ABWIN (1994) Pte Ltd Posted: 20-Nov-2018 Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter FEB21	\$65,800	\$8,400 /yr	23-Sep-2016	2,998 cc	-	Truck	Available
Fuel Type: Diesel No VPC Required, Class 3 Licence Can Drive. 1 Owner Only, Very Suitable For Ferry Workers, No Repair Needed. Very Good Condition. Can Carry Up To 2.6 Ton. High Loan And High Trade In Available. Call U... ABWIN (1994) Pte Ltd Posted: 20-Nov-2018 Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter FEB21	\$63,800	\$8,310 /yr	28-Jul-2016	2,998 cc	95,875 km	Truck	Available
Fuel Type: Diesel Low Mileage Driven By Previous Owner. The Most Highly 14ft Japanese Commercial Vehicle That Cater Your Business Need. Call Now For A Non Obligatory Discussion. Car (S) Pte Ltd Posted: 19-Nov-2018 Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi									
	Pro-Jex V2D Auto Pte Ltd - Specialty Workshops Power up for excellent performance with PRO-JEX V2D, your one-stop automobile solution provider. More info about this shop								
	Mitsubishi	Fuso Canter FEB21	\$59,800	\$8,330 /yr	27-Jan-2016	2,998 cc	-	Truck	Available
Fuel Type: Diesel 1 Owner Only. 15 Feet Wooden Deck With Full Length Canopy. Can Drive With Class 3 Licence. No VPC Required. High COE Value Of \$42,036. Posted: 19-Nov-2018 Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter FEB21	\$59,800	\$8,370 /yr	13-Jan-2016	2,998 cc	18,800 km	Truck	Available
Fuel Type: Diesel As Good As New! 1 Owner, New Paintwork, Super Low Mileage Done At 9,000km Yearly, Good Condition, Easy In House Loan Available, Class 3 Can Drive, No VPC Needed, Call Now. Posted: 18-Nov-2018 Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter FEB21	\$66,800	\$8,410 /yr	02-Nov-2016	2,998 cc	-	Truck	Available
Fuel Type: Diesel									

Compare



fax: 6225 7778

Vfix Auto Pte Ltd
60 Kaki Bukit Ave 6 Ark@KB
Singapore 417892
Email : contact@vfixauto.com.sg
Tel : 6448 9268 Fax: 6445 2368
UEN / GST Reg No.: 201830761R

CHINA TAIPING INS (S'PORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

ATTN : MOTOR CLAIMS DEPT

RE : VEHICLE NO : YP4945S FUSO FEB21

ESTIMATE

DATE : 20/11/2018
ACC DATE : 19/11/2018
REF NO : VFIX-OD20180100
POLICY NO : DMCVSN3094151801

DESCRIPTION		AMOUNT S\$	
1	1 FRONT WINDSCREEN GLASS	1131.37	one 1,445.00
2	1 FRONT WINDSCREEN GLASS WEATHERSTRIP		new 425.00
3	2 CORNER PANEL R+L	475.20	o/s one 950.40 loc
4	1 WIPER PANEL	649.11	new 951.00
5	1 FRONT PANEL		o/s 1,122.40
6	1 FRONT PANEL (FUSO) EMBLEM	125	new 250.00
7	1 FRONT GRILLE	1053.15	new 1,105.70
8	2 FRONT HEADLAMP R+L	660.00	new 1,320.00
9	2 FRONT SIDE LAMP R+L	255.00	one 510.00
10	2 FRONT HEADLAMP LOWER RUBBER	45.00	o/s 90.00
11	2 FRONT SIGNAL LAMP	295.00	o/s 590.00
12	1 FRONT BUMPER		new 1,010.30
13	2 FRONT BUMPER BRACKET R+L	196.30	new 392.60
14	1 FRONT BUMPER EXTENSION RH	pad 341.71	new 342.00
15	1 DOOR RH		new 1,873.80
16	1 DOOR PILLAR INNER RH		new 1,982.20
17	1 DOOR PILLAR OUTER RH		new 1,978.30
18	1 DOOR HINGE UPPER RH		new 145.30
19	1 DOOR HINGE LOWER RH		new 132.00
20	2 DOOR INNER LOCK LH/RH		new 411.00
21	1 WIPER WASHER TANK C/W MOTOR		new 320.00
22	1 FRONT CHASSIS CROSS MEMBER ASSY		new 2,855.20
23	1 CABIN ROLL OVER TORSION BAR	2115.30	new 2,988.50
24	2 CABIN ROLL OVER TORSION BAR BRACKET	428.00	new 856.00
25	1 HORN		new 105.00
26	1 BRAKE PIPE JOINT C/W SWITCH		new 285.50
27	2 BRAKE PIPE JOINT BRAKE		new 45.00
28	1 WATER HEATER PIPE	166.00	new 215.00
29	1 DASHBOARD PANEL		new 1,255.20
30	1 DASHBOARD REINFORCEMENT		new 652.20
			\$ 26,604.60
		LESS 10%	\$ 2,660.46
			\$ 23,944.14

SPECIAL NETT		AMOUNT S\$
1	1 AIR CON COOLING UNIT ASSY, 2840.21	2,896.30 ✓
2	1 FAN BLOWER ASSY complete	1,855.20 X
3	1 AIR CON SUCTION HOSE 194.57	352.00 ✓
4	1 AIR CON DISCHARGE HOSE (25h)	385.00 X
5	1 FRONT NUMBER PLATE	35.00 14
6	1 FUSE BOX C/W HARNESS WIRE ASSY	1,445.30 X
7	1 BRAKE FULID	60.00 X
8	1 RADIATOR COOLANT	60.00 X
		\$ 7,088.80

LABOUR & MISCELLANEOUS:		AMOUNT S\$
1	To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front floor panel, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	1000 1,800.00
2	To spray paint replaced/repared body panels inclusive of preparatory works and painting materials	900 1,600.00
3	To remove, replace front windscreen glass and water test	120 150.00
4	To transfer front door components with all necessary attachments	111 X 150.00
5	To remove, refit dashboard panel with all necessary components	200 250.00
6	To remove, replace air con cooling unit, fan blower motor vacuum refill gas	100 250.00
7	To straighten front chassis member, remove, replace front cross member cabin roll over torsion bar parts align into position	111 X 800.00
8	To conduct front headlamp alignment	20 30.00
9	Towing charge	2711 80.00 X
		\$ 5,110.00

GRAND TOTAL : \$ 36,142.94

SINGAPORE DOLLARS : THIRTY SIX THOUSAND ONE HUNDRED FORTY TWO & CENTS NINETY FOUR ONLY

Vfix Auto Pte Ltd



KK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

P-14375-26
252
10787.44
51.24 14.00
labour + 2340
13135.44
202
10508

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Nov 2018		23 Nov 2018 11:53 Edit Adj Rpt	S\$10,500.00 Edit Estimates	S\$10,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	M/S MENTAL LINK HARDWARE PTE LTD, Co. Reg. No.: -								
Vehicle Reg. No.:	YP4945S	Date of Loss:	19/11/2018 11:00 - :59 [22 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM18D05457C01	Policy/Cover Note No.:	DMCVSN3094151700 (Comprehensive)						
		Excess:	S\$550.00						
Repairer:	Vfix Auto Service Pte Ltd (HQ) 60 Kaki Bukit Ave 6, ARK@KB, 417892 Kaki Bukit - Tel: 64552957								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 04/12/2018]								
Driver/Custodian:	TAN CHUNG ENG (49 / Male), NRIC: S6905691A, Tel: +6596328989								
Adj Asg. Remarks:	Please check consistency of the damage & economical repair limit. Kindly revert. Thanks.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
CHINA_TAIPING (26/11/2018): Alert - Adj Mandate Approved (S\$18735.97) - YP4945S - Claim Handler: Elaine Cheo...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***YP4945S (SNM18D05457C01)**
OD
Nov 19 2018 11:00AM
[M/S MENTAL LINK HARDWARE PTE LTD]
Vfix Auto Service Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	20/11/18 14:28	Accident Statement	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/11/18 16:01	Adjuster Immediate Advice	 Load HTM	

Photos/Images

3 per page ▼ ☒

No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	20/11/18 14:27	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
2	20/11/18 14:27	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
3	20/11/18 14:27	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
4	20/11/18 14:27	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
5	20/11/18 14:27	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
6	20/11/18 14:27	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
7	20/11/18 14:27	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/11/18 16:07	Odometer Reading	 Load JPG	☒
2	23/11/18 16:07	Chassis Number	 Load JPG	☒
3	23/11/18 16:07	General View	 Load JPG	☒
4	23/11/18 16:07	General View	 Load JPG	☒
5	23/11/18 16:07	General View	 Load JPG	☒
6	23/11/18 16:07	General View	 Load JPG	☒
7	23/11/18 16:07	General View	 Load JPG	☒
8	23/11/18 16:07	General View	 Load JPG	☒
9	23/11/18 16:07	General View	 Load JPG	☒
10	23/11/18 16:07	General View	 Load JPG	☒
11	23/11/18 16:07	General View	 Load JPG	☒
12	23/11/18 16:07	General View	 Load JPG	☒
13	23/11/18 16:07	General View	 Load JPG	☒
14	23/11/18 16:07	General View	 Load JPG	☒
15	23/11/18 16:07	General View	 Load JPG	☒
16	23/11/18 16:07	General View	 Load JPG	☒
17	23/11/18 16:07	General View	 Load JPG	☒
18	23/11/18 16:07	General View	 Load JPG	☒
19	23/11/18 16:07	General View	 Load JPG	☒
20	23/11/18 16:07	General View	 Load JPG	☒
21	23/11/18 16:07	General View	 Load JPG	☒
22	23/11/18 16:07	General View	Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
23	23/11/18 16:07	General View	 Load JPG	✓
24	23/11/18 16:07	General View	 Load JPG	✓
25	23/11/18 16:07	General View	 Load JPG	✓
26	23/11/18 16:07	General View	 Load JPG	✓
27	23/11/18 16:07	General View	 Load JPG	✓
28	23/11/18 16:07	General View	 Load JPG	✓
29	23/11/18 16:07	General View	 Load JPG	✓
30	23/11/18 16:07	General View	 Load JPG	✓
31	23/11/18 16:07	General View	 Load JPG	✓
32	23/11/18 16:07	General View	 Load JPG	✓
33	23/11/18 16:07	General View	 Load JPG	✓
34	23/11/18 16:07	General View	 Load JPG	✓
35	23/11/18 16:07	General View	 Load JPG	✓
36	23/11/18 16:07	General View	 Load JPG	✓
37	23/11/18 16:07	General View	 Load JPG	✓
38	23/11/18 16:07	General View	 Load JPG	✓
39	23/11/18 16:07	General View	 Load JPG	✓
40	23/11/18 16:07	General View	 Load JPG	✓
41	23/11/18 16:07	General View	 Load JPG	✓
42	23/11/18 16:07	General View	 Load JPG	✓
43	23/11/18 16:07	General View	 Load JPG	✓
44	23/11/18 16:07	General View	 Load JPG	✓
45	23/11/18 16:07	General View	 Load JPG	✓
46	23/11/18 16:07	General View	 Load JPG	✓
47	23/11/18 16:07	General View	 Load JPG	✓
48	23/11/18 16:07	General View	 Load JPG	✓
49	23/11/18 16:07	General View	 Load JPG	✓
50	23/11/18 16:07	General View	 Load JPG	✓
51	23/11/18 16:07	General View	 Load JPG	✓
52	23/11/18 16:07	General View	 Load JPG	✓
53	23/11/18 16:07	General View	 Load JPG	✓
54	23/11/18 16:07	General View	 Load JPG	✓
55	23/11/18 16:07	General View	 Load JPG	✓
56	23/11/18 16:07	General View	 Load JPG	✓
57	23/11/18 16:07	General View	 Load JPG	✓
58	23/11/18 16:07	General View	 Load JPG	✓
59	23/11/18 16:07	General View	 Load JPG	✓
60	23/11/18 16:07	General View	 Load JPG	✓
61	23/11/18 16:07	General View	 Load JPG	✓
62	23/11/18 16:07	General View	 Load JPG	✓
63	23/11/18 16:07	General View	 Load JPG	✓
64	23/11/18 16:07	General View	 Load JPG	✓
65	23/11/18 16:07	General View	 Load JPG	✓
66	23/11/18 16:07	General View	 Load JPG	✓
67	23/11/18 16:07	General View	 Load JPG	✓
68	23/11/18 16:07	General View	 Load JPG	✓
69	23/11/18 16:07	General View	 Load JPG	✓
70	23/11/18 16:07	General View	Load JPG	✓

Assessment Reports			1 per page ▾	✓
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
71	23/11/18 16:07	General View	 Load JPG	✓
72	23/11/18 16:07	General View	 Load JPG	✓
73	23/11/18 16:07	General View	 Load JPG	✓
74	23/11/18 16:07	General View	 Load JPG	✓
75	23/11/18 16:07	General View	 Load JPG	✓
76	23/11/18 16:07	General View	 Load JPG	✓
77	23/11/18 16:07	General View	 Load JPG	✓
78	23/11/18 16:07	General View	 Load JPG	✓
79	23/11/18 16:07	General View	 Load JPG	✓
80	23/11/18 16:07	General View	 Load JPG	✓
81	23/11/18 16:07	General View	 Load JPG	✓
82	23/11/18 16:07	General View	 Load JPG	✓
83	23/11/18 16:07	General View	 Load JPG	✓
84	23/11/18 16:07	General View	 Load JPG	✓
85	23/11/18 16:07	General View	 Load JPG	✓
86	23/11/18 16:07	General View	 Load JPG	✓
87	23/11/18 16:07	General View	 Load JPG	✓
88	23/11/18 16:07	General View	 Load JPG	✓
89	23/11/18 16:07	General View	 Load JPG	✓
90	23/11/18 16:07	General View	 Load JPG	✓
91	23/11/18 16:07	General View	 Load JPG	✓
92	23/11/18 16:07	General View	 Load JPG	✓
93	23/11/18 16:07	General View	 Load JPG	✓
94	23/11/18 16:07	General View	 Load JPG	✓
95	23/11/18 16:07	General View	 Load JPG	✓
96	23/11/18 16:07	General View	 Load JPG	✓
97	23/11/18 16:07	General View	 Load JPG	✓
98	23/11/18 16:07	General View	 Load JPG	✓
99	23/11/18 16:07	General View	 Load JPG	✓
100	23/11/18 16:07	General View	 Load JPG	✓
101	23/11/18 16:07	General View	 Load JPG	✓
102	23/11/18 16:07	General View	 Load JPG	✓
103	23/11/18 16:07	General View	 Load JPG	✓
104	23/11/18 16:07	General View	 Load JPG	✓
105	23/11/18 16:07	General View	 Load JPG	✓
106	23/11/18 16:07	General View	 Load JPG	✓
107	27/11/18 17:18	Reinspection Photo	 Load JPG	✓
108	27/11/18 17:18	Reinspection Photo	 Load JPG	✓
109	27/11/18 17:18	Reinspection Photo	 Load JPG	✓
110	27/11/18 17:18	Reinspection Photo	 Load JPG	✓
111	27/11/18 17:18	Reinspection Photo	 Load JPG	✓
112	27/11/18 17:18	Reinspection Photo	 Load JPG	✓
113	27/11/18 17:18	Reinspection Photo	 Load JPG	✓
114	27/11/18 17:18	Reinspection Photo	 Load JPG	✓
115	27/11/18 17:18	Reinspection Photo	 Load JPG	✓
116	27/11/18 17:18	Reinspection Photo	 Load JPG	✓
117	27/11/18 17:18	Reinspection Photo	 Load JPG	✓
118	27/11/18 17:18	Reinspection Photo	 Load JPG	✓

Assessment Reports			1 per page ▾	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
119	27/11/18 17:18	Reinspection Photo	 Load JPG	☒
120	27/11/18 17:18	Reinspection Photo	 Load JPG	☒
121	27/11/18 17:18	Reinspection Photo	 Load JPG	☒
122	27/11/18 17:18	Reinspection Photo	 Load JPG	☒
123	27/11/18 17:18	Reinspection Photo	 Load JPG	☒
124	27/11/18 17:18	Reinspection Photo	 Load JPG	☒
125	27/11/18 17:18	Reinspection Photo	 Load JPG	☒
126	27/11/18 17:18	Reinspection Photo	 Load JPG	☒
127	27/11/18 17:18	Reinspection Photo	 Load JPG	☒
128	27/11/18 17:18	Reinspection Photo	 Load JPG	☒
129	06/12/18 15:27	Photo After Spray	 Load JPG	☒
130	06/12/18 15:27	Photo After Spray	 Load JPG	☒
131	06/12/18 15:27	Photo After Spray	 Load JPG	☒
132	06/12/18 15:27	Photo After Spray	 Load JPG	☒
133	06/12/18 15:27	Photo After Spray	 Load JPG	☒
Documentation			1 per page ▾	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/11/18 13:09	REPAIR ESTIMATE	 Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	20/11/18 14:26	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	20/11/18 14:26	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
3	20/11/18 14:27	DRIVING DOC [Linked Accident Report Documents]	 Load JPG	☒
4	20/11/18 14:27	DRIVING DOC [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/11/18 16:06	ESTIMATE MARKED.pdf	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser ▾
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	20/11/18 14:28	Accident Statement	 Load HTM	
Photos/Images			3 per page ▾	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	20/11/18 14:27	Accident Photo	 Load JPG	☒
2	20/11/18 14:27	Accident Photo	 Load JPG	☒
3	20/11/18 14:27	Accident Photo	 Load JPG	☒
4	20/11/18 14:27	Accident Photo	 Load JPG	☒
5	20/11/18 14:27	Accident Photo	 Load JPG	☒
6	20/11/18 14:27	Accident Photo	 Load JPG	☒
7	20/11/18 14:27	Accident Photo	 Load JPG	☒
Documentation			1 per page ▾	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	20/11/18 14:26	Accident Sketch Plan	 Load JPG	☒
2	20/11/18 14:26	Accident Sketch Plan	 Load JPG	☒
3	20/11/18 14:27	DRIVING DOC	 Load JPG	☒

Assessment Reports			1 per page ▾	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
4	20/11/18 14:27	DRIVING DOC	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18021205/USD3S2

Date: 12/12/2018

REFERENCE

Insured/Claimant: M/S MENTAL LINK HARDWARE PTE LTD

Policy No: DMCVSN3094151700

Date of Loss: 19/11/2018

Nature of Claim: OD

Claim No: SNM18D05457C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP4945S	Engine No:	4P10C36980
Make & Model:	MITSUBISHI CANTER, 3.0 D (M)	Chassis No:	FEB21EA21028
Reg. Date:	28/12/2016 (Man. Year: 2016)	Odometer:	23165 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	S\$66,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/85R15	Rear Tyre Size:	195/85R15 (D)
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5/5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,032.94	10,795.44	20,237.50	65.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,110.00	2,340.00	2,770.00	54.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,142.94	13,135.44	23,007.50	63.66
Approved Total (Overridden) (S\$)		10,500.00		
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	35,592.94	9,950.00	25,642.94	72.05
+ GST 7.00/7.00% (S\$)	2,491.51	696.50	1,795.01	72.05
Nett Amount (S\$)	38,084.45	10,646.50	27,437.95	72.05

INSPECTION

Date of Assignment: 23/11/2018

Date Inspected: 23/11/2018

Estimated Period of Repair: 5.0 days

Inspected At:

Vfix Auto Service Pte Ltd (HQ)
60 Kaki Bukit Ave 6, ARK@KB
Singapore 417892

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Dec 2018)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP4945S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Cracked	1,445.00 FL	*1,131.37 FL
2	1		*FRONT WINDSCREEN GLASS WEATHERSTRIP	Necessary	425.00 FL	*425.00 FL
3	1		*CORNER PANEL R+L	O/s Cracked	950.40 FL	*475.20 FL
4	1		*WIPER PANEL	Dented/Cracked	951.00 FL	*649.11 FL
5	1		*FRONT PANEL	Badly Dented	1,122.40 FL	*1,122.40 FL
6	1		*FRONT PANEL (FUSO) EMBLEM	Necessary	250.00 FL	*125.00 FL
7	1		*FRONT GRILLE	Missing/Broken	1,105.70 FL	*1,053.15 FL
8	2		*FRONT HEADLAMP R+L	Broken	1,320.00 FL	*1,320.00 FL
9	2		*FRONT SIDE LAMP R+L	Cracked	510.00 FL	*510.00 FL
10	1		*FRONT HEADLAMP LOWER RUBBER	O/s Torn	90.00 FL	*45.00 FL
11	1		*FRONT SIGNAL LAMP	O/s Broken	590.00 FL	*295.00 FL
12	1		*FRONT BUMPER	Dented	1,010.30 FL	*1,010.30 FL
13	2		*FRONT BUMPER BRACKET R+L	Not Necessary	392.60 FL	*-FL
14	1		*FRONT BUMPER EXTENSION RH PAD	Torn	342.00 FL	*341.71 FL
15	1		*DOOR RH	Repair	1,873.80 FL	*-FL
16	1		*DOOR PILLAR INNER RH	Repair	1,982.20 FL	*-FL
17	1		*DOOR PILLAR OUTER RH	Repair	1,978.30 FL	*-FL
18	2		*DOOR INNER LOCK LH & RH	Not Necessary	411.00 FL	*-FL
19	1		*WIPER WASHER TANK C/W MOTOR	Not Necessary	320.00 FL	*-FL
20	1		*FRONT CHASSIS CROSS MEMBER ASSY	Repair	2,855.20 FL	*-FL
21	1		*CABIN ROLL OVER TORSION BAR	Dented/Bent	2,988.50 FL	*2,115.30 FL
22	2		*CABIN ROLL OVER TORSION BAR BRACKET	Dented/Bent	856.00 FL	*856.00 FL
23	1		*HORN	Not Necessary	105.00 FL	*-FL
24	1		*BRAKE PIPE JOINT C/W SWITCH	Not Necessary	285.50 FL	*-FL
25	2		*BRAKE PIPE JOINT BRAKE	Not Necessary	45.00 FL	*-FL
26	1		*WATER HEATER PIPE	Bent	215.00 FL	*166.00 FL
27	1		*DASHBOARD PANEL	Not Necessary	1,255.20 FL	*-FL
28	1		*DASHBOARD REINFORCEMENT	Not Necessary	652.20 FL	*-FL
29	1		*AIR CON COOLING UNIT ASSY }	Cracked	2,896.30 F	*2,540.21 FN
30	1		*FAN BLOWER ASSY }		1,855.20 F	*-FN
31	1		*AIR CON SUCTION HOSE	Dented	352.00 F	*194.51 FN
32	1		*AIR CON DISCHARGE HOSE	Not Necessary	385.00 FS	*-FS
33	1		*FRONT NUMBER PLATE	Bent	35.00 FS	*14.00 FS
34	1		*FUSE BOX C/WHARNES WIRE ASSY	Not Necessary	1,445.30 FS	*-FS
35	1		*BRAKE FLUID	Not Necessary	60.00 FS	*-FS
36	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*-FS
37	1		*DOOR HINGE UPPER RH	Not Necessary	145.30 FL	*-FL
38	1		*DOOR HINGE LOWER RH	Not Necessary	132.00 FL	*-FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	33,693.40	14,389.26
- List Item Discount on L Items 10.00/25.00% (\$\$)	2,660.46	2,910.14
- Nett Item Discount on N Items 0.00/25.00% (\$\$)	0.00	683.68

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	31,032.94
						10,795.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE DAMAGED BODY PANEL WITH ALL NECESSARY COMPONENTS/ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN FRONT FLOOR PANEL,REPAIR/RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS/ATTACHMENTS	New	1,800.00	1,000.00
2	TO SPRAY PAINT REPLACED/REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	1,600.00	900.00
3	TO REMOVE,REPLACE FRONT WINDSCREEN GLASS AND WATER TEST	New	150.00	120.00
4	TO TRANSFER FRONT DOOR COMPONENTS WITH ALL NECESSARY ATTACHMENTS	New	150.00	-
5	TO REMOVE,REFIT DASHBOARD PANEL WITH ALL NECESSARY COMPONENTS	New	250.00	200.00
6	TO REMOVE,REPLACE AIR CON COOLING UNIT,FAN BLOWER MOTOR VACUUM REFILL GAS	New	250.00	100.00
7	TO STRAIGHTEN FRONT CHASSIS MEMBER,REMOVE,REPLACE FRONT CROSS MEMBER CABIN ROLL OVER TORSION BAR PARTS ALIGN INTO POSITION	New	800.00	-
8	TO CONDUCT FRONT HEADLAMP ALIGNMENT	New	30.00	20.00
9	TOWING CHARGE	New	80.00	-
Gross Labour Cost (S\$)			5,110.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >