

INSURER

INS. CASE OWNER:

CC Y HSM-  
AXA1802

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VA, YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting Ir (1st):

Non-Reporting Ir (2nd):

Non-Reporting Ir (Final):

Notification Ir (if non-pickup):

Call OI: 5/12/18

After call Ir to OI: 6/11/18

Documentation Check List: Handler Typist

Notification Ir (if non-pickup)

After call Ir to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: PIP

SS 4861.59

( 5 days) Reduction: \$20 = 5

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final Liability:

SS 100

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost: (W/SS)

SS 5201.90

Loss of Rental (LOR):

SS 320.00

( 4 days) x \$80

Loss of Use (LOU):

SS -

(5 x days)

Loss of Income (LOI):

SS -

(5 x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GLA/LTA Search

SS 8.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 5529.90

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1:

SS 5529.90

Name 1:

Cheng Hioe Motor Pk Ltd

Payee 2: (Strike if N.A.)

SS -

Name 2:

Payee 3: (Strike if N.A.)

SS -

Name 3:

✓ GIA.

ASS. REC. BY:

REF:

ALA/

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.:

Yes or No

Lum Sum:

1-B.1 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBG 4939E Yr Regn: 08.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota c.c. 2982

Colour:

Silver A/C: Insured / Std / NI / NA

Sp. Reading

2803, T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFAT35Y.XOK 208877

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195 R15X8

R: 155 R12X8(10)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9 mm

Rear

R/Bal.

8 mm

L/Bal.

9 mm

L/Bal.

8 mm

D.O.A.

20/11/18

D.O.I.

13/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/12 File pass to Catherine

B 4861.59 base on calculation

C5X

(Red. \$270 / 5%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / L.B.I: (\$

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

GBG 4939E  
 TP/AXA

M/S : AXA INSURANCE (S) PTE LTD  
 8 SHENTON WAY  
 #27-02 AXA TOWER  
 SINGAPORE 068811

TEL: 63387288 FAX: 68804739  
 ATTN: Motor Claim Department

WS Ref: TP/AXA  
 Claim Type: Third Party  
 Accident Date: 20/11/2018  
 TP Veh Reg No: YL3188M

Estimate No: ES1891407/WS  
 Date: 13 Dec 2018  
 Policy No: DMCVSN1755881801  
 Veh Reg No: GBG4939E  
 Make/Model: TOYOTA TOYOTA  
 DYNA 150 5MT  
 Chassis No: JTFAT35YX0K208877  
 Engine No: 1KD2742533  
 Reg. Date: 21/08/2017

Not Authorized

Resurvey by paint

3 days

## Estimate Repair Cost to Vehicle No :GBG4939E

| Description                                                                                                                           | U/Price  | Quantity | List Price           | Amount       |
|---------------------------------------------------------------------------------------------------------------------------------------|----------|----------|----------------------|--------------|
|                                                                                                                                       |          |          | <u>S\$</u>           | <u>S\$</u>   |
| <b>List Price</b>                                                                                                                     |          |          |                      |              |
| 1 FRONT PANEL                                                                                                                         | 1,156.70 | 1 PC     | 1,156.70             | —            |
| 2 FRONT PANEL EMBLEM "DYNA"                                                                                                           | 49.75    | 1 PC     | 49.75                | —            |
| 3 FRONT WINDSCREEN GLASS RUBBER                                                                                                       | 278.22   | 1 PC     | 278.22               | —            |
| 4 FRONT GRILLE                                                                                                                        | 569.75   | 1 PC     | 569.75               | —            |
| 5 FRONT GRILLE EMBLEM                                                                                                                 | 61.70    | 1 PC     | 61.70                | —            |
| 6 FRONT GRILLE CLIP                                                                                                                   | 3.50     | 4 PC     | 14.00                | —            |
| 7 AIRCON EVAPORATOR                                                                                                                   | 1,850.70 | 1 PC     | 1,850.70             | —            |
| 8 FRONT LH SIDE MIRROR " ROUND " & STAY                                                                                               | 581.30   | 1 PC     | 581.30               | —            |
|                                                                                                                                       |          |          | 4,562.12             |              |
|                                                                                                                                       |          | Less 25% | 1,140.53             | 3,421.59     |
| <b>Labour</b>                                                                                                                         |          |          |                      |              |
| 9 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS                                                                                   | 100      | 1 LA     | 100.00               | ✓            |
| 10 REMOVE AND REFIT FRONT WINDSCREEN GLASS.                                                                                           | 60       | 1 PCS    | 60.00                | ✓            |
| 11 REMOVE AND REFIT FRT BUMPER ASSY, GRILLE, HEADLAMPS, FRT WIPER ASS, GARNISH. TO CUT,WELD AND RENEW FRT PANEL AND REALIGN THE SAME. | 800.00   | 1 PCS    | 800.00               | 600          |
| 12 REMOVE AND REFIT DASHBOARD, METER ASSY AND CHECK WIRING.                                                                           | 250.00   | 1 PCS    | 250.00               | ✓            |
| 13 PUTTY & RESPRAY ON FRT GRILLE. FRT PANEL AND ALL OTHER AFFECTED AREAS.                                                             | 500.00   | 1 PC     | 500.00               | 400          |
|                                                                                                                                       |          |          | 1,710.00             | 1,710.00     |
|                                                                                                                                       |          |          | Total                | S\$ 5,131.59 |
|                                                                                                                                       |          |          | Add GST @ 7%         | 359.21       |
|                                                                                                                                       |          |          | Total Amount Payable | S\$ 5,490.80 |

Resurvey by

na

\$ 50

300

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
 Signature:  
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

 > Back to OneMotoring**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

|                |         |
|----------------|---------|
| Owner ID Type: | Company |
| Owner ID:      | 8328H   |

**Vehicle Details**

|                               |                   |
|-------------------------------|-------------------|
| Vehicle No.:                  | GBG4939E          |
| Vehicle to be Exported:       | No                |
| Intended Deregistration Date: | 21 Nov 2018       |
| Vehicle Make:                 | TOYOTA            |
| Vehicle Model:                | DYNA 150 5MT      |
| Primary Colour:               | Silver            |
| Manufacturing Year:           | 2017              |
| Engine No.:                   | 1KD2742533        |
| Chassis No.:                  | JTFAT35YX0K208877 |
| Maximum Power Output:         | -                 |
| Open Market Value:            | \$27,084.00       |
| Original Registration Date:   | 21 Aug 2017       |
| First Registration Date:      | 21 Aug 2017       |
| Transfer Count:               | 0                 |
| Actual ARF Paid:              | \$1,355.00        |

**Intended PARF Rebate Details**

|                               |        |
|-------------------------------|--------|
| PARF Eligibility:             | No     |
| PARF Eligibility Expiry Date: | -      |
| PARF Rebate Amount:           | \$0.00 |

**Intended COE Rebate Details**

|                             |                         |
|-----------------------------|-------------------------|
| COE Expiry Date:            | 20 Aug 2027             |
| COE Category:               | C - Goods Vehicle & Bus |
| COE Period(Years):          | 10                      |
| PQP Paid:                   | \$29,651.00             |
| COE Rebate Amount:          | \$25,936.00             |
| <b>Total Rebate Amount:</b> | <b>\$25,936.00</b>      |

The information contained herein is correct as at 21 Nov 2018

OK



## Service Request Details

Claim

S8M013V0

Reference

None 

Loss Date

November 20, 2018

Request Date

November 23, 2018

Due Date

November 30, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

23-11-2018 @ 1028am  
Jure wh in  
not

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

GBG4939E

Make

TPVD TOYOTA



Model  
DYNA 150 5MT

Service Address

---

...

Primary Contact/Insured

---

MEDIAWIZ PTE LTD  
10 ADMIRALTY STREET, #06-02, NORTH LINK BUILDING, 757695, Singapore  
6562922886  
INSURANCE@VCINSURANCE.COM.SG

Claim Handler

---

WANG Peter  
  
peter.wang@axa.com.sg

Additional Instructions

- 
- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes
- 

New Message

**Catherine Chong (LKK Auto)**

---

**From:** Cheng Hoe Motor Pte Ltd (Yishun-June) <chmotor@singnet.com.sg>  
**Sent:** Thursday, 22 November, 2018 2:41 PM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey  
**Subject:** REMINDER (1)- Repair Survey (Single Joint Expert) - GBG4939E  
**Attachments:** 4939.pdf  
  
**Categories:** Namrata

RE-SEND

Thank you.

Rgds  
June Phua  
Cheng Hoe Motor Pte Ltd  
Tel :67556142  
Fax : 67557719

**From:** Cheng Hoe Motor Pte Ltd (Yishun-June)  
**Sent:** Wednesday, November 21, 2018 3:51 PM  
**To:** [axa survey](#)  
**Subject:** Repair Survey (Single Joint Expert) - GBG4939E

Dear Sir,

**OUR CLIENT – GBG4939E**

**DOA : 20/11/18 @12.50pm**  
**Y**  
**OUR INSURED : YL3188M (MEDI AWIZ PTE LTD)**

We refer to the above.

**Under Protocol - SJE**, pls provide list of surveyors for our selection.

Thank you.

Regards  
June  
Cheng Hoe Motor Pte Ltd  
Tel :67556142  
Fax : 67557719

mediawiz pte ltd

10 Admiralty Street,  
#06-02 Northlink Building,  
Singapore 757695  
T: (+65) 6481 2962  
F: (+65) 6481 3026  
E: mediawizsg@gmail.com  
mediawiz@singnet.com.sg



Company registration number: 201502990Z  
GST registration number: 201502990Z

To:

**LKK Auto Consultants Pte Ltd**

Blk 51, Paya Ubi Industrial Park,

Ubi Avenue 1, #02-25,

Singapore 408933.

**Attn.to: Ms Cecilia Chong**

Dear Madam,

We MEDIAWIZ PTE LTD(201502990Z) authorised Mr Yong Poh Chiang(S0159254H)  
to drive the vehicle number of YL3188M.

The driver Mr Yong Poh Chiang is the Director of the Company, MEDIAWIZ PTE LTD.

Regards,

Sign & Company Chop



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 18/10/2019

### Survey Details:

|                     |                    |
|---------------------|--------------------|
| Date of loss        | 20-Nov-18          |
| Date of appointment | 23-Nov-18          |
| Date of survey      | 13-Dec-18          |
| Location of survey  | CHENG HOE MOTOR PL |

### Vehicle Details:

|                      |                     |
|----------------------|---------------------|
| Claim Type:          | Third party         |
| Vehicle number       | GBG 4939E           |
| Make and Model       | TOYOTA DYNA 150 SMT |
| Date of registration | 21/8/2017           |
| Excess               |                     |
| Market Value         | \$58,000            |
| Parf Rebate          | \$25,936            |
| Nett Loss            | \$32,064            |

### Repair details:

|                  |             |
|------------------|-------------|
| Initial Estimate | \$ 5,131.59 |
|------------------|-------------|

### Proposed/Revised repair cost:

|                         |                    |
|-------------------------|--------------------|
| Parts                   | \$ 3,421.59        |
| Check items (estimate)  | \$ -               |
| Labour                  | \$ 1,440.00        |
| <b>Total</b>            | <b>\$ 4,861.59</b> |
| Lump Sum(if applicable) | \$ -               |

|                           |   |
|---------------------------|---|
| Number of days for repair | 5 |
|---------------------------|---|



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

|  |
|--|
|  |
|--|

**Mandate:**

| Liability(TP)        | 100%        |               |
|----------------------|-------------|---------------|
| Proposed repair cost | \$ 5,201.90 | W/GST         |
| Loss of use          | \$ -        |               |
| Loss of rental       | \$ 400.00   | 4days x \$100 |
| Loss of income       | \$ -        |               |
| LTA search fees      | \$ 8.00     |               |
| Others               | \$ -        |               |
| Proposed Total       | \$ 5,609.90 |               |



## <MANDATE IA> - S8M013V0 {ACCIDENT INVOLVING YL 3188M (OI) & GBG 4939E (TP) ON 20/11/2018}

Type

Question

Message

LIABILITY: 100% BOLA S22 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$5,609.90 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL

Reply

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

## TAX INVOICE

M/S : AXA INSURANCE (S) PTE LTD  
8 SHENTON WAY  
#27-02 AXA TOWER  
SINGAPORE 068811  
TEL: 63387288 FAX: 68804739  
ATTN: Motor Claim Department

NO: CL8190880  
Date: 21 Aug 2019  
Policy No: DMCVSN1755881801  
Veh Reg No: GBG4939E  
Make/Model: TOYOTA TOYOTA  
DYNA 150 5MT  
Job No: JC1600348

WS Ref: TP/AXA  
Claim Type: Third Party  
Accident Date: 20/11/2018  
TP Veh Reg No: YL3188M

PAGE:1

| Description                                                                                                                           | Quantity | List Price   | Amount       |
|---------------------------------------------------------------------------------------------------------------------------------------|----------|--------------|--------------|
|                                                                                                                                       |          | <u>S\$</u>   | <u>S\$</u>   |
| To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges.<br>(As recommended by your appointed surveyor) | 1 PC     | S\$ 4,861.59 | S\$ 4,861.59 |

|                      |                     |
|----------------------|---------------------|
| Total                | S\$ 4,861.59        |
| Add GST @ 7%         | 340.31              |
| Total Amount payable | <u>S\$ 5,201.90</u> |

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE



## Pls get OI LOA and proceed DS with quantum as proposed


Type

🔗 Question

Message

LOR is subject to rental receipt.

Reply



## CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

Date: 01 OCT 2019

AXA Insurance (S) Pte Ltd  
C/O LKK Auto Consultants

Attn : THE MOTOR CLAIMS DEPT

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLE NO. GBG4939E & YL3188M ON 20/11/2018  
YISHUN IND PK A TWRDS CANBERRA LINK.**

We are authorized by GBG4939E for their above matter.

Record reveals that you are the insurer of YL3188M. We therefore wish to seek compensation from you as below:-

|                               |                    |
|-------------------------------|--------------------|
| 1. Cost of Repairs            | S\$ 5201.90        |
| 2. Loss of Use                | S\$ 0.00           |
| 3. Hire of Vehicle            | S\$ 480.00         |
| 4. LTA Search Fee/GIA Reports | S\$ 8.00           |
| <b>TOTAL</b>                  | <b>S\$ 5689.90</b> |

Please let us have your reply soonest possible.

Thank you.

Yours faithfully



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                      |                              |            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|------------------------------|------------|-------------------------------------------------------------------------------------|
| AXA INSURANCE PTE LTD                                                                                                                  |                                                                                      | Ref : CC4/ASM18021220/Kga3q2 |            |                                                                                     |
| 8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811<br>ATTN:PETER                                                                        |                                                                                      | Date : 05-03-2020            |            |  |
|                                                                                                                                        |                                                                                      | Code : ASM                   |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                      |                              |            |                                                                                     |
| Insured Veh.                                                                                                                           | YL 3188M                                                                             | Veh. Inspected               | GBG 4939E  |                                                                                     |
| Policy No.                                                                                                                             | GA314362/1                                                                           | Coverage (\$)                | 0.00       |                                                                                     |
| Claim No.                                                                                                                              | S8M013V0                                                                             | Excess (\$)                  | 0.00       |                                                                                     |
| Assign From                                                                                                                            |                                                                                      | Assign Date                  | 23/11/2018 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                      |                              |            |                                                                                     |
| Make & Model                                                                                                                           | TOYOTA DYNA (M)                                                                      | c.c                          | 2982       |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                               | Year of Reg.                 | 2017       |                                                                                     |
| Chassis No.                                                                                                                            | JTFAT35YX0K208877                                                                    | Colour                       | SILVER     |                                                                                     |
| Odometer                                                                                                                               | 28031                                                                                | Steering                     | IN ORDER   |                                                                                     |
| Brakes                                                                                                                                 | IN ORDER                                                                             | Modification                 | NIL        |                                                                                     |
| General                                                                                                                                | GOOD                                                                                 |                              |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                      |                              |            |                                                                                     |
|                                                                                                                                        | Size                                                                                 | Make                         | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                         | 195 R15X8                                                                            | BRIDGESTONE                  | 9 mm       |                                                                                     |
| L/H Front Tyre                                                                                                                         | 195 R15X8                                                                            | BRIDGESTONE                  | 9 mm       |                                                                                     |
| R/H Rear Tyre                                                                                                                          | 155 R12X8 (D)                                                                        | BRIDGESTONE                  | 8/8 mm     |                                                                                     |
| L/H Rear Tyre                                                                                                                          | 155 R12X8 (D)                                                                        | BRIDGESTONE                  | 8/8 mm     |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                      |                              |            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.<br>DAMAGES SEE DETAILS.                                                            |                                                                                      |                              |            |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                      |                              |            |                                                                                     |
| Accident Date                                                                                                                          | 20/11/2018                                                                           | Inspection Date              | 13/12/2018 |                                                                                     |
| Survey held at                                                                                                                         | CHENG HOE MOTOR PL<br>BLK 1019 YISHUN IND. PARK A<br>#01-374/382<br>SINGAPORE 768761 |                              |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                      |                              |            |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                      |                              |            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                      |                              |            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                      | <b>5 Working Days</b>        |            |                                                                                     |

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 4939E**

| Qty                                | Description of Parts                                                                                                               | Condition    | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|------------------------------------------------------------------------------------------------------------------------------------|--------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b>        |                                                                                                                                    |              |                           |                   |
| 1                                  | FRONT PANEL (CONSISTENT)                                                                                                           | BENT         | 1,156.70                  | 1,156.70          |
| 1                                  | FRONT PANEL EMBLEM 'DYNA' (CONSISTENT)                                                                                             | NECESSARY    | 49.75                     | 49.75             |
| 1                                  | FRONT WINDSCREEN GLASS RUBBER (CONSISTENT)                                                                                         | NECESSARY    | 278.22                    | 278.22            |
| 1                                  | FRONT GRILLE (CONSISTENT)                                                                                                          | DENTED / CUT | 569.75                    | 569.75            |
| 1                                  | FRONT GRILLE EMBLEM (CONSISTENT)                                                                                                   | NECESSARY    | 61.70                     | 61.70             |
| 4                                  | FRONT GRILLE CLIP @\$3.50 (CONSISTENT)                                                                                             | NECESSARY    | 14.00                     | 14.00             |
| 1                                  | AIRCON EVAPORATOR (CONSISTENT)                                                                                                     | MTG CRACKED  | 1,850.70                  | 1,850.70          |
| 1                                  | FRONT LH SIDE MIRROR 'ROUND' & STAY (CONSISTENT)                                                                                   | BENT         | 581.30                    | 581.30            |
|                                    | LESS 25% DISCOUNT                                                                                                                  |              | -1,140.53                 | -1,140.53         |
|                                    |                                                                                                                                    |              | 3,421.59                  | 3,421.59          |
| <b>LABOUR</b>                      |                                                                                                                                    |              |                           |                   |
|                                    | REMOVE AND REFIX AIRCON ,CHECK ,VACUUM & REFILL GAS.                                                                               |              | 100.00                    | 100.00            |
|                                    | REMOVE AND REFIT FRONT WINDSCREEN GLASS.                                                                                           |              | 60.00                     | 60.00             |
|                                    | REMOVE AND REFIT FRT BUMPER ASSY ,GRILLE,HEADLAMPS ,FRT WIPER ASS ,GARNISH .TO CUT ,WELD AND RENEW FRT PANEL AND REALIGN THE SAME. |              | 800.00                    | 600.00            |
|                                    | REMOVE AND REFIT DASHBOARD ,METER ASSY AND CHECK WIRING .                                                                          |              | 250.00                    | 250.00            |
|                                    | PUTTY & RESPRAY ON FRT GRILLE ,FRT PANEL AND ALL OTHER AFFECTED AREAS.                                                             |              | 500.00                    | 400.00            |
|                                    | RUSTPROOFING .                                                                                                                     |              | 50.00                     | 30.00             |
|                                    |                                                                                                                                    |              | 1,760.00                  | 1,440.00          |
| <b>GRAND TOTAL</b>                 |                                                                                                                                    |              | <b>5,181.59</b>           | <b>4,861.59</b>   |
| <b>RECOMMENDED COST OF REPAIRS</b> |                                                                                                                                    |              |                           | <b>4,861.59</b>   |

Report Ref No. CC4/ASM18021220/Kga3q2

**KONG SENG CHEONG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

|              |                         |
|--------------|-------------------------|
| Claim        | SIM013V0                |
| Reference    | CC4/ASM41B021220/Kga3a2 |
| Loss Date    | 20 November 2018        |
| Report Date  | 21 Nov 2018 1:05:00 PM  |
| Request Date | 23 November 2018        |
| Due Date     |                         |

|              |                                          |
|--------------|------------------------------------------|
| Vendor Name  | LKK AUTO CONSULTANTS PTE LTD (TP)        |
| Type of Loss | Third Party Vehicle Damage               |
| Services     | Pending verification - Direct Settlement |

Actions

Next Step

Wait for Approve Invoice

Add Invoice

|                                 |              |
|---------------------------------|--------------|
| Vehicle Information             |              |
| Incident Vehicle Registration # | GBG493WB     |
| Make                            | TMVD TOYOTA  |
| Model                           | DYNA 150 SMT |
| Service Address                 |              |

|                                                                     |
|---------------------------------------------------------------------|
| Primary Contact/Insured                                             |
| MEDIAWIZ PTE LTD                                                    |
| 10 ADMIRALTY STREET, #06-02, NORTH LINK BUILDING, 757695, Singapore |
| 6562922886                                                          |
| INSURANCE@VCINSURANCE.COM.SG                                        |

|                       |
|-----------------------|
| Claim Handler         |
| WANG Peter            |
| peter.wang@axa.com.sg |

Additional Instructions

MessagesInvoicesHistoryDocumentsAssessmentMedicsNotes

Document Type

Document SubType

+ Upload Documents

| NAME                | TYPE    | SUB-TYPE                   | AUTHOR                            | DATE UPLOADED |
|---------------------|---------|----------------------------|-----------------------------------|---------------|
| LKKInvoice1 (7).pdf | Invoice | Surveyor/ Assessor expense | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 March 2020 |

| NAME                                                                                                                               | TYPE                       | SUB-TYPE                         | AUTHOR                            | DATE<br>UPLOADED |
|------------------------------------------------------------------------------------------------------------------------------------|----------------------------|----------------------------------|-----------------------------------|------------------|
|  RENTAL RECEIPT.pdf                             | Forms / Claim Documents    | Others                           | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 March 2020    |
|  LTA SEARCH.pdf                                 | Forms / Claim Documents    | Others                           | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 March 2020    |
|  LKK Inspection (1).pdf                         | Forms / Claim Documents    | Others                           | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 March 2020    |
|  LKK Adjustment 1a (1).pdf                      | Forms / Claim Documents    | Others                           | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 March 2020    |
|  PAYMENT BREAKDOWN, EXPRESS SETTLEMENT FORM.pdf | Forms / Claim Documents    | Satisfaction / Discharge Voucher | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 March 2020    |
|  AUTHORISATION TO ACT FORM.pdf                  | Forms / Claim Documents    | PCA / Authority Letter           | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 March 2020    |
|  LETTER TO OI.pdf                               | Letters and Correspondence | Policy Holders / Insured         | LKK AUTO CONSULTANTS PTE LTD (TP) | 19 March 2020    |
|  OI LOA.pdf                                     | Reports & Statement        | Others                           | LKK AUTO CONSULTANTS PTE LTD (TP) | 23 October 2019  |
|  LOD AND OTHER DOCUMENTS.pdf                    | Reports & Statement        | Others                           | LKK AUTO CONSULTANTS PTE LTD (TP) | 18 October 2019  |
|  PMIF COE REBATE.pdf                          | Reports & Statement        | Others                           | LKK AUTO CONSULTANTS PTE LTD (TP) | 18 October 2019  |
|  TP FINAL EST LIST.pdf                        | Reports & Statement        | Others                           | LKK AUTO CONSULTANTS PTE LTD (TP) | 18 October 2019  |
|  MANDATE IN DO 18102019.pdf                   | Reports & Statement        | Others                           | LKK AUTO CONSULTANTS PTE LTD (TP) | 18 October 2019  |
|  LKK SURVEY PHOTO.pdf                         | Reports & Statement        | Others                           | LKK AUTO CONSULTANTS PTE LTD (TP) | 18 October 2019  |
|  LKK RESURVEY PHOTO.pdf                       | Reports & Statement        | Others                           | LKK AUTO CONSULTANTS PTE LTD (TP) | 18 October 2019  |

| NAME                                                                                                                                   | TYPE                          | SUB-TYPE             | AUTHOR                                | DATE<br>UPLOADED    |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|----------------------|---------------------------------------|---------------------|
|  TP estimate- Marked.pdf                            | Reports & Statement           | Estimate / Quotation | LINK AUTO CONSULTANTS PTE<br>LTD (TP) | 12 January<br>2019  |
|  EMAIL FROM LAWYER WITH CIBC4939E GIA<br>REPROT.mig | Letters and<br>Correspondence | Solicitor / Advocate | DHIVAR Namrata                        | 22 November<br>2018 |
|  YL31604 INSD GIA.PDF                               | Reports & Statement           | GIA Report           | BATAN BHOSALE Pragati                 | 21 November<br>2018 |