

ASSIGNMENT

Sic / Yr:

KSL

CIN:

26/11/18

Date / Time:

23/11/18

Registered in Merimen:

23/11/18

Pre-assign / CCU / FTE

SGD 9501H



Insured Vehicle No.:

UOW SMOG HOB

Claim No.:

:

Name of Insured:

Policy No.:

:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

20/11/18

Place of Accident:

PIE 16/can Mark

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final? Yes / No

SJL 68742

INSRS:
WSP:
Tel:
Liability:
RMKS:

Guan Motor

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

2/11/19

CHT

SJL 68742 - Malina (2014/26/18) : 001 20/11/18
SGD 9501H - x

STAGE	DATE / PIC	
Non-Reporting ltr (1st)		
Non-Reporting ltr (2nd)		
Non-Reporting ltr (Final)		
Notification ltr (if non-pickup)		
Call OI:	12/01/2019	
After call ltr to OI:		
Documentation Check List:	Handler	Typist
Notification ltr (if non-pickup)	☒	☐
After call ltr to OI:	☒	☐
Authorisation To Act:	☒	☐
Release Voucher:	☒	☐
Final Repair Bill:	☒	☐
Car Rental Invoice:	☒	☐
Towing Invoice	☒	☐
LTA / GIA :	☒	☐
Medical Bill:	☒	☐
PIR:	☒	☐
Mandate/Reject Instruction:	☒	☐
LOD	☒	☐
Payment Breakdown Form:	☒	☐
Post-Repair Photos:	☒	☐
Others:	☒	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
--------------	------------	---------------	-------------

Repair Cost:	SS	(days) Reduction:	%	Email ☐ Call ☐
--------------	----	--------------------	---	--

FINAL SETTLEMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
------------------	------------	---------------	--

Final Liability:	%	(Agreed / Assessed) BOLA S/N No:	NO or B 28, Ass. Lia:
------------------	---	----------------------------------	-----------------------

Repair Cost:	SS	9700.00	last car Malaysia
--------------	----	---------	-------------------

Loss of Rental (LOR):	SS	(days)	
-----------------------	----	---------	--

Loss of Use (LOU):	SS	1000.00 (5 x 18 days)	
--------------------	----	-----------------------	--

Loss of Income (LOI):	SS	(5 x days)	
-----------------------	----	------------	--

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]			
---	--	--	--

GIA/LTA Search	SS	7.45	
Medical:	SS	-	
Disbursement:	SS	-	(e.g. Tow/ Independent)
Legal Cost	SS	-	
Total:	SS	10,787.45	Global Sum SS:
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	SS	10,787.45	Name 1: Guan Motor Works
Payee 2: (Strike if N/A.)	SS	-	
Payee 3: (Strike if N/A.)	SS	-	

ASS. REC. BY:

REF:

CS/ALG1802/251/K d3

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Azlan Syazaidin

of

AG

Date/Time:

23/11/2018 03:58pm

Estimated Cost:

Bill to:

OD + TB + WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIL 68742

Insured:

SGD 95014

at Workshop m/s

Guan Motor

Tel:

6453 6111

of

176 Sin Ming Drive #02-03

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/11/18

CA / REV / REP. / REV 24 HRS

(up)

26/11/18

H.O.D. Endorsement:

Date/Time:

4:14pm @ 23/11/18

Person Contacted:

Ah Beng

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓) Estimate

SIL 68742 - NA/INC 12014 226/K

D.O.A. 20/11/2018

28/12 @ 4:42pm

1/Ly @ 9 Foot error confirmed with Ah Guan

28/12/18

@ 4:42pm Ah Guan said he want to do D/s

REF: **AIG****ASSIGNMENT**From: _____ Date: **26/11/2018**

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: **SJL 68742**
at Workshop with: **Guoh Motor**
of: **176 Sin Ming Drive #02-03**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **18** days Res: Yes or NoLump Sum: **20** % 3 Val: Yes or NoCA / REV / REP. / 24 HRS **up**

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SJL 68742** Yr Regn: **12/08**Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Suz Swift** C.C. **1586**Colour: **M. Gray** A/C: ☒ Insured / Std / NI / NASp. Reading: **190339** T/Radio: ☒ Insured / Std / NI / NA

Eng/No: _____

C/No: **JSAE 8C31500201786**Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orMod: **Nil / S/Rim** STD A/Rim orTyre Size: F: **195/55R15**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: **7** mmL/Bal: **7** mmD.O.A: **20/11/18**

Survey held at: _____

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or**& 1st**

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/11 15h 19/11/18 Collection AMTP

Und = \$5521 20/26%

45 = \$9700.00 - with 18 days

Date/Time: File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time: File Return to?

2)

Days Of Repair: **18**

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)

Report Format: _____

Lump Sum / L.B.t (\$)

Survey Fee:

Transportation

) S + R + G

) Phone

) Other

TOTAL

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SJL6874Z

26-11-18

Not Notioned
11 Sep 89700h
Assuming After Point
18 days

No. Qty

List Items

1	1	Front bumper	GRS	668.15	✓
2	2	Front bumper fog lamp cover	mf cm	164.90	✓
3	2	Front bumper fog lamp	\$ Sn	376.40	X
4	1	Front bumper tow cover	\$ dd	26.70	✓
5	1	Front bumper grille	cm	169.95	✓
6	2	Front bumper side retainer	\$ D11	56.60	✓
7	1	Front bumper inner lower reinforcement	R1 \$ R	148.70	✓
8	1	Front bumper inner lower reinforcement outer garnish cover	\$ Rd	85.35	✓
9	1	Front bumper inner top reinforcement	\$ R	172.75	✓
10	1	Front bumper inner top reinforcement outer garnish cover	\$ Rd	92.65	✓
11	1 set	Front bumper clips	\$ R	30.00	✓
12	1	Front lower cover	\$ D11	60.75	✓
13	2	Headlamp	mf cm	670.10	✓
14	1	Front grille	\$ cm	72.80	✓
15	1	Front grille centre "S" logo	\$ R	19.65	✓
16	1	Front bonnet	\$ R	463.25	✓
17	2	Front bonnet hinge	\$ R	51.50	X
18	1	Front bonnet lock	\$ D11	51.60	✓
19	1	Front bonnet lock cable	\$ Sn	31.70	X
20	1	Front support panel	R	494.30	✓
21	1	Front support panel RH side air garnish	\$ Sn	91.15	X
22	1	Front support panel LH side air garnish	\$ L	16.45	X
23	1	Air con condenser	R	686.30	✓
24	1	Air con condenser pipe	\$ R	103.65	✓
25	1	Air con low pressure pipe	\$ Rd	162.85	✓
26	1	Radiator	\$ R	863.70	✓
27	1	Radiator fan cowling	\$ R	116.25	✓
28	1	Radiator fan motor	\$ R	424.00	✓
29	1	Radiator fan blade	\$ D11	65.45	✓
30	2	Front fender	\$ R	471.20	X
31	2	Front fender under shield	\$ Sn	127.80	X
32	1 set	Front fender under shield clips	\$ R	40.00	X
33	1	Rear bumper	R	649.65	✓
34	1	Rear bumper grille	\$ cm	169.65	✓
35	2	Rear bumper reverse lamp	cm	160.50	✓
36	2	Rear bumper side retainer	\$ D11	34.00	✓
37	1 set	Rear bumper clips	\$ R	30.00	✓
38	2	Rear bumper inner side impact bracket	\$ R	51.10	X
39	1	Rear number plate lamp	\$ R	20.75	X
40	2	Taillamp	cm	451.30	✓
41	1	Rear tailgate	\$ R	628.15	X
42	1	Rear tailgate outer handle	\$ Sn	75.90	X
43	1	Rear tailgate inner trim board	\$ R	123.55	X
44	1 set	Rear tailgate inner trim board clips	\$ R	40.00	X

- 45 1 Rear tailgate top lock
- 46 1 Rear tailgate lower lock catch
- 47 1 Rear tailgate weatherstrip
- 48 1 Rear end panel
- 49 1 Rear end panel top garnish
- 50 1 Rear spare tyre panel
- 51 1 Rear spare tyre top board
- 52 2 Rear exhaust silencer
- 53 2 Rear exhaust chrome pipe

\$ Od	180.10	✓
\$ R	17.95	x
nd/og	92.65	501n
\$ B	274.85	✓
\$ Di	82.75	✓
BH/Bu	\$ 382.15	✓
\$ CM	145.00	✓
\$ B	745.40	✓
ols du	\$ 240.00	4 120
	\$ 11,672.00	
Less 15%	\$ 1,750.80	
Total :	\$ 9,921.20	

Special nett Items

- 54 1 Front number plate
- 55 1 Rear number plate
- 56 1 set Rear windscreent sealant
- 57 1 set Rear end panel/spare tyre panel sealant

\$ CM	45.00	✓
\$ Bro	45.00	205n
\$ na	50.00	x
na	\$ 100.00	605n
	\$ 240.00	

Labour

- 1 Towing charges.
- 2 Labour Charges for remove/refit, cut/weld, panel beating and replace accident damages.
- 3 To putty and spray Spray Paintings charges.
- 4 To check wirings and lightings (front & rear).
- 5 To remove, refix A/C condenser, radiator etc., including refill of A/C gas.
- 6 To remove, refix rear windscreen glass.
- 7 To remove, refix rear upholstery and attachments.
- 8 To remove, refix rear tailgate fittings.
- 9 To remove, refix rear exhaust silencer.
- 10 To supply and apply anti rust treatment

\$	60.00	50h
\$	2,200.00	2000l
\$	2,000.00	1600l
\$	80.00	40l
\$	150.00	100l
\$ na	150.00	x
\$	120.00	80l
\$ na	80.00	x
\$	100.00	60l
\$	120.00	✓
Total :	\$ 5,060.00	

Total Parts and Labour : \$ 15,221.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7723B
Vehicle Details	
Vehicle No.:	SJL6874Z
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Dec 2018
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT 1.6 AT
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	M16A1373234
Chassis No.:	J5AEZC31500201786
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$15,112.00
Original Registration Date:	10 Dec 2008
First Registration Date:	10 Dec 2008
Transfer Count:	2
Actual ARF Paid:	\$15,112.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Dec 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,786.00
COE Rebate Amount:	\$13,707.00
Total Rebate Amount:	\$13,707.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 19 Dec 2018

OK

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Cool Renewal Toyota Altis 1.6A



2.89% P.A. Lowest Interest @ Gv
Car Financing \$1800
Downpayment Monthly \$588
GV Credit Pte Ltd Standard

• Free VICOM evaluation
 • Free grooming and 6 months maintenance
 • In-house workshop ensures quality service
 • Member of SVTA and hire purchase association
 • 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category ▼

« Back (1 2) Next »

Sort by Date Posted ▼

20 results/page ▼

27 vehicles

Suzuki Swift

Advanced Search

Make	Model	Price	Depreciation	Reg. Class	Eng. Cap	Mileage	Veh. Type	Status
Search Selection	Suzuki Swift	Any	Any	2008	Any	Any	Any	Available
	Suzuki Swift Sport 1.6M (New 5-yr COE)	\$27,888	\$5,570 /yr	01-Dec-2008	1,586 cc	-	Hatchback	Available
No Gimmicks! Well Maintained By Previous Owner, Wear And Tears All Done. View To Believe The Prestige Condition Of Swift Sports. Engine And Gearbox! 100% Loan Approval! Bank And In House Loan Availabl...								
Posted: 18-Dec-2018 Tags: 2008 Suzuki Swift, 2008 suzuki swift, Suzuki Swift, suzuki swift, Suzuki, Swift, swift, Used Suzuki								
	Suzuki Swift Sport 1.6A (New 5-yr COE)	\$24,999	\$5,000 /yr	12-Dec-2008	1,586 cc	-	Hatchback	Available
If You Are A Speed Demon You Would Love This Car! Wear And Tear Parts Would Be Replaced! In-House Warranty And High Loan Available! Hurry Call Our Friendly Salesman Now! Optional Add On Of \$2188 Packa...								
Posted: 18-Dec-2018 Tags: 2008 Suzuki Swift, 2008 suzuki swift, Suzuki Swift, suzuki swift, Suzuki, Swift, swift, Used Suzuki								
	Suzuki Swift Sport 1.6A (New 10-yr COE)	\$43,800	\$4,380 /yr	22-Dec-2008	1,586 cc	119,000 km	Hatchback	Available
Deposit \$1K. AA Trust Certified Quality 1 Owner Vehicle! Fully Maintained By Champion Motor! The Compact Hatchback That Packs A Punch Among It's Class! Powerful Engine That Enables Head Start And Stab...								
AA Trust Automotive								
Posted: 17-Dec-2018 Tags: 2008 Suzuki Swift, 2008 suzuki swift, Suzuki Swift, suzuki swift, Suzuki, Swift, swift, Used Suzuki								
	Suzuki Swift Sport 1.6A (New 5-yr COE)	\$28,800	\$5,760 /yr	19-Dec-2008	1,586 cc	121,337 km	Hatchback	Available
Graded B by STRA								
\$3,500 Drive Away Monthly \$500 Including Insurance Possible With Our Flexible In House Finance Packages With Attractive Interest Rates. We Provide 6 Months Warranty On Engine And Gearbox If You Purcha...								
Posted: 16-Dec-2018 Tags: 2008 Suzuki Swift, 2008 suzuki swift, Suzuki Swift, suzuki swift, Suzuki, Swift, swift, Used Suzuki								
	Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.							
	Suzuki Swift 1.2A XG (COE till 05/2023)	\$24,900	\$5,680 /yr	09-May-2008	1,242 cc	111,000 km	Hatchback	Available
In Times Of Market Uncertainties And COE Fluctuating Prices, This Beautiful Cool Silver Suzuki Swift 1.2A Will Be Easy On Your Pocket And Probably One Of The Most Reasonably Priced Unit In Town So Def...								
Posted: 16-Dec-2018 Tags: 2008 Suzuki Swift, 2008 suzuki swift, Suzuki Swift, suzuki swift, Suzuki, Swift, swift, Used Suzuki								
	Suzuki Swift Sport 1.6M (New 5-yr COE)	\$28,800	\$5,760 /yr	17-Dec-2008	1,586 cc	107,000 km	Hatchback	Available
Up To 95% Loan, Immediate Approval. New 5 Years COE. Original Stock Condition! View To Believe The Prestige Condition Of Swift Sports. Engine And Gearbox! Bank And In House Loan Available! STA Gradin...								
Posted: 15-Dec-2018 Tags: 2008 Suzuki Swift, 2008 suzuki swift, Suzuki Swift, suzuki swift, Suzuki, Swift, swift, Used Suzuki								
	Suzuki Swift 1.2A XG (New 5-yr COE)	\$23,800	\$4,760 /yr	15-Dec-2008	1,242 cc	92,664 km	Hatchback	Available

Compare


Suzuki Swift Sport 1.6M (New 10-yr COE)

\$49,800

\$4,980 /yr

11-Dec-2008

1,586 cc

Hatchback

Available

Best Handling And Sporty Look White Swift Sport. Healthy Gearbox And Mild Upgraded Engine. Some Cosmetic Mod. Well Maintained By Owner. Selling Due To Upgrading. Accident Free. New Paintwork For The N...

Posted: 02-Dec-2018 Tags: 2008 Suzuki Swift, 2008 suzuki swift, Suzuki Swift, suzuki swift, Suzuki, Swift, swift, Used Suzuki


Suzuki Swift 1.5A (New 5-yr COE)

\$25,800

\$5,160 /yr

16-Dec-2008

1,490 cc

123,000 km

Hatchback

Available

AA Trust Certified Quality Pre-Owned Vehicle! Extremely Well Maintained By Previous Owner! Regularly Serviced And Maintained By Reputable Japanese Workshop! Powerful Yet Quiet Engine, Fuel Efficient! ...

AA Trust Automotive

Posted: 28-Nov-2018 Tags: 2008 Suzuki Swift, 2008 suzuki swift, Suzuki Swift, suzuki swift, Suzuki, Swift, swift, Used Suzuki


Suzuki Swift 1.2A XG (COE till 09/2023)

\$23,300

\$4,900 /yr

19-Sep-2008

1,242 cc

155,000 km

Hatchback

Available

Selling Away All My Cars To Fund My Next Purchase. Guaranteed Tip Top Condition With No Hidden Issues As I Am A Car Enthusiast. Oil Change Done Every 8k Km, With All Major Servicing Done. I Will Intro...

DRIFT OWNER

Posted: 25-Nov-2018 Tags: 2008 Suzuki Swift, 2008 suzuki swift, Suzuki Swift, suzuki swift, Suzuki, Swift, swift, Used Suzuki


Suzuki Swift 1.3A (New 5-yr COE)

\$24,788

\$4,950 /yr

15-Dec-2008

1,328 cc

80,257 km

Hatchback

Available

We Are The COE Specialist, No Gimmicks, Honest Dealing. 1 Owner With Low Mileage Clocked. Car In Superb Condition, High Loan With \$3000 Down Payment Drive Away! 100% Approval. Bank Loan Available. Cal...

PREMIUM ED

Posted: 24-Nov-2018 Tags: 2008 Suzuki Swift, 2008 suzuki swift, Suzuki Swift, suzuki swift, Suzuki, Swift, swift, Used Suzuki

Save this search criteria, to get email alerts whenever a match is found.

Model Price Depreciation Reg. Class Eng. Cap. Mileage Veh. Type Status

For old advertisements, view Expired ads

« Back (1 2) Next »

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Suzuki Swift, Suzuki Swift Singapore, used Suzuki Swift Singapore, used Suzuki Swift, used vehicles Singapore or even buy used Suzuki Swift Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2018 sgCarMart. All rights reserved.

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7723B
Vehicle Details	
Vehicle No.:	SJL6874Z
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Nov 2018
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT 1.6 AT
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	M16A1373234
Chassis No.:	JSAEZC31S00201786
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$15,112.00
Original Registration Date:	10 Dec 2008
First Registration Date:	10 Dec 2008
Transfer Count:	2
Actual ARF Paid:	\$15,112.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Dec 2018
PARF Rebate Amount:	\$7,556.00
Intended COE Rebate Details	
COE Expiry Date:	09 Dec 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$7,721.00
COE Rebate Amount:	\$25.00
Total Rebate Amount:	\$7,581.00

The information contained herein is correct as at 27 Nov 2018

OK

Print Received Message

This mail is associated with :

***SJL6874Z (0521876760SG)**
[SGD9501H]
TP
TEO CHYE LIAN
Nov 20 2018 11:00AM
[LIOW SWEE HOE]
Guan Motor Works

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 05/04/2019 10:52 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11466.45) - SJL6874Z - Claim Handler: Syed-Yusoff, Saliha

Approved:11466.45:Pls offer \$60/ day for LOU, the approval is subject to final repair bill & ATA

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Wednesday, 27 March 2019 12:23 PM
To: 'Syed-Yusoff, Saliha'
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: YOUR REF: 0521876760SG** OUR REF: CC4/AIG18021251/Kpa3**(ACCIDENT INVOLVING SGD 9501H & SJL 6874Z ON 20/11/2018)**

AIG Ref: **0521876760SG**

LKK Ref: CC4/AIG18021251/Kpa3

Dear Sirs/Madam,

ACCIDENT INVOLVING SGD 9501H(OI) /SJL 6874Z(TP) /OTHERS ON 20/11/2018

We refer to the above matter.

It is a chain collision. Liability is not in our driver's favour.

We did clarify with insured the nature of the accident and he is aware that NCD (if any) would be affected.

We seek your approval to offer to Third Party repairer, "**Guan Motor Works**" is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 16,286.68	\$ 10,379.00
2. Loss of Use (18days x \$80.00)	\$ 1,440.00	\$ 1,440.00 (18days x \$80.00)
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
Total	\$ 17,734.13	\$ 11,826.45

**18days recommendation for repair

All the relevant documents had been uploaded in Merimen.

Kindly let us have your mandate in Merimen.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG18021251/Kpa3

12 MARCH 2019

LIOW SWEE HOE
APT BLK 812B CHOA CHU KANG AVE 7
#18-639
SINGAPORE 682812

Dear Sir/Madam,

**ACCIDENT INVOLVING SGD 9501H(AIG) / SJL 6874Z/ OTHERS ALONG/ AT
PIE 16KM MARK ON 20/11/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SJL 6874Z against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
Email: chewht@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*


AUTHORISATION TO ACT


I/We, TEO CHYE LIAN ("the third party claimant") of BLK 237 CHOA
CHU KANG CENTRAL #05-71 5 2368023 (address), owner of SJL 6874Z (vehicle
no.) hereby authorize GUAN MOTOR WORKS ("the workshop")
to act for me with respect to my claim for repair costs and/or rental and/or loss of use
("claim") for my vehicle no. SJL 6874Z that was damaged pursuant to the accident which
occurred on 20/11/2018 (date) along PIE TOWARDS CHANGI NEAR TO TOA PAYOH SAFRA
(location) involving vehicle no/s SQD 9501 H & WQD 2956 & SJH 5273L ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they
deem fit and the workshop is further authorized to receive payment further to settlement of
my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a
without prejudice and without admission of liability basis insofar as the driver/owner/insurers
of the other vehicle/s is concerned.

Dated this 15 (day) of April (month) 2019 (year)


Signed by "the third party claimant"
(with chop if applicable)


Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, GUAN MOTOR WORKS ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$9,700.00 (Repair Cost), S\$1,080.00 (Loss of Use/Rental), S\$ 7.45 (Disbursement) for vehicle no. SJL 6874Z that was damaged pursuant to the accident which occurred on 20/11/2018 (date) along PIE (location) involving vehicle no/s SGD 9501H. This is pursuant to the inspection conducted on 26/11/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TEO CHYE LIAN ("the third party claimant") of vehicle no. SJL 6874Z make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".


We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJL 6874Z (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 16 (day) of May (month) 2019 (year)

KSC
Signed by appointed surveyor


Signed by "the workshop" (with chop)

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 081026-00E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 H/P: 9742 6003

Messrs: TEO CHYE LIAN

Invoice No: 4941

Date: 24-12-2018

SUZUKI SWIFT - 1.6 (A) SJL 6874 Z

Lump sum for total repair cost inclusive of spare parts and labour charges.

S 9,700.00

Dollars Nine thousand Seven hundred only.



E.&O.E.

20-11-'18 15:17 FROM-

Enquire Vehicle & Owner Information (Vehicle No. SGD9501H As At 20 Nov 2018 / 11:00:00)**Law Firm Search Details****Search Reason:** Insurance claim in relation to traffic accident**Law Firm Case No.:** TCKWITLTA.2018 GM**Current Owner Details****Owner ID Type:** Singapore NRIC**Owner ID:** S7337331Z**Owner Name:** LIOU SWEE HOE**Registered Address Type:** HDB / HUDC**Registered Block/House No.:** 812B**Registered Street Name:** CHOA CHU KANG AVENUE 7**Registered Unit No.:** # 18 - 639**Registered Building Name:****Registered Postal Code:** 682812**Current Vehicle Details****Vehicle No.:** SGD9501H**Make Description/Model:** TOYOTA / WISH 1.8 A**Insurance Company Name:** AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Nov 2018 Edit Reg		23 Nov 2018 00:00 Edit Adj Rpt	\$59,700.00 Edit Estimates	\$59,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LIOW SWEE HOE , ID: 57337331Z									
Main Claimant: TEO CHYE LIAN , ID: S1397723B									
Vehicle Reg. No.: SJL6874Z		Date of Loss: 20/11/2018 11:00 - :59 [119 Months and 10 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 0521876760SG		Policy/Cover Note No.: 2100064960 (Third Party Only)							
Vehicle Reg. No. (Insured): SGD9501H		Policy No. (Claimant): MT100891							
		Excess:							
Repairer: Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare, 575721 Sin Ming - Tel: 64536111									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha, Syed-Yusoff@aig.com									
Claimant's Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 04/12/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (05/04/2019): Alert - Adj Mandate Approved (\$511466.45) - SJL6874Z - Claim Handler: Syed-Yusof... - AIG_SG (26/11/2018): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJL6874Z (0521876760SG)
[SGD9501H]
TP
TEO CHYE LIAN
Nov 20 2018 11:00AM
[LIOW SWEE HOE]
Guan Motor Works

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			☒		
No		Finalized On		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print			
1		(Draft)		Third Party Express Settlement - Payment Breakdown													Edit			
Photos/Images															3 per page			☒		
No		Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print			
1		27/03/19 12:30		General View													Load JPG ☒			
2		27/03/19 12:30		General View													Load JPG ☒			
3		27/03/19 12:30		General View													Load JPG ☒			
4		27/03/19 12:30		General View													Load JPG ☒			
5		27/03/19 12:30		General View													Load JPG ☒			
6		27/03/19 12:30		General View													Load JPG ☒			
7		27/03/19 12:30		General View													Load JPG ☒			
8		27/03/19 12:30		General View													Load JPG ☒			
9		27/03/19 12:30		General View													Load JPG ☒			
10		27/03/19 12:30		General View													Load JPG ☒			
11		27/03/19 12:30		General View													Load JPG ☒			
12		27/03/19 12:30		General View													Load JPG ☒			
13		27/03/19 12:30		General View													Load JPG ☒			
14		27/03/19 12:30		General View													Load JPG ☒			
15		27/03/19 12:30		General View													Load JPG ☒			
16		27/03/19 12:30		General View													Load JPG ☒			
17		27/03/19 12:30		General View													Load JPG ☒			
18		27/03/19 12:30		General View													Load JPG ☒			
19		27/03/19 12:30		General View													Load JPG ☒			
20		27/03/19 12:30		General View													Load JPG ☒			
21		27/03/19 12:30		General View													Load JPG ☒			
22		27/03/19 12:30		General View													Load JPG ☒			
23		27/03/19 12:30		General View													Load JPG ☒			
24		27/03/19 12:30		General View													Load JPG ☒			
25		27/03/19 12:30		General View													Load JPG ☒			
26		27/03/19 12:30		General View													Load JPG ☒			
27		27/03/19 12:30		Odometer Reading													Load JPG ☒			
28		27/03/19 12:30		Chassis Number													Load JPG ☒			
29		27/03/19 12:36		Reinspection Photo													Load JPG ☒			
30		27/03/19 12:36		Reinspection Photo													Load JPG ☒			
31		27/03/19 12:36		Reinspection Photo													Load JPG ☒			
32		27/03/19 12:36		Reinspection Photo													Load JPG ☒			
33		27/03/19 12:36		Reinspection Photo													Load JPG ☒			
34		27/03/19 12:36		Reinspection Photo													Load JPG ☒			

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
36	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
37	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
38	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
39	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
40	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
41	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
42	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
43	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
44	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
45	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
46	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
47	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
48	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
49	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
50	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
51	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
52	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
53	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
54	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
55	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
56	27/03/19 12:36	Reinspection Photo	 Load JPG	☒
57	27/03/19 12:45	Photo After Spray	 Load JPG	☒
58	27/03/19 12:45	Photo After Spray	 Load JPG	☒
59	27/03/19 12:45	Photo After Spray	 Load JPG	☒
60	27/03/19 12:45	Photo After Spray	 Load JPG	☒
61	27/03/19 12:45	Photo After Spray	 Load JPG	☒
62	27/03/19 12:45	Photo After Spray	 Load JPG	☒
63	27/03/19 12:45	Photo After Spray	 Load JPG	☒
64	27/03/19 12:45	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/11/18 13:28	Singapore Accident Statement	 Load PDF	
2	27/11/18 13:29	Police Report	 Load PDF	
3	08/01/19 10:51	EMAIL FROM AIG DD 23.11.2018	 Load PDF	
4	08/01/19 10:51	NOTIFICATION FROM WORKSHOP + TP GIA REPORT	 Load TIF	
5	10/01/19 14:35	TP ESTIMATE - MARKED	 Load PDF	
6	21/03/19 16:35	LETTER TO OI	 Load PDF	
7	21/03/19 16:35	LTA SEARCH	 Load PDF	
8	22/05/19 13:49	WORKSHOP INVOICE	 Load PDF	
9	22/05/19 13:49	AUTHORISATION TO ACT FORM	 Load PDF	
10	22/05/19 13:49	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	26/11/18 10:47	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGD9501H (Insd veh)	Model:	SUZUKI SWIFT 1.6 (A)
	SJL6874Z (TP veh)		
Date of Accident:	20/11/2018		

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	: \$	15,221.20		
Final Repair Cost	: \$	9,700.00		
Loss of Use	: \$	1,080.00		
Rental (if any)	: \$	0.00		
LTA / GIA Search Fee	: \$	7.45		
Others:	: \$	0.00		
	: \$			
Final Settlement Sum	: \$	10,787.45		

18.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)				
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ 100 _____ (%)		
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 0 _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Guan Motor Works	: \$	10,787.45
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

22 May
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18021251/KGA3Q2

Date: 22/05/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100064960
Claimant Vehicle No : SJL6874Z **Insured Vehicle No :** SGD9501H
 Date of Loss: 20/11/2018 Nature of Claim: TP Claim No: 0521876760SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJL6874Z**
 Make & Model: SUZUKI SWIFT, 1.6 (A) Engine No: M16A1373234
 Reg. Date: 10/12/2008 (Man. Year: 2008) Chassis No: JSAEJC31S00201786
 Colour: Metallic Grey Odometer: 140339 km
 Engine Capacity: 1586 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,161.20	8,072.71	2,088.49	20.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,060.00	4,050.00	1,010.00	19.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,221.20	12,122.71	3,098.49	20.36
Approved Total (Overridden) (S\$)		9,700.00		
Nett Amount (S\$)	15,221.20	9,700.00	5,521.20	36.27
+ Loss of Use (18.0 x S\$60.00/day) (S\$)		1,080.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,787.45		

INSPECTION

Date of Assignment: 23/11/2018
 Date Inspected: 26/11/2018 Inspected At: Guan Motor Works (HQ)
 176 Sin Ming Drive #02-03 Sin Ming
 Autocare
 Singapore 575721
 Estimated Period of Repair: 18.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	668.15 FL	*668.15 FL
2	2		*FRONT BUMPER FOG LAMP COVER	Mtg Cracked	164.90 FL	*164.90 FL
3	2		*FRONT BUMPER FOG LAMP	Serviceable	376.40 FL	*- FL
4	1		*FRONT BUMPER TOW COVER	Dented	26.70 FL	*26.70 FL
5	1		*FRONT BUMPER GRILLE	Cracked	169.95 FL	*169.95 FL
6	2		*FRONT BUMPER SIDE RETAINER	Distorted	56.60 FL	*56.60 FL
7	1		*FRONT BUMPER INNER LOWER REINFORCEMENT	Bent	148.70 FL	*148.70 FL
8	1		*FRONT BUMPER INNER LOWER REINFORCEMENT OUTER GARNISH COVER	Dented	85.35 FL	*85.35 FL
9	1		*FRONT BUMPER INNER TOP REINFORCEMENT	Bent	172.75 FL	*172.75 FL
10	1		*FRONT BUMPER INNER TOP REINFORCEMENT OUTER GARNISH COVER	Dented	92.65 FL	*92.65 FL
11	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
12	1		*FRONT LOWER COVER	Distorted	60.75 FL	*60.75 FL
13	2		*HEADLAMP	Mtg Cracked	670.10 FL	*670.10 FL
14	1		*FRONT GRILLE	Cracked	72.80 FL	*72.80 FL
15	1		*FRONT GRILLE CENTRE S LOGO	Necessary	19.65 FL	*19.65 FL
16	1		*FRONT BONNET	Buckled	463.25 FL	*463.25 FL
17	2		*FRONT BONNET HINGE	Repair	51.50 FL	*- FL
18	1		*FRONT BONNET LOCK	Distorted	51.60 FL	*51.60 FL
19	1		*FRONT BONNET LOCK CABLE	Serviceable	31.70 FL	*- FL
20	1		*FRONT SUPPORT PANEL	Buckled	494.30 FL	*494.30 FL
21	1		*FRONT SUPPORT PANEL RH SIDE AIR GARNISH	Serviceable	91.15 FL	*- FL
22	1		*FRONT SUPPORT PANEL LH SIDE AIR GARNISH	Serviceable	16.45 FL	*- FL
23	1		*AIR CON CONDENSER	Punctured	686.30 FL	*686.30 FL
24	1		*AIR CON CONDENSER PIPE	Punctured	103.65 FL	*103.65 FL
25	1		*AIR CON LOW PRESSURE PIPE	Dented	162.85 FL	*162.85 FL
26	1		*RADIATOR	Punctured	863.70 FL	*863.70 FL
27	1		*RADIATOR FAN COWLING	Bent	116.25 FL	*116.25 FL
28	1		*RADIATOR FAN MOTOR	Jammed	424.00 FL	*424.00 FL
29	1		*RADIATOR FAN BLADE	Distorted	65.45 FL	*65.45 FL
30	2		*FRONT FENDER	Repair	471.20 FL	*- FL
31	2		*FRONT FENDER UNDER SHIELD	Serviceable	127.80 FL	*- FL
32	1		*SET FRONT FENDER UNDER SHIELD CLIPS	Not Necessary	40.00 FL	*- FL
33	1		*REAR BUMPER	Buckled	649.65 FL	*649.65 FL
34	1		*REAR BUMPER GRILLE	Cracked	169.65 FL	*169.65 FL
35	2		*REAR BUMPER REVERSE LAMP	Cracked	160.50 FL	*160.50 FL
36	2		*REAR BUMPER SIDE RETAINER	Distorted	34.00 FL	*34.00 FL
37	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
38	2		*REAR BUMPER INNER SIDE IMPACT BRACKET	Repair	51.10 FL	*- FL
39	1		*REAR NUMBER PLATE LAMP	Serviceable	20.75 FL	*- FL
40	1		*TAILLAMP (2 PCS)	Cracked	451.30 FL	*451.30 FL
41	1		*REAR TAILGATE	Repair	628.15 FL	*- FL
42	1		*REAR TAILGATE OUTER HANDLE	Serviceable	75.90 FL	*- FL
43	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	123.55 FL	*- FL
44	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	40.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*REAR TAILGATE TOP LOCK	Dented	180.10 FL	*180.10 FL
46	1		*REAR TAILGATE LOWER LOCK CATCH	Repair	17.95 FL	*- FL
47	1		*REAR TAILGATE WEATHERSTRIP (50%)	Dented / Cut	78.75 FS	*46.32 FS
48	1		*REAR END PANEL	Bent	274.85 FL	*274.85 FL
49	1		*REAR END PANEL TOP GARNISH	Distorted	82.75 FL	*82.75 FL
50	1		*REAR SPARE TYRE PANEL	Bent / Buckled	382.15 FL	*382.15 FL
51	1		*REAR SPARE TYRE TOP BOARD	Cracked	145.00 FL	*145.00 FL
52	2		*REAR EXHAUST SILENCER	Bent	745.40 FL	*745.40 FL
53	1		*REAR EXHAUST CHROME PIPE	O/S Dented	240.00 FL	*120.00 FL
54	1		*FRONT NUMBER PLATE	Cracked	45.00 FS	*45.00 FS
55	1		*REAR NUMBER PLATE	Broken	45.00 FS	*20.00 FS
56	1		*SET REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
57	1		*SET REAR END PANEL /SPARE TYRE PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.				Sub Total (\$\$)	11,898.10	9,467.07
				- List Item Discount on L Items 15.00/15.00% (\$\$)	1,736.90	1,394.36
				Total Parts (\$\$)	10,161.20	8,072.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	60.00	50.00
2	LABOUR CHARGES FOR REMOVE/REFIT ,CUT/WELD ,PANEL BEATING AND REPLACE ACCIDENT DAMAGES	New	2,200.00	2,000.00
3	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES	New	2,000.00	1,600.00
4	TO CHECK WIRINGS AND LIGHTINGS (FRONT & REAR)	New	80.00	40.00
5	TO REMOVE ,REFIX A/C CONDENSER ,RADIATOR ETC.....INCLUDING REFILL OF A/C GAS	New	150.00	100.00
6	TO REMOVE,REFIX REAR WINDSCREEN GLASS	New	150.00	0.00
7	TO REMOVE,REFIX REAR UPHOLSTERY AND ATTACHMENTS	New	120.00	80.00
8	TO REMOVE,REFIX REAR TAILGATE FITTINGS	New	80.00	0.00
9	TO REMOVE,REFIX REAR EXHAUST SILENCER	New	100.00	60.00
10	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	120.00	120.00
Gross Labour Cost (\$\$)			5,060.00	4,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >