

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

TAX INVOICE

EST No.: EST0020816
Tong Hock Chuan

GST Reg No: M2-0128609-3
Page: 1 of 2
Number: INV0020531
Your ref.: TP - SKB 2249X AXA
Job No.: 70016
Our ref.: 18.11.36
Payment
Date: 24/11/2018

Attn

Vehicle No: SDP 3738D
Vehicle Model : Toyota Altis
Accident on ...: 21/11/2018

Not Withheld
Assuming B4 paint

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Bonnet	1,028.00	25.00	B1 771.00 ✓
1.00	Pc	Front bonnet hinge LH	55.90	25.00	R 41.93 x
1.00	Pc	Front bonnet hinge RH	55.90	25.00	DRY 41.93 ✓
1.00	Pc	Front bumper	458.10	25.00	CMA 343.58 ✓
1.00	Pc	Front bumper side holder RH	55.79	25.00	CMA 41.84 ✓
1.00	Pc	Front bumper sponge	65.59	25.00	CMA 49.19 ✓
1.00	Pc	Front fog lamp RH	248.20	25.00	Mtg CMA 186.15 ✓
1.00	Pc	Front fog lamp cover RH	119.14	25.00	R 89.36 ✓
1.00	Pc	Front head lamp RH	2,814.50	25.00	CMA 2,110.88 ✓
1.00	Pc	Front fender LH	761.45	25.00	B1 571.09 ✓
1.00	Pc	Front fender RH	761.45	25.00	B1 571.09 ✓
1.00	Pc	Front fender inner shield RH	137.62	25.00	DRY 103.22 ✓
1.00	Pc	Front bumper side clip RH	3.00	25.00	M 2.25 ✓
16.00	Pcs	Front fender inner shield clips LH	3.50	25.00	M 42.00 ✓
16.00	Pcs	Front fender inner shield clips RH	3.50	25.00	M 42.00 ✓
1.00	Pc	Front washer tank	170.38	25.00	DRY 127.79 ✓
1.00	Pc	Front support panel	977.60	25.00	B1 733.20 ✓
1.00	Pc	Front head lamp chrome moulding RH	137.70	25.00	CMA 103.28 ✓
1.00	Pc	Dual VVT-i emblem LH	39.43	25.00	M 29.57 ✓
1.00	Pc	Dual VVT-i emblem RH	39.43	25.00	M 29.57 ✓
1.00	Pc	Front sport rim 17 inches (Original)	1,644.50	25.00	DRY 1,233.38 ✓

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0020816
Tong Hock Chuan

Page 2 of 3
Your ref. TP - SKB 2249X AXA
Job No. 70016
Our ref. 18.11.36
Payment
Date 27/11/2018

Attn

Vehicle No SDP 3738D
Vehicle Model : Toyota Altis
Accident on ... 21/11/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Dual VVT-i emblem LH ×	39.43	25.00	29.57 ✓
1.00	Pc	Dual VVT-i emblem RH ×	39.43	25.00	29.57 ✓
1.00	Pc	Front sport rim 17 inches (Original) ×	1,644.50	25.00	1,233.38 ✓
1.00	Pc	Front shock absorber RH	425.90	25.00	319.43 ✓
1.00	Pc	Front shock absorber top mounting RH	169.82	25.00	127.37 ✓
1.00	Pc	Front knuckle arm RH	441.90	25.00	331.43 ✓
1.00	Pc	Front wheel bearing RH	119.43	25.00	89.57 ✓
1.00	Pc	Front lower arm RH	459.43	25.00	344.57 ✓
1.00	Pc	Front steering rack crossmember	1,925.30	25.00	1,443.98 ✓
1.00	Pc	Front driveshaft RH	1,633.20	25.00	1,224.90 ✓
Labour & Misc:					
1.00		Towing charge	70.00		70.00 ✓
1.00		To check wheel alignment (computerised)	60.00		60.00 ✓
1.00		To dismantle + renew steering rack cross member + transfer steering rack	300.00		300.00 ✓

— Repeated

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给 Asknowledge by Repairer 给于快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

Signature:

Date:

? 240L

來發 (明 記) 摩 哆 有 限 公 司

LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
 GST No: M2-0128609-3
 UEN: 199407592C

ESTIMATE

EST. No EST0020816
 Tong Hock Chuan

Page 3 of 3
 Your ref. TP - SKB 2249X AXA
 Job No. 70016
 Our ref 18.11.36
 Payment
 Date 27/11/2018

Attn

Vehicle No SDP 3738D
 Vehicle Model : Toyota Altis
 Accident on ... 21/11/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To dismantle + renew front suspension parts RH and drive shaft RH and press wheel bearing, etc	350.00		350.00 <i>200</i>
1.00		To straighten front body including cutting, welding; to knock dents on wheelhouse panel RH and renew above parts	900.00		900.00 <i>800</i>
1.00		To respray paint (including blending of front door RH)	1,000.00		1,000.00 <i>900</i>

Sub-Total 13,825.55
 GST 7.00% 967.79
 Total S\$ 14,793.34

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
 GST No: M2-0128609-3
 UEN: 199407592C

SUPPLEMENTARY ESTIMATE

EST. No. EST0020816
 Tony Chuan

Page 1 of 1
 Your ref. TP- SKB 2249X AXA
 Job No. 70016
 Our ref. 18.11.36
 Payment
 Date 4/12/2018

Attention:

Vehicle No. SDP 3738D
 Vehicle Model Toyota Altis
 Accident on 21/11/2018

Quantity	Unit	Description	Unit price	Disc. pct	Amount
SUPPLEMENTARY ITEM:					
1.00	Pc	Radiator spare tank	160.80	25.00	120.60
1.00	Pc	Lower arm ball joint RH	197.80	25.00	148.35
1.00	Pc	Steering rack end RH	127.30	25.00	95.48
1.00	Pc	Stabilizer bar link RH	180.53	25.00	135.40

Sub-Total 499.83
 GST 7.00% 34.99
 Total S\$ 534.82

本公司拥有最先进的 CAROLINER MARK IV 机械，可供给多种款式的车身及给予快速与准确的测量方式和钢铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。
 "Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."