

INS. CASE OWNER:

CC 4 / LPC1802

LKK:

DAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

S/N 92508

YAP WATSIANA

HP: 9222440

D.O.A: 18/11/18

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

18/11/18 18/11/18 18/11/18

218 UP05018 218

KIA

10R 3 DEYLANA

If NO. Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SHB 21857



INSRS:

WSP:

Tel:

Liability:

RMKS:

Dmg
PTE

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

7/1/19
Aster

SHB 21857 - X

S/N 92508 - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:
After call ltr to OI:

20.1.19

FILE PASS TO TYPST TO PREPARE REPORT.

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)	☐	☐
After call ltr to OI:	☐	☐
Authorisation To Act:	☒	☐
Release Voucher:	☒	☐
Final Repair Bill:	☒	☐
Car Rental Invoice:	☒	☐
Towing Invoice:	☐	☐
LTA / GIA:	☒	☐
Medical Bill:	☐	☐
PIR:	☐	☐
Mandate/Reject Instruction:	☒	☐
LOD	☒	☐
Payment Breakdown Form:	☐	☐
Post-Repair Photos:	☒	☐
Others:	☐	☐

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: MTH

Repair Cost:

45 \$5,100

(2 days) Reduction:

72 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 27.2.19

Confirm with KENNETH

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28. Ass. Lia:

Repair Cost:

0/69 \$5,171.00

01 REAR ENDED TP

Loss of Rental (LOR):

\$5,101.47

(1 days) x +107.47

Loss of Use (LOU):

\$5

(5 x days)

Loss of Income (LOI):

\$50.00

(\$50 x 1 days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LO ☒

[Tick only one]

GIA/LTA Search

\$57.45

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost:

\$5

Total:

\$5,134.93

Global Sum \$5:

FINAL PAYMENT

Date/Time: 27.2.19

Confirm with: KENNETH

Email ☒ Call ☐

Payee 1:

\$5

1,341.93

Name 1:

DING AUTOMOTIVE PTE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle
2) Report Format: TP
3) Survey fee: +450

COPY SENT

Tuphi

REF:

LPC

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHB2265J

Yr Regn:

2016 Aug

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai T40

C.C

1685

Colour:

Yellow

A/C:

Insured / Std / NI / NA

Sp. Reading

323093.

T/Radio:

Insured / Std / NI / NA

Eng/No:

Ch/No:

KMHL641UM64093539.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: N / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle

Front

6

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

mm

D.O.A.

D.O.I.

26/11/18

Survey held at

Ding Noto Capetown Rd

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4: 41,100 (Rd: 2,850.88 75%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Colours

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607196R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC18021323/T1eb3

Date: 27.11.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB2265J


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26.11.2018 at the premises of M/s Ding Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	3,950.88
Revised Estimate Amount	: S\$	1,364.46
"Check" Items Amount	: S\$	886.46
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

26/11/2018 11:41

JOB-NO: 50111155

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHB2265J

TRANS: AUTO

CHASSIS: KMHLB41UMGU093539

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU670618

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00		Y	200
2 R&R SPARE TYRE & CARPET & TRIM	1.00	80.00	0.00	80.00		Y	X
3 RESPRAY REAR BUMPER	1.00	230.00	0.00	230.00		Y	200
4 RESPRAY REAR BUMPER DIFFUSER	1.00	200.00	0.00	200.00		Y	100
5 RESPRAY BOOTLID	1.00	230.00	0.00	230.00		Y	X
6 REMOVE & RE-DRILL REVERSE SENSOR	1.00	80.00	0.00	80.00		Y	30
TOTAL:		1,820.00	0.00	1,820.00			
<u>MATERIALS</u>							
1 REAR BUMPER	1.00	599.32	119.86	479.46	L	Y	de
2 REAR BUMPER REINFORCEMENT	1.00	438.40	87.68	350.72	L	Y	X NW
3 REAR BUMPER REINFORCEMENT BRACKET LHS	1.00	85.63	17.13	68.50	L	Y	X NW
4 REAR BUMPER REINFORCEMENT BRACKET RHS	1.00	85.63	17.13	68.50	L	Y	X NW
5 REAR BUMPER REINFORCEMENT SPONGE	1.00	150.15	30.03	120.12	L	Y	X CRAM
6 REAR BUMPER RETAINER LHS	1.00	49.14	9.83	39.31	L	Y	X NW
7 REAR BUMPER RETAINER RHS	1.00	49.14	9.83	39.31	L	Y	X NW
8 REAR BUMPER DIFFUSER	1.00	218.40	43.68	174.72	L	Y	X NW
9 REPAIR BOOTLID	1.00	0.00	0.00	0.00	L	Y	X
10 BOOTLID EMBLEM-LOGO	1.00	33.55	6.71	26.84	L	Y	X NW
11 BOOTLID EMBLEM-I 40	1.00	36.50	7.30	29.20	L	Y	X NW
12 BOOTLID EMBLEM-CRDI	1.00	36.50	7.30	29.20	L	Y	X NW
13 REAR BUMPER RUBBER PROTECTOR PAD	1.00	160.00	0.00	160.00	S	Y	new
14 REAR BUMPER REVERSE SENSOR	1.00	230.00	0.00	230.00	S	Y	200 X NW
15 BOOTLID STICKER-COMFORTDELGRO BOOKING 65521111	1.00	120.00	0.00	120.00	S	Y	X NW
16 REAR BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	new
17 REAR BUMPER ADS STICKER	1.00	160.00	0.00	160.00	S	Y	new
TOTAL:		2,487.36	356.48	2,130.88			
TOTAL PARTS & LABOUR :		4,307.36	356.48	3,950.88			

EXCESS/LOADING: S\$ 0.00

No. Of Day: 02

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: S\$

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

DATE OF SURVEY: 20, 11, 18

SURVEYED BY: Tanjun

surel@klean.com

CONTACT NO: 9744 5119

FAX NO:

wp

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 26 November 2018 9:05 AM
To: taxiscs@stengg.com; MT_Claim_SG; assignments@lkkauto.com; 'Admin-D (LKKAuto)'
Cc: ACCOUNTS@DINGAUTO.SG; ADMIN@DINGAUTOMOTIVE.COM.SG; carlor.chan@dingauto.sg
Subject: RE: ACCIDENT INVOLVING SHB2265J AND SJU9350B ON 18/11/2018 ARRANGE SURVEY Our Ref: TBA
Attachments: SAS2507587.pdf; SHB2265J-SJU9350B.HTML

9:08am @ 26/11/18
Vehicle In
Person @ Alex
Surrounding

Dear Catherine/Nivitha

Please arrange TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: taxiscs@stengg.com [mailto:taxiscs@stengg.com]
Sent: Friday, 23 November, 2018 5:40 PM
To: MT_Claim_SG; CHEW BENG KEE
Cc: ACCOUNTS@DINGAUTO.SG; ADMIN@DINGAUTOMOTIVE.COM.SG; carlor.chan@dingauto.sg
Subject: ACCIDENT INVOLVING SHB2265J AND SJU9350B ON 18/11/2018 ARRANGE SURVEY

Dear Officer ,

Please arrange survey SHB2265J ASAP

The vehicle SHB2265J already in 31 Corporation Road 649825 .

Thanks

Best Regards

Ding Automotive Pte Ltd
Alex Khong
Hp : 83039588 / 62657130

NOTE !!!

All mailed letter & cheque payment is to be mailed to our main office address :
BLOCK 10 #01-20
SIN MING INDUSTRIAL EST. SEC C
SINGAPORE 575645

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you]


Shu Pei (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 27 December 2018 3:04 PM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: ACCIDENT INVOLVING SHB2265J AND SJU9350B ON 18/11/2018 ARRANGE SURVEY Our Ref: TBA
Attachments: 27122018150104.pdf

Dear Shu Pei,

Attached copy of insured's report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Monday, 10 December, 2018 9:09 AM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG
Subject: RE: ACCIDENT INVOLVING SHB2265J AND SJU9350B ON 18/11/2018 ARRANGE SURVEY Our Ref: TBA

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>

Sent: Wednesday, 28 November 2018 9:10 AM

To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: RE: ACCIDENT INVOLVING SHB2265J AND SJU9350B ON 18/11/2018 ARRANGE SURVEY Our Ref: TBA

Our Ref : 18/18/18/VP05/021149

Dear Shu Pei,

Our insured driver has yet to lodge a report and we are making enquiries.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]

Sent: Tuesday, 27 November, 2018 6:02 PM

To: ONG LI LI

Cc: MT_Claim_SG; Admin A; Asher Sng (LKKAuto)

Subject: RE: ACCIDENT INVOLVING SHB2265J AND SJU9350B ON 18/11/2018 ARRANGE SURVEY Our Ref: TBA

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SHB 2265J at M/s Ding Auto Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice

Our case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 26 November 2018 9:14 AM
To: 'ONG LI LI' <llong@lonpac.com>; assignments <assignments@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING SHB2265J AND SJU9350B ON 18/11/2018 ARRANGE SURVEY Our Ref: TBA

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:llong@lonpac.com>]
Sent: Monday, 26 November 2018 9:05 AM
To: taxiscs@stengg.com; MT_Claim_SG <mt_claim@lonpac.com>; assignments@lkkauto.com; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>
Cc: ACCOUNTS@DINGAUTO.SG; ADMIN@DINGAUTOMOTIVE.COM.SG; carlor.chan@dingauto.sg
Subject: RE: ACCIDENT INVOLVING SHB2265J AND SJU9350B ON 18/11/2018 ARRANGE SURVEY Our Ref: TBA

Dear Catherine/Nivitha

Please arrange TP survey.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: taxiscs@stengg.com [<mailto:taxiscs@stengg.com>]
Sent: Friday, 23 November, 2018 5:40 PM
To: MT_Claim_SG; CHEW BENG KEE
Cc: ACCOUNTS@DINGAUTO.SG; ADMIN@DINGAUTOMOTIVE.COM.SG; carlor.chan@dingauto.sg
Subject: ACCIDENT INVOLVING SHB2265J AND SJU9350B ON 18/11/2018 ARRANGE SURVEY

Dear Officer ,

Please arrange survey SHB2265J ASAP

The vehicle SHB2265J already in 31 Corporation Road 649825 .

Thanks

Best Regards

Ding Automotive Pte Ltd

Alex Khong
Hp : 83039588 / 62657130

NOTE !!!

All mailed letter & cheque payment is to be mailed to our main office address :

BLOCK 10 #01-20

SIN MING INDUSTRIAL EST. SEC C

SINGAPORE 575645

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you]



This email has been checked for viruses by AVG antivirus software.

www.avg.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18021323/T1eb3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSE SINGAPORE 199555

Date : 11-03-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJU 9350B	Veh. Inspected	SHB 2265J
Policy No.	Z18VP05018238	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/021149	Excess (\$)	0.00
Assign From	GERALD	Assign Date	26/11/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU093539	Colour	YELLOW
Odometer	323093	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	TRIANGLE	6 mm
L/H Front Tyre	205/60 R16	TRIANGLE	6 mm
R/H Rear Tyre	205/60 R16	TRIANGLE	6 mm
L/H Rear Tyre	205/60 R16	TRIANGLE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/11/2018	Inspection Date	26/11/2018
Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 2265J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	599.32	599.32
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	438.40	-
1	REAR BUMPER REINFORCEMENT BRACKET LHS	NOT NECESSARY	85.63	-
1	REAR BUMPER REINFORCEMENT BRACKET RHS	NOT NECESSARY	85.63	-
1	REAR BUMPER REINFORCEMENT SPONGE	NOT NECESSARY	150.15	-
1	REAR BUMPER RETAINER LHS	NOT NECESSARY	49.14	-
1	REAR BUMPER RETAINER RHS	NOT NECESSARY	49.14	-
1	REAR BUMPER DIFFUSER	TO REPAIR SEE LABOUR	218.40	-
1	REPAIR BOOTLID (NPA)	NOT NECESSARY	-	-
1	BOOTLID EMBLEM -LOGO	NOT NECESSARY	33.55	-
1	BOOTLID EMBLEM -I 40	NOT NECESSARY	36.50	-
1	BOOTLID EMBLEM -CRDI	NOT NECESSARY	36.50	-
	LESS 20% DISCOUNT		-356.48	-119.86
			1,425.88	479.46
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER RUBBE PROTECTOR PAD (SN)	NECESSARY	160.00	160.00
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	230.00	-
1	BOOTLID STICKER -COMFORTDELGRO BOOKING 65521111 (SN)	NOT NECESSARY	120.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	35.00	35.00
1	REAR BUMPER ADS STICKER (SN)	NECESSARY	160.00	160.00
			705.00	355.00
<u>LABOUR</u>				
	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS.INCLUSIVE OF THE REPAIR OF REAR BUMPER DIFFUSER .		1,000.00	200.00
	R&R SPARE TYRE & CARPET & TRIM .	NOT NECESSARY	80.00	-
	RESPRAY REAR BUMPER.		230.00	200.00
	RESPRAY REAR BUMPER DIFFUSER.		200.00	100.00
	RESPRAY BOOTLID .	NOT NECESSARY	230.00	-

Report Ref No. CC4/LPC18021323/T1eb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & RE-DRILL REVERSE SENSOR .		80.00	30.00
			1,820.00	530.00
GRAND TOTAL			3,950.88	1,364.46
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,100.00

Report Ref No. CC4/LPC18021323/T1eb3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.