

ASS. REC. BY:

REF:

CS/FCI/8021440/Ksd3

02

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person):

CWS

Karen Tan

of

ref

Date/Time:

2:48pm @ 27/11/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJM7054L

Insured:

SH7066Y

at Workshop m/s

Cheng Hoe Motor

Tel:

67556142

of

Blk 1019, Yishun Ind. Park A #01-37A

Policy No:

Claim No:

018008409MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/10/18

CA / REV / REP. / REV 24 HRS

Cup

H.O.D. Endorsement:

Date/Time:

3:42pm @ 27/11/18

Person Contacted:

jue

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SJM7054L-X

SH7066Y-CO/MIDA15016680/j

D.O.A: 12/9/15

28/11/18-

vehicle not in.

4/12/18-

UNI yet.

13/12/18

@ 16:50 p.m. revised PA to Karen Tan via email.

ASS. REC. BY:

REF: FCZ/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Choy Hoe

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 87k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJM 70541 Yr Regn: 01, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Vios c.c. 1497

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 191548 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR053114 930 508 444

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size: F: 185 / 60 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 18/10/18

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 10/12/18

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

Rear d/s door

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/12 File pass to Catherine

4/1 L1P2 @ 900 Custom Estimate

07/01/19 Confirmed L1S @ 900 @ 2 days with Kenneth.

(\$ 338.25 Red = 27%)

MV - \$ 7,000/-

LTA - \$ 5,107.00

NET - \$ 1,293.00

RECEIVED 07 JAN 2019

[Signature]
7/1/2019

Date/Time, File Pass to?

07/01/19

: Prell. Report

: Final Report

1) Date/Time, File Return to?

2) _____

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

100
50
50
12
212

Report Format :

Lump Sum / I.B.I: (\$ 900/- L1S)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008409MFSH

Date: 13 December 2018

Our Ref: CS/FC118021440/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJM 7054L .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 10/12/2018 at the premises of M/s Cheng Hoe Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 1,238.25</u> .
Revised Estimate Amount	: <u>S\$ 1,148.24</u> .
"Check" Items Amount	: <u>S\$</u> .
Market Value	: <u>S\$</u> .
LTA Reimbursement Value	: <u>S\$</u> .
Nett Value	: <u>S\$</u> .

Description of Damage:

The vehicle sustained damages at the rear o/s door portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 2 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	26-11-2018	Our Ref No. D18008409MFSH
Accident Date	16-10-2018	Claim Type. Third Party
Insured Vehicle	SH7066Y	Third Party Vehicle. SJM7054L
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	JUNE	
Contact No.	67556142/ 0	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 13 December 2018 4:50 PM
To: 'Karen Tan'; 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D18008409MFSH/1
Attachments: SJM 7054L - Preli Advise -.pdf

Dear Karen,

Enclosed preliminary revised of vehicle SJM 7054L.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 27 November 2018 3:43 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008409MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 27 November 2018 2:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008409MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1548J
Vehicle Details	
Vehicle No.:	SJM7054L
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	1NZX860888
Chassis No.:	MR053HY9305098444
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$11,900.00
Original Registration Date:	14 Jan 2009
First Registration Date:	14 Jan 2009
Transfer Count:	1
Actual ARF Paid:	\$9,975.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jan 2019
PARF Rebate Amount:	\$4,987.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jan 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$4,191.00
COE Rebate Amount:	\$120.00
Total Rebate Amount:	\$5,107.00

The information contained herein is correct as at 16 Oct 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

*SJM 7054L
TP/FC*

M/S : MS FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

TEL: 65073848
 ATTN: Motor Claim Department
 WS Ref: TP/FC/YS
 Claim Type: Third Party
 Accident Date: 16/10/2018
 TP Veh Reg No: SH7066Y

FAX: 65073849

*Not Withheld
L1 Imp & 900L
Resurvey After Paint 2 days*

Estimate No: ES1891386/YISHUN
Date: 10 Dec 2018
Policy No: 5078945879-02
Veh Reg No: **SJM7054L**
Make/Model: TOYOTA VIOS E AUTO
Chassis No: MR053HY9305098444
Engine No: 1NZX860888
Reg. Date: 14/01/2009

Estimate Repair Cost to Vehicle No :SJM7054L

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR RH DOOR	684.38	1 PC	<i>B1</i> 684.38	—
2 REAR RH DOOR FRAME STICKER	60.15	1 PC	<i>M</i> 60.15	—
3 REAR RH DOOR PROTECTOR	79.80	1 PC	<i>B1</i> 79.80	—
			824.33	
		Less 25%	206.08	618.25
Labour				
4 PANEL BEATING	280.00	1 LA	280.00	<i>22d</i>
5 REMOVE & REFIX REAR RH DOOR GLASS AND CHECK CENTRE LOCKING & POWER MIRROR	60.00	1 LA	60.00	✓
6 PUTTY & RESPRAY	280.00	1 LA	280.00	<i>25d</i>
			620.00	620.00
		Total		S\$ 1,238.25
		Add GST @ 7%		86.68
		Total Amount Payable		S\$ 1,324.93

For Cheng Hoe Motor Pte Ltd

[Signature]

 AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18021440/Ksd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-01-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 7066Y	Veh. Inspected	SJM 7054L
Policy No.		Coverage (\$)	0.00
Claim No.	D18008409MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	27/11/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA VIOS (A)	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MR053HY9305098444	Colour	METALLIC BLACK
Odometer	191548	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S DOOR. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/10/2018	Inspection Date	10/12/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 7054L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR RH DOOR	BENT	684.38	684.38
1	REAR RH DOOR FRAME STICKER	NECESSARY	60.15	60.15
1	REAR RH DOOR PROTECTOR	BENT	79.80	79.80
	LESS 25% DISCOUNT		-206.08	-206.08
			618.25	618.25
LABOUR				
	PANEL BEATING.		280.00	220.00
	REMOVE & REFIX REAR RH DOOR GLASS AND CHECK CENTRE LOCKING & POWER MIRROR.		60.00	60.00
	PUTTY & RESPRAY.		280.00	250.00
			620.00	530.00
GRAND TOTAL			1,238.25	1,148.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				900.00

Report Ref No. CS/FC118021440/Ksd3n2

MARKET VALUE: \$7,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$5,107.00=NETT VALUE: \$1,893.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.