

LKK

INS. CASE OWNER:

Clara

CC 4 / FWD1802

1475, A2639

LKK
IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

26/11/18

Date / Time:

27/11/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SG8 9304E

Name of Insured:

Muan Jin Teik Weng

Insured Tel No.:

HP:

8300006

Excess Sec II :\$5

D.O.A.:

26/11/18

Is driver the owner?

(YES) / NO

Nature of Accident:

Claim No.:

1201800016429

Policy No.:

PWP0017-0005237-01

Make / Model:

Toyota

Place of Accident:

SHP RD IF TOA TAYEH LOR 2

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SUD 7154

INSRS:
WSP:
Tel:
Liability:
RMKS:mg
solutionINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time		STAGE	DATE / PIC
27/11/18	SUD 7154-X	Non-Reporting 1st (1st)	
		Non-Reporting 1st (2nd)	
		Non-Reporting 1st (Final)	
		Notification 1st (if non-pickup)	
		Call OI	
		After call 1st to OI	
20.12.18	SMR8 WSP Liability Claim	Documentation Check List:	Handler Typist
24/11/19	File pass to typist type report	Notification 1st (if non-pickup)	
20/11/19	Seek mandate via merimen	After call 1st to OI	
20/11/19	Mandate approval via Merimen	Authorisation To Act	
		Release Voucher	
		Final Repair Bill	
		Car Rental Invoice	
		Towing Invoice	
		LTA / GIA	
		Medical Bill	
		PIR	
		Mandate/Reject Instruction	
		LOD	
		Payment Breakdown Form	
		Post-Repair Photos	
		Others	

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	\$5	(days) Reduction:	%
FINAL SETTLEMENT Date/Time:		Confirm with:	
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	37
Repair Cost:	\$5 3852.00	OI RATE ENDED TP.	
Loss of Rental (LOR):	\$5	(days)	
Loss of Use (LOU):	\$5 640.00	(5 80 x 8 days)	
Loss of Income (LOI):	\$5	(5 x days)	
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LO ☐	[Tick only one]	
GIA/LTA Search	\$5 7.45		
Medical:	\$5	1) Claim status: Normal/Reject/Private Settle	
Disbursement:	\$5	2) Report Format:	
Legal Cost:	\$5	3) Survey fee:	
Total:	\$5 4499.45	Global Sum \$5:	
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1:	\$5 4499.45	Name 1:	MG Solution Pte Ltd
Payee 2: (Strike if N.A.)	\$5	Name 2:	
Payee 3: (Strike if N.A.)	\$5	Name 3:	

REF:

ASSIGNMENT

28/12/09

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s: _____

of: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

6

days

Res: _____

Yes or No

Lum Sum: _____

20

%

3 Val: _____

Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLQ72154

Yr Regn: 2009

BC

Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic

CC 1799

Colour: Black

A/C

Insured / Std / NI / NA

Sp. Reading: 241229

T/Radio

Insured / Std / NI / NA

Eng/No: _____

C/No: JHMFD163085203186

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06

mm

R/Bal: 06

mm

L/Bal: 06

mm

L/Bal: 06

mm

D.O.A: _____

D.O.I: 28/11/18

Survey held at: M6 Selection

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/11/09

TP FWD.

Confirm US \$3600.00 with 6 working days.

MV: 22K
 PV: 16.6K
 Net: 5.4K

Net: \$846.32
 69.11

Case/Time: File Pass to?

☐

Prel. Report

FI

☐

Final Report

Case/Time: File Return to?

DI

Add Fee:

☐

Site Insp. IS

☐

Interview IS

☐

Tech. Insp. IS

☐

Workshop IS

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Exemption

1. S-RS 51

2. Phone

3. Other

Report Format:

Lump Sum / I.B.I. IS

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CC4/FWD18021475/Aeb3

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 28-11-2018



Code : FWD

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGJ 5304E	Veh. Inspected	SLQ 7215U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	28/11/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	26/11/2018	Inspection Date	28/11/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: FWD	DATE	: 27/11/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLQ7215U		
MODEL	: HONDA CIVIC 1.8A	Asher	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 26-Nov-18
		TIME	: 16:30HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Dented</i>	1	\$ 868.50	\$ 868.50 693.
2	BOOTLID LOGO	1	\$ 78.00	\$ 78.00 ✓
3	BOOTLID 'CIVIC' EMBLEM	1	\$ 65.00	\$ 65.00 ✓
4	BOOTLID 'I-VTEC' EMBLEM	1	\$ 58.00	\$ 58.00 ✓
5	BOOTLID '1.8' EMBLEM	1	\$ 42.00	\$ 42.00 ✓
6	BOOTLID LOCK <i>Damaged</i>	1	\$ 254.50	\$ 254.50 115
7	BOOTLID LOCK CATCH <i>New</i>	1	\$ 95.50	\$ 95.50 x
8	BOOTLID HINGE <i>New</i>	2	\$ 78.60	\$ 157.20 x.
9	BOOTLID REFLECTOR <i>LH cracked</i>	2	\$ 169.90	\$ 339.80 169.90
10	BOOTLID WEATHERSTRIP <i>lt</i>	1	\$ 148.60	\$ 148.60 -
11	REAR BUMPER <i>Deland</i>	1	\$ 785.00	\$ 785.00 638.
12	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 58.50	\$ 117.00 48.
13	REAR TAIL LAMP <i>LH cracked</i>	2	\$ 458.00	\$ 916.00 320.
14	REAR TAIL LAMP LOWER BRACKET <i>New</i>	2	\$ 36.80	\$ 73.60 x
15	REAR FENDER INNER TRIM <i>New</i>	2	\$ 225.00	\$ 450.00 x
16	REAR END PANEL <i>Dented</i>	1	\$ 540.50	\$ 540.50 355
17	REAR END PANEL TOP GARNISH <i>Deland</i>	1	\$ 88.70	\$ 88.70 ✓
18	REAR FLOOR PANEL <i>Repair</i>	1	\$ 965.00	\$ 965.00 x.

19	REAR FLOOR PANEL TOP BOARD <i>del</i>	1	\$ 138.70	\$ 138.70	✓
20	SPARE TYRE TOOL SPONGE CARRIER <i>new</i>	1	\$ 46.20	\$ 46.20	+
21	REAR EXHAUST CHROME PIPE <i>new</i>	1	\$ 865.00	\$ 865.00	+
22	REAR EXHAUST INSULATOR <i>2 pc</i>	1	\$ 196.80	\$ 196.80	+
23	REAR EXHAUST MOUNTING <i>1 pc</i>	4	\$ 45.20	\$ 180.80	+

2957.90

TOTAL PRICE \$ 7,470.40

2366.32

LESS 20% \$ 1,494.08

SUB TOTAL PRICE \$ 5,976.32

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	30
3	TAILLAMP PANEL SEALANT <i>new</i>	2	\$ 60.00	\$ 120.00	+
4	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	10
5	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
6	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 200.00	\$ 200.00	f
7	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	200

TOTAL \$ 860.00

300.

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	800	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	800	
3	TUFF COAT	\$ 250.00	50	
4	WIRING CHECK	\$ 180.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 180.00	50	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50	
7	TRANSFER BOOTLID MECHANISM	\$ 80.00	60	
8	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x	
9	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	x	
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x	

TOTAL

\$4,810.00

1840

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,836.32
TOTAL LABOUR COST : \$ 4,810.00
TOTAL REPAIR COST : \$ 11,646.32

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian King
L/S 28/11/18

total: 4506.32

L/S 3.6K

OGP

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1457B
Vehicle Details	
Vehicle No.:	SLQ7215U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	28 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	HONDA CIVIC 1.8L 5AT
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	R18A14016703
Chassis No.:	JHMFD163095203186
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$26,585.00
Original Registration Date:	28 Dec 2009
First Registration Date:	28 Dec 2009
Transfer Count:	1
Actual ARF Paid:	\$26,585.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2019
PARF Rebate Amount:	\$14,621.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$18,267.00
COE Rebate Amount:	\$1,940.00
Total Rebate Amount:	\$16,561.00

The information contained herein is correct as at 28 Nov 2018

OK



Posted: 13-Nov-2018 Tags: 2008 Honda Civic, 2008 honda civic, Honda Civic, honda civic, Honda Civic, civic, Used Honda



Honda Civic 1.8A VTI-S \$16,800 N/A 24-Mar-2009 1,799 cc - Sedan Available

4 Months To Be Driven, Drive And Get Back \$13708 PARF Value And \$3000 Body Value At End Of COE=\$16708, Total=\$16800 Selling Price) Trade In, 1 Owner, Cheapest And Best Price In Town, An Option For 10 ...

Posted: 28-Nov-2018 Tags: 2008 Honda Civic, 2008 honda civic, Honda Civic, honda civic, Honda Civic, civic, Used Honda



Honda Civic 1.8A VTI-S \$18,800 N/A 27-Mar-2009 1,799 cc - Sedan Available

Only 1 Owner! Affordable Down Payment At \$6K Plus Only! High PARF Value! Extended Warranty And Professional Evaluation Available! A Stylish Sedan That You Must Not Miss! Buy It From Us With A Peace Of...

Dickson Automobile

Posted: 13-Nov-2018 Tags: 2008 Honda Civic, 2008 honda civic, Honda Civic, honda civic, Honda Civic, civic, Used Honda



Honda Civic 1.8A \$19,500 \$9,720 /yr 10-Jun-2009 1,799 cc 164,459 km Sedan Available

Low Mileage, Factory Fitted Sound System, Paddle Shift, Multi Function Steering, Reverse Sensor, New Sports Rims And Tyre, Leather Seats, With Road Tax Till 9/6/2019, No Repairs Needed. When COE End G...

Posted: 10-Nov-2018 Tags: 2008 Honda Civic, 2008 honda civic, Honda Civic, honda civic, Honda Civic, civic, Used Honda



Auction your Car to 500+ Dealers

Get a Bid Price ready in 1 hour with sgCarMart Quotz - Singapore's most efficient bidding system with a network of 500+ Dealers. Get paid immediately with FAST iBanking and a flexible 2-week handover. Highest Price Guaranteed, or get \$100 cash from us.

Find out more!



Honda Civic 1.8A VTI-S \$20,999 \$12,570 /yr 16-Jul-2009 1,799 cc - Sedan Available

\$0K Down Payment, Monthly Installment \$1400K New Paintwork, Pristine Condition. Very Suitable For Short Term Drive With An Option For COE Renewal.

Posted: 30-Nov-2018 Tags: 2008 Honda Civic, 2008 honda civic, Honda Civic, honda civic, Honda Civic, civic, Used Honda



Honda Civic 1.8A VTI-S \$23,800 \$10,760 /yr 20-Nov-2009 1,799 cc - Sedan Available

Low Down Payment. Low Interest Rate. 1 Year Warranty. In-house Financing Options Available. Buy With A Peace Of Mind. Low Mileage. 100% Genuine Mileage. Well Maintained. Immaculate Condition. All Trad...

GOwheeler Pte Ltd

Posted: 20-Nov-2018 Tags: 2008 Honda Civic, 2008 honda civic, Honda Civic, honda civic, Honda Civic, civic, Used Honda



Honda Civic 1.8A \$22,800 \$8,260 /yr 07-Dec-2009 1,799 cc - Sedan Available

Affordable And Reasonable Price! Well Maintained And Regularly Serviced Interior Leather Well Maintained!

Posted: 23-Nov-2018 Tags: 2008 Honda Civic, 2008 honda civic, Honda Civic, honda civic, Honda Civic, civic, Used Honda



Honda Civic 1.8A \$22,300 \$8,800 /yr 15-Dec-2009 1,799 cc 160,000 km Sedan Available

Well Maintain By Owner, Accident Free, No Repair Needed, High Trade In And Loan Available, Hurry.

Posted: 24-Nov-2018 Tags: 2008 Honda Civic, 2008 honda civic, Honda Civic, honda civic, Honda Civic, civic, Used Honda



Honda Civic 1.8A VTI-S \$21,800 \$9,200 /yr 21-Dec-2009 1,799 cc 111,211 km Sedan Available

2 Owners Facelift Unit With Regular Maintenance Done And Well Taken Care By Ex Owner As Well, Grey With Black Leather Upholstery, Major Servicing Carried Out By Owner At 98k Km, Owned And Drive Worrie...

Posted: 26-Nov-2018 Tags: 2008 Honda Civic, 2008 honda civic, Honda Civic, honda civic, Honda Civic, civic, Used Honda



Honda Civic 1.8A VTI-S \$26,000 \$10,840 /yr 26-Dec-2009 1,799 cc 138,000 km Sedan Available

Best Buy! Quality Pre-Owned At A Affordable And Reasonable Price! Well Maintained And Regularly Serviced! Straight Chassis. No Leaks! Interior Leather Well Maintained!

Posted: 29-Sep-2018 Tags: 2008 Honda Civic, 2008 honda civic, Honda Civic, honda civic, Honda Civic, civic, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

WORKSHEET REPORT

Compare

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

Nivitha (LKK Auto)

From: motorclaims.sg@fwd.com
Sent: Tuesday, 27 November 2018 3:00 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com; AsherSng@lkkauto.com
Cc: clara.li@fwd.com
Subject: FW: SLQ7215U- (Pre-Inspection) ;Your Ref: SGJ5304E -DOA 26/11/2018
Attachments: SLQ7215U-(PRE-INSPECTION); YOUR REF SGJ5304E.pdf

3.45pm @ 27/11/18
Ms. Hong
vehicle in

Hi LKK team,

Please refer to the email below and liaise with TP repairer for survey arrangement.

Attached is the repair estimate, TP GIA report.


Please create the case in Merimen.

Thank you.

Kind Regards
Clara Li
Senior Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722
E clara.li@fwd.com
W fwd.com.sg



From: MG Solution [mailto:mg3solution@gmail.com]
Sent: Tuesday, 27 November, 2018 12:39 PM
To: Motor Claims SG - SG Common; FWD -Beliana
Subject: SLQ7215U- (Pre-Inspection) ;Your Ref: SGJ5304E -DOA 26/11/2018

Dear person in charge,

Please refer to attach file and arrange for pre-inspection.

we prefer our single joint expert as below:

ADRIAN LING WAI PING	LKK AUTO CONSULTANTS PTE LTD
-------------------------	------------------------------

Thanks,

Best Regards,

MS hong

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4(South Wing)

#02-03B Vicom Inspection Centre

Singapore 415933

Tel : 6744 4165

Fax : 6744 4604

Co. Reg. No. 201427944N

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

View Received Message

This mail is associated with :

***SLQ7215U (1201800016429)**
[SGJ5304E]

TP
GOH BENG TECK
Nov 26 2018 4:00PM
[Huan Jin Teck Philip]
MG Solution Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 21/08/2019 19:02 PM,
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4499.45) - SLQ7215U - Claim Handler: Clara Li Zi Rong

Approved:4499.45,

DOCUMENTS SUMMARY

There are no documents.



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 201427944N)

Date : 26/04/2019
Your Ref : SGJ5304E
To : FWD INSURANCE PTE LTD
Attn : Motor Claims Department

Dear Sir/Mdm,

**RE: ACCIDENT INVOLVING VEHICLE SLQ7215U & SGJ5304E ON 26/11/2018 AT
SLIP ROAD FROM LORONG 2 TAO PAYOH TOWARDS PIE (CHANGI).**

We refer to the above matter.

Attached copies of the following for your kind perusal:

- 1) Proforma Bill No.198135 @ S\$3,852.00 (Inclusive Of 7% GST)
- 2) Loss of Use @ S\$1,920.00 (8 Days x S\$240)
- 3) LTA Search @ S\$7.45
- 4) Authorisation to Act
- 5) GIA Report

Hope the above is in order and kindly let us have your confirmation soon.

Tax invoice will be issue upon amount finalized.

Thank You.

Yours faithfully,



Sharon Chia

HP: 9188 6931

E-mail: mg3solution@gmail.com

LETTER OF AUTHORITY

Name : Goh Beng Teck
Address : BLK 272 PASIR RIS STREET 21
#01-484 SINGAPORE 510272
Contact No : _____
TO: FWD Insurance Pte Ltd

Dear Sirs,

ACCIDENT INVOLVING SLQ 72154 AND SKJ 5304E ON 26/11/2018
AT/ALONG Slip Road from Lorong 2 Toa Payoh towards PIE (Changi)

I/We, Goh Beng Teck, am/are the registered owner of
motor car no. SLQ 72154

Please note that I have assigned all compensations monies due to me/us in the above said accident
to **M/S MG SOLUTION PTE LTD.**

I/We, hereby authorize you to release all compensation monies pertaining to the above-mentioned
accident to **M/S MG SOLUTION PTE LTD** and forward your settlement cheque to **M/S MG SOLUTION
PTE LTD** whom I had authorized to collect the said compensation monies.

Thank you



Signature of Claimant



Witness By

Provided always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect my further claim for general and special damages for my personal injuries sustained in the same accident.

RELEASE

Claim Reference:	1201800016429
Surveyor's Reference:	CC4/FWD18021475/Awb3
TP Reference:	SLQ 7215U

We, MG Solution Pte Ltd ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle SLQ 7215U ("Vehicle") to accept the sum of \$ 4,499.45, being the amount claimed for \$3852.00 (repair costs), \$640.00 (loss of rental use), NIL (loss of income), \$7.45 (search fees) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on 26/11/2018 (date of accident) at / along SLIP RD OF TOA PAYOH LOR 2 TWDS PIE (location) involving vehicle no/s. SGJ 5304E and SLQ 7215U.

This is pursuant to the inspection conducted on 28/11/2018 (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of SLQ 7215U be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this 03 day of 01 2019

CLAIMANT



[Signed by the "Workshop" with Co. Stamp]

For and on behalf of the "Claimant"



[FWD's appointed surveyor with Co. Stamp]

For and on behalf of FWD Singapore Pte. Ltd.



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 20-1427944-N)

TAX INVOICE

Bill To:

FWD INSURANCE PTE LTD

6 TEMASEK BOULEVARD

#18-01 SUNTEC TOWER FOUR

SINGAPORE 038986

INVOICE No : TI 199239

PB No : 198135

Date : 03-September-2019

ATTN : MOTOR CLAIMS DEPARTMENT

Vehicle Number : SLQ 7215U

QTY	DESCRIPTION	AMOUNT
1	To carried out accident repair as per surveyor's recommendation (Lump Sum)	\$ 3,600.00
BEFORE GST		3,600.00
7% GST		252.00
TOTAL		\$ 3,852.00

Cheque should be made payable to MG Solution Pte Ltd

Co's stamp & Authorised Signature

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 27 Nov 2018 / 09:47:36

Receipt Date/Time : 27 Nov 2018 / 09:47:35

Tax Invoice/Receipt

Receipt No. : ITNET-00000-181127-000494

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - SGJ5304E As at 26 Nov 2018/16:30:00 Insurance Co: FWD SINGAPORE PTE. LTD.			
1	Insurance Enquiry - SGJ5304E Enquiry Fee 20181127094646724824	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	20181127094654897 Direct Debit: eNETS Debit (Internet Banking)			7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Nov 2018 Edit Reg		27 Nov 2018 00:00 Edit Adj Rpt	\$43,600.00 Edit Estimates	\$43,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Huan Jin Teck Philip, ID: S6911400H								
Main Claimant:	GOH BENG TECK, ID: S1801457B								
Vehicle Reg. No.:	SLQ7215U	Date of Loss:	26/11/2018 16:00 - :59 [106 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201800016429	Policy/Cover Note No.:	PNPV2017-00005237-01 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	SGJ5304E	Policy No. (Claimant):	5096669792						
		Excess:							
Repairer:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre, 415933 Kaki Bukit - Tel: 91886931								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 07/12/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
FWD_SG (21/08/2019): Alert - Adj Mandate Approved (\$4499.45) - SLQ7215U - Claim Handler: Clara Li Zi...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ7215U (1201800016429)
[SGJ5304E]

TP
GOH BENG TECK
Nov 26 2018 4:00PM
[Huan Jin Teck Philip]
MG Solution Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/04/19 00:09	General View	1	Load JPG	☒
2	10/04/19 00:09	General View	1	Load JPG	☒
3	10/04/19 00:09	General View	1	Load JPG	☒
4	10/04/19 00:09	General View	1	Load JPG	☒
5	10/04/19 00:09	General View	1	Load JPG	☒
6	10/04/19 00:09	General View	1	Load JPG	☒
7	10/04/19 00:09	General View	1	Load JPG	☒
8	10/04/19 00:09	General View	1	Load JPG	☒
9	10/04/19 00:09	General View	1	Load JPG	☒
10	10/04/19 00:09	General View	1	Load JPG	☒
11	10/04/19 00:09	General View	1	Load JPG	☒
12	10/04/19 00:09	General View	1	Load JPG	☒
13	10/04/19 00:09	General View	1	Load JPG	☒
14	10/04/19 00:09	General View	1	Load JPG	☒
15	10/04/19 00:09	General View	1	Load JPG	☒
16	10/04/19 00:09	General View	1	Load JPG	☒
17	10/04/19 00:09	General View	1	Load JPG	☒
18	10/04/19 00:09	General View	1	Load JPG	☒
19	10/04/19 00:09	General View	1	Load JPG	☒
20	10/04/19 00:09	General View	1	Load JPG	☒
21	10/04/19 00:09	General View	1	Load JPG	☒
22	10/04/19 00:09	General View	1	Load JPG	☒
23	10/04/19 00:09	General View	1	Load JPG	☒
24	10/04/19 00:09	General View	1	Load JPG	☒
25	10/04/19 00:09	General View	1	Load JPG	☒
26	10/04/19 00:09	General View	1	Load JPG	☒
27	10/04/19 00:09	General View	1	Load JPG	☒
28	10/04/19 00:09	General View	1	Load JPG	☒
29	10/04/19 00:09	Reinspection Photo	1	Load JPG	☒
30	10/04/19 00:09	Reinspection Photo	1	Load JPG	☒
31	10/04/19 00:09	Reinspection Photo	1	Load JPG	☒
32	10/04/19 00:09	Reinspection Photo	1	Load JPG	☒
33	10/04/19 00:09	Reinspection Photo	1	Load JPG	☒
34	10/04/19 00:09	Reinspection Photo	1	Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	10/04/19 00:09	Reinspection Photo	 Load JPG	☒
36	10/04/19 00:09	Reinspection Photo	 Load JPG	☒
37	10/04/19 00:09	Reinspection Photo	 Load JPG	☒
38	10/04/19 00:09	Reinspection Photo	 Load JPG	☒
39	10/04/19 00:09	Reinspection Photo	 Load JPG	☒
40	10/04/19 00:09	Reinspection Photo	 Load JPG	☒
41	10/04/19 00:09	Reinspection Photo	 Load JPG	☒
42	10/04/19 00:09	Reinspection Photo	 Load JPG	☒
43	10/04/19 00:09	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/11/18 16:09	EMAIL FROM FWD DD 27112018	 Load PDF	
2	28/11/18 16:09	FWD EMAIL TO OI DD 27112018	 Load PDF	
3	28/11/18 16:09	NOTICE & GIA REPORT	 Load PDF	
4	29/07/19 16:17	LTA SEARCH	 Load PDF	
5	29/07/19 16:17	LOD	 Load PDF	
6	05/09/19 12:12	WORKSHOP INVOICE	 Load PDF	
7	05/09/19 12:12	AUTHORISATION TO ACT FORM	 Load PDF	
8	05/09/19 12:12	Release Voucher	 Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	28/11/18 16:42	OI GIA Report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGJ5304E (Insd veh)	Model:	HONDA CIVIC 1.8 L 5AT (A)
	SLQ7215U (TP veh)		
Date of Accident:	26/11/2018		

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	: \$	12,461.56		
Final Repair Cost	: \$	3,852.00		
Loss of Use	: \$	640.00		8.00 days at \$80.00 per day
Rental (if any)	: \$	0.00		days
LTA / GIA Search Fee	: \$	7.45		
Others:	: \$	0.00		
	: \$			
Final Settlement Sum	: \$	4,499.45		

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	MG Solution Pte Ltd	: \$	4,499.45
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

05 Sep
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD18021475/AWB3Q2

Date: 05/09/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00005237-01

Claimant Vehicle No: SLQ7215U Insured Vehicle No: SGJ5304E

Date of Loss: 26/11/2018 Nature of Claim: TP Claim No: 1201800016429

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ7215U
 Make & Model: HONDA CIVIC, 1.8 L 5AT (A) Engine No: R18A14016703
 Reg. Date: 28/12/2009 (Man. Year: 2009) Chassis No: JHMFD16309S203186
 Colour: Black Odometer: 241229 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,836.32	2,666.32	4,170.00	61.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,810.00	1,840.00	2,970.00	61.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,646.32	4,506.32	7,140.00	61.31
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	11,646.32	3,600.00	8,046.32	69.09
+ GST 7.00/7.00% (S\$)	815.24	252.00	563.24	69.09
Nett Amount (S\$)	12,461.56	3,852.00	8,609.56	69.09
+ Loss of Use (8.0 x S\$80.00/day) (S\$)		640.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,499.45		

INSPECTION

Date of Assignment: 27/11/2018

Date Inspected: 28/11/2018 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B, VICOM

Inspection Centre
Singapore 415933

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2019)
Parts: 143	HONDA CIVIC 1.8 L 5AT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLQ7215U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	868.50 FL	*693.00 FL
2	1		*BOOTLID LOGO	Necessary	78.00 FL	*78.00 FL
3	1		*BOOTLID CIVIC EMBLEM	Necessary	65.00 FL	*65.00 FL
4	1		*BOOTLID I-VTEC EMBLEM	Necessary	58.00 FL	*58.00 FL
5	1		*BOOTLID 1.8 EMBLEM	Necessary	42.00 FL	*42.00 FL
6	1		*BOOTLID LOCK	Damaged	254.50 FL	*115.00 FL
7	1		*BOOTLID LOCK CATCH	Not Necessary	95.50 FL	*- FL
8	2		*BOOTLID HINGE	Not Necessary	157.20 FL	*- FL
9	1		*BOOTLID REFLECTOR	N/S Cracked	339.80 FL	*169.90 FL
10	1		*BOOTLID WEATHERSTRIP	Cut	148.60 FL	*148.60 FL
11	1		*REAR BUMPER	Deformed	785.00 FL	*638.00 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	117.00 FL	*48.00 FL
13	1		*REAR TAIL LAMP	N/S Cracked	916.00 FL	*320.00 FL
14	2		*REAR TAIL LAMP LOWER BRACKET	Not Necessary	73.60 FL	*- FL
15	2		*REAR FENDER INNER TRIM	Not Necessary	450.00 FL	*- FL
16	1		*REAR END PANEL	Dented	540.50 FL	*355.00 FL
17	1		*REAR END PANEL TOP GARNISH	Deformed	88.70 FL	*88.70 FL
18	1		*REAR FLOOR PANEL	Repair	965.00 FL	*- FL
19	1		*REAR FLOOR PANEL TOP BOARD	Deformed	138.70 FL	*138.70 FL
20	1		*SPARE TYRE TOOLS SPONGE CARRIER	Not Necessary	46.20 FL	*- FL
21	1		*REAR EXHAUST CHROME PIPE	Not Necessary	865.00 FL	*- FL
22	1		*REAR EXHAUST INSULATOR	Not Necessary	196.80 FL	*- FL
23	4		*REAR EXHAUST MOUNTING	Not Necessary	180.80 FL	*- FL
24	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
25	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
26	2		*TAILLAMP PANEL SEALANT	Not Necessary	120.00 FS	*- FS
27	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	60.00 FS	*10.00 FS
28	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
29	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	200.00 FS	*- FS
30	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,330.40	3,257.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,494.08	591.58
Total Parts (\$\$)	6,836.32	2,666.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,000.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	800.00
3	TUFF COAT	New	250.00	50.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	180.00	50.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	TRANSFER BOOTLID MECHANISM	New	80.00	60.00
8	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
9	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
10	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			4,810.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >