

ASS. REC. BY:

REF: CS/FCI18021567/ GS d3ⁿ²

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time: 4:03pm @ 28/11/18

Estimated Cost:

Bill to:

OD (TV) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 9675C

Insured:

SHA 3256J

at Workshop m/s

Gold Bell Engineering

Tel:

9755 7336

of

10 Tuas Ave 18

Policy No:

Claim No:

D18008428MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/11/2018

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

9:37am @ 29/11/18

Person Contacted:

Jewei

Vehicle:

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

GBH 9675C - X

SHA 3256J - CS/FCI16023775/R/wh 352

DOA: 11/12/16

03/12/18

@ 13:46 p.m. revised PA to Karen Tan via email.

Signature

XRL

REF: FCI

B5400A

ASSIGNMENT

From:

Date: 30/11/2018

Veh No:

6BH 9675C Yr Regn: 16 Nov 2018

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

GBH 9675C

Make:

Fiat Fiorino c.c. 1248

at Workshop m/s

GodBell

Colour:

Brown

A/C: Insured / Std / NI / NA

of

48 Changi south street 1

Sp. Reading

757

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

2FA 2250000 6H33301

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

3:30pm @ owner waiting
Jewei @ 9755 7336

Modi: Nil / S/Rim / STD / A/Rim or

(Policy Condition)


Tyre Size:

F:

185/65R15

R:

11

Remark: The veh had commenced its
repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PUS / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

9

mm

R/Bal.

9

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

9

mm

L/Bal.

9

mm

Est. Repairs:

5

days

Res.: Yes or No

D.O.A.

D.O.I.

30-11-18

Lum Sum:

%

3 Val.: Yes or No

Survey held at

W/S

3:30pm

CA / REV / REP. / 24 HRS (DS)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4656.48

22/04/19

Confirmed P/P @ 4,656.48
(\$2,821.48 Red - 38%)

@ 5 days with X60

RECEIVED 26 APR 2019.

22/4/2019

Date/Time, File Pass to?


26/04/19

1)

Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

150

Transportation:

50

) \$ + RS. SI

50

) Photos:

35

) Other:

TOTAL

285

Report Format:

Lump Sum / I.B.I: (\$) 4,656.48 P/P

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008428MFSH

Date: 03 December 2018

Our Ref: CS/FCI18021567/Gsd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBH 9675C .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/11/2018 at the premises of M/s Goldbell Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 7,477.96 .
Revised Estimate Amount	: S\$ 4,551.04 .
"Check" Items Amount	: S\$ 706.60 .
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 5 Days

Yours faithfully,
Xing Guo Qiang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	27-11-2018	Our Ref No. D18008428MFSH
Accident Date	25-11-2018	Claim Type. Third Party
Insured Vehicle	SHA3256J	Third Party Vehicle. GBH9675C
Survey Location	10 TUAS AVENUE 18	
Contact Person.	LI LEWEI	
Contact No.	68640637/ 97557336	Fax No. 68630425
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	GOLDBELL ENGINEERING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Brian Eng Kwok Long <EngKwokLong@goldbell.com.sg>
Sent: Thursday, 25 April 2019 11:12 AM
To: Shirley Hiew (LKK Auto); Guo Qiang (LKKAuto); Cecilia Chong (LKK Auto)
Cc: Ashlyn Chng; William Oh Soon Lee; Ramesh
Subject: Re: Finalise - GBH 9675 C

Dear Shirley,

We confirm finalise @ \$ 4,656.48 @ 5 days of repairs before GST.

Thanks and Best Regards



Brian Eng Kwok Long | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6864 0637 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 9755 7336 | Web: <http://www.goldbell.com.sg>



From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 25 April 2019 11:08:45 AM
To: Brian Eng Kwok Long; Guo Qiang (LKKAuto); Cecilia Chong (LKK Auto)
Cc: Ashlyn Chng; William Oh Soon Lee; Ramesh
Subject: RE: Finalise - GBH 9675 C

Dear Brian,

Please re-confirm final fig \$ 4,656.48 @ 5 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Brian Eng Kwok Long [mailto:EngKwokLong@goldbell.com.sg]

Sent: Thursday, 25 April 2019 10:45 AM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Guo Qiang (LKKAuto) <guoqiang@lkkauto.com>; Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>

Cc: Ashlyn Chng <AshlynChng@goldbell.com.sg>; William Oh Soon Lee <WilliamOhSL@goldbell.com.sg>; Ramesh <Ramesh@goldbell.com.sg>

Subject: Re: Finalise - GBH 9675 C

Dear Shirley & Guo Qiang,

Please refer to the attached for GBE8697L survey by LKK at Year 2016, The price for sticker 70km/H sticker is already \$20.

While the reverse sensor assy at year 2016 is \$250, now already 3 year at the price \$280 is fair enough.

We sincerely hope the above explanation.

Can we finalise the amount @ \$4686.48?

Thanks and Best Regards,

Brian Eng Kwok Long | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6864 0637 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 9755 7336 | Web: <http://www.goldbell.com.sg>

From: Brian Eng Kwok Long
Sent: Wednesday, 24 April 2019 6:49:26 PM
To: Shirley Hiew (LKK Auto); Guo Qiang (LKKAuto); Cecilia Chong (LKK Auto)
Cc: Ashlyn Chng; William Oh Soon Lee; Ramesh
Subject: Re: Finalise - GBH 9675 C


Dear Shirley,

It is our standard pricing for number plate as \$20 and reverse sensor assy for \$280.

Can we finalise the amount @ \$4686.48?


We sincerely hope the above explanation will clarify your queries.

Thanks and Best Regards,



Brian Eng Kwok Long | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6864 0637 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 9755 7336 | Web: <http://www.goldbell.com.sg>



From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 23 April 2019 10:54:04 AM
To: Brian Eng Kwok Long; Ramesh; Guo Qiang (LKKAuto); Cecilia Chong (LKK Auto)
Cc: Ashlyn Chng; William Oh Soon Lee
Subject: RE: Finalise - GBH 9675 C

Dear Brian,

Please re-confirm final fig \$ 4,596.48 @ 5 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Brian Eng Kwok Long [mailto:EngKwokLong@goldbell.com.sg]

Sent: Monday, 22 April 2019 9:33 AM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Ramesh <Ramesh@goldbell.com.sg>; Guo Qiang (LKKAuto) <guoqiang@lkkauto.com>; Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>


Cc: Ashlyn Chng <AshlynChng@goldbell.com.sg>; William Oh Soon Lee <WilliamOhSL@goldbell.com.sg>

Subject: Re: Finalise - GBH 9675 C

Dear Shirley,


Kindly refer to the attached.

Thanks and Best Regards



Brian Eng Kwok Long | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6864 0637 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 9755 7336 | Web: <http://www.goldbell.com.sg>



From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent: Monday, 22 April 2019 9:07:58 AM

To: Ramesh; Guo Qiang (LKKAuto); Cecilia Chong (LKK Auto); Guo Qiang (LKKAuto)

Cc: Ashlyn Chng; Brian Eng Kwok Long; William Oh Soon Lee

Subject: RE: Finalise - GBH 9675 C

Hi Ramesh,

Kindly send us before paint photo.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ramesh [mailto:Ramesh@goldbell.com.sg]

Sent: Thursday, 18 April 2019 2:23 PM

To: guoqiang@lkkauto.com; 'thinthin@lkkauto.com' <thinthin@lkkauto.com>; 'Guo Qiang (LKKAuto)' <GuoQiang@lkkauto.com>

Cc: Ashlyn Chng <AshlynChng@goldbell.com.sg>; Brian Eng Kwok Long <EngKwokLong@goldbell.com.sg>; William Oh Soon Lee <WilliamOhSL@goldbell.com.sg>

Subject: RE: Finalise - GBH 9675 C

Importance: High

Hi Guo Qiang,

Up to today you did not reply our email.

Monday, March 18, 2019 8:05 PM

Wednesday, 6 March 2019 3:16 PM

Monday, 25 February 2019 7:45 PM

Monday, 18 February, 2:41 pm

This is a Third Party claim against First Capital Insurance,
As such we engage your surveyor service through Third Party Insurance as per 2016 NIMA Protocol.

Unfortunately, we did not receive any reply on your repair finalization confirmed amount since Feb 2019.
We hope to receive your reply soonest by **22 Apr 2019 (Monday)**.

Then after we shall seek payment directly to First Capital Insurance,
Hence you may answer directly to Insurer on your failure.
(Attached above is our intended "Letter of Demand" to Insurer - FYI)

Regards.

 **Ramesh | Goldbell Engineering Pte Ltd**
Senior Executive, Motor Claims

DID: +65 6864 0695 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 8157 8014 | Web: <http://www.goldbell.com.sg>

From: Brian Eng Kwok Long

Sent: Monday, March 18, 2019 8:05 PM

To: guoqiang@lkkauto.com

Cc: Ramesh <Ramesh@goldbell.com.sg>; Ashlyn Chng <AshlynChng@goldbell.com.sg>

Subject: Finalise - GBH 9675 C

Dear Guo Qiang,

Kindly refer to the attached above.

Can we finalise the amount @ \$4686.48?

Thanks & Best Regards,

Brian Eng Kwok Long | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6864 0637 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 9755 7336 | Web: <http://www.goldbell.com.sg>

From: Brian Eng Kwok Long
Sent: Wednesday, 6 March 2019 3:16 PM
To: guoqiang@lkkauto.com
Cc: Ramesh; Ashlyn Chng
Subject: Finalise - GBH 9675 C

Dear Guo Qiang,

Kindly refer to the attached above.

Can we finalise the amount @ \$4686.48?

Thanks & Best Regards,



Brian Eng Kwok Long | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6864 0637 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 9755 7336 | Web: <http://www.goldbell.com.sg>



From: Brian Eng Kwok Long
Sent: Monday, 25 February 2019 7:45 PM
To: guoqiang@lkkauto.com
Cc: Ashlyn Chng; Ramesh
Subject: Finalise - GBH 9675 C

Dear Guo Qiang,

Kindly refer to the attached above.

Can we finalise the amount @ \$4686.48?

Thanks & Best Regards,

 Brian Eng Kwok Long | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6864 0637 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 9755 7336 | Web: <http://www.goldbell.com.sg>





From: Brian Eng Kwok Long
Sent: Monday, 18 February, 2:41 pm
Subject: Finalise - GBH 9675 C
To: guoqiang@lkkauto.com
Cc: Ramesh, Ashlyn Chng

Dear Guo Qiang,

Kindly refer to the attached above.

Can we finalise the amount @ \$4686.48?

Thanks & Best Regards,
Brian Eng Kwok Long

|
Goldbell Engineering Pte Ltd

Customer Service Advisor, Motor Claims

DID:

+65 6864 0637

| Tel:

+65 6861 0007

| Fax:

+65 6863 0425

|

Mobile:

+65 9755 7336

| Web:

<http://www.goldbell.com.sg>

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 3 December 2018 1:46 PM
To: 'Karen Tan'; 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D18008428MFSH/1
Attachments: GBH 9675C - Preli Advise.pdf

Dear Karen,

Enclosed preliminary revised of vehicle GBH 9675C.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 29 November 2018 9:39 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008428MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 28 November 2018 4:03 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008428MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	5400A
Vehicle Details	
Vehicle No.:	GBH9675C
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Dec 2018
Vehicle Make:	FIAT
Vehicle Model:	FIORINO CARGO 1.3MTA E6 GLAZED
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	225A20006494013
Chassis No.:	ZFA22500006H33301
Maximum Power Output:	-
Open Market Value:	\$17,155.00
Original Registration Date:	16 Nov 2018
First Registration Date:	16 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$858.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Nov 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$28,501.00
COE Rebate Amount:	\$28,358.00
Total Rebate Amount:	\$28,358.00

The information contained herein is correct as at 03 Dec 2018

OK



ORIGINAL COPY

MC No A 0006148

MOTOR INSURANCE COVER NOTE

Whereas the applicant named in the Schedule below having proposed for insurance in respect of the Motor Vehicle described in the Schedule below the risk is hereby HELD COVERED in the terms of the Company's usual form of Policy applicable thereto for the period as stated below unless the cover be terminated by the Company by notice in writing in which case the insurance thereupon will cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

Name of Insured: A.P. MINI MART

DESCRIPTION OF MOTOR VEHICLE

Type of Vehicle:

Class Description: COMMERCIAL VEHICLE

Registered Number: TO BE ADVISED

Make: FIAT

Year of Registration: 2018

Model: FIORINO 1.3 MJ

Seating Capacity: 2

Chassis Number: ZFA225000064B3301

Engine Capacity/Max Laden Weight: 1700 KG (0.49 tonnes) Engine Number: 25A20006414013

Estimated Value: Market Value

COVERAGE OF MOTOR POLICY

COMPREHENSIVE

PERIOD OF INSURANCE

16/11/2018 to 15/11/2019

VALIDITY PERIOD OF COVER NOTE

VALID FOR 30 DAYS FROM DATE OF ISSUE

HIRE-PURCHASE OWNER

GOLOBELL FINANCIAL SERVICES PTE LTD

I/We hereby certify that this Cover Note is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and the The Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Republic of Singapore).



Signature of the Intermediary


Date of Issue:

Billing A/C: B3675D2

Signed For And on Behalf Of

Authorised Person

Allied World Assurance Company, Ltd





GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3678 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No.: 168003963G

Page 1 / 3

ESTIMATE

Date	: 26/11/2018	Reg No	: GBH9675C
To	: MS FIRST CAPITAL INSURANCE LIMITED	Model	: 225.2LR.1 (444 BRONZE)
Attn.	:	Chassis No	: ZFA22500006H33301
Office / Mobile	:	Engine No	: 225A20006494013
Email Address	:	Quotation No.	: 76638
		Ref. No.	: GBE/SVC/SALES-4743/181126
From	: MOTORVIVA PTE LTD	D.O.A.	: 25/11/2018
Attn.	: LILEWEI	Policy No.	: A0006148
Office / Mobile	: +65 6864 0637	Claim Type	: TP CLAIM - MSFCIS
Email / Fax No.	: LiLewei@goldbell.com.sg	Workshop	: 29 TANJONG PENJURU

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1	735666169	BUMPER, RR / <i>Re</i>	1	510.75	-10	459.68	459.68 ✓
2	735482370	TOW HOOK COVER X <i>NN</i>	1	53.82	-10	48.44	48.44 ✓
3	1355231080	REAR BUMPER SUPPORT <i>BT</i>	1	150.48	-10	135.43	135.43 ✓
4	1362666080	REAR BUMPER BRACKET LH X <i>NN</i>	1	69.22	-10	62.30	62.30 ✓
5	1362665080	REAR BUMPER BRACKET RH X <i>NN</i>	1	69.22	-10	62.30	62.30 ✓
6	1389334080	REAR DOOR - LHS <i>buc</i>	1	1,491.31	-10	1,342.18	1,342.18 ✓
7	1355051080	TAILGATE HINGE LH X <i>BT</i>	1	65.77	-10	59.19	59.19 ✓
8	1388875080	DOOR CHECK - REAR X <i>NN</i>	1	99.51	-10	89.56	89.56 ✓
9	735500163	DOOR INNER TRIM LHS X <i>NN</i>	1	144.48	-10	130.03	130.03 ✓
10	1389751080	SEALING GASKET -WEATHERSTIP X <i>NN</i>	1	420.94	-10	378.85	378.85 ✓
PARTS TOTAL :						2,767.96	

SPECIAL NETT ITEMS

1	REAR NUMBER PLATE X <i>NN</i>	1	20.00
2	REAR NUMBER PLATE HOLDER X <i>NN</i>	1	20.00
3	SEALANT / <i>Spec</i>	1	40.00 ✓
4	"70 KM/H" STICKER / <i>Spec</i>	1	20.00 ✓
5	REVERSE SENSOR ASSY / <i>ph.</i>	1	280.00 ✓
PARTS TOTAL:			380.00

bizSAFE
STAR



Certificate No: AJA/S/0101242 Certificate No: AJA/S/0101242



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No.: 198303963G

Page 2 / 3

ESTIMATE

Date	: 26/11/2018	Reg No	: GBH9675C
To	: MS FIRST CAPITAL INSURANCE LIMITED	Model	: 225.2LR.1 (444 BRONZE)
Attn.	:	Chassis No	: ZFA22500006H33301
Office / Mobile	:	Engine No	: 225A20006494013
Email Address	:	Quotation No.	: 76638
		Ref. No.	: GBE/SVC/SALES-4743/181126
From	: MOTORVIVA PTE LTD	D.O.A.	: 25/11/2018
Attn.	: LILEWEI	Policy No.	: A0006148
Office / Mobile	: +65 6864 0637	Claim Type	: TP CLAIM - MSFCIS
Email / Fax No.	: LiLewei@goldbell.com.sg	Workshop	: 29 TANJONG PENJURU

LABOUR CHARGES

1	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTIC CHECK	120	180.00	-
2	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC (600)	1200	2400.00	-
3	TO REMOVE AND REFIX DOOR COMPARTMENTS	/	180.00	-
4	TO REMOVE AND REFIX REAR DOOR GLASS	/	120.00	-
5	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC (350)	700	1400.00	-
6	SUNDRIES NEW	30	50.00	-

LABOUR TOTAL :	4,330.00
SUB-TOTAL :	7,477.96
GST @ 7% for \$ 7,477.96	523.46
GRAND TOTAL (S\$) :	8,001.42

5 Days.
part by part
3/12/18

before paint photos.

Guo Qiang - 82880282

30/11/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No.: 198003863G

Page 3 / 3

ESTIMATE

Date	: 26/11/2018	Reg No	: GBH9675C
To	: MS FIRST CAPITAL INSURANCE LIMITED	Model	: 225.2LR.1 (444 BRONZE)
Attn.	:	Chassis No	: ZFA22500006H33301
Office / Mobile	:	Engine No	: 225A20006494013
Email Address	:	Quotation No.	: 76638
		Ref. No.	: GBE/SVC/SALES-4743/181126
From	: MOTORVIVA PTE LTD	D.O.A.	: 25/11/2018
Attn.	: LILEWEI	Policy No.	: A0006148
Office / Mobile	: +65 6864 0637	Claim Type	: TP CLAIM - MSFCIS
Email / Fax No.	: LiLewei@goldbell.com.sg	Workshop	: 29 TANJONG PENJURU

PREPARED BY : LILEWEI

DATE / TIME : _____

SURVEYOR : _____

MOBILE NO : _____

OFFICE FAX NO : _____

EMAIL ADDRESS : _____

EXCESS AMOUNT : _____

REPAIR TYPE : PART-BY-PART / LUMP SUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : _____

REMARKS : _____



MS FIRST CAPITAL INSURANCE LIMITED
6 RAFFLES QUAY #21-00
SINGAPORE 048580
Attn: MOTOR CLAIM DEPT

TAX INVOICE

GST Reg No. : M9-0002514-E
Invoice No. : MXI00026142
Invoice Date. : 28-03-2019
Account No. : C00000247
Quotation No. : 76638
Work Order No. : 701916
Service Centre. : 8 TUAS AVE 18
Agreement No. : MV-3720

PARTICULARS		AMOUNT SGD			
Reg No	: GBH9675C				
Chassis No	: ZFA22500006H33301				
Engine No	: 225A20006494013				
Model No	: 225.2LR.1 (444 BRONZE)				
Mileage	: 905				
SRR No	:				
ACCIDENT REPAIR: GBE/SVC/SALES-4743/181126					
DATE OF ACCIDENT: 25/11/2018					
POLICY NO.: A0006148					
**** TP CLAIM - MSFCIS ****					
ITEM 1: TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTIC CHECK					
ITEM 2: TO REMOVE AND REFIX DAMAGED ARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC					
ITEM 3: TO REMOVE AND REFIX DOOR COMPARTMENTS					
ITEM 4: TO REMOVE AND REFIX REAR DOOR GLASS					
ITEM 5: TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC					
ITEM 6: SUNDRIES					
Description	QTY	U/Price	Disc	Net Price	Ext Price
BUMPER RR	1	459.68	N	459.68	459.68
REAR DOOR LHS	1	1342.18	N	1342.18	1342.18
TAILGATE HINGE LH	1	59.19	N	59.19	59.19
SUPPORT	1	135.43	N	135.43	135.43
SEALANT	1	40.00	N	40.00	40.00
"70 KM/H" STICKER	1	20.00	N	20.00	20.00
REVERSE SENSOR	1	280.00	N	280.00	280.00
LABOUR CHARGES (REFER TO ITEM 1)	1	120.00	N	120.00	120.00
LABOUR CHARGES (REFER TO ITEM 2)	1	1200.00	N	1200.00	1200.00
LABOUR CHARGES (REFER TO ITEM 3)	1	180.00	N	180.00	180.00



IVECO



Description	QTY	U/Price	Disc	Net Price	Ext Price
LABOUR CHARGES (REFER TO ITEM 4)	1	120.00	N	120.00	120.00
LABOUR CHARGES (REFER TO ITEM 5)	1	700.00	N	700.00	700.00
LABOUR CHARGES (REFER TO ITEM 6)	1	30.00	N	30.00	30.00
Parts Charges:					4686.48
Sub Total:					4686.48
GST @ 7.00 %					328.05
E. & O. E					
TOTAL					5014.53

Please make all cheques payable to MOTORVIVA PTE LTD.
When making payment, please quote our Invoice numbers.
No receipts will be issued for Cheque Payments.

Terms and conditions of sales

Interest at 1.5% per month will be charged on overdue account

This is a computer generated document. No signature is required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18021567/Gsd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 30-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3256J	Veh. Inspected	GBH 9675C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008428MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	28/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	FIAT FIORINO	c.c	1248	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	ZFA22500006H33301	Colour	BROWN	
Odometer	757	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	PIRELLI	9 mm	
L/H Front Tyre	185/65 R15	PIRELLI	9 mm	
R/H Rear Tyre	185/65 R15	PIRELLI	9 mm	
L/H Rear Tyre	185/65 R15	PIRELLI	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/11/2018	Inspection Date	30/11/2018	
Survey held at	48 CHANGI SOUTH STREET 1			
Repairer	GOLDBELL ENGINEERING PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 9675C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER,RR	DEFORMED	510.75	510.75
1	TOW HOOK COVER	NOT NECESSARY	53.82	-
1	REAR BUMPER SUPPORT	BENT	150.48	150.48
1	REAR BUMPER BRACKET LH	NOT NECESSARY	69.22	-
1	REAR BUMPER BRACKET RH	NOT NECESSARY	69.22	-
1	REAR DOOR-LHS	BUCKLED	1,491.31	1,491.31
1	TAILGATE HINGE LH	BENT	65.77	65.77
1	DOOR CHECK-REAR	NOT NECESSARY	99.51	-
1	DOOR INNER TRIM LHS	NOT NECESSARY	144.48	-
1	SEALING GASKET-WEATHERSTRIP	NOT NECESSARY	420.94	-
	LESS 10% DISCOUNT		-307.55	-221.83
			2,767.95	1,996.48
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	20.00	-
1	REAR NUMBER PLATE HOLDER (SN)	NOT NECESSARY	20.00	-
1	SEALANT (SN)	NECESSARY	40.00	40.00
1	"70KM/H" STICKER (SN)	NECESSARY	20.00	20.00
1	REVERSE SENSOR ASSY (SN)	DAMAGED	280.00	250.00
1	SUNSHIES (SN)	NECESSARY	50.00	30.00
			430.00	340.00
LABOUR				
	TO CHECK FOR AND RECTIFY WIRING FAULTS,TO CONDUCT DIAGNOSTIC CHECK.		180.00	120.00
	TO REMOVE AND REFIX DAMAGED PARTS,CUT,WELD,PANEL BEAT,STRAIGHTEN & REALIGN,ETC.		2,400.00	1,200.00
	TO REMOVE AND REFIX DOOR COMPARTMENTS.		180.00	180.00
	TO REMOVE AND REFIX REAR DOOR GLASS.		120.00	120.00
	TO PUTTY,CLEAN,SPRAY PAINT AND POLISH,ETC.		1,400.00	700.00
			4,280.00	2,320.00



GRAND TOTAL		7,477.95	4,656.48
RECOMMENDED COST OF REPAIRS			4,656.48

Report Ref No. CS/FCI18021567/Gsd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.