

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

29 NOV 2018

E S T I M A T E

Page No. : 1 of 6

Estimate No. : b1 49289
Date Estimated : 29/11/2018
Prepared By : Chua Kee Sin**- ESTIMATE REPAIR FOR -**Cheng Yin Mei
12 Woodgrove Drive
#02-53

Singapore 738212

- ACCOUNT - 40000Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDG288C	D828423	10/04/2015	520iA	0

DESCRIPTION

Replace tail end panel, rear boot lid, rear bumper and remove attachment etc include repair on the accident damage area

850

2550 4,250.00

Spray painting rear both side fender, rear boot lid, rear bumper and tail end panel

2537.1 4,589.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 271.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To carry out body cavity preservation.
(For cut panel).

(451) ? 531.00

To carry out body cavity preservation.
(Per panel).

100 118.00

To supply rear emboss number plate.

/ 83.00

Sundries.

? 150.00

Total Labour 1: **10,169.00**DESCRIPTION

TAIL END PANEL ?

LH BOOTLID HINGE X YNN

RH BOOTLID HINGE X YNN

BOOTLID / BNC

SET MOUNTS PDC SENSOR REAR R / SMC

SET MOUNTS PDC SENSOR REAR R / SMC

RR BUMPER BOTTOM CENTRE GUIDE ?

RR BUMPER CARRIER / BT

PROTECTION FOIL L=55MM / ABC

ADAPTOR ?

QTY	PRIC	VALUE
1	817.30	817.30
1	116.50	116.50
1	116.50	116.50
1	1,642.45	1,642.45
1	58.60	58.60
1	58.60	58.60
1	60.45	60.45
1	732.10	732.10
2	4.75	9.50
1	70.15	70.15

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No. : **b1 49289**
Date Estimated : **29/11/2018**
Prepared By : **Chua Kee Sin**

Page No. : **2 of 6**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDG288C	D828423	10/04/2015	520ia	0

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER CENTRE GUIDE ?	1	61.55	61.55
RR LH MOUNT X <i>YNN</i>	1	192.15	192.15
RR RH MOUNT X <i>YNN</i>	1	198.30	198.30
REAR BUMPER PRIMED (PDC) - <i>re</i>	1	1,503.90	1,503.90
REAR BUMPER TOWING EYE COVER PRIMED - <i>dis</i>	1	47.60	47.60
EMBLEM GROMMET	2	0.80	1.60
MODEL LETTERING 520i - <i>YNN</i>	1	64.10	64.10
BMW EMBLEM	1	71.25	71.25
STRIKER BOOT LID X <i>NN</i>	1	53.55	53.55
TENSION SPRING TRUNK LID/TAILGATE X <i>NN</i>	1	40.35	40.35
STOP BUFFER - <i>YNN</i>	2	28.60	57.20
TRUNK LID LOCK TOP X	1	217.15	217.15
TRUNK LID POWER LOCK DRIVE X	1	601.30	601.30
TRIGGER CONTACT X	1	135.25	135.25
LH SPINDLE DRIVE X	1	522.65	522.65
RH TENSION SPRING TAILGATE X	1	89.05	89.05
BOOTLID TAILGATE PUSH BUTTON X	1	48.40	48.40
BOOTLID TAILGATE PUSH BUTTON X	1	48.40	48.40
LOADING SILL COVER	1	115.55	115.55
TRIM PANEL TRUNK LID X <i>YNN</i>	1	121.15	121.15
LH GUTTER STRIP X	1	17.20	17.20
RH GUTTER STRIP X	1	17.20	17.20
BOOTLID SEALING ?	1	115.25	115.25
PLUG BLACK D=5MM - <i>YNN</i>	7	0.90	6.30
REAR LH REFLECTOR ?	1	36.10	36.10
REAR RH REFLECTOR ?	1	36.10	36.10
(S/L) RUBBER BUFFER ?	2	2.00	4.00
RR LH LIGHT IN TRUNK LID X <i>NN</i>	1	346.45	346.45
RR RH LIGHT IN TRUNK LID - <i>CNA</i>	1	346.45	346.45
DECOUPLING RING PDC TORQUE CONVERTE - <i>YNN</i>	4	5.05	20.20
BUMPER PDC SENSOR A83 GLACIERSILBER ?	4	368.80	1,475.20
BLIND RIVET AVIBVLB - <i>YNN</i>	40	0.55	22.00
SCREW (SF PLUS M5X15) ?	2	0.55	1.10
(DG/SL) BODY ADHESIVE K5B (195ML) ?	1	326.80	326.80
(DG) CLEANER R1 (100ML) ?	1	26.15	26.15
PUNCH RIVET N4 ?	8	0.55	4.40
(S/L) SEAM SEAL 300ML ?	1	33.80	33.80

Total Parts : **10,707.30**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49289
Date Estimated : 29/11/2018
Prepared By : Chua Kee Sin

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDG288C	D828423	10/04/2015	520ia	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time _____ Excess S\$ _____

Surveyor's Name Emo Qiong Sign _____

Surveyor's Tel 82880282 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail emo.qiong@lkkauto.com

No. of Working Days Recommend 5

before paint photos.

Labour 1	:	10,169.00
Parts	:	10,707.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,461.34
Grand Total	:	22,337.64

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **