

ASS. REC. BY:

REF: CS/LPC18021661/Ktber

Special Instruction:

SUPERVISOR

Kumuth

ASSIGNMENT (Office)

From (Person):

Gerald Poh

of

LPC

Date/Time:

03/12/2018 11:51am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 6431U

Insured:

at Workshop m/s

S & H Motor

Tel:

of

Bdk 160 Sin Ming Drive #07-02

Policy No:

T18VP05019538

Claim No:

18/18/18/VP05/021169

Sum Insured:

Excess:

TBA

Make of Veh:

D.O.A.

23/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

03/12/2018 12:12pm

Person Contacted:

Doris

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLL 6431U - x

4/2 - Report via menimen.

offer 10.000 to WLS.

Report lump sum Bdk.

7/12/2018 @ 10:22am authorise repair by gerald poh. via email.

ASS. REC. BY:

REF: UPC/Kennerth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/12

File pass to Carhenge

7/12@

10:33am inform DONS authorise repair not exceeding \$12,000 - US

21/3

1/1 by B11,400 email & confirm.

(Red: 6031.25, 3400)

RECEIVED 25 MAR 2019

Date/Time, File Pass to?

12/13 Typist

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair: 8Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fixed

Others

TOTAL

Report Format: 00

Lump Sum / I.B.I. (\$

11400/-7x15 = 105105+190 = 295295+20% = 3303305050+5042522+10532

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Dec 2018 Sendback Est	03 Dec 2018 11:38 S\$16,578.50	03 Dec 2018 11:51 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	TEO CHUAN HOCK, ID: S1661286C, Tel: +6582012272, Email: NOEMAIL								
Vehicle Reg. No.:	SLL6431U	Date of Loss:	28/11/2018 23:00 - :59 [93 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 18/18/18/VP05/021169	Policy/Cover Note No.:	Z18VP05019578 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730								
Handling Insurer:	Longpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/12/2018]								
Driver/Custodian:	TEO CHUAN HOCK (54 / Male), NRIC: S1661286C, Tel: +6582012272								
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
View All Compose Case Mail									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Friday, 7 December 2018 10:22 AM
To: Admin-D (LKKAuto)
Cc: MT_Claim_SG; enquiry@sh-motor.com
Subject: FW: OD CLAIM - SLL6431U

Dear Catherine,

Your Immediate Advice dated 7 December 2018 refers.

You may proceed to authorize repair as adjusted.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: GERALD POH WEE BIN
Sent: Monday, 3 December, 2018 11:56 AM
To: 'Admin-D (LKKAuto)'
Cc: 'mt_claim@lonpac.com'
Subject: OD CLAIM - SLL6431U

Our Ref : 18/18/18/VP05/021169

Dear Catherine,

Kindly proceed to survey and revert.

The details are in Merimen.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gerald Poh

Date: 07 Dec 2018

Preliminary Advice

Vehicle No	: SLL6431U	Accident Date	: 28/11/2018
Make	: MERCEDES-BENZ C180K	Policy No.	: Z18VP05019578
Assignment Date	: 03/12/2018	Excess	: S\$0.00
Date of Inspection	: 03/12/2018	Est. Duration of Repair	: 8.00
Inspection At	: S & H MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #07-02, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,578.50
Revised Amount	:S\$	10,629.85
Check Items (Estimated)	:S\$	3,698.40
Total	:S\$	14,328.25
 Lump Sum Repair	:S\$	 12,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	42,000.00
COE / PARF Rebate	:S\$	29,374.00
Salvage Value	:S\$	
Margin for Repair	:S\$	12,626.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Repairer on lump sum all in \$12,000/-.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gerald Poh

Date: 04 Dec 2018

Preliminary Advice

Vehicle No	: SLL6431U	Accident Date	: 28/11/2018
Make	: MERCEDES-BENZ C180K	Policy No.	: Z18VP05019578
Assignment Date	: 03/12/2018	Excess	: S\$0.00
Date of Inspection	: 03/12/2018	Est. Duration of Repair	: 8.00
Inspection At	: S & H MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #07-02, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,578.50
Revised Amount	:S\$	10,629.85
Check Items (Estimated)	:S\$	3,698.40
Total	:S\$	14,328.25
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	41,000.00
COE / PARF Rebate	:S\$	29,374.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,626.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : pending repair cost from repairer



Beautiful Number Plate. Always Parked Under Shelter. Stock Condition. Car Is Still In Good Condition. Please Call Now To Arrange An Appointment For Viewing Before It Is Gone. Up To 90% Loan Available....

Monster Motors Pte Ltd

Posted: 27-Nov-2018 Tags: 2011 Mercedes-Benz C180K, 2011 mercedes-benz c180k, Mercedes-Benz C180K, mercedes-benz c180k, Mercedes-Benz, C180K, c180k, Used Mercedes-Benz



Mercedes-Benz C-Class C180K \$42,900 \$12,780 /yr 13-Jan-2011 1,597 cc 158,051 km Luxury Available

Compact But Powerful. Smooth And Stable Drive Every Single Time. Stylish Design And Guaranteed Performance Of Mercedes. Great For Any Professional Or A Small Family. Superbly Maintained By Owner And I...

Posted: 25-Nov-2018 Tags: 2011 Mercedes-Benz C180K, 2011 mercedes-benz c180k, Mercedes-Benz C180K, mercedes-benz c180k, Mercedes-Benz, C180K, c180k, Used Mercedes-Benz



Mercedes-Benz C-Class C180K \$52,900 \$12,560 /yr 25-Nov-2011 1,597 cc - Luxury Available

The Mercedes C180K Offers Top Notch Luxury Along With Outstanding Engine Performance. Serviced And Maintained Regularly With Mercedes-Benz Expert Garage. High Trade In, Minimum Down Payment And Attrac...

Pang's Motor Trading Pte Ltd

Posted: 24-Nov-2018 Tags: 2011 Mercedes-Benz C180K, 2011 mercedes-benz c180k, Mercedes-Benz C180K, mercedes-benz c180k, Mercedes-Benz, C180K, c180k, Used Mercedes-Benz



Mercedes-Benz C-Class C180K Avantgarde \$50,800 \$12,870 /yr 01-Sep-2011 1,597 cc 108,000 km Luxury Available

Cheapest In Market! Wear And Tears Just Changed! No Repairs Needed! Servicing Just Done! New Facelift Model! Hassle Free, High Loan And Trade-In Available! Call Now For Book A Viewing/Test Drive Appoi...

Posted: 23-Nov-2018 Tags: 2011 Mercedes-Benz C180K, 2011 mercedes-benz c180k, Mercedes-Benz C180K, mercedes-benz c180k, Mercedes-Benz, C180K, c180k, Used Mercedes-Benz



Pimp Your Ride With Sports Rim

Sports rim do not just perk up the aggressive outlook of a car, it actually does improve performance with its lighter weight. Find yourself a beautiful set of rims from the list of tyre & rims retailers.

Find out more!



Mercedes-Benz C-Class C180 Coupe \$57,500 \$12,940 /yr 14-Nov-2011 1,796 cc 103,000 km Sports Available

Down Payment \$5,800 Only! Fr \$1,060/Month. New Road Tax! C&C Unit. Mint Condition! Fervently Maintained/Serviced Regularly With No Expense Spared. 100% Accident Free, Genuine Mileage, Non Abused, Shel...

Cars 88 Pte Ltd

Posted: 22-Nov-2018 Tags: 2011 Mercedes-Benz C180, 2011 mercedes-benz c180, Mercedes-Benz C180, mercedes-benz c180, Mercedes-Benz, C180, c180, Used Mercedes-Benz



Mercedes-Benz C-Class C180K \$43,000 \$12,180 /yr 23-Feb-2011 1,597 cc 98,890 km Luxury Available

Well Maintained, New Original Aircon Compressor, New Original Brake Pad, Regular Servicing Done, Loan And Trade In Available, Viewing By Appointment Only.

Posted: 21-Nov-2018 Tags: 2011 Mercedes-Benz C180K, 2011 mercedes-benz c180k, Mercedes-Benz C180K, mercedes-benz c180k, Mercedes-Benz, C180K, c180k, Used Mercedes-Benz



Mercedes-Benz C-Class C180K \$39,800 \$11,630 /yr 10-Jan-2011 1,597 cc - Luxury Available

Stunning Red Unit Not To Be Missed, Very Well Maintained, Fuel Efficient Yet Luxury And Affordable Continental Car! Flexible In House Loan Available To Assist Low Budget Situation! Call Us Today For A ...

Posted: 17-Nov-2018 Tags: 2011 Mercedes-Benz C180K, 2011 mercedes-benz c180k, Mercedes-Benz C180K, mercedes-benz c180k, Mercedes-Benz, C180K, c180k, Used Mercedes-Benz



Mercedes-Benz C-Class C180 CGI \$58,300 \$13,160 /yr 17-Nov-2011 1,796 cc 69,000 km Luxury Available

New Road Tax, Well Maintained By Only 1 Driver! 1.8L Turbo-Charged Engine Much Easier To Maintain Than SuperCharge Turbo, Higher Torque Than C180K. Always Parked Under Shelter. Genuine Low Mileage. CL...

Posted: 16-Nov-2018 Tags: 2011 Mercedes-Benz C180, 2011 mercedes-benz c180, Mercedes-Benz C180, mercedes-benz c180, Mercedes-Benz, C180, c180, Used Mercedes-Benz



Mercedes-Benz C-Class C180K Avantgarde \$58,888 \$14,620 /yr 22-Nov-2011 1,597 cc 64,000 km Luxury Available

Driven By Careful Lady Driver With Low Mileage (9.2Km/Yr). Elegant Silver With Leather Interior, Spacious Boot Space. Accident Free With 0 Breakdown. Reliable And Low Running Cost. No Repairs Needed. Regul...

Posted: 15-Nov-2018 Tags: 2011 Mercedes-Benz C180K, 2011 mercedes-benz c180k, Mercedes-Benz C180K, mercedes-benz c180k, Mercedes-Benz, C180K, c180k, Used Mercedes-Benz



Mercedes-Benz C-Class C180K \$51,868 \$12,820 /yr 06-Oct-2011 1,597 cc - Luxury Available

Stylish LED Interior On Black. Responsive Acceleration. Supercharged Inline Kompressor.

Posted: 12-Nov-2018 Tags: 2011 Mercedes-Benz C180K, 2011 mercedes-benz c180k, Mercedes-Benz C180K, mercedes-benz c180k, Mercedes-Benz, C180K, c180k, Used Mercedes-Benz



Mercedes-Benz C-Class C180 Avantgarde \$45,300 \$12,720 /yr 18-Apr-2011 1,597 cc 91,000 km Luxury Available

2nd Car. Park In Door, Beautiful Leather Seats. Enjoy New Road Tax Till Middle Of Next Year! Drive With Passion! Trade In And High Loan ie. Please Call For Appointment.

Posted: 10-Nov-2018 Tags: 2011 Mercedes-Benz C180, 2011 mercedes-benz c180, Mercedes-Benz C180, mercedes-benz c180,

Mercedes-Benz, C180, c180, Used Mercedes-Benz

**Mercedes-Benz C-Class C180K Avantgarde****\$49,800****\$13,180 /yr****26-Jul-2011****1,597 cc****120,150 km****Luxury****Available**

Cheapest In Market! Beautiful In Black Well Maintained Excellent Condition Low Depreciation, Powerful, Fuel Efficient Drive. Fairly Low Mileage. Trade In Are Welcome! Call Us Now!

Posted: 02-Nov-2018

Tags: 2011 Mercedes-Benz C180K, 2011 mercedes-benz c180k, Mercedes-Benz C180K, mercedes-benz c180k, Mercedes-Benz, C180K, c180k, Used Mercedes-Benz

**Mercedes-Benz C-Class C180K Avantgarde****\$50,800****\$12,210 /yr****25-Oct-2011****1,597 cc****-****Luxury****Available**

Beautiful In Black Well Maintained Excellent Condition Low Depreciation. Low Down Payment In House Finance. Don't Miss Must View Call Now.

Posted: 28-Oct-2018

Tags: 2011 Mercedes-Benz C180K, 2011 mercedes-benz c180k, Mercedes-Benz C180K, mercedes-benz c180k, Mercedes-Benz, C180K, c180k, Used Mercedes-Benz

**Mercedes-Benz C-Class C180K****\$42,500****\$11,980 /yr****17-Mar-2011****1,597 cc****162,000 km****Luxury****Available**

Well Maintained And Serviced Regularly. Trade Ins Welcome. Contact Us To View This Unit Now! Carefully Driven And Maintained By Single Owner

Posted: 25-Oct-2018

Tags: 2011 Mercedes-Benz C180K, 2011 mercedes-benz c180k, Mercedes-Benz C180K, mercedes-benz c180k, Mercedes-Benz, C180K, c180k, Used Mercedes-Benz

Save this search criteria, to get email alerts whenever a match is found.

Make: Model: Price: Depreciation: Reg Date: Eng Cap: Mileage: Veh Type: Status:

For old advertisements, view Expired ads

« Back (1 2) Next »

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used mercedes c180, mercedes c180 Singapore, used mercedes c180 Singapore, used mercedes c180, used vehicles Singapore or even buy used mercedes c180 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

Compare:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 1286C

Vehicle Details

Vehicle No.: SLL6431U
Vehicle to be Exported: Yes
Intended Deregistration Date: 29 Nov 2018
Vehicle Make: MERCEDES BENZ
Vehicle Model: C180K
Primary Colour: Black
Manufacturing Year: 2010
Engine No.: 27191031343853
Chassis No.: WDD2040452A502171
Maximum Power Output: 115.0 kW (154 bhp)
Open Market Value: \$31,893.00
Original Registration Date: 17 Feb 2011
First Registration Date: 17 Feb 2011
Transfer Count: 1
Actual ARF Paid: \$31,893.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 16 Feb 2021
PARF Rebate Amount: \$19,135.00

Intended COE Rebate Details

COE Expiry Date: 16 Feb 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$46,129.00
COE Rebate Amount: \$10,239.00
Total Rebate Amount: \$29,374.00

The information contained herein is correct as at 29 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/11/2018 13:59
Date Of Accident	28/11/2018 23:30
Exact Location Of Accident	ALONG PIE OUTSIDE OLD POLICE ACADEMY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL6431U
Insured/Policyholder	
Name Of Registered Owner	TEO CHUAN HOCK
NRIC No	S1661286C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82012272
Alternative Phone No	OFFICE-82012272

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	-

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z18VP05019578
Cover Note Number	

Driver

Name of Driver	TEO CHUAN HOCK
NRIC No	S1661286C
Date Of Birth	02/08/1964
Occupation	INDOOR
Date Of Driving Pass	27/02/1982
Driving Experience	36 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82012272
Fax Number	
Contact Number	OFFICE-82012272
Email Address	NOEMAIL

SKETCH PLAN



A - SLL 6431U

B - GBE 6230M

C - SJY 8341M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along PIE outside Old Police Academy
 the front vehicle B applied sudden brake but
 I could not stop in time and hit onto his
 car's rear portion. When I alighted from my
 car and discovered that it was a chain
 collision.

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature

Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

INSURER: **Lonpac Insurance Bhd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	Z18VP05019578	Date of Loss:	20/11/10
Vehicle Reg. No.:	SLL6431U	Driveable?	
Driver Age/Info:	54 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved:	
Insured/Claimant:	TEO CHUAN HOCK	Contact No:	+6582012272
Driver:	TEO CHUAN HOCK		

Make/Model:	MERCEDES-BENZ C180K, 1.6 (A)	Vehicle Reg. Date:	17/02/2011
Vehicle Colour:	Metallic Black		
Engine No:	27191031343853	Chassis No:	WDD2040452A502171
Odometer:	0 KM		

Paint Type: *FM*

Total Loss? **NO**

Est. Duration of Repair (day) *12 days*

Description of Accident/Loss **REFER ATTACHED REPORT.**

Present Location: **S & H MOTOR PTE LTD (SIN MING)**

Not Withheld
Resurvey After Repair
6 Days @ 7

Fax: 62564315

COST OF CLAIMS	Amount
Parts	13,788.50
Miscellaneous Items	90.00
Labour	2,580.00
Paintwork Labour	0.00
Towing	120.00
Gross Total (S\$)	16,578.50
+ GST 7.00% (S\$)	1,160.50
Nett Amount (S\$)	17,739.00

This claim is handled by: **LUM WEE KEAT**

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Dec 2018)
Parts:	143	MERCEDES-BENZ C180K 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	S & H Motor Pte Ltd/SLL6431U/03/12/2018 11:38	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*Bonnet	Bu	0.00	0.00	*1,150.00 F	✓
2	1		*LH roof moulding	Ro	0.00	0.00	*280.00 F	✓
3	1		*Bonnet emblem	Re	0.00	0.00	*65.00 F	✓
4	1		*RH bonnet hinge	Di	0.00	0.00	*95.00 F	✓
5	1		*LH bonnet hinge	Di	0.00	0.00	*95.00 F	✓
6	1		*Bonnet insulator	Reform	0.00	0.00	*160.00 F	✓
7	1		*Bonnet insulator clips (1 set)	Re	0.00	0.00	*25.00 F	✓
8	1		*RH bonnet lock	Di	0.00	0.00	*55.00 F	✓
9	1		*LH bonnet lock	Di	0.00	0.00	*55.00 F	✓
10	1		*Bonnet spare hook	B	0.00	0.00	*55.00 F	✓
11	1		*RH bonnet lock top hook	B	0.00	0.00	*48.00 F	✓
12	1		*LH bonnet lock top hook	B	0.00	0.00	*48.00 F	✓
13	1		*Bonnet front rubber	M	0.00	0.00	*25.00 F	✓
14	1		*LH bonnet rubber stopper	M	0.00	0.00	*12.00 F	✓
15	1		*RH bonnet shock absorber	N	0.00	0.00	*80.00 F	X
16	1		*LH bonnet shock absorber	N	0.00	0.00	*80.00 F	X
17	2		*Bonnet spring stoppers	M	0.00	0.00	*36.00 F	✓
18	1		*RH head lamp	M	0.00	0.00	*680.00 F	✓
19	1		*LH head lamp	C	0.00	0.00	*680.00 F	✓
20	1		*LH head lamp top garnish	C	0.00	0.00	*28.00 F	✓
21	1		*RH head lamp top garnish	C	0.00	0.00	*28.00 F	✓
22	1		*RH head lamp holder bracket (metal)	B	0.00	0.00	*90.00 F	✓
23	1		*LH head lamp holder bracket (metal)	B	0.00	0.00	*90.00 F	✓
24	1		*LH front fender	B	0.00	0.00	*550.00 F	✓
25	1		*RH front fender	R	0.00	0.00	*550.00 F	X
26	1		*Bonnet lock top metal panel	B	0.00	0.00	*90.00 F	✓
27	1		*Bonnet spare hook bracket	Di	0.00	0.00	*55.00 F	✓
28	1		*Bonnet lock top air duct	C	0.00	0.00	*90.00 F	✓
29	1		*RH head lamp adjuster bracket	R	0.00	0.00	*35.00 F	X
30	1		*LH head lamp adjuster bracket	R	0.00	0.00	*35.00 F	X
31	1		*RH air con condensor side garnish	C	0.00	0.00	*45.00 F	✓
32	1		*LH air con condensor side garnish	C	0.00	0.00	*45.00 F	✓
33	1		*Grille	M	0.00	0.00	*480.00 F	✓
34	1		*Grille top center plastic bracket	R	0.00	0.00	*20.00 F	✓
35	1		*Engine Air cleaner	S	0.00	0.00	*280.00 F	X
36	1		*Engine air cleaner air hose	M	0.00	0.00	*75.00 F	✓
37	2		*Engine compartment rubbers	S	0.00	0.00	*170.00 F	X
38	2		*Engine air cleaner air hose joints	S	0.00	0.00	*190.00 F	X
39	1		*Radiator	P	0.00	0.00	*780.00 F	✓
40	1		*Radiator top hose	P	0.00	0.00	*55.00 F	✓
41	1		*Radiator bottom hose	S	0.00	0.00	*85.00 F	X
42	1		*Radiator fan assy	T	0.00	0.00	*780.00 F	✓
43	1		*Front steering coolant oil pipe	B	0.00	0.00	*190.00 F	✓
44	1		*Air con condensor	P	0.00	0.00	*750.00 F	✓
45	1		*Air con condensor aluminium pipe inlet	D	0.00	0.00	*245.00 F	✓
46	1		*Air con condensor aluminium pipe outlet	S	0.00	0.00	*245.00 F	X
47	1		*Front bumper	C	0.00	0.00	*800.00 F	✓

48	1	*RH front bumper chrome moulding	<i>Re</i>	0.00	0.00	*60.00 F	✓
49	1	*LH front bumper chrome moulding	<i>Re</i>	0.00	0.00	*60.00 F	—
50	1	*Front bumper reinforcement	<i>B</i>	0.00	0.00	*240.00 F	✓
51	1	*RH alloy reinforcement bracket	<i>R</i>	0.00	0.00	*160.00 F	X
52	1	*LH alloy reinforcement bracket	<i>R</i>	0.00	0.00	*160.00 F	X
53	1	*Front bumper insulator spongh	<i>CM</i>	0.00	0.00	*110.00 F	✓
54	1	*Front bumper number plate holder	<i>CM</i>	0.00	0.00	*90.00 F	✓
55	1	*RH front bumper tow cover	<i>RI</i>	0.00	0.00	*35.00 F	✓
56	1	*RH front bumper head lamp bottom metal retainer	<i>R</i>	0.00	0.00	*25.00 F	✓
57	1	*LH front bumper head lamp bottom metal retainer	<i>B</i>	0.00	0.00	*25.00 F	✓
58	1	*LH wiper water tank	<i>SW</i>	0.00	0.00	*95.00 F	X
59	1	*RH head lamp metal inner panel	<i>Re Re</i>	0.00	0.00	*165.00 F	✓
60	1	*LH head lamp metal inner panel	<i>Re Re</i>	0.00	0.00	*165.00 F	✓

F=Franchise part

Sub Total (S\$)	11,990.00
+ Margin on L,N Items 15.00% (S\$)	1,798.50

Total Parts (S\$)	13,788.50
-------------------	-----------

S & H Motor Pte Ltd/SLL6431U/03/12/2018 11:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Engine coolant	45.00 <i>na 30m</i>
2	1	Front number plate	45.00 <i>cm</i>
Sub Total (S\$)			90.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality	New	120.00 <i>100%</i>
2	To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp	New	80.00 <i>20%</i>
3	To remove radiator, engine fan, clutch, hoses and replace damaged parts and check engine cooling system functionality	New	150.00 <i>80%</i>
4	To remove front damaged parts, to jack out front support panel, front body, and cut out damaged parts, to straighten out front chassis, to reweld, reshape and repair bonnet hinge panel, front fender and inner panel, head lamp inner panel, front support panel, front chassis member and adjust body panel alignment	New	1,100.00 <i>80%</i>
5	To spray paint affected front and inner damaged portion inclusive of preparatory works and material	New	1,150.00 <i>100%</i>
Gross Labour Cost (S\$)			2,580.00

S & H Motor Pte Ltd/SLL6431U/03/12/2018 11:38. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 15 Dec 2018)**Parts:** 143 **MERCEDES-BENZ C180K 1.6 (A) (Catalogue:Merimen Singapore 1.0)****Labour:** Repairer's **(Price-denominated Standard List)****Print Code:** S & H Motor Pte Ltd/SLL6431U/15/12/2018 12:37**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet cable	0.00	0.00	<i>Jan</i> *55.00 F ✓
2	1		*Front cooler	0.00	0.00	<i>An</i> *730.00 F ✓
						Sub Total (S\$) 785.00
						+ Margin on L,N Items 15.00% (S\$) 117.75
						Total Parts (S\$) 902.75

F=Franchise part.

S & H Motor Pte Ltd/SLL6431U/15/12/2018 12:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Dec 2018 Sendback Est	03 Dec 2018 11:38 S\$16,578.50	03 Dec 2018 11:51 Edit Adj Rpt	S\$11,400.00 Edit Estimates	S\$11,400.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	15 Dec 2018 12:36	15 Dec 2018 12:37 S\$902.75	15 Dec 2018 12:37			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	TEO CHUAN HOCK, ID: S1661286C, Tel: +6582012272, Email: NOEMAIL		
Vehicle Reg. No.:	SLL6431U	Date of Loss:	28/11/2018 23:00 - :59 [93 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 18/18/18/VP05/021169	Policy/Cover Note No.:	Z18VP05019578 (Comprehensive)
		Excess:	S\$0.00
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730		
Handling Insurer:	Lompac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 12/12/2018]		
Driver/Custodian:	TEO CHUAN HOCK (54 / Male) , NRIC: S1661286C, Tel: +6582012272 Email: NOEMAIL		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- LONPAC_HQ (10/12/2018): Alert - Adj Mandate Approved (S\$12000.00) - SLL6431U - Claim Handler: Gerald Poh

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLL6431U (18/18/18/VP05/021169)

OD

Nov 28 2018 11:00PM

[TEO CHUAN HOCK]

S & H Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	03/12/18 11:38	Repairer Estimates	Load HTM	
2	15/12/18 12:37	Repairer Estimates Suppl. #1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/12/18 14:43	Adjuster Immediate Advice	Load HTM	
2	07/12/18 09:35	Adjuster Immediate Advice	Load HTM	
3	07/12/18 09:43	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/12/18 14:22	General View	Load JPG	☒
2	04/12/18 14:22	General View	Load JPG	☒
3	04/12/18 14:22	General View	Load JPG	☒
4	04/12/18 14:22	General View	Load JPG	☒
5	04/12/18 14:22	General View	Load JPG	☒
6	04/12/18 14:22	General View	Load JPG	☒
7	04/12/18 14:22	General View	Load JPG	☒
8	04/12/18 14:22	General View	Load JPG	☒
9	04/12/18 14:22	General View	Load JPG	☒
10	04/12/18 14:22	General View	Load JPG	☒
11	04/12/18 14:22	General View	Load JPG	☒
12	04/12/18 14:22	General View	Load JPG	☒
13	04/12/18 14:22	General View	Load JPG	☒
14	04/12/18 14:22	General View	Load JPG	☒
15	04/12/18 14:22	General View	Load JPG	☒
16	04/12/18 14:22	General View	Load JPG	☒
17	04/12/18 14:22	General View	Load JPG	☒
18	04/12/18 14:22	General View	Load JPG	☒
19	04/12/18 14:22	General View	Load JPG	☒
20	04/12/18 14:22	General View	Load JPG	☒
21	04/12/18 14:22	General View	Load JPG	☒
22	04/12/18 14:22	General View	Load JPG	☒
23	04/12/18 14:22	General View	Load JPG	☒
24	04/12/18 14:22	General View	Load JPG	☒
25	04/12/18 14:22	General View	Load JPG	☒
26	04/12/18 14:22	General View	Load JPG	☒
27	22/03/19 14:06	Reinspection Photo	Load JPG	☒
28	22/03/19 14:06	Reinspection Photo	Load JPG	☒
29	22/03/19 14:06	Reinspection Photo	Load JPG	☒
30	22/03/19 14:06	Reinspection Photo	Load JPG	☒
31	22/03/19 14:06	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
32	22/03/19 14:06	Reinspection Photo	 Load JPG	☒
33	22/03/19 14:06	Reinspection Photo	 Load JPG	☒
34	22/03/19 14:06	Reinspection Photo	 Load JPG	☒
35	22/03/19 14:06	Reinspection Photo	 Load JPG	☒
36	22/03/19 14:06	Reinspection Photo	 Load JPG	☒
37	22/03/19 14:06	Reinspection Photo	 Load JPG	☒
38	22/03/19 14:06	Reinspection Photo	 Load JPG	☒
39	22/03/19 14:06	Reinspection Photo	 Load JPG	☒
40	22/03/19 14:06	Reinspection Photo	 Load JPG	☒
41	22/03/19 14:09	Reinspection Photo	 Load JPG	☒
42	22/03/19 14:09	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/12/18 15:12	ESTIMATE	 Load PDF	
2	27/03/19 15:39	Supplementary	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	29/11/18 17:06	Accident Statement	 Load HTML	
Photos/Images			3 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	29/11/18 16:16	Accident Photo	 Load JPG	☒
2	29/11/18 16:16	Accident Photo	 Load JPG	☒
3	29/11/18 16:16	Accident Photo	 Load JPG	☒
4	29/11/18 16:16	Accident Photo	 Load JPG	☒
5	29/11/18 16:16	Accident Photo	 Load JPG	☒
6	29/11/18 16:16	Accident Photo	 Load JPG	☒
7	29/11/18 16:16	Accident Photo	 Load JPG	☒
8	29/11/18 16:16	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	29/11/18 15:09	Sketch Plan	 Load TIF	
2	29/11/18 15:09	Sketch Plan #2	 Load TIF	
3	29/11/18 15:09	Sketch Plan #3	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC18021661/KTBE2

Date: 27/03/2019

REFERENCE

Insured/Claimant: TEO CHUAN HOCK Policy No: Z18VP05019578
Date of Loss: 28/11/2018 Nature of Claim: OD Claim No: 18/18/18/VP05/021169

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL6431U**
Make & Model: MERCEDES-BENZ C180K, 1.6 (A) Engine No: 27191031343853
Reg. Date: 17/02/2011 (Man. Year: 2010) Chassis No: WDD2040452A502171
Colour: Metallic Black Odometer: 119686 km
Engine Capacity: 1597 cc
Market Value/New Car Price: S\$42,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R17 Rear Tyre Size: 225/45Z R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,691.25	12,172.75	2,518.50	17.14
Miscellaneous Items	90.00	75.00	15.00	16.67
Labour	2,580.00	2,000.00	580.00	22.48
Paintwork Labour	0.00	0.00	0.00	
Towing	120.00	0.00	120.00	100.00
Calculated Gross Total (S\$)	17,481.25	14,247.75	3,233.50	18.50
Approved Total (Overridden) (S\$)		11,400.00		
(S\$)	17,481.25	11,400.00	6,081.25	34.79
+ GST 7.00/7.00% (S\$)	1,223.69	798.00	425.69	34.79
Nett Amount (S\$)	18,704.94	12,198.00	6,506.94	34.79

INSPECTION

Date of Assignment: 03/12/2018 Present Location: S & H Motor Pte Ltd (Sin Ming)
Date Inspected: 03/12/2018 Inspected At: S & H Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #07-02, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Mar 2019)
Parts:	143	MERCEDES-BENZ C180K 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL6431U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Bonnet (WCP)	Buckled	1,150.00 F	*1,150.00 F
2	1		*LH roof moulding (WCP)	Dented	280.00 F	*280.00 F
3	1		*Bonnet emblem (WCP)	Dented	65.00 F	*65.00 F
4	1		*RH bonnet hinge (WCP)	Distorted	95.00 F	*95.00 F
5	1		*LH bonnet hinge (WCP)	Distorted	95.00 F	*95.00 F
6	1		*Bonnet insulator (WCP)	Deformed	160.00 F	*160.00 F
7	1		*Bonnet insulator clips (1 set) (WCP)	Necessary	25.00 F	*25.00 F
8	1		*RH bonnet lock (WCP)	Distorted	55.00 F	*55.00 F
9	1		*LH bonnet lock (WCP)	Distorted	55.00 F	*55.00 F
10	1		*Bonnet spare hook (WCP)	Bent	55.00 F	*55.00 F
11	1		*RH bonnet lock top hook (WCP)	Bent	48.00 F	*48.00 F
12	1		*LH bonnet lock top hook (WCP)	Bent	48.00 F	*48.00 F
13	1		*Bonnet front rubber (WCP)	Missing	25.00 F	*25.00 F
14	1		*LH bonnet rubber stopper (WCP)	Missing	12.00 F	*12.00 F
15	1		*RH bonnet shock absorber (WCP)	No such part	80.00 F	*- F
16	1		*LH bonnet shock absorber (WCP)	No such part	80.00 F	*- F
17	2		*Bonnet spring stoppers (WCP)	Missing	36.00 F	*36.00 F
18	1		*RH head lamp (WCP)	Mtg Broken	680.00 F	*680.00 F
19	1		*LH head lamp (WCP)	Cracked	680.00 F	*680.00 F
20	1		*LH head lamp top garnish (WCP)	Cracked	28.00 F	*28.00 F
21	1		*RH head lamp top garnish (WCP)	Cracked	28.00 F	*28.00 F
22	1		*RH head lamp holder bracket (metal) (WCP)	Bent	90.00 F	*90.00 F
23	1		*LH head lamp holder bracket (metal) (WCP)	Bent	90.00 F	*90.00 F
24	1			Buckled	550.00 F	*550.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*LH front fender (WCP)			
25	1		*RH front fender (WCP)	Repair	550.00 F	*- F
26	1		*Bonnet lock top metal panel (WCP)	Bent	90.00 F	*90.00 F
27	1		*Bonnet spare hook bracket (WCP)	Distorted	55.00 F	*55.00 F
28	1		*Bonnet lock top air duct (WCP)	Cracked	90.00 F	*90.00 F
29	1		*RH head lamp adjuster bracket (WCP)	Repair	35.00 F	*- F
30	1		*LH head lamp adjuster bracket (WCP)	Repair	35.00 F	*- F
31	1		*RH air con condensor side garnish (WCP)	Cracked	45.00 F	*45.00 F
32	1		*LH air con condensor side garnish (WCP)	Cracked	45.00 F	*45.00 F
33	1		*Grille (WCP)	Missing	480.00 F	*480.00 F
34	1		*Grille top center plastic bracket (WCP)	Necessary	20.00 F	*20.00 F
35	1		*Engine Air cleaner (WCP)	Serviceable	280.00 F	*- F
36	1		*Engine air cleaner air hose (WCP)	Missing	75.00 F	*75.00 F
37	2		*Engine compartment rubbers (WCP)	Serviceable	170.00 F	*- F
38	2		*Engine air cleaner air hose joints (WCP)	Serviceable	190.00 F	*- F
39	1		*Radiator (WCP)	Punctured	780.00 F	*780.00 F
40	1		*Radiator top hose (WCP)	Punctured	55.00 F	*55.00 F
41	1		*Radiator bottom hose (WCP)	Serviceable	85.00 F	*- F
42	1		*Radiator fan assy (WCP)	Jammed	780.00 F	*780.00 F
43	1		*Front steering coolant oil pipe (WCP)	Dented	190.00 F	*190.00 F
44	1		*Air con condensor (WCP)	Punctured	750.00 F	*750.00 F
45	1		*Air con condensor aluminium pipe inlet (WCP)	Dented	245.00 F	*245.00 F
46	1		*Air con condensor aluminium pipe outlet (WCP)	Serviceable	245.00 F	*- F
47	1		*Front bumper (WCP)	Cracked	800.00 F	*800.00 F
48	1		*RH front bumper chrome moulding (WCP)	Necessary	60.00 F	*60.00 F
49	1		*LH front bumper chrome moulding (WCP)	Necessary	60.00 F	*60.00 F
50	1		*Front bumper reinforcement (WCP)	Bent	240.00 F	*240.00 F
51	1		*RH alloy reinforcement bracket (WCP)	Repair	160.00 F	*- F
52	1		*LH alloy reinforcement bracket (WCP)	Repair	160.00 F	*- F
53	1		*Front bumper insulator spongh (WCP)	Cracked	110.00 F	*110.00 F
54	1		*Front bumper number plate holder (WCP)	Cracked	90.00 F	*90.00 F
55	1		*RH front bumper tow cover (WCP)	Missing	35.00 F	*35.00 F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*RH front bumper head lamp bottom metal retainer (WCP)	Repair	25.00 F	*- F
57	1		*LH front bumper head lamp bottom metal retainer (WCP)	Bent	25.00 F	*25.00 F
58	1		*LH wiper water tank (WCP)	Serviceable	95.00 F	*- F
59	1		*RH head lamp metal inner panel (WCP)	Buckled	165.00 F	*165.00 F
60	1		*LH head lamp metal inner panel (WCP)	Buckled	165.00 F	*165.00 F
Supplementary #1						
61	1		*Bonnet cable (WCP)	Jammed	55.00 F	*55.00 F
62	1		*Front cooler (WCP)	Punctured	730.00 F	*730.00 F
F=Franchise part.						
Sub Total (S\$)					12,775.00	10,585.00
+ Margin on L,N Items 15.00/15.00% (S\$)					1,916.25	1,587.75
Total Parts (S\$)					14,691.25	12,172.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Engine coolant (NECESSARY)	45.00	30.00
2	1	Front number plate (CRACKED)	45.00	45.00
Sub Total (S\$)			90.00	75.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality	New	120.00	100.00
2	To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp	New	60.00	20.00
3	To remove radiator, engine fan, clutch, hoses and replace damaged parts and check engine cooling system functionality	New	150.00	80.00
4	To remove front damaged parts, to jack out front support panel, front body, and cut out damaged parts, to straighten out front chassis, to reweld, reshape and repair bonnet hinge panel, front fender and inner panel, head lamp inner panel, front support panel, front chassis member and adjust body panel alignment	New	1,100.00	800.00
5	To spray paint affected front and inner damaged portion inclusive of preparatory works and material	New	1,150.00	1,000.00
Gross Labour Cost (S\$)			2,580.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >