



ESTIMATE TO REPAIR

VEHICLE NO. : SKE 1232 J
MAKE : B.M.W.
MODEL : 335i AT 3.0L ABS D/AB HID 2WD 4DR
YEAR : 2009
CHASSIS NO : WBAPM72030A381035

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

DATE : 26-Nov-18
DATE OF ACCIDENT : 24-Nov-18
THIRD PARTY REF : SLM 3270 G / AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front Bumper				\$ 967.00
1 pc	N/S Front Bumper Retainer				\$ 8.65
1 pc	N/S Headlamp				\$ 2,376.20
1 pc	N/S Front Fender				\$ 664.60
1 pc	N/S Front Door				\$ 1,204.15
1 pc	N/S Front Door Rubber				\$ 136.50
1 pc	N/S Front Door Outer Handle				\$ 70.70
					\$ 5,427.80
1 pc	N/S Front Sport Rim	S.Nett			\$ 680.00
	To putty and spray painting				\$ 1,000.00
	To check front wiring and focus headlights				\$ 30.00
	To check wheel alignment				\$ 60.00
	To transfer door fittings				\$ 50.00
	Labour Charges				\$ 600.00
TG-RA/-	TOTAL				\$ 7,847.80

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel:65-64520893 Fax:65-64589127 Website : www.LTM.sg
 Co.Reg No.199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd