

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST #04-05 IOB BUILDING

049711

Attention : Motor Claim Department

Contact : 6223 8122

Estimate : ES180017

Date : 27/11/2018

Vehicle Num. : SLR 1140K (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 21/11/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

1.	1	REAR TAILGATE 00		1,100.90 ✓
2.	1	REAR TAILGATE INNER LOCK NN		155.80 X
3.	1	REAR TAILGATE VEZEL EMBLEM NEC		84.60 ✓
4.	1	REAR TAILGATE HYBRID EMBLEM NEC		88.60 ✓
5.	1	REAR BUMPER 00		865.00 ✓
6.	1	REAR END PANEL NN		830.00 X
7.	1	REAR END PANEL TOP GARNISH NN		155.00 X
8.	1	REAR WINDSCREEN GLASS MOULDING NEC		215.00 ✓
9.	1	SMART BUZZER SENSOR		155.00 ?

List TotalS\$:

3,649.90

20.00% Discount S\$:

729.98

2,919.92

SPECIAL NETT ITEMS :

1.	1SET	REAR TAILGATE INNER TRIM BOARD CLIPS NEC		30.00 ✓
2.	1SET	REAR BUMPER CLIP NEC		30.00 ✓
3.	1SET	REAR END PANEL TOP GARNISH CLIPS NN		30.00 X
4.	1SET	REVERSE SENSOR		200 280.00 ?

Special Nett Total S\$:

370.00

LABOUR :

WIRINGS CHECK AND RECTIFY WHERE NECESSARY

60 180.00 ✓

REMOVE & REFIT REAR WINDSCREEN GLASS

120 180.00 ✓

TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES

60 180.00 ✓

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST #04-05 IOB BUILDING

049711

Attention : Motor Claim Department

Contact : 6223 8122

Estimate : ES180017

Date : 27/11/2018

Vehicle Num. : SLR 1140K (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 21/11/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE
REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN
CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS

500 1,600.00 ✓

DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE
REPAIRS AND REACTIVATE BACK SAME
(HV HYBRID SYSTEM SAFETY PROCEDURES)

450.00 ✕

PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING
FAULT CODES AND REINITIALISE HV HYBRID SYSTEM FOR POST
REPAIRS
(HV HYBRID SYSTEM SAFETY PROCEDURES)

450.00 ✕

PUTTY AND SPRAY PAINT ALL AFFECTED AREAS
(INNER/OUTER)

500 1,200.00 ✓

Labour Total S\$:

4,240.00

Resul
Hp 900/100 68
5 days
4 p/p
28/11/18 @ 1440
Resurvey by paint

E. & O.E.**Total S\$: 7,529.92**

=====

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: