

10/10/18

INS. CASE OWNER:

Global

CC /LPC1802

1790, R2563 m

LKK:

IDAC:

Surveyor:

Rasul

DOI:

ASSIGNMENT

10/1/18

polki

Date / Time:

10/1/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

YL 55513

Name of Insured:

TIA MEI TEAPING (S) PTE

Insured Tel No.:

HP:

Claim No.:

18/18/18/1000/021179

Policy No.:

1/18/1200/101515

Make / Model:

MITSUBISHI

Place of Accident:

VISSAN RD 3 BLK 133 LP

Excess Sec II :SS

D.O.A.:

20/1/18

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Lin Guan Siang

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L YES / NO)

Insured Liability:

%

Final ? Yes / No

GOL 751AK



INSRS:

WSP:

Tel:

Liability:

RMKS:

Sin sheng



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

10/1/18  
polki

GOL 751AK - x

YL 55513 - x

BOLA 27, 100%

pending finalise LOR

He pass to finalise LOR

pending LOR

Original LOR with LPC

He pass to type mandate report

After repair photo

STAGE

DATE / PIC

Non-Reporting Lr (1st):

Non-Reporting Lr (2nd):

Non-Reporting Lr (Final):

Notification Lr (if non-pickup):

Call OI:

After call Lr to OI:

Documentation Check List: Handler Typist

Notification Lr (if non-pickup):

After call Lr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / CCA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

11/1/18

Sent By:

LSP

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS 3,150.00

(

5

days) Reduction:

40.24

%

Email

Call

FINAL SETTLEMENT

Date/Time:

20/1/2019

Confirm with:

Susan

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

24

If NO or B 28, Ass. Lia:

Repair Cost:

(w/hst)

SS 3,390.50

Loss of Rental (LOR):

SS

-

(

days)

Loss of Use (LOU):

SS

720.00

(S120.00 x 1 days)

Loss of Income (LOI):

SS

-

(S

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick: only one)

GIA/LTA Search

SS

2.00

Medical:

SS

-

1) Claim status: Normal/Reject/Private Settle

Exbursement:

SS

-

(e.g. Tow/Independent)

2) Report Format:

TP

Legal Cost:

SS

-

3) Survey fee:

\$450.00

Total:

SS

4,090.50

Global Sum SS:

4,090.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

4,090.00

Name 1:

Sin Sheng Engineering Services

Payee 2 (Strike if N.A.)

SS

Name 2:

Payee 3 (Strike if N.A.)

SS

Name 3:

COPY SENT

OLD reverse out from parking lot

--	--




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC18021790/R1fb3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 04-12-2018	
		Code : LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	YL 5551J	Veh. Inspected	GBC 7519K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/12/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	29/11/2018	Inspection Date	14/12/2018
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC4/LPC18021790/R1fb3

Date: 17.12.2018

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**GBC7519K**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14.12.2018 at the premises of M/s Sin Sheng Engineering Services and have the following to report:-

Workshop Estimate Amount	: S\$	5,275.78
Revised Estimate Amount	: S\$	3,468.37
"Check" Items Amount	: S\$	476.29
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the  
Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

MOHD. RASUL  
Licensed Appraiser

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

1196N

### Vehicle Details

Vehicle No.:

GBC7519K

Vehicle to be Exported:

No

Intended Deregistration Date:

31 Dec 2018

Vehicle Make:

MITSUBISHI

Vehicle Model:

CANTER FB70BB15RDEA

Primary Colour:

Blue

Manufacturing Year:

2013

Engine No.:

4M42A91970

Chassis No.:

FB70BBA20645

Maximum Power Output:

-

Open Market Value:

\$23,158.00

Original Registration Date:

02 Oct 2013

First Registration Date:

02 Oct 2013

Transfer Count:

0

Actual ARF Paid:

\$1,158.00

### Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

### Intended COE Rebate Details

COE Expiry Date:

01 Oct 2023

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$73,999.00

COE Rebate Amount:

\$35,169.00

**Total Rebate Amount:**

**\$35,169.00**

The information contained herein is correct as at 03 Dec 2018

OK



# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002693

Date : 13/12/2018

Vehicle Num. : GBC7519K

Make/Model : MITSUBISHI FB 70-2013

Chassis/Eng# : FB70BBA20645/4M42A91970

Accident Date : 29/11/2018

Claim No. :

Reference : YL5551J

Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT PANEL <i>repair</i>		1,508.15
2.	1	WIPER PANEL <i>SCA</i>		545.20
3.	1	FRONT GRILLE <i>SCA</i>		1,144.71
4.	1	FUSO EMBLEM <i>new</i>		154.96
5.	1	'MITSUBISHI' EMBLEM <i>new</i>		85.20
6.	1	CANTER LOGO <i>new</i>		69.20
7.	1	FRONT BUMPER <i>BT</i>		821.47
8.	1	SIGNAL LAMP, LHS <i>car</i>		197.89
9.	1	HEADLAMP, LHS <i>?</i>		635.06
10.	1	MIRROR COVER <i>SCA</i>		115.20
List Total S\$ :				5,277.04
25.00% Discount S\$ :				1,319.26
				3,957.78
NETT ITEMS :				
1.	1	NUMBER PLATE <i>BT</i>		20.00
Nett Total S\$ :				20.00
10.00% Discount S\$ :				2.00
				18.00

CONTINUE / ...

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002693

Date : 13/12/2018

Vehicle Num. : GBC7519K

Make/Model : MITSUBISHI FB 70-2013

Chassis/Eng# : FB70BBA20645/4M42A91970

Accident Date : 29/11/2018

Claim No. :

Reference : YL5551J

Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

TO PANEL BEAT/REPAIR FR BODY

TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS

SPRAY PAINTING

LOSS OF USE : 5 DAYS @ \$ 120/DAY

Labour Total S\$ :

600

~~750~~ 750.00

500 ~~550~~ 550.00

1,300.00

*Rose*  
*Hp 90010068*  
*5 days*  
*1/1*  
*14/12/18*

Total S\$ : 5,275.78

*Rose & the*  
*repair*

SIN SHENG ENGINEERING SERVICES

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002693

Date : 13/12/2018

Vehicle Num. : GBC7519K

Make/Model : MITSUBISHI FB 70-2013

Chassis/Eng# : FB70BBA20645/4M42A91970

Accident Date : 29/11/2018

Claim No. :

Reference : YL5551J

Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT PANEL <i>repair</i>		
2.	1	WIPER PANEL <i>SCA</i>		1,508.15 X
3.	1	FRONT GRILLE <i>SCA</i>		545.20
4.	1	FUSO EMBLEM <i>new</i>		1,144.71
5.	1	'MITSUBISHI' EMBLEM <i>new</i>		154.96
6.	1	CANTER LOGO <i>new</i>		85.20
7.	1	FRONT BUMPER <i>BT</i>		69.20
8.	1	SIGNAL LAMP, LHS <i>CH</i>		821.47
9.	1	HEADLAMP, LHS <i>? CH</i>		197.89
10.	1	MIRROR COVER <i>SCA</i>		635.06
				115.20
		List Total S\$ :	3768.89	5,277.04
		25.00% Discount S\$ :	259	1,319.26
			2826.66	3,957.78
NETT ITEMS :				
1.	1	NUMBER PLATE <i>BT</i>		20.00
		Nett Total S\$ :		20.00
		10.00% Discount S\$ :		2.00
			18	18.00

CONTINUE / ...



# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT  
SINGAPORE 638129  
Tel No. : 6863-9595 Fax No. : 6863-6477  
E-Mail : sinsheng1981@gmail.com  
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD  
59 SENOKO ROAD  
SINGAPORE 758123

Attention : Motor Claim Department  
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002693

Date : 13/12/2018  
Vehicle Num. : GBC7519K  
Make/Model : MITSUBISHI FB 70-2013  
Chassis/Eng# : FB70BBA20645/4M42A91970  
Accident Date : 29/11/2018  
Claim No. :  
Reference : YL5551J  
Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :  
TO PANEL BEAT/REPAIR FR BODY  
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS

SPRAY PAINTING

LOSS OF USE : 5 DAYS @ S 120/DAY

Labour Total S\$ :

600  
~~750~~ 750.00

500 ~~550~~ 550.00

1100

1,300.00

Rose  
Hp 90010068

5 days

4/5

14/12/18

Total S\$ : 5,275.78

Rose & the  
repair

SIN SHENG ENGINEERING SERVICES

2826.66

18.00

1100.00

3944.66

209

3155.72

45-3,150 5 days

**Catherine Chong (LKK Auto)**

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Monday, 3 December, 2018 4:02 PM  
**To:** Admin-D (LKKAuto)  
**Cc:** MT\_Claim\_SG  
**Subject:** FW: Accident involving GBC7519K with YL5551J on 29/11/2018

Dear Catherine,

Kindly proceed with the survey accordingly.

*03-12-2018 @ 4:05pm  
Susan veh not in*

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** sinsheng engineerservices [mailto:sinsheng1981@gmail.com]  
**Sent:** Monday, 3 December, 2018 3:54 PM  
**To:** GERALD POH WEE BIN  
**Cc:** MT\_Claim\_SG  
**Subject:** Re: Accident involving GBC7519K with YL5551J on 29/11/2018

Hi Mr Gerald,

We are selected Mr Taufikh.

*Thank You  
Regards*

*Susan  
Sin Sheng Engineering Services  
3 Tech Park Crescent  
Tuas Tech Park  
Singapore 638129  
Tel: 6863 9595  
Fax: 6863 6477*

On Mon, 3 Dec 2018 at 15:56, GERALD POH WEE BIN <geraldpoh@lonpac.com> wrote:

WITHOUT PREJUDICE

Our Ref : 18/18/18/VC00/021179

Dear Susan,

Attached list of motor surveyors for your necessary action.

We are unable to comment on liability yet as our insured has not lodged a report.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** sinsheng engineerservices [mailto:[sinsheng1981@gmail.com](mailto:sinsheng1981@gmail.com)]

**Sent:** Monday, 3 December, 2018 2:51 PM

**To:** GERALD POH WEE BIN

**Subject:** Accident involving GBC7519K with YL5551J on 29/11/2018

Dear Officer Incharge,

We are repairer of motor vehicle GBC7519K . Enclosed Accident Statement and LTA search fee for your attention please. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two (2) workings days upon received this email.

Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection.

Kindly assist to revert the liability issue or offer if direct settlement is in order

*Thank You  
Regards*

*Susan  
Sin Sheng Engineering Services*

3 Tech Park Crescent  
Tuas Tech Park  
Singapore 638129  
Tel: 6863 9595  
Fax: 6863 6477

## Shu Pei (LKKAuto)


---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Tuesday, 18 December 2018 9:04 AM  
**To:** Shu Pei (LKKAuto)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Accident involving GBC7519K with YL5551J on 29/11/2018  
**Attachments:** 18122018090043.pdf

Dear Shu Pei,

Attached copy of insured's GIA report for your attention.

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



---

**From:** Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]  
**Sent:** Monday, 17 December, 2018 7:37 PM  
**To:** GERALD POH WEE BIN  
**Cc:** MT\_Claim\_SG; Admin A; Poh Kin (LKKAuto)  
**Subject:** RE: Accident involving GBC7519K with YL5551J on 29/11/2018

### WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle GBC 7519K at M/s Sin Sheng Engineering Services on a WP basis and TP repairer proposed for a direct settlement.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Our case handler in-charge is Poh Kin and he can be contacted at DID: 6841-2132.

Thank you.



Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)

**Sent:** Monday, 3 December 2018 4:07 PM

**To:** 'GERALD POH WEE BIN' <[geraldpoh@lonpac.com](mailto:geraldpoh@lonpac.com)>

**Cc:** 'MT\_Claim\_SG' <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: Accident involving GBC7519K with YL5551J on 29/11/2018

Dear Mr Gerald,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]

**Sent:** Monday, 3 December, 2018 4:02 PM

**To:** Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>

**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>

**Subject:** FW: Accident involving GBC7519K with YL5551J on 29/11/2018

Dear Catherine,

Kindly proceed with the survey accordingly.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** sinsheng engineerservices [<mailto:sinsheng1981@gmail.com>]

**Sent:** Monday, 3 December, 2018 3:54 PM

**To:** GERALD POH WEE BIN

**Cc:** MT\_Claim\_SG

**Subject:** Re: Accident involving GBC7519K with YL5551J on 29/11/2018

Hi Mr Gerald,

We are selected Mr Taufikh.

*Thank You  
Regards*

*Susan  
Sin Sheng Engineering Services  
3 Tech Park Crescent  
Tuas Tech Park  
Singapore 638129  
Tel: 6863 9595  
Fax: 6863 6477*

On Mon, 3 Dec 2018 at 15:56, GERALD POH WEE BIN <[geraldpoh@lonpac.com](mailto:geraldpoh@lonpac.com)> wrote:

WITHOUT PREJUDICE

Our Ref : 18/18/18/VC00/021179

Dear Susan,

Attached list of motor surveyors for your necessary action.

We are unable to comment on liability yet as our insured has not lodged a report.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** sinsheng engineerservices [mailto:[sinsheng1981@gmail.com](mailto:sinsheng1981@gmail.com)]

**Sent:** Monday, 3 December, 2018 2:51 PM

**To:** GERALD POH WEE BIN

**Subject:** Accident involving GBC7519K with YL5551J on 29/11/2018

Dear Officer Incharge,

We are repairer of motor vehicle GBC7519K . Enclosed Accident Statement and LTA search fee for your attention please.  
Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two (2) workings days upon received this email.

Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection.

Kindly assist to revert the liability issue or offer if direct settlement is in order

*Thank You*

*Regards*

*Susan*

*Sin Sheng Engineering Services*

*3 Tech Park Crescent*

*Tuas Tech Park*

*Singapore 638129*

*Tel: 6863 9595*

*Fax: 6863 6477*

**Poh Kin (LKKAuto)**

---

**From:** sinsheng engineering services <sinsheng1981@gmail.com>  
**Sent:** Monday, 29 April 2019 2:39 PM  
**To:** Poh Kin (LKKAuto)  
**Cc:** Admin A  
**Subject:** Re: Accident involving GBC7519K with YL5551J on 29/11/2018 [External Confidential]

Hi Ms Poh Kin,

We are agreed, please forward us with the Discharge Voucher.

*Thank You  
Regards*

*Susan  
Sin Sheng Engineering Services  
3 Tech Park Crescent  
Tuas Tech Park  
Singapore 638129  
Tel: 6863 9595  
Fax: 6863 6477*

On Mon, 29 Apr 2019 at 14:29, Poh Kin (LKKAuto) <pohkin@lkkauto.com> wrote:

**WITHOUT PREJUDICE**  
**SAVE AS TO COSTS**

Our Ref: CC4/LPC18021790/R1fb3  
Your Ref: GBC 7519K

Dear Susan,

We refer to above matter and your letter of demand.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement at global sum of **\$4,090.00**(all in) on this matter.

kindly confirm acceptance.

Your prompt reply will be very much appreciated.

## Poh Kin (LKKAUTO)

---

**From:** Poh Kin (LKKAUTO)  
**Sent:** Monday, 29 April 2019 2:29 PM  
**To:** sinsheng1981@gmail.com  
**Cc:** Admin A  
**Subject:** RE: Accident involving GBC7519K with YL5551J on 29/11/2018 [External Confidential]

### WITHOUT PREJUDICE SAVE AS TO COSTS

Our Ref: CC4/LPC18021790/R1fb3  
Your Ref: GBC 7519K

Dear Susan,

We refer to above matter and your letter of demand.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement at global sum of \$4,090.00(all in) on this matter.

kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Poh Kin, Chong (Mr) | Case Handler**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Poh Kin (LKKAUTO)  
**Sent:** Thursday, 18 April 2019 3:07 PM  
**To:** GERALD POH WEE BIN <geraldpoh@lonpac.com>



## Poh Kin (LKKAUTO)

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Tuesday, 23 April 2019 5:41 PM  
**To:** Poh Kin (LKKAUTO)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. YL 5551J (OI) AND GBC 7519K (TP) ON 29-11-2018; LKK ref : CC4/LPC18021790/K1fb3; Lonpac ref: 18/18/18/VC00/021179 [External Confidential]


**Categories:** clear

### Lonpac External - Confidential

Dear Poh Kin,

We are agreeable to your proposal for cost of repair but for loss of use, we proposed the amount \$720.00 ( 6 days x \$120).

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

---

**From:** Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]  
**Sent:** Monday, 22 April, 2019 2:57 PM  
**To:** GERALD POH WEE BIN  
**Cc:** MT\_Claim\_SG; Admin A  
**Subject:** SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. YL 5551J (OI) AND GBC 7519K (TP) ON 29-11-2018; LKK ref : CC4/LPC18021790/K1fb3; Lonpac ref: 18/18/18/VC00/021179  
**Importance:** High

#### Without Prejudice

Our Ref: CC4/LPC18021790/R1fb3  
Your Ref: 18/18/18/VC00/021179

Dear Sir/Madam,

**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. YL 5551J (OI) AND GBC 7519K (TP) ALONG CARPARK OF BLK 173 YISHUN AVENUE 3 ON 29/11/2018**

## Poh Kin (LKKAUTO)

---

**From:** Poh Kin (LKKAUTO)  
**Sent:** Monday, 22 April 2019 2:57 PM  
**To:** 'GERALD POH WEE BIN'  
**Cc:** 'MT\_Claim\_SG'; Admin A  
**Subject:** SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. YL 5551J (OI) AND GBC 7519K (TP) ON 29-11-2018; LKK ref : CC4/LPC18021790/K1fb3; Lonpac ref: 18/18/18/VC00/021179  
**Attachments:** LKK Adjustment report.pdf; LKK Inspection report.pdf; LKK Resurvey photo.pdf; LKK Survey photo.pdf; TP LOD.pdf  
**Importance:** High

### Without Prejudice

Our Ref: CC4/LPC18021790/R1fb3  
Your Ref: 18/18/18/VC00/021179

Dear Sir/Madam,

### ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. YL 5551J (OI) AND GBC 7519K (TP) ALONG CARPARK OF BLK 173 YISHUN AVENUE 3 ON 29/11/2018

We refer to the above matter.

Liability: The accident occurred when our insured driver collided with third party vehicle while reversing. Liability is down against our insured as Vehicle reversing in/out of parking lot should exercise greater caution.

Summary to offer to third party repairer, Sin Sheng Engineering Services is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair	\$ 5,275.78	\$ 3,370.50 (\$3,150.00 + 7% gst)
2. Loss of Use	\$ 840.00 (\$120.00 x 7 days)	\$ 840.00 (\$120.00 x 7 days)
3. LTA search fee	\$ 2.00	\$ 2.00
<b>Total</b>	<b>\$ 6,117.78</b>	<b>\$ 4,212.50</b>

**\*\*5 days recommendation for repair + 1 day downtime/survey + 1 day weekend = 7 days**

Relevant supporting claim documents are attached herewith for your perusal and reference.

The above is for your approval.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18021790/R1fb3n2

300 BEACH ROAD  
#17-04/07 THE CONCOURSE SINGAPORE 199555

Date : 13-05-2019



Code : LPC2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YL 5551J	Veh. Inspected	GBC 7519K
Policy No.	Z/18/VC00/101525	Coverage (\$)	0.00
Claim No.	18/18/18/VC00/021179	Excess (\$)	0.00
Assign From	GERALD	Assign Date	04/12/2018

## 2. Vehicle Particulars & Condition

Make & Model	mitsubishi FB70BB	c.c	2977
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	FB70BBA20645	Colour	BLUE
Odometer	161564	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/75 R15	BRIDGESTONE	7 mm
L/H Front Tyre	185/75 R15	BRIDGESTONE	7 mm
R/H Rear Tyre	185/75 R15 (D)	BRIDGESTONE	7/7 mm
L/H Rear Tyre	185/75 R15 (D)	BRIDGESTONE	7/7 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.
---

## 5. General Information

Accident Date	29/11/2018	Inspection Date	14/12/2018
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 7519K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT PANEL	TO REPAIR SEE LABOUR	1,508.15	-
1	WIPER PANEL	SCRATCHED	545.20	545.20
1	FRONT GRILLE	SCRATCHED	1,144.71	1,144.71
1	FUSO EMBLEM	NECESSARY	154.96	154.96
1	'MITSUBISHI' EMBLEM	NECESSARY	85.20	85.20
1	CANTER LOGO	NECESSARY	69.20	69.20
1	FRONT BUMPER	BENT	821.47	821.47
1	SIGNAL LAMP ,LHS	CRACKED	197.89	197.89
1	HEADLAMP ,LHS	CRACKED	635.06	635.06
1	MIRROR COVER	SCRATCHED	115.20	115.20
	LESS 25% DISCOUNT		-1,319.26	-942.22
			3,957.78	2,826.67
	<b><u>NETT ITEMS</u></b>			
1	NUMBER PLATE (N)	BENT	20.00	20.00
	LESS 10% DISCOUNT		-2.00	-2.00
			18.00	18.00
	<b><u>LABOUR</u></b>			
	TO PANEL BEAT /REPAIR FR BODY TO DISMANTLE /REPLACE ABOVEMENTIONED PARTS.INCLUSIVE OF THE REPAIR OF FRONT PANEL .		750.00	600.00
	SPRAY PAINTING.		550.00	500.00
			1,300.00	1,100.00
	<b>GRAND TOTAL</b>		<b>5,275.78</b>	<b>3,944.67</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,150.00</b>

Report Ref No. CC4/LPC18021790/R1fb3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.