

15/5/2019

15/5/2019 15:00 21792, 15/5/2019

15/5/2019

Arnk

ASSIGNMENT

Date / Time:

21/11/18

Registered in Merimen:

Pre-assign / CCU / FTE

GBD 152L



Insured Vehicle No.

Name of Insured

Leo Furniture & Construction

Insured Tel No.

HP:

Excess Sec II :SS

D.O.A:

30/11/2018

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SHD 1144X



INSRS:

WSP: Premier

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SHD 1144X - 15/11/18 3015284/m/g/b, DOA: 21/11/18

GBD 152L - X

21/11/18

LIABILITY UNCLEAR : PENDING FOR BY-DANCE.

RED TP 1:00 SAVE IN (V: ASHER: 2019) VIDEO SHOW OLD CUT INTO TP LANE AND HIT TP.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

Email 23.10.19

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Arnk

Repair Cost: P/P \$5693.99

(1 days) Reduction: 7 %

Email ☒ Call ☐

FINAL SETTLEMENT Date/Time: 15.11.19

Confirm with SHAM JYE

Email ☒ Call ☐

Final Liability: % 100

(Agreed / Assessed) BOLA S/N No. : NIL

If NO or B 28, Ass. Lia :

Repair Cost: W/LST \$5743.57

OLD CUT INTO TP LANE AND HIT TP.

Loss of Rental (LOR): \$5311.37 (3 days) x 103.71

Loss of Use (LOU): \$5 - (\$ x days)

Loss of Income (LOI): \$5100.00 (\$40 x 3 days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☒ [Tick only one]

GIA/LTA Search \$52.00

Medical: \$5 -

Disbursement: \$5 -

Legal Cost \$5 -

Total: \$51,115.94

Global Sum \$5: 1,170.00

FINAL PAYMENT Date/Time: 15.11.19

Confirm with: SHAM JYE

Email ☒ Call ☐

Payee 1: \$51,170.00

Name 1: PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.) \$5

Name 2:

Payee 3: (Strike if N.A.) \$5

Name 3:

1) Claim status: ~~Normal~~/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 400

CONFIRMED 21/11/19



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI18021792/K1pa3

Date: 05.12.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD 1144X


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 03/12/2018 at the premises of M/s Premier Automotive Services Pte Ltd - Changi have the following to report:-

Workshop Estimate Amount	: S\$	743.99
Revised Estimate Amount	: S\$	693.99
"Check" Items Amount	: S\$	
Total (Including Check Items)	: S\$	693.99
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
N/S wing mirror



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 1.0 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Text size + -

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
Owner ID Type: Company
Owner Name: PREMIER TAXIS PTE. LTD.
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
Mailing Address: -
Birth Date: -

Vehicle Particulars

Vehicle No.: SHD1144X
Previous Vehicle No.: -
Effective Date of Ownership: 25 Jan 2017
Original Regn Date: 25 Jan 2017
Registration Date: 25 Jan 2017
Year of Manufacture: 2016
Vehicle Type: Public Transport Taxi (Motor Car)
Vehicle Scheme: Taxi (Company)
Vehicle Attachment 1: Air-Con (Taxi)
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Make: HYUNDAI
Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
Primary Colour: Silver
Secondary Colour: -
Passenger Capacity: 4
Chassis No.: TMAD281UVHJ119070
Engine No.: D4FBGZ095197
Engine Capacity/Power Rating: 1582 cc / -
Maximum Power Output: 100.0 kW (134 bhp)
Propellant: Diesel
Max Unladen Weight: 1496 kg
Maximum Laden Weight: 1940 kg
Open Market Value: \$20,830.00
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 24 Jan 2025
Minimum PARF Benefit: \$8,197.00
No. of Transfers: 0
IU Label No.: 1050703123
COE No.: 2017012501003880C
COE Expiry Date: 24 Jan 2025
COE Category: A - Car (up to 1600cc & 97kW (130bhp))
COE Registration Category: A - Car (up to 1600cc & 97kW (130bhp))

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

3-Dec-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) REGN NO: SHD 1144 X

1 pc	n/s mirror assy	<i>Broken</i>	\$	742.49
		Less 20%	\$	148.50
			\$	593.99
	Sundry	<i>nec</i>	\$	50.00 <i>20</i>
	To labour charge for dismantle and renew the accident damaged parts.		\$	100.00 <i>80</i>
			\$	743.99

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Kahinukky

3/12/18 1550h
1 Pk.

PIP

Before PIP

5/12/18
white
PIP \$ 693.99 / 1 Pk

- LKK Auto Consultant's hereby notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

3-Dec-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) REGN NO: SHD 1144 X

1 pc	n/s mirror assy		\$	742.49
		Less 20%	\$	148.50
			\$	593.99
	Sundry		\$	50.00 20
	To labour charge for dismantle and renew the accident damaged parts.		\$	100.00 100
			\$	743.99

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Kahinilley

3/12/18 1550h
1 Pcy.

P/P

Before P/P

LKK & Associates hereby certify that the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mei Kwan (LKKAUTO)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Friday, 11 October, 2019 2:43 PM
To: Mei Kwan (LKKAUTO); Asher Sng (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GBD2152L (OI : CTI - SNM18D05866C02) and SHD1144X (TP : LKK REF - CC3/CTI18021792/K1ea3) on 30/11/2018
Attachments: GBD2152L.PDF
Categories: HMK

Dear Mei Kwan,

We refer to your email below.

Attached is our insured's GIA report for your necessary actions.

Please keep us posted on the status of the claim.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Tuesday, October 8, 2019 11:09 AM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Subject: FW: Direct Settlement - Accident Involving GBD2152L (OI : CTI - SNM18D05866C02) and SHD1144X (TP : LKK REF - CC3/CTI18021792/K1ea3) on 30/11/2018

Dear All,

Officer in charge – Kah Leong.

Dear Kah leong,

Please revert LKK.

Thank you

Claims Department

From: Mei Kwan (LKKAuto)
Sent: Monday, 4 March, 2019 10:36 AM
To: Catherine Thia <catherine.thia@sg.cntaiping.com>; claimsdept@sg.cntaiping.com
Cc: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving GBD2152L (OI : CTI - SNM18D05866C02) and SHD1144X (TP : LKK REF - CC3/CTI18021792/K1ea3) on 30/11/2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)
Sent: Monday, 24 December, 2018 1:36 PM
To: Lucas Lee <lucas.lee@sg.cntaiping.com>
Cc: Catherine Thia <catherine.thia@sg.cntaiping.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving GBD2152L (OI : CTI - SNM18D05866C02) and SHD1144X (TP : LKK REF - CC3/CTI18021792/K1ea3) on 30/11/2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Lucas,

Please provide us appointment letter.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Thursday, 20 December, 2018 3:59 PM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Cc: Catherine Thia <catherine.thia@sg.cntaiping.com>
Subject: RE: Direct Settlement - Accident Involving GBD2152L (OI : CTI - SNM18D05866C02) and SHD1144X (TP : LKK REF - CC3/CTI18021792/K1ea3) on 30/11/2018

Dear Sir,

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI18021792/K1ea3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 06-12-2019	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 2152L	Veh. Inspected	SHD 1144X	
Policy No.	DMCVSN1531151803	Coverage (\$)	0.00	
Claim No.	SNM18D05866C02	Excess (\$)	0.00	
Assign From		Assign Date	03/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I30	c.c	1582	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	TMAD281UVHJ119070	Colour	SILVER	
Odometer	163268	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MAXXIS	7 mm	
L/H Front Tyre	195/65 R15	MAXXIS	7 mm	
R/H Rear Tyre	195/65 R15	MAXXIS	7 mm	
L/H Rear Tyre	195/65 R15	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S WING MIRROR. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/11/2018	Inspection Date	03/12/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1144X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	N/S MIRROR ASSY	BROKEN	742.49	742.49
	LESS 20% DISCOUNT		-148.50	-148.50
			593.99	593.99
	SPECIAL NETT ITEMS			
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			50.00	20.00
	LABOUR			
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.		100.00	80.00
			100.00	80.00
	GRAND TOTAL		743.99	693.99
RECOMMENDED COST OF REPAIRS				693.99

Report Ref No. CC3/CTI18021792/K1ea3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.