

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

03/12/2018

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1

Veh # :- YN8068H

Veh Model :- ISUZU NHR85AUE4A R1

Estimate# :- CK418374

Claim # :-

ACC. Date :- 28/11/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR GATE <i>RM</i>	1 PC	1,600.00	1,600.00
2.	REAR GATE HINGES (LOWER)	1 PC <i>1pc</i>	110.00	440.00
3.	REAR GATE STICKER 'ISUZU' <i>rm</i>	1 PC	253.00	253.00
4.	REAR GATE LOWER MEMBER - REPAIR	1 PC		
	LIST TOTAL S\$			2,293.00
	15% DISCOUNT S\$			-343.95
				1,949.05
SPECIAL NET ITEMS :				
1.	REAR GATE INNER BOARD <i>X</i>	1 PC	400.00	400.00
2.	REAR GATE STICKER '60KM/H' <i>rm</i>	1 PC	10.00	10.00
	SPECIAL NET TOTAL S\$			410.00
LABOUR :				
TO REPAIR REAR GATE LOWER MEMBER, REAR SIDE GATE RH. TO REMOVE AND REFIX DAMAGED PARTS. STRAIGHTEN AND RE-ALIGN AFFECTED AREAS				
TO SPRAY AFFECTED AREAS				
	LABOUR TOTAL S\$			900.00

Repair
Hy 90010068

4 days

4/5

01/01/19 @ 1150

Repair after repair

300 400.00
400 500.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 3,259.05

GST @ 7 % 228.13

AMOUNT DUE S\$ 3,487.18

Acknowledged by Repairer

Signature:

Date:

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**