

Our Ref : SH/2018/152/11/013/TP

Date : 02 April 2019

The Motor Claims Department
AIG ASIA PACIFIC INSURANCE PTE LTD
BLK 78 #08-16
SHENTON WAY
CHARTIS BUILDING
SINGAPORE 079120

Dear Sir / Madam,

RE: Accident Involving SLA1101M & SGN2880G on 10.11.2018

I forward herewith copies of the following documents for claiming against your insured for my loss of use :-

Cost Of Repair - Invoice No: AR201903-0142	:	S\$ 3,050.10
Loss Of Use (\$ 100.00 x 4 days)	:	S\$ 400.00
		<u>S\$ 3,450.10</u>


Your co-operation and prompt settlement towards this matter are much appreciated.

Kindly acknowledge the receipt of this letter.

Thank you very much for your kind attention.

Yours faithfully,

encl



Tax Invoice No.: AR201903-0142



AIG ASIA PACIFIC INSURANCE PTE LTD

File No: SH/2018/152/II/013/TP

BLK 78 #08-16
SHENTON WAY
CHARTIS BUILDING
SINGAPORE 079120

Date: 29-March-2019

Cost of repair for vehicle no: SLA1101M Model: HYUNDAI ELANTRA
Accident involving vehicle no: SLA1101M & SGN2880G on 10-November-2018

Description

Front bumper	\$	448.30
RH head lamp	\$	1,756.40
RH bumper focus lamp	\$	233.50
	\$	2,438.20
Less 20%	\$	-487.64
	\$	1,950.56
 RH bumper parking sensor	\$	 180.00
To spray paint bonnet bumper and accident repair areas.	\$	400.00
Labour charges to fixed and removed front bumper, head lamp, and install damaged areas.	\$	300.00
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.	\$	20.00
	Cost of Repair \$	2,850.56
	7% GST \$	199.54
	\$	3,050.10

T/Party: AIG ASIA PACIFIC INSURANCE PTE LTD

Received By

No signature is required as this is a computer generated invoice